

ENDURA SUPPLY

Ziehl Abegg Product List

- Part No: QK08A-4EM.50.CB
- Part No: 406513
- Part No: 18165
- Part No: 18684
- Part No: 18694
- Part No: 2006458
- Part No: 2006939
- Part No: 23781
- Part No: 07094213/AB
- Part No: 1 25797
- Part No: 107975
- Part No: 109016
- Part No: 109016-FB063-6EQ.4I.V4P
- Part No: 10A LAK
- Part No: Type: RH28M-2EK.3F.1R
- Part No: 130599/A01
- Part No: 134011
- Part No: Artikelnummer: 138274
- Part No: 140 677
- Part No: FN050-VDK.4I.V7P1
- Part No: 142185, IP54 THCL 155
- Part No: 1614686
- Part No: 168216 /FN063-4DQ.6N.A7P6
- Part No: 1S404PR35
- Part No: 209773
- Part No: TX140L06 400V50HZ
- Part No: 262309000
- Part No: 3,5 HP MOTOR
- Part No: 3-400W +/-10% D/Y50HZ 2.1/1025KW P1 4.0/2.3A 980/660MM CCSY0.74 R/N50.C IP547HDLF
- Part No: 500 AXIAL FAN ABSORBENT
- Part No: 52-16-310

- Part No: 650018
- Part No: 760 5035P01
- Part No: 7605070P01
- Part No: A0900 4PA27
- Part No: A900 4PA27
- Part No: TX140L08 400V/56Hz B01 Ref.-No. 5001023510
- Part No: A9000PA2717TX140L06
- Part No: TX140L06 400V56HZ # 5001019007
- Part No: TX140L08 400V56HZ B1
- Part No: A900PA2717, TX140L06
- Part No: A900PA2717TX140L08
- Part No: TX140L08 400V56HZ
- Part No: APR-35
- Part No: CAPACITOR FOR 107975
- Part No: CODE:153975 MODEL:FN080-SDQ.6N.V7
- Part No: DIVFMV
- Part No: DIVFMV FAN A0400PL30 MX040P04 230V/50HZ
- Part No: DIVFMV S04203PL30TX033P04 REF.# 018325E
- Part No: DIVFMV, FMV S0350 VD46 MG050W04
- Part No: DIVFMV, S600VIL44 TG100L04
- Part No: DIVFMV,FAN S0600 4PR30 TX100L04
- Part No: FA 035 4DK.2C.V6
- Part No: FA035-VDL.2C.V6
- Part No: FB 045 VDK
- Part No: FB 045 VDK-4-I V4S 400V
- Part No: FB 063-6EK.4I.V4P - OEM
- Part No: FB025-2EA.WC.A5
- Part No: FB030 a “ 4EK a “ WC a “ V5
- Part No: FB045VDK4L.V4S
- Part No: FB050-4EK.4I-6-P
- Part No: FB063-6DK.41.V4P
- Part No: FC035-4DA.2C.A7
- Part No: FC040-4DA.2C.A7
- Part No: FC080-SDA.6N.V5
- Part No: FC080-SDA.6N.V5 ARTICLE NO:120 802 460VCA. PH: 3

- Part No: FE040-4DA.2C.A7 (138721)
- Part No: FE050-4EA.41.V7, 1-230V +- 10% 50HZ P1 0.78KW P160C, 3.4A DI 0% 1280RPM, 16UF/400V
- Part No: FE050-VDK.41.V7
- Part No: FE050-VDS.41.V7 (400V +-10% 1330D/DK COS D.0,79 55C) 3 FAZ 0,79/0,48KW 1,45/0,89A
- Part No: FE080-SDA.6N.2 alternative FN080-SDA.6N.V7
- Part No: Type:FN080-SDA.6N.V7
- Part No: FE080-SDA.6N.V7 OBSOLETE NEW MODEL 153975 - FN080-SDQ.6N.V7
- Part No: FE080-SDS.6N.7
- Part No: FE080-SDS.6N.S
- Part No: FE-080-SDS.6N.V7
- Part No: FE080-SDS.6N.V7
- Part No: FE100-NDS.6N.7
- Part No: FL050-VDK.4I.V5S (136471)
- Part No: FN080- DQ6V7
- Part No: FN080-NDQ.6K.V7
- Part No: FN080-SDQ.6N.V7 INVALID CODE
- Part No: FV50V-2DF.G7.45.G
- Part No: GS-FAN-PFN-005
- Part No: HCE42(LH)CU/AL
- Part No: HELICE FOR MOTOR MX05DP06
- Part No: HYTDTA 180.56-4 (QUIRI)
- Part No: 134598 type MK165-6DK.18.N
- Part No: MGC30W8
- Part No: MK096-6IK.10.LK-OBSOLETE
- Part No: MODEL - A900PA2717 TX12L12
- Part No: MOT TX033P04 230/400V 56Hz # 5001028819
- Part No: MX05DP06
- Part No: Type:QK08A-2EM.35.CF
- Part No: QK08A-2EM.35.CF 205156
- Part No: QK08A-2EM.50 CH (Artikelnummer 105644) QuerstromgeblÄse mit Kapillarkeilzunge und Einphasen- Wechselstrommotor
- Part No: (105644) QK08A-2EM.50.CH
- Part No: QK08A-4EM.50.CD
- Part No: QK08A-4EM-50.CB 230V 0,29A 50HZ 0,006KW FAN

- Part No: QK10 A -2DM-38,400V AC 50HZ
- Part No: Type: QK10A-2EM.48.FK
- Part No: QK10A-2DM.38.FK
- Part No: Type:QK10A-2DM.48.FK
- Part No: RE 28P - 4DK 4I 1R
- Part No: REPLACEMENT FOR FAN MOTOR, 380. 415 VOLTS 50HZ
- Part No: RF22P-2DD.5H.1R Artikelnummer: 112473E
- Part No: RF22P-2DK.3F.1R
- Part No: RF28P-4DN.C5.4L (OEM)
- Part No: RFA 60/30-TD 1
- Part No: RG12S-2EP.W6.AR 113071
- Part No: RG28P-4EK.4I.1R Artikelnummer: 112305
- Part No: RH25V-6IK.BA.1R
- Part No: RH28M-2DK 3F1R
- Part No: RH28M-2DK.3F.1R
- Part No: RH28M-2EK.3F.1R.
- Part No: 125797
- Part No: Art. Nr. 125999E , type RH35B-2EK.6N.2R
- Part No: Type: RH35M-4EK.2F.1R
- Part No: RH71M-6DK.7M.1R
- Part No: S0350 VD43 TG030W04 400V/50HZ REF.-NO. 018260
- Part No: 18708
- Part No: S0355 VD46 MG030W03
- Part No: S04203PL30TX033P04
- Part No: S0630 4PR25
- Part No: S0630 VIL38 TG050L06
- Part No: S0630V5L38/TG050L06
- Part No: S50-APR32 TX70P6
- Part No: S710 VIL51
- Part No: S710 VIL51 TG80L8 REF.# 023781
- Part No: SO650VIL51
- Part No: ST1-24V
- Part No: ST2-24V
- Part No: THCL 155 A/C
- Part No: FC040-4DQ.2F.A7

- Part No: TX 090P4 400V,50 HZ, # 018830
- Part No: TX033P4
- Part No: DGZA0605A
- Part No: TX140L06 400V/ 50 HZ
- Part No: TX140L06 Ref.950641
- Part No: TYPE : 50450 CR 46 MG 060W04 A1
- Part No: Type S0350 VD43 MG030W04 , Nr. 5001018265E
- Part No: TYPE: S355 4PR30 TA35W4 , REF NO.353 45 703 041 42 703- NO LONGER PRODUCE.THE ALTERNATIVE IS TF040
- Part No: TYPE:A40PL30 MBC50P4 ,REF:408-23-204 140 22~204 NICHT MEHR LIEFERBAR
- Part No: TYPG•:SD 400
- Part No: Typ: U-EK230E Artikelnummer: 382008
- Part No: VENTILATEUR
- Part No: VOTLTAGES: 230VAC 50HZ, 1~ POWER: 0.3KW CURRENT: 1.4A SPEED: 1340RPM
- Part No: FE050-VDA.4 (OBSOLETE) 3028852/0001 REPLACED BY FN050-VDA.4I.V7P1 (141406)
- Part No: POE-MSPLT-USB
- Part No: FN050-VDA.4I.V7P1 (141406) Axialventilator mit gesicherten FIAGeln ohne Aufbauten
- Part No: MKP 6,0 uF/ 425V UL Artikelnummer 02006935 Motorkondensator
- Part No: A60-4PR30, 018583
- Part No: S-35 PR-35 No.ref : 386-47-701 4-48-701 obsolete replaced by 5001018311 TA 30 w4
- Part No: FC040-4DQ.2F.3 - OEM - REPLACED BY FC040-4DQ.2F.A7
- Part No: 5001018311 S0355 3PL25 TF030W04 230/400V 50Hz
- Part No: FC080-6N 230V
- Part No: 112473E
- Part No: 142603E (OEM for Siemens)
- Part No: Type: RH40M-4EK.4I.1R Artikelnummer: 130172E
- Part No: RH40M-4DK.4F.1R
- Part No: 1PH8912-1BC80-0AA0
- Part No: Type:FN080-SDQ.6N.V7
- Part No: Type: RH50M-4EK.6K. 1R
- Part No: 128888
- Part No: FB045-VDK.4F.V4P
- Part No: 5001018997
- Part No: FN080-NDQ.6K.V7 / 153161E
- Part No: 102372K RE22P-20K-3F.1R
- Part No: MOT TX140L06

- Part No: Type:QK10A-4EM.78.CH (210800)
- Part No: FN080-SDQ.6N.V7
- Part No: 141384 FN063-SDK.4I.V7P1
- Part No: S0350 VD43 TG030W04 # 5001018269
- Part No: S 450 CR46MG060W04A1
- Part No: FN050-4EK.4I.V7P1
- Part No: MAL 1
- Part No: 210800
- Part No: Type: RH28M-2DK.3F.1R
- Part No: IA90-4PA27
- Part No: MAL1 384017
- Part No: P/N.138274,Type FB050-4DK.4I.V4P
- Part No: Type:FN050-VDA.4I.V7P1
- Part No: 110653 Type: RG35P-4Dk.7M.1L
- Part No: S0355VD46
- Part No: FC063-VDK.6K.V7 OEM
- Part No: FX 33P4
- Part No: TX 33P4 obsolete, alternativ TX033P04
- Part No: X-FC056-6EF
- Part No: 142505
- Part No: THCL F IP54 obsolete, alternative FN045-VDK.4F.V7P1
- Part No: RF18P-2DK.1B.1R
- Part No: M4Q045-EA01-90 old reference, new reference M4Q045-EA01-86
- Part No: MS43048-15-217
- Part No: F8040 VDK 2F (05 or OS)
- Part No: FB050-4EK.4I.V4P - OEM
- Part No: 134921 - RH31M-4DK.2C.1R
- Part No: XGZA9999W
- Part No: 104724 - QR6A-2EM.38.AB
- Part No: S0355 VD43 MG050W04
- Part No: S710 VIL51 TG80L8
- Part No: FE080-ADS.6N.V7 (122420) - obsolete, 161361 - alternative
- Part No: Article no: 161361 - FN080-ADS.6N.V7
- Part No: S0600 4PR30
- Part No: QK12A-4EM.68.GF A oem

- Part No: QK12A-4EM.68.GF B oem
- Part No: R H 28M-2EK.3F.1R (125797E)
- Part No: 160932 (FN045-4DK.4I.V7P1)
- Part No: S0457VD41 TG060W04
- Part No: TX140L06 400V/50Hz B21 N135
- Part No: blades for S0457 VD41
- Part No: TX140L06 400V/ 50 HZ B21 N135
- Part No: IA0900 4PA25 TX140L06
- Part No: 401-47-701 obsolete, replacement TG050W04
- Part No: 210917 / QK10A-2DM.48.FK
- Part No: TG050W04
- Part No: A50-4PR30
- Part No: FB050-4EK.4I.6P LE
- Part No: RF22P-2DD.5H.1R
- Part No: 18947
- Part No: Type:FN025-4ED.W8.A7 (Art. Nr. 140400/UL02)
- Part No: FL050-VDK.41 V5S
- Part No: 203437
- Part No: 203625
- Part No: RH31M-4DK.
- Part No: IS04004PR35
- Part No: RH28M-2DK.3F.1R (126387)
- Part No: RF22P-2DK.3F.5R
- Part No: 26154
- Part No: TX140L08 400V/56HZ (10)
- Part No: TX140L08 400V/56HZ (20)
- Part No: TX140L08 400V/56HZ (30)
- Part No: (00150684) DSG2000
- Part No: 109319E
- Part No: 2006938
- Part No: 2006935
- Part No: FC091-SDQ.7Q.V7
- Part No: RE28P-4DK.6F.1R
- Part No: 109016E
- Part No: 206837

- Part No: 303615
- Part No: S0500 VIP48 TG090P04 400V50HZ
- Part No: QK10A-2DM.48.FK
- Part No: 112083
- Part No: IA0900 4PA25 TX140L06 400V50HZ (# 5001018695)
- Part No: TX140L06 400V50HZ (# 5001019042)
- Part No: 5001029585
- Part No: 136471 - FL050-VDK.4I.V5P
- Part No: 125999E
- Part No: FB063-6EK.4I.V4L
- Part No: 1809005265 - TX100L4
- Part No: L-ErP-Pauschale
- Part No: 142676
- Part No: RE28P-4EK.4I.1R
- Part No: RG28P-4EK.4I.1R
- Part No: 1809001012 - S0457VIP35
- Part No: RH28M-4DK.2A.1R
- Part No: RH35M-4DK.4C.1R 131479
- Part No: 1809000096 - TX140L8 018981
- Part No: 318 a “ 17 a “ 310 replaced by IA300 5P28 MK34
- Part No: IA300 5P28 MK34
- Part No: 157139 - RH35M-4DK.4C.1R
- Part No: A1A091386 / 6SR3900-0GM05-0AD0
- Part No: 134906 FL045-SDW.2C.A5S
- Part No: S0355VD43.TG030W04 FA35037P01 018263
- Part No: Type A900PA2717 TX140L08, REF 018981 VE375000 - replaced by A0900.4PA27.TX140L08 018694
- Part No: THCL155 IP54 - obsolete , alternative is 138777 ,type FN080-SDL.6N.V7
- Part No: A0900 4PA27 TX140L08
- Part No: 160587 / FN050-VDW.4I.A7P1
- Part No: 128869 FC080-SDA.6K.V7
- Part No: FN063-ZIQ.GL.V7P3
- Part No: A900PA2717.TX140L6 VE3750800
- Part No: 102372K
- Part No: S0500 4PR30 TX070P04
- Part No: A900PA2717 018979 OEM

- Part No: FC056-4DF.4I.A7
- Part No: A0900 4PA27 TX140L06
- Part No: FC091-6DQ-7QV7
- Part No: S0710VIL51 OEM replaced by S0710 VIL51 TG100L06
- Part No: 905 04-810
- Part No: S0710 VIL51 TG100L06
- Part No: S0400 COMPR46 MG050W04 230V50
- Part No: 08055933, FE050-VDK-4I-V7
- Part No: FB0454DE4IV4S
- Part No: IP20 THCL 155
- Part No: GTF210
- Part No: GRCF.1
- Part No: ENS-(D762)
- Part No: A900PA2717.TX140L6 VE3750600
- Part No: 406206
- Part No: PTC K 130
- Part No: TX140L06 400V56HZ
- Part No: FB063-6EK.4I.V4P
- Part No: 06254353 OEM for GAntner
- Part No: FC091-SDS.7Q.V7
- Part No: TX140L06 400V56HZ # 5001023509
- Part No: Bearing for 762-02-805 551-01-805
- Part No: A0762 4PB35 TX140L06 400V50HZ
- Part No: FE050-4DS.4I.V7 oem
- Part No: TX033P04 230/400V 50HZ
- Part No: GR331M-6ID.BF.2R oem
- Part No: UNICON CTD A-M
- Part No: FN063-ZIQ.GL.A7P4
- Part No: MAL1 a “ X obsolete, replacement MAL1-X 384050
- Part No: 121250 obsolete replaced by 138298
- Part No: S0600 4PR30 TX100L04 400V50HZ
- Part No: MS45 obsolete, replacement by MK34 FM.46309A 5001031249
- Part No: MAL1-X (384050)
- Part No: CXE/AVE 320056
- Part No: TX100L04 400V56HZ

- Part No: MK34 FM.46309A 5001031249
- Part No: S355VD46.MGC30W4 018314
- Part No: 138298
- Part No: 104370
- Part No: FC035-4EQ.2C.A7
- Part No: 5001018399E
- Part No: 2006942
- Part No: A90-4PA27 TX140L
- Part No: FB050.4DK.4I.V4P 209026
- Part No: QK12A-4EM.98.GK
- Part No: QK12B-4EM.98.GK
- Part No: 104724
- Part No: 105689
- Part No: S35-4PR35
- Part No: 153203
- Part No: 335-4PR35
- Part No: A900PA2717.TX120L12 VE3751200
- Part No: RH50M-VDK-6K-5R
- Part No: FB050-vdk.4I.6L obsolete, alternative FB050-VDK.4I.V4L
- Part No: 880/660 COSY 0,74 THCL F IP 54 obsolete, replaced by 138757, FN080-SDS.6N.V7
- Part No: 5001023509
- Part No: S0300 VD46 TG030W04
- Part No: S0450 VD46 TG060W04 400V50hz
- Part No: 138757, FN080-SDS.6N.V7
- Part No: FH065-4IU.4I3 obsolete, alternative FN063-ZIW.DG.A7P2
- Part No: S355 VD43 MG30W4
- Part No: S0450 VD46 TG060W04
- Part No: FB050-VDK.4I.V4L
- Part No: FN063-ZIW.DG.A7P2
- Part No: FX 045-4DK.4I.V7P1
- Part No: GR31M-6ID.BF.2R - OEM for Siemens, order code - 1PH8912-1BC80-0AA0
- Part No: 041-42-703
- Part No: GR25V-6IK.BF.1R 114182 30748923 - OEM For Siemens in NArnberg
- Part No: FC056-4DF 4I.3 Obsolete Replaced by FC056-4DF.4I.A7
- Part No: TA 33 P4

- Part No: S0420 VD46 TG060W04
- Part No: 142502380V
- Part No: A762-4PR35
- Part No: Type:QK10A-4EM.B8.CH
- Part No: Type: MK106-4DK.14.U Artikelnummer: 125775
- Part No: MSR220K2, Us AC 230 V T221945
- Part No: CAPACITOR 15mF FOR 510-29-203
- Part No: RH63N-4DK.7Q.AR Artikelnummer: 129266E
- Part No: IP55 THCL 155
- Part No: 88922A (QR06A-GKM.43.BP) REPLACED BY Type:QR06A-GIM.43.11 (110400X)
- Part No: FN050-4DK.4I.V7P1
- Part No: 110400X QR06A-GIM.43.11
- Part No: FN040-6EL.0F.A7P1 Artikelnummer: 152911
- Part No: FN030-4EL.WC.A7 Artikelnummer: 139721
- Part No: MOTOR TX033P04 230/400V 50HZ
- Part No: MKP 3,0uF/400V UL Artikelnummer: 02006932
- Part No: 23149
- Part No: RH40A-4EK.4I.AR
- Part No: MKP 14,0uF/400V UL (02006940)
- Part No: RH35M-4/131479
- Part No: FLAœGEL 4PR30 BORE16 FRONT EBU
- Part No: Typ: MPR300 (384020)
- Part No: S0500 4PR30 TX090P04
- Part No: TX120L08
- Part No: 210181E
- Part No: FB063-6EQ.4I.5P
- Part No: FB063-6EQ.4I.V4P (109016E)
- Part No: 125797E
- Part No: Typ: PKE-2.5 Acontro (Artikelnummer:303600)
- Part No: S900-PWR30-TX140L8PV, obsolete, alternative 5001032035 Type: TX140L08 400V50HZ
- Part No: FN050-VDQ.4I.V7P1
- Part No: 5001032035 Type: TX140L08 400V50HZ
- Part No: FE 050-VDO.4I.V7 - obsolete , alternative is FN050-VDQ.4I.V7P1
- Part No: 5001026466 Type: S0457 VIP35 TG070P04 380/460V56
- Part No: RH45M-4EK.6C.1R

- Part No: MKP 14,0uF/400V UL
- Part No: A9004PA27TX140L08
- Part No: Type:FB065-SDW.4I.A4S
- Part No: Obsolete FB065-SDW.4I.3S replaced by FB065-SDW.4I.A4S
- Part No: FN031-4DZ.0C.A7P2
- Part No: Type: RH40M-4DK.4F.1R (120915) obsolete alternative 128857
- Part No: Obsolete FE031-4DZ.OC.3 replaced by FN031-4DZ.0C.A7P2
- Part No: Type: FN050-4EK.4I.V7P1
- Part No: THCL155 IP54 900
- Part No: FC091-SDS.7Q.V7 209589-07106723
- Part No: FB045-4EK.4F.V4L
- Part No: 164434 (Type:FN050-VDK.4I.V7P1)
- Part No: 1809009050 Boite 2PNN11
- Part No: FN 071 SDK.6KV7P1 154251 OEM for GAntner GmbH & Co. KG
- Part No: FA35038P01
- Part No: 3800 M3/Hr
- Part No: RH 35B-2EK.6N.2R ZIEHL-ABEGG 3/4.6KW , alternative is Art. Nr. 125999E , type RH35B-2EK.6N.2R
- Part No: A762-4PA30 TX80L12 alternative XGZA9999W
- Part No: MKP 6,0uF/425V UL
- Part No: 018695-020591
- Part No: 222387
- Part No: XGGU9999W
- Part No: GR25V-6IK.BF.1R oem
- Part No: 5001022201
- Part No: 018265 7605038P01
- Part No: 156556 (FN050-VDW.4I.A7P1)
- Part No: FN080-SDL.6N.V7
- Part No: FN063-VDS.6N.V7P6
- Part No: 026202 7605086P01
- Part No: RH35M- 20K.6F.2R - cannot offer us separate
- Part No: Type:MK137-2DK.10.N
- Part No: FE050-4DK 4I.V7 (135486) 60050111 REPLACED BY :FN050-4DK.4I.V7P1
- Part No: XGXX2070A
- Part No: FN050-4DK.4I.V7P1 (153540)
- Part No: THCL F IP 10

- Part No: GR-25V-61K.BF1R 0,27KW 164024 (OEM)
- Part No: GR-31M-61D.BF.2R 0,43KW 114180 (OEM)
- Part No: MKP 8,0uF/425V UL Artikelnummer:02006937
- Part No: FC063-6EA.4I.V7
- Part No: 30809142 OEM
- Part No: 155234
- Part No: FB050-VDK.4I.V4S
- Part No: 132503
- Part No: 134604 , type MK165-6DK.18.U
- Part No: Art.Nr. 02006932
- Part No: TG050L06
- Part No: VN080-SDL.6N.V7P obsolete, replaced by FN080-SDL.6N.V7
- Part No: IA0600
- Part No: 136471
- Part No: Type RF22P-2DK.3F.5R - OEM for Siemens
- Part No: Art.-Nr. 141073 Type:FC040-4EQ.4C.A7
- Part No: Art.-Nr. 161250 Type:FC031-4EQ.2A.A6
- Part No: Art.-Nr. 141178 Type:FC045-4EQ.4F.A7
- Part No: 141183 FC050-4EQ.4I.A7
- Part No: S0900 4PA27 BORE 16KEY
- Part No: 207611 , type FB040-VDK.2F.V4S
- Part No: A0900
- Part No: FE080-ADA.6N.V7., obsolete, replaced by FN080-ADA.6N.V7
- Part No: FN080-ADA.6N.V7
- Part No: FB063-6EQ.4I.V4P (101780E)
- Part No: 05067745 obsolete, alternative 154500 (Type FN050-VDS.4I.V7P1)
- Part No: 154500 (Type FN050-VDS.4I.V7P1)
- Part No: S457-VD46
- Part No: S0450 VD46 (230V 50HZ)
- Part No: Type:FC071-VDQ.6N.V7
- Part No: S0350 4PR35
- Part No: 04190172/0019 obsolete, no alternative
- Part No: FB063-6EQ.4I.V4L
- Part No: S0300 VD41 TG030W04
- Part No: RH31M-2DK.3I.1R

- Part No: GR25V6IKBF1R OEM
- Part No: GR31M61DBF2R OEM
- Part No: MG030W04 (# 5001018741)
- Part No: 21087 fa035-vdl 2c v6
- Part No: FE080-ADQ 6N.V7 - obsolete, alternative - Type: FN080-ADQ.6N.V7
- Part No: Type: FN080-ADQ.6N.V7
- Part No: A0762 4PB35
- Part No: IA300 5P28
- Part No: FE050-SDQ.4F.V7
- Part No: Type:FN050-SDQ.4F.V7P1
- Part No: Type:FN071-ZIQ.GG.V7P4 (Art. Nr. 159832)
- Part No: Type: RG28P-4EK.4I.1R
- Part No: FE080-SDS.6N.6
- Part No: FN080-SDS.6N.V7
- Part No: RD35P-4DW.7T.1L
- Part No: 103676E
- Part No: 109544 00214073
- Part No: FC040-4DQ.2F.3
- Part No: 164084
- Part No: S0355 VD46 MG030 W04
- Part No: FC031-4DH.2A.V6 (130511) (OEM)
- Part No: FN045-6IK.BF.V7P2, code 140623
- Part No: 301032
- Part No: Art. Nr. 107123 Type: FB045-VDK.4C.V4L
- Part No: QK10A-4EM.78.CF
- Part No: FN040-40EK.OF.V7P1
- Part No: Artikelnummer: 128857
- Part No: FE050-4EK.4I.V7 - obsolete, replaced by - Type:FN050-4EK.4I.V7P1
- Part No: 103676E (Type:FB050-VDK.4I.V4S)
- Part No: 103676 (Type:FB050-VDK.4I.V6S)
- Part No: RH22V-6IP.0E.2R REPLACED BY RH22V-4IP.ZC.BR Artikelnummer: 115891
- Part No: RH22V-4IP.ZC.BR
- Part No: D33-0140-A (00407899)
- Part No: Type: RH56C-ZID.GG.1R (Art.Nr. 113974)
- Part No: D400B001 (OEM FOR Sumitomo (SHI) Cyclo Drive Germany GmbH)

- Part No: 1PH8912-1AB64-0AA0
- Part No: RF22P-2DK-3F.5R 30285031 (OEM)
- Part No: Art. Nr.121687E , Type RH56A-4DK.7M.AR
- Part No: 112473E Type: RF22P-2DD.5H.1R
- Part No: 141690
- Part No: FC091-SDS.7Q.V7 / 1,5kW
- Part No: FC091-SDS.7Q.V7 / 2,5kW
- Part No: MKP 12,0uF/400V UL
- Part No: 125137E Type: RH28M-2DK.3I.1R
- Part No: Type: FN080-VDS.7Q.V5P7
- Part No: FM-46309A MK 34
- Part No: Art. Nr. 130900E , type RH40G-4EK.4F.1R
- Part No: 02006937 type MKP 8,0uF/425V UL
- Part No: FN045-VDK.4F.V7P1
- Part No: 205157 , Type:QK08A-2EM.50.CH
- Part No: QK08A-2EM.35.CF
- Part No: XGZA9999W , type A0762 4PB35 TX140L06
- Part No: FB061-6EK.4I.V4P
- Part No: QK10A-2EM.38.FK
- Part No: 209904 Type: RD28S-4DW.4R.2L
- Part No: RH31M-4EK.2C.1R
- Part No: 78130216 obsolete
- Part No: FN080-SDA.6N.V7.
- Part No: S0450 CR40 TG060W04 (5001007202)
- Part No: RH31M-2DK.3I.2R Artikelnummer: 134471
- Part No: RD31S-4DW.6Q.AL
- Part No: FE040-4DA.2C.2 obsolete,alternative FN040-4DA.0F.V7P2
- Part No: FN040-4DA.0F.V7P2
- Part No: RH35B -2EK.6N.2R
- Part No: 384020
- Part No: FN045-ZIK.DC.V5P4 (168968)
- Part No: S0450 VD46, ref: 5001018089
- Part No: 5001018395
- Part No: TX033P04
- Part No: FN071-SDQ.6K.V7P1

- Part No: 205503
- Part No: 163742
- Part No: 407899
- Part No: RH40V-4EK.4F.1R
- Part No: IA0300 5P28 MK34
- Part No: IA0300 5P28 MK34,5001026468
- Part No: 08185751 obsolete replaced by FB050-4DK.4I.V4P
- Part No: 05215528 obsolete, alternative FN050-4DK.4I.V7P1
- Part No: MKP 10,0uF/400V UL
- Part No: FB050-4DK.4I.V4P
- Part No: 141407
- Part No: RH25V-6IK.BD.1R
- Part No: 139693/UL01
- Part No: 126930
- Part No: 171275K Type: RH25V-6IK.BD.1R
- Part No: 30588033/001
- Part No: 163827 Type: RH28C-2DD.3I.CR
- Part No: RH50M-4DK.6Y.1R (131491)
- Part No: RH19L-2EP.W6.1R
- Part No: S FN080-SDQ.6N.V7 400V
- Part No: 2006930
- Part No: FN080-SDQ.6N.V7 (139938)
- Part No: FH065-6DP.6K.V