

# ENDURA SUPPLY

## Konan Product List

- Part No: 02-44250/S-MVS2-EF
- Part No: 359-4277E
- Part No: 414 D 603 C-ZA1
- Part No: 414 S 603 C-ZA1
- Part No: 453S202C-N2
- Part No: 454D202C-M5
- Part No: 454S202C-J1
- Part No: 454S202C-J5,24 VDC PRESS. 0.2-1 MPA
- Part No: 454S202C-M5
- Part No: 5AP160L-4-7AA
- Part No: AF2-02-6A
- Part No: SC6-04.15A-HT
- Part No: AIR DISTRIBUTOR FOR HTOP-540
- Part No: CB1-20A =- UNCERTAIN
- Part No: COIL FOR AIR DISTRIBUTOR FOR HTOP-540
- Part No: CP611H-N-TC-250X100N
- Part No: CP611-N-FA-100X25
- Part No: CP61-J-TFS-134205
- Part No: CV1-40A
- Part No: ES3-10A
- Part No: ES3-15A
- Part No: ES3-20A
- Part No: HT8344A71
- Part No: KS1-AC100
- Part No: LA3-MVD2N-08-20A
- Part No: MVD2-15A-10A
- Part No: MVD2F-03-15A-N
- Part No: MVD2F-03-E2M-15A
- Part No: MVD2F-08-20A-N AC110V/50HZ
- Part No: MVD2-X-PB15AAC220V12
- Part No: MVNIS-15A
- Part No: MVPC1-10A

- Part No: MVPC1-15A-X-AC22050HZ
- Part No: MVS 2 SN:719084
- Part No: MVW7N-14-D-50A-AC110. Konan Solenoid Valve.
- Part No: QEV3-06 3/4"
- Part No: RB10C-10A
- Part No: REPAIR KIT TO SUIT SOLENOID VALVE MVD2 - 15A a " AC110
- Part No: SAU3-MVD2F-03-15A
- Part No: VB5-02-10A-HT-BR
- Part No: QEV3-04-15A Konan Quick Release Valve
- Part No: PV-M08SN-12 110VAC 50HZ
- Part No: PV-M07HN-12 110VAC 50HZ
- Part No: PV-M07SN-12 110VAC 50HZ
- Part No: CS4AF02A24 110VAC 50HZ P / N: YS211 and YS333 is USED IN VALVE
- Part No: 415S302 C-Z1/110V 5/2 1/4"
- Part No: cp611-n-ca160300
- Part No: YS333GF02N4BC9KMN
- Part No: 453H403C-D4
- Part No: MVN1S-15A-C-G3793
- Part No: REPAIR KIT FOR MVN1S-A-C-G3793
- Part No: S3C116-SVO-781
- Part No: solenoid valve for heeling tank VV.17
- Part No: SPARE PARTS KIT FOR MVN1S-15A-O/CAC120-TB1-20A-G3658
- Part No: ARU3A-04-15N-G-G4540
- Part No: Asco J353C35
- Part No: MVN1S-15A-C-DC110-TB1-15A-G3507
- Part No: CV1-50A
- Part No: MVS803K-02-10A obsolete, replaced by MVS813K-02-10A-DC48
- Part No: MVS813K-02-10A-DC48
- Part No: 4545102C-L1
- Part No: ES4-40A
- Part No: 454s202cJI
- Part No: VB5-02-10A
- Part No: 430-3507.
- Part No: 454S202C-15
- Part No: CP61-G60758

- Part No: CP61-G522892-B 450X1100
- Part No: MVS801K-02-10A obsolete/replaced by MSV811K-02-10A
- Part No: H2115 125 VDC
- Part No: MSV811K-02-10A
- Part No: MVS2-15A-AC220
- Part No: CP61-G49983
- Part No: MVS801K-02-8A
- Part No: PCB-50-250-12-400514LE
- Part No: MVS2D-25A-DC100
- Part No: MVS 2 SN:734603
- Part No: MVS801F-02-BA obsolete, replacement MVS811K-02-8A-NO-DC110
- Part No: MVS811K-02-8A-NO-DC110
- Part No: QEV 3-06-20A
- Part No: TA2-063D-00-G32893
- Part No: CP61-N-FB-300 X 150
- Part No: MVS2- AC- 15A- AC110
- Part No: RV2-2-04-RC 1/2"
- Part No: RV2-2-08-RC 1"
- Part No: AF2-1-08-RC 1"
- Part No: AF21-04-RC 1/2"
- Part No: AF21-04-RC 3/8"
- Part No: OL2-1-08
- Part No: CV3-04-15A
- Part No: ES3-25A
- Part No: PG2-19-A-275-30A
- Part No: 454S102C-L1
- Part No: PV-M06SN-12-L