

# ENDURA SUPPLY

## A-Ryung Product List

- Part No: 8080818
- Part No: 2119430
- Part No: 5132240 ACP-1500HMFS70
- Part No: AR-99-00097
- Part No: AHGP-700
- Part No: AMFP-X
- Part No: AMGP-01AF-T03-T-200
- Part No: AR-99-00056 A-RYUNG AMGP-01A-F
- Part No: AR-99-00065
- Part No: AR-99-00109 ACP1500
- Part No: AR-99-00126 ACP-1500 HMFS 70
- Part No: AR-99-00131
- Part No: AR-99-00132 ACP3700
- Part No: ASPK4 11/3 60HZ
- Part No: ASPK4 11/5
- Part No: ASPK4 11/8
- Part No: ASPK8 7/5
- Part No: ASPK8 7/7
- Part No: ASPK8 7/7 50HZ
- Part No: ASPK8 7/7 60HZ
- Part No: ASPKE4 11/5
- Part No: ATR-216HA(VB)
- Part No: AWS-NR.: 5132230
- Part No: AWS-NR.: 5135000
- Part No: PVO-30
- Part No: SHAFT FOR PUMP TYPE: ACRK-2-150/15, S/N: 07070862
- Part No: ACRK4-100/5
- Part No: ACP-180F AWS-Nr.: 5136340
- Part No: ACP-3700 HMFS 115
- Part No: AMTP-212HA
- Part No: AR-99-00281
- Part No: AR-99-03045

- Part No: ACP-1500 HMFS70 obsolete, replacement ACP-1800HMFS70
- Part No: ACP-1800HMFS70
- Part No: T- Rotor 220 HAVB
- Part No: ACP-3700HMFS145
- Part No: AR-99-00142
- Part No: 2 HP (1.5KW) 4P alternativ 216 HWM + Mo 1500W
- Part No: 216 HWM + Mo 1500W
- Part No: 2VB-4L
- Part No: AR-99-00174
- Part No: INTERNAL DIA.240/THICKNESS 3
- Part No: ACP-900HMFS45 (5132260), obsolete replaced by T.P.ACP-1100HMFS45 30L/3Bar
- Part No: ARD-345 0.03 (cc/st)
- Part No: ARD-345 0.06 (cc/st)
- Part No: ARD-345 0.10 (cc/st) part name, the correct name ARD-345-33333
- Part No: AR-99-00062
- Part No: ACP-3700HMFS145/5132180
- Part No: 5010160
- Part No: 5151430
- Part No: Motor for Type ACRK4-100/10, 2.2 kW, 100 L/min
- Part No: Impeller For:ACP-1500 HMFS 70
- Part No: Mechanical Seal For:ACP-1500 HMFS 70
- Part No: ACP-1500 HMFS 70, obsolete/replacement ACP-1800HMFS 70
- Part No: AR-99-00528
- Part No: T.P.ACP-900HMFS45
- Part No: 5134870 (ATP-216HA)
- Part No: ATP-212HA
- Part No: ACP-3700 MFC200H obsolete, replacement ACP-4000HMFD
- Part No: ACP-4000HMFD
- Part No: ATP-206HA
- Part No: ACP-2200 HMFS 100 obsolete replaced by ACP-2500HMFS100
- Part No: ACP-1500HMFS1500 - NO LONGER AVAILABLE
- Part No: ACP-1800HMFS 70
- Part No: ACP - 2500HMFS100
- Part No: 5135000
- Part No: ACP-3700 obsolete, replacement ACP-4000HMFD

- Part No: ACP 3700 HMFS 145 obsolete, replaced by ACP4000HMFS145
- Part No: ACP-4000HMFS145
- Part No: ACP3700HMFS145,obsolete replaced by ACP4000HMFS145
- Part No: ACP-1500HMFS 70 obsolete,replaced by ACP-1800HMFS70
- Part No: ACP-900 HMFS45 obsolete,replaced by ACP-1100HMFS45
- Part No: ACP-1500 HMFS70 obsolete,replaced by ACP-1800HMFS70
- Part No: ACP-1800HMFS70 (5161790)
- Part No: 5136360
- Part No: ACP-3700HMFS145-390 obsolete, replacement ACP-4000HMFS145
- Part No: AMGP-01NS-220
- Part No: ACP-750HF 19 -NO LONGER AVAILABLE
- Part No: ACP-600HF28
- Part No: ACP-600HF18
- Part No: ARD-345-33333
- Part No: ACP-101A
- Part No: P/n.5161760 Type T.P.ACP-1100HMFS45 30L/3Bar
- Part No: T.P.ACP-2200HMFS100
- Part No: ACP-180F (5136340)
- Part No: ATP-216HA
- Part No: ATP-212HA (5135000)
- Part No: ACP-4000HMFD200V
- Part No: AMGP-01AF-T03-T 110
- Part No: p/n:5161840 Type:4000HMFS145
- Part No: ACP3700HMFS145
- Part No: ACP-1100HMFS45
- Part No: HCP-1100MF
- Part No: ACP-1100HMFS30
- Part No: 5195750
- Part No: ACP-4000HMFD200H
- Part No: P/N: 5245010, Type: AMTP-1500-216HAVBF
- Part No: MECHANICAL SEAL FOR PUMP ACRK 2-150/15
- Part No: AMTP-3M-750-220HA
- Part No: ACP-1800MF
- Part No: AMGP-01SF-100
- Part No: ACP-1800 HMF

- Part No: T-Rotor 206 HWM
- Part No: Motor For T-Rotor 206 HWM
- Part No: 5134800
- Part No: ATP-320HVB
- Part No: Pumpenmotor T-Rotor 1500W 2HP
- Part No: AMTP-400-204HA-VB 1.5
- Part No: 5135040
- Part No: 5100400
- Part No: AGP-15C-CT 220V
- Part No: AGP700, 700cc
- Part No: AMTP-200-13MSVB
- Part No: ACRK 16-50/2
- Part No: ATP-216CHVD-30
- Part No: ATP-216HA(VB)
- Part No: AMGP-01 AF
- Part No: ACHK 2-40/4
- Part No: ARV-4SS
- Part No: 1010670
- Part No: Pumpenmotor T-Rotor 400W
- Part No: ACP-250F 250W
- Part No: AMTP-216CH-30 see AMTP-3000-216CHVD-30
- Part No: Mechanical seal for ACP 1500
- Part No: ACP400HMFS-WH
- Part No: AMTP-1500-220HAVBF (5187090)
- Part No: seal kit for ACRK4-160/16
- Part No: 5142320
- Part No: Gasket for ACP-1100HMFS45
- Part No: O-Ring for ACP-1100HMFS45
- Part No: T.P.ACP-1100HMFS45
- Part No: AMGP-01MF, 110V
- Part No: motor fan cover for CHX-60/6
- Part No: AMGP-01MF, 220V
- Part No: HAVBF 100MESH
- Part No: Repair kit for ACP-2200 HMFS 100
- Part No: ACRK 2-130/13

- Part No: TD-4
- Part No: ACP-4000MF
- Part No: 17030304
- Part No: AMGP-025NS-T12-TY
- Part No: Coupling for AMTP-216HAVD
- Part No: ARD-345-44444
- Part No: ARD-342-44
- Part No: ARD-343-444
- Part No: ACPQ-300HSP-200
- Part No: ACP-400HF18
- Part No: 5135030
- Part No: AMTP-216LNVT
- Part No: P/N: 5240450, Type: AMGP-01SF-200
- Part No: MCP 3700 MFC 200 H
- Part No: AMGP-3M2-01N-T03-TY
- Part No: AMGP-01NS
- Part No: 5232690
- Part No: 5240130
- Part No: 5135070
- Part No: ATP-206HA (5135030)
- Part No: MGP-200NS-T03-220 (5212630)
- Part No: ARU-6R
- Part No: AMTP-216HAVD
- Part No: AR-3S
- Part No: OHMFS 70
- Part No: ACP-180HF18 (5233720)
- Part No: ACP-60F
- Part No: ARD-343-111 (5195120)
- Part No: ACP-2500MF (5161740)
- Part No: POV-3
- Part No: PVO-3 M10x1.0P
- Part No: PVO-3 M8x1.0P
- Part No: 5164330
- Part No: AMGP-01AFT03110
- Part No: T-Rotor 206 HA + Motor 750W (AMTP-750-206 HA)

- Part No: Elastic joint for AMTP-206HA (VB)
- Part No: T.P.ACP-2500HMFS85
- Part No: ATP-220HA
- Part No: AMGP-01AF-T
- Part No: 5134870
- Part No: AMTP-400-206HAVB
- Part No: ACP-400F
- Part No: ACP-600HE28
- Part No: ACP-400
- Part No: ACP-4000BMF
- Part No: AMTP-750-220HAVB
- Part No: ACP-1100MF
- Part No: AMGP-01AF-T03-T
- Part No: ACP-750HF19-1P
- Part No: ATP-206HA(VB)
- Part No: 6030694
- Part No: 21102603
- Part No: P/N: 5238200, Type: AMGP-025NS-T12-TY 220V
- Part No: P/N: 5246370, Type: AMGP-01AF 220
- Part No: ACP-1800HMFS60
- Part No: P/N: 5238200, Type: AMGP-025NS-T12-TY 110V
- Part No: ATP-210HA
- Part No: P/N: 5212630, Type: AMGP-200NS-T03-220
- Part No: ACP-2500MF
- Part No: P/N: 5141080, Type: S.P.ACPQ-300HSP-200 20L/14bar
- Part No: ATP-208HA
- Part No: p/n:5161760 Type: ACP-1100HMFS45
- Part No: ACRA 2 - 150/15
- Part No: ARG-00
- Part No: ARD-342-33
- Part No: ACHK 2- 60/6
- Part No: AMTP-212HA(VB)
- Part No: AMTP-100-11 MS / PN 5132550
- Part No: ACRK 4-100/4
- Part No: DKC-102K-11K

- Part No: AMTP-750-208HAVB
- Part No: AMTP-200-12MSVB
- Part No: 1/4HP (0.2 KW) 4P
- Part No: ACP-180F 1003430
- Part No: 1/2 HP (0.4KW) 4P
- Part No: rotor unit for ACP 1800HMFS 70
- Part No: mechanical seal for ACP 1800HMFS 70
- Part No: ACRK4-30/3
- Part No: ACP-4000HMFD220V
- Part No: AMTP-208HAVD
- Part No: AMGP-025NS
- Part No: 5194480
- Part No: AMGP-01NS-T03
- Part No: AMGP-01NS-T03-220
- Part No: ARU-8R
- Part No: 3 (0.10 cc/st)
- Part No: ACPQ-400HSP-280
- Part No: AMTP-216LNVA (VT)
- Part No: AMTP-400-216LNVT
- Part No: ARD-345
- Part No: ACP2500BMF 220/380V 60HZ 2
- Part No: 216HABP 220/380V 60HZ 4 PÓLOS
- Part No: AMGP-01MF
- Part No: ACP-1800MFS
- Part No: ACP-1100MFS
- Part No: Type: ACP-1500 old No. / new No. ACP-1800HMFS70
- Part No: AMGP-01A
- Part No: Mechanical Seal for ACP-1100HMFS45
- Part No: ATP-204HA
- Part No: ACRK 2-150/15
- Part No: T03-TY
- Part No: AMPT-216HA
- Part No: AMTP-100-11MS
- Part No: AMTP 1500-216HAVB
- Part No: ATP-210208HA

- Part No: ARD-345(0,16)
- Part No: Type 3 1HP (0.75kW) 4 poles Serial No.- 1303302
- Part No: AMTP-750-216HA
- Part No: ATP-204HA(VB)
- Part No: SN:04072982
- Part No: ACP-2200
- Part No: ARD-343
- Part No: ACP-4000HMFS-115
- Part No: REBUILD SEAL KIT for ACP900HMFS45
- Part No: AMGP-01S(F)
- Part No: ATP-204HA(VB) + SN:04072982
- Part No: AR1-3F
- Part No: ATP-212HA(VB)
- Part No: SEAL KIT FOR ACP-1800HMFS70
- Part No: 5240270