

ENDURA SUPPLY

AVENTICS Product List

- Part No: 344/360
- Part No: 346/030
- Part No: STR:65 MM
- Part No: T777770021
- Part No: 451276905
- Part No: 04842 00602
- Part No: 04903 991 00
- Part No: 490367306
- Part No: 490399607
- Part No: 04904-073-08
- Part No: 490603603
- Part No: 04983.171.03
- Part No: 498317103
- Part No: 049-83-175 ,24 V DC 5 W
- Part No: 498317502
- Part No: 5531210000
- Part No: 04983-175-02 24V DC 5W,
- Part No: 110 V AC 8 W
- Part No: 110V 50-60HZ 8VA
- Part No: 1303-02-000-2
- Part No: 131-55 1045-1 NEW ITEM NUMBER --- 1315510450
- Part No: 1315510450
- Part No: 1603-02-089-1
- Part No: 1670812000
- Part No: 167-02-0000-1
- Part No: 167-02-08001-SY04
- Part No: 1670425000
- Part No: 167-06-0000-1
- Part No: 167-06-16 00
- Part No: 167-12-0000-1
- Part No: 167-250,500
- Part No: 170 04 0200 a “ Q40MM a “ S:200MM ISO 6431/VDMA

- Part No: 204-254928-1
- Part No: 24V DC PT NUMBER 348/1, MOD
- Part No: 250H/125
- Part No: 250H/50/25 350
- Part No: 250H/64/32 150
- Part No: 268H/76/40 445
- Part No: 2991160360
- Part No: 3/2 SPLITTER MECMAN
- Part No: 312 374 9021
- Part No: 322-12 0310 (24V)
- Part No: 322-12-0310
- Part No: 322-20 0311 obsolete/we need to know the type of cylinder where the product is installed
- Part No: 322-20-0300
- Part No: 322-20-0311 (150MA)
- Part No: 322-25 0310 Obsolete Replaced by R412022876
- Part No: 3353200000
- Part No: 340 3/2 WAY
- Part No: 340/55
- Part No: 348/1 MOD C obsolete, alternative V563-3/2NC-SR-024DC-5W
- Part No: 366 608 000
- Part No: 3701204000
- Part No: 370-12 0400-0
- Part No: 370-MA-M042-0080-N
- Part No: 371-80-0002-1
- Part No: 412/210
- Part No: 413/16, MOD A
- Part No: 475/201, MOD A
- Part No: 48V 5WATT
- Part No: 5/2.5812220-0
- Part No: 530-271 000-1 TYPE 2
- Part No: 5428110070
- Part No: 563/301 MOD 2
- Part No: 5633010000
- Part No: 565-231 000-1 (obsolete)
- Part No: 565-301-0001-3

- Part No: 5672010000
- Part No: 567-231 000-2 40-297940 DISCONTINUED / REPLACEMENT 5672310000
- Part No: 5672310000 VENTIL 567/231
- Part No: 5755 FOR (PROXIMITY SWITCH 24VDC MECMAN 322-120310 "ON PNEUMATIC CYLINDER" TYPE TYPE: 322-120310, 24
- Part No: 5802710000 OBSOLETE, REPLACEMENT 5812110100
- Part No: 5802710000
- Part No: 580271000-1-OBSOLETE, REPLACED BY 5802710000
- Part No: 5802810000
- Part No: 581211
- Part No: 581-13 5/2
- Part No: 5812110000
- Part No: 581-211-000-0
- Part No: 5812420000
- Part No: 5812420100 VALVE 581-242 24V
- Part No: 5832131000
- Part No: 8VA
- Part No: 586-123 000 1
- Part No: 586-213 00 1
- Part No: 735-030 000-1
- Part No: 735-030 000-1 00W04
- Part No: 735-420-000-1
- Part No: 735-420-000-10
- Part No: 8JA 002 264-001
- Part No: 90.03.335 G1 1/2"
- Part No: CDM1/100/56-M
- Part No: DCM1MP5
- Part No: CDM1MP5-50
- Part No: CYL:25MM STROK:65MM
- Part No: D10807
- Part No: D10807 SY 19 SERIES 0 CYL 50 STROKE 15 10 BAR
- Part No: DIN 51524-150VG32.
- Part No: FS07-000-100-G014-WH
- Part No: FS07-000-100-G014-WHL (0,1-5,1)
- Part No: 5632310000
- Part No: PART NO:2991160360 581-211-010+580-271/SPEC.24V DC

- Part No: PART NO:322-20-0311
- Part No: Q 63-100 1670610000
- Part No: Repair Kit for 3-Way Valve Position no. 26 & 117
- Part No: Repair Kit for Air Cylinder (Pos. 57)
- Part No: Repair Kit for Series 164 164-05 2000-1 HUK04
- Part No: Repair Kit Series:167 REFNR A12766 SU10
- Part No: RUBBER SEALS FOR D10807 CYLINDER
- Part No: SDR P 6 HN P315
- Part No: SERIES 344 A^{3/4}a ■ NPT
- Part No: Series 164 164-05 2000-1 HUK04
- Part No: Series:167 REFNR A12766 SU10
- Part No: SPULE FUR WEDE 42 C 6-O VAC F6HT
- Part No: TEZ G 4.334.003 0616101706 97735
- Part No: TIPE 348/1 MOD. D 24V 60~ 38VA
- Part No: TYPE 304/20 MOD B
- Part No: WEDE 42 C 6-O VAC F6HT
- Part No: WEDE 42A 6 V-O AC
- Part No: WUVP-1MC0-10-2 24V DC
- Part No: 5812111420 / V581-5/2SR-230AC-I2-1P22-HB2-PA-X-C-T1
- Part No: 563 301 000 2
- Part No: 5811150100
- Part No: 370-20 0800-1
- Part No: 5510200000
- Part No: Pyropress S 60
- Part No: 5776225280 Type: CD07-5/2XX-DO-230DC-I-M014
- Part No: 343-30-000-1
- Part No: 5763490920 obsolete/alternative ES05 series
- Part No: SERIE344 Code no:3441400000
- Part No: 5652310000
- Part No: Series 132
- Part No: 490394400
- Part No: MODEL 343
- Part No: 3460565500
- Part No: 100 0 822 363 004
- Part No: (0821300303) NL2-FRE-G014-GAU-100-PNB-AO-05,00

- Part No: 1823300020, CM2-MR9-M010-M2-A
- Part No: 1300 CV/20- obsolete
- Part No: 5772070220
- Part No: 820045021
- Part No: R480146192
- Part No: 822123003
- Part No: R480070965
- Part No: R480702757
- Part No: R480702755
- Part No: HPC 865
- Part No: 2992344140
- Part No: 322-12-00251
- Part No: 581-42
- Part No: 212-20-160
- Part No: 04983 a “ 175 a “ 02
- Part No: 3710750000
- Part No: R412006111
- Part No: Piston Series 166 obsolete
- Part No: R414002402 Type: ED02-000-060-010-1M12X
- Part No: 821200195
- Part No: 322-21 0310 obsolete, replaced by 0493859408
- Part No: 493859408
- Part No: 1026100000
- Part No: 0830100631 Type: ST6-PN-K03U-030
- Part No: 322-12-0310 24V DC
- Part No: 580-172 000-1
- Part No: 2992344125
- Part No: 2992344130
- Part No: R412010328
- Part No: 820403002
- Part No: 5776279920
- Part No: R414002331
- Part No: V563-3/2NC-SR-024DC-5W
- Part No: 563/442
- Part No: 1825805226

- Part No: 277-0/40-360-MOD-544-00-B10000W-0
- Part No: 5811290650
- Part No: 1825503286
- Part No: 1825503294
- Part No: MAG-SP 11-2501F-24D
- Part No: 3670305000, CM2-MR9-M16X1,5-A2
- Part No: 5652010001
- Part No: 822233015
- Part No: 5654420000
- Part No: 5653010000 , V565-3/2NC-SR-NO_COIL
- Part No: 822066003
- Part No: 812 132
- Part No: 498316905
- Part No: TIC-024-0744
- Part No: TIC-024-0745
- Part No: TIC-024-0746
- Part No: TIC-024-0747
- Part No: 5776070220
- Part No: 5812220000
- Part No: 413/20 obsolete, replaced by 0820260003
- Part No: 5776075302 Type: CD07-5/2XX-SR-NONE-I-G014
- Part No: 820260003
- Part No: R412006108 - alternative for 53514222001 - Rexroth
- Part No: 413/20-1 POS 21207 ITEM 22RC
- Part No: R412007251
- Part No: R412007237
- Part No: 830100630
- Part No: A-12200
- Part No: 343/5 MOD B
- Part No: 5811490540
- Part No: 820402023
- Part No: 7472B01571 - OEM Alternative is 0822342002 + 1827020249
- Part No: 7472Y09619
- Part No: 822123004
- Part No: MNR0822123004. - same as 0822123004

- Part No: 5791500220
- Part No: 5790005332
- Part No: Obsolete 322 23 0311 direct replacement 0493859505
- Part No: 2992343005
- Part No: 493859505
- Part No: 1827004819
- Part No: 5772080220
- Part No: 1827020249
- Part No: 1827414016
- Part No: 1823462028 (pack x25)
- Part No: 820005150
- Part No: 0490393803 obsolete
- Part No: 1670516000
- Part No: R412007366
- Part No: 5728410620
- Part No: R412014867
- Part No: R412014868
- Part No: 5772550220
- Part No: 5342010100
- Part No: type 413/16
- Part No: 822343805
- Part No: 822344008
- Part No: 822343204
- Part No: 822345841
- Part No: 822345833
- Part No: 822344014
- Part No: 822342002
- Part No: 822342004
- Part No: R480048344
- Part No: R412006272
- Part No: R412006200
- Part No: R412006285
- Part No: R412006250
- Part No: R412006370
- Part No: R412006371

- Part No: R432000729
- Part No: 821100023
- Part No: 820024997
- Part No: R414002004
- Part No: seal kit for cylinder FSBS Obsolete
- Part No: 822120005
- Part No: 830100355
- Part No: 5794620620
- Part No: HF0332
- Part No: 580-271-000-1 - obsolete, replaced by 5802710000
- Part No: 498317707
- Part No: 5812110300
- Part No: 0822010667 Type: KHZ-DA-050-0050-M
- Part No: R412010767
- Part No: 342-002-000
- Part No: 342-005-000
- Part No: R412018252 Type: 16DO32SC
- Part No: 830100304
- Part No: 822392008
- Part No: 498319718
- Part No: R480717477
- Part No: 1,827,020,285 replaced by 1827A20285
- Part No: 1827A20285
- Part No: R412010325
- Part No: 822010530
- Part No: R412005574 (pack x5)
- Part No: 1834484253
- Part No: 1 834 484 253
- Part No: 577 207
- Part No: 830100487
- Part No: 5813170650
- Part No: 830100453
- Part No: 821300308
- Part No: R414002401
- Part No: 820055601

- Part No: R412019683
- Part No: 5672310000
- Part No: 5812110100
- Part No: 5812010000
- Part No: 820402103
- Part No: 5684420000
- Part No: 830100486
- Part No: 7472ZZ4120
- Part No: R412022858
- Part No: 1827020283
- Part No: 3610607300
- Part No: 822010576
- Part No: 822354009
- Part No: 1827000002
- Part No: R424B09638
- Part No: 820025152
- Part No: 5725450220
- Part No: 5776075280
- Part No: 5776600220
- Part No: 5772075280
- Part No: 5811110100
- Part No: 5813110100
- Part No: 1827000001
- Part No: 1827000003
- Part No: 8994701900
- Part No: 821201103
- Part No: 821201105
- Part No: 1824210223
- Part No: 1824210220
- Part No: 1834484101
- Part No: 1834484048
- Part No: 3610710500
- Part No: ES-ES05X10-SWC (R480765843)
- Part No: 8940410612
- Part No: 2750111320

- Part No: 1332502000
- Part No: SERAE 250 H
- Part No: R422103006
- Part No: 1827020299
- Part No: 822419006
- Part No: 583-211 100-1 obsolete, replaced by 5832111000
- Part No: 5832111000
- Part No: 5500520000
- Part No: 206-160/90 MP6
- Part No: 376/4 (3760040000)
- Part No: 8186120000 (pack x10)
- Part No: 1670608001 old p./n.,1670608000 new p./n.
- Part No: R480161535 obsolete,alternative R412020997
- Part No: R412020997
- Part No: 1670608000
- Part No: 164041600 obsolete,alternative 1670416000
- Part No: 1670416000
- Part No: 3353200022
- Part No: 8993809904
- Part No: 821302055
- Part No: BT 7BZ0BF5
- Part No: C 73540079-299-116-036-0
- Part No: 11312-1263
- Part No: Seal kit for 0820060026
- Part No: R422002730
- Part No: 1827414808 replaced by R422102730
- Part No: R422102730
- Part No: 820060026
- Part No: 5776270220
- Part No: R412009320
- Part No: R412009329
- Part No: R412007315
- Part No: 8941016112
- Part No: 821302427
- Part No: 1671020000

- Part No: 1829207068
- Part No: R412007209
- Part No: Repair kit for R417000888 OEM for Caterpillar Motoren GmbH & Co. KG
- Part No: R431003039
- Part No: R412009690
- Part No: 5811170540
- Part No: 3630630010
- Part No: RA54728322
- Part No: RA54727811
- Part No: R412010712
- Part No: 830100630 old code, new code R412022870
- Part No: R404063451
- Part No: R412022870
- Part No: 250-4/65
- Part No: 0490311408 (Zyl:D 150)
- Part No: 04903116028 (zyl: d 200)
- Part No: 4353-20-131
- Part No: 4337-10-121
- Part No: 4336-10-121
- Part No: 4117-44-105
- Part No: 4116-44-105
- Part No: 4113-46104
- Part No: 8140-00-100
- Part No: 4127-47-103
- Part No: 5353-01-111
- Part No: 12453-G1 R1"
- Part No: Schalldampfer R 1 1/2
- Part No: Luftbehälter 30 IA±tre
- Part No: 250 P / 200/ 65/ 196
- Part No: 5610214520
- Part No: R412008990 Type: BDC-B-BCAN 32SB
- Part No: PE5 R412007979 old code, new code R412010767
- Part No: R422100600
- Part No: 821401284
- Part No: 343

- Part No: 3223003100
- Part No: 822121004
- Part No: 822350002
- Part No: R412004417
- Part No: R412006251
- Part No: R412006381
- Part No: R422102526
- Part No: R422102526 25V2 / 16Y4
- Part No: R422102526 25V1 /16Y3
- Part No: R422102526 24V4 / 16Y2
- Part No: R422102526 24V2 / 17Y3 / Y4
- Part No: R422102526 24V1 a “ 17Y1 / Y2
- Part No: R422102526 23V2/16Y7/Y8
- Part No: R422102526 23V1 16Y5 /Y6
- Part No: 3610390000 obsolete, replacement 361 062 860 0
- Part No: 361 062 860 0
- Part No: 413/15 MOD. A obsolete
- Part No: R412022876
- Part No: R422001179
- Part No: 167-16-1600-1 Obsolete Replaced by 16751-160 and 164/7/8-160/200
- Part No: 16751-160
- Part No: 164/7/8-160/200
- Part No: R480627300
- Part No: 3223010000
- Part No: 5776980220
- Part No: 5764460220 CD99-5/2DS-ISO1-024DC (OEM/customized)
- Part No: 0830100629, obsolete replaced by R412022869
- Part No: R412022869
- Part No: 5672310002 obsolete/replacement 5672310000
- Part No: 820408002
- Part No: 5812290050
- Part No: 5776085280 Type: CD07-5/2XX-SR-230AC-E-G014
- Part No: 822384005
- Part No: 5812111100
- Part No: 1670520000

- Part No: 490394508
- Part No: R412010773
- Part No: 820400001
- Part No: R431003806
- Part No: R431003808
- Part No: R422000471
- Part No: R422103001
- Part No: 3410582000
- Part No: 3702002000
- Part No: 3702004000
- Part No: 3702005000
- Part No: 5420507022
- Part No: R037541002
- Part No: R422103003
- Part No: R412006209
- Part No: 4616 / H2
- Part No: 4616 / 12
- Part No: 4616 / FN
- Part No: 4616 / FO
- Part No: 4616 / H1
- Part No: 4616 / J5
- Part No: Repairing kit of pneumatic jacks for R480623757 CVI
- Part No: 5777055280
- Part No: 822334535
- Part No: R416001418
- Part No: 5762010002
- Part No: 8985003592
- Part No: C12P.FCM.40AP25 G1 KA AJLN2901
- Part No: C12PN 40AP50 G1 KCA JLN 29.0.
- Part No: 822392000
- Part No: GSP-P-72
- Part No: 5812290650
- Part No: 822390204
- Part No: 822393226
- Part No: 822394210

- Part No: 820025250
- Part No: P/N: 0820058026 Type: TC15-5/2XX-SR-024DC-I-FORM_C-SGL
- Part No: 167-12-0000-1 old model / actual model 0822306216
- Part No: 170 04 0200 – Q40MM – S:200MM ISO 6431/VDMA
- Part No: 348/1 MOD C obsolete, alternative 5633011340 + 5634420000
- Part No: 3610507600 (FS07-000-100-G014-PLU-(0,1-7,1))
- Part No: 3701204000 / 370-MA-M027-0040-N
- Part No: 5340051010
- Part No: 565-301-000-3
- Part No: 5672010000 / V567-3/2NC-SR
- Part No: MP5
- Part No: R431002820
- Part No: R431002939
- Part No: R480094066 / VTS HF 03 VER 11 AAABB
- Part No: SERIES 344 ¾" NPT
- Part No: 370-MA-M042-0080-N (3702008000)
- Part No: 5610141310
- Part No: 1827009359
- Part No: 1827231010
- Part No: P/N: 5776225280 Type: CD07-5/2XX-DO-230DC-I-M014
- Part No: 821303816
- Part No: 821303809
- Part No: 821300858
- Part No: 821300977
- Part No: 821300978
- Part No: 5210560002
- Part No: 5710301100
- Part No: 5724550220 / CD12-3/2NC-SR-024DC-I-G012-G012-EN175301
- Part No: 1824210291 / CO1-FORM_B-024DC-4,7W-22MM
- Part No: P/N: 0821300303 Type: NL2-FRE-G014-GAU-100-PNB-AO-05,00
- Part No: 5750020500
- Part No: 5735040100
- Part No: R480070965 obsolete
- Part No: 822010511
- Part No: 04983 – 175 – 02

- Part No: p/n: 0822010516, Type: KHZ-DA-016-0040-O
- Part No: 0821302558 (NL2-RGS-G014-GAH-MAN-100-SS)
- Part No: R431004674
- Part No: P/N: R414002402 Type: ED02-000-060-010-1M12X
- Part No: P/N: 0822010823 Type: KHZ-DA-020-0020-M-NR
- Part No: 0821401132 / LU1-050/063-AL-AN
- Part No: P/N: 0830100631 Type: ST6-PN-K03U-030
- Part No: R412010328 / SA1-MA-M033-050-H-N
- Part No: 5633011340
- Part No: 5634420000
- Part No: BDC-B-CO.32sb
- Part No: P/N: R412008990, Type: BDC-B-BCAN 32SB
- Part No: R412004418
- Part No: P/N: 5776075302 Type: CD07-5/2XX-SR-NONE-I-G014
- Part No: 0820260003 / TC08-5/2XX-DO-E-SGL
- Part No: R412007251 (AS3-DIS-G012-NC3)
- Part No: 343/5 MOD B - not available, replaced by 2992343005
- Part No: P/N: 0820402023, Type: VVST-3/2NC-PLU
- Part No: 5791500220 (V579-3/2NC-DA06-024DC-04-RV2)
- Part No: R412012576
- Part No: 1303020000
- Part No: 5772080220 / CD07-3/2NC-SR-024DC-E-G014
- Part No: R412012576 / TRB-PRX-125-ST
- Part No: 5772555302 (CD04-3/2NC-SR-NONE-I-G018-G018)
- Part No: R414002004 / ED05-000-060-420-1M12A
- Part No: 0822120005 / PRA-DA-032-0125-0-2-2-1-1-1-B
- Part No: 0820055101 / HF03-3/2CC-024DC
- Part No: P/N: 0822010667 Type: KHZ-DA-050-0050-M
- Part No: R412010767 / PE5-PN-G014-100-M12
- Part No: P/N: R412018252 Type: 16DO32SC
- Part No: R417000184
- Part No: 2992343002 - 343/2
- Part No: 0830100487 (ST9-PN-M008-036)
- Part No: 5727400220
- Part No: R414002401 / ED02-000-060-420-1M12A

- Part No: 0820055601 / HF03 - 5/3CC - 024DC
- Part No: R412019683 (ST4-PN-M08R-030)
- Part No: SER■E 250 H
- Part No: 3760040000
- Part No: 0820038152 (CD02-5/2AS-024DC)
- Part No: 5776270220 (CD07-5/2XX-DO-024DC-I-G014)
- Part No: R412007209 / AS3-FRE-G012-GAU-080-PBP-HO-05.00
- Part No: Luftbehälter 30 l■tre
- Part No: 3223003100 Discontinued
- Part No: R412006251 \ AS2-DIS-G038-NC3
- Part No: R422102526 24V1 – 17Y1 / Y2
- Part No: 3610628600 / FS07-000-100-G014-LEV-(0,1-7,1)
- Part No: 16751-160 / 0490351507
- Part No: 5672310000 (V567-3/2NC-SR-30BAR)
- Part No: 0820408002 (VVAP-3/2NC-ROL)
- Part No: P/N: 5776085280 Type: CD07-5/2XX-SR-230AC-E-G014
- Part No: R412010773 (PE5-A1-G014-000-100-M12)
- Part No: R422103001 / AV05-5/2AS-VT00-024VDC-NLC
- Part No: 3702005000 / 370-MA-M042-0050-N
- Part No: R416001832 (OEM)
- Part No: P/N: R412022872, Type: ST6-R3-M08R-030
- Part No: 5420507022 / CO1-FORM_A-024DC-2,1W-30MM
- Part No: R412006209 / AS2-FRE-G038-GAU-080-PBP-HO-05,00
- Part No: 0822121004 (PRA-DA-040-0100-0-2-2-1-1-1-BA)
- Part No: R976751062
- Part No: R414004198
- Part No: 1827004819 obsolete/replacement R412012576
- Part No: R424B10755
- Part No: R480141461
- Part No: TYPE:ISO6431
- Part No: P/N: 0821303309, Type: NL2-FLP-G014-PNB-AO-00,3
- Part No: 430-300 000 not available, alternative 8940400122
- Part No: 8940400122
- Part No: 821003051
- Part No: 8940415122 obsolete/please provide cylinder type so we could find alternative for you

- Part No: 821401321
- Part No: R412006225
- Part No: P/N: OT-BRR021656, Type: R422101600
- Part No: 821303053
- Part No: R431002833
- Part No: R431004994
- Part No: R431005003
- Part No: R431006326
- Part No: R431000671
- Part No: R431006586
- Part No: R902400240/000
- Part No: R431006321
- Part No: R432022628
- Part No: 5894400000
- Part No: R480188305
- Part No: 5351403200 obsolete/alternative R412006120
- Part No: R422002577
- Part No: R422003651
- Part No: R422003625
- Part No: 820055501
- Part No: R480602823
- Part No: R412006120
- Part No: R901099789
- Part No: R416004775
- Part No: R422000299
- Part No: 820038102
- Part No: 735-060-000-1 (01w08)
- Part No: 821302400
- Part No: R412010713
- Part No: 0821300354 / NL4-FRE-G012-GAU-100-PBS-AO-05
- Part No: 821303418
- Part No: 820055051
- Part No: 5814220100
- Part No: 5804710000
- Part No: 3701202000

- Part No: 1827000005
- Part No: 5634010100 (CD04-3/2NC-SR-R-G018-G018-S)
- Part No: 1316104050
- Part No: R412006999
- Part No: 1827009557
- Part No: 1322512000
- Part No: 0 820 223 010 obsolete/alternative 0820238103 + 1825503890
- Part No: 822010776
- Part No: 0830100488 obsolete/replacement P/N: R412022872, Type: ST6-R3-M08R-030
- Part No: R480243717
- Part No: P/N: 5790280220 Type: 3/2NC-DA06-024DC-1,2-RV1-MODI
- Part No: ES05 series
- Part No: 0820043035 (OEM)
- Part No: 1827020284
- Part No: 1812124805
- Part No: R424E19394
- Part No: R424E19395
- Part No: R424E19397
- Part No: 820024326
- Part No: 820027303
- Part No: 821200005
- Part No: 7472802424
- Part No: 7472802425
- Part No: 821100103
- Part No: 1827020282
- Part No: 830100489
- Part No: P/N: R412007045, Type: AS3-FLC-G012-PBP-HO-00,01
- Part No: 821300303
- Part No: R987025261
- Part No: P/N: R404065058, Type: 167-DA-200-0160-A116-Temposonics obsolete/ replaced by ITS-DA-200-0160-2-2-1-1-8-000-00-000-BAS
- Part No: 5420527022
- Part No: 5428477082
- Part No: ITS-DA-200-0160-2-2-1-1-8-000-00-000-BAS
- Part No: SM6-AL-M08T-030-179
- Part No: R412010883 / SM6-AL-M08T-030-215

- Part No: R412008970; BDC-B-CO.32.sb - (OEM)
- Part No: P/N: 3513000040, Type: AR1-G100-0200
- Part No: 1827414900
- Part No: 5610141530 / ED05-000-100-010-2DICA
- Part No: 820060361
- Part No: P/N: 5727405480, Type: V740-5/2AR-230AC-07
- Part No: 793116918
- Part No: 493828509
- Part No: 580-175-000-1(98w51) old code/new code 5801750000
- Part No: Pneumatic distributor Repair kit for 580-175-000-1(98w51)
- Part No: 5801750000
- Part No: Pneumatic distributor Repair kit for 580-175-000-0 (00w13)
- Part No: 793116705
- Part No: Control valve Repair kit for 07931-167-05(07931-069-04)98w51
- Part No: P/N: R412010410, Type: SM6-A4-M08T-036-160
- Part No: P/N: R976501075, Type: CCY-SA-025-0015-MODI - OEM/customized
- Part No: 586-211 000-1 obsolete/alternative 5776075302 + coil
- Part No: P/N: 0822350010, Type: PRA-DA-032-0400-0-2-2-1-1-1-BAS
- Part No: P/N: 0822391003, Type: KPZ-DA-020-0020-004122411000020-B
- Part No: P/N: R481601029, Type: TRB-DA-125-0160-0-2-2-1-3-7-ACC
- Part No: 1828391301
- Part No: 5257645840
- Part No: 830100452
- Part No: 821003075
- Part No: P/N: 0822061004, Type: GPC-DA-016-0050-BV-SB
- Part No: 822233003
- Part No: 822932228
- Part No: R037551033
- Part No: 830100381
- Part No: 523-403-080-0 (523-400-080-0) obsolete/alternative P/N: 0822344010, Type: TRB-DA-080-0400-0-2-2-1-1-1-BA
- Part No: R414002005
- Part No: P/N: 0822344010, Type: TRB-DA-080-0400-0-2-2-1-1-1-BA
- Part No: R412004576
- Part No: 5777250220

- Part No: R431005013
- Part No: P-059339-00000 old code/new code R431005013
- Part No: P-059339-00003 old code/new code R431005015
- Part No: P-059339-00002 old code/new code R431005014
- Part No: 7472800146
- Part No: 820024601
- Part No: 820022026
- Part No: 820057005
- Part No: P/N: R480645515, Type: TRB-DA-080-0210-0-2-2-1-1-1-ACC
- Part No: R412009200
- Part No: P/N: 0822333202, Type: MNI-DA-20-0025-U-31-01-1-00-000-00
- Part No: R412007109
- Part No: 5284010050
- Part No: 1938281000
- Part No: 412301014
- Part No: 820260002
- Part No: P/N: R412006105 Type: AS2-RGS-G014-GAU-040
- Part No: P/N: 2650113460, Type: ZSC-DA-020-0030-BV-SE
- Part No: 820212200
- Part No: 820251004
- Part No: R431002613
- Part No: R431005217
- Part No: R431008258
- Part No: R431003557
- Part No: R431004918
- Part No: R431003427
- Part No: R431002821
- Part No: R431002913
- Part No: R431002937
- Part No: 821302559
- Part No: 821302401
- Part No: 820005101
- Part No: 821302711
- Part No: 822334204
- Part No: R412009260

- Part No: R412009003
- Part No: R412009265
- Part No: 821305028
- Part No: 0820038181 / CD02-5/2AS-024DC
- Part No: 820024552
- Part No: 5812260000
- Part No: R412006175
- Part No: 5634210100 (CD04-5/2SR-G018-ROL)
- Part No: 0820057101 same as 0820A57101
- Part No: 0820A57101
- Part No: R412007017
- Part No: R412007703
- Part No: 5218535110
- Part No: ED05-000-0060-420-1M12A check code R414002004 (ED05-000-060-420-1M12A)
- Part No: R415015650
- Part No: 520 005 184 0 - obsolete/alternative P/N: 0822406372, Type: KHZ-SA-063-0025-O
- Part No: 822406372
- Part No: 821302810
- Part No: R412006268
- Part No: R412006009
- Part No: R412006045
- Part No: R412006133
- Part No: R412006107
- Part No: 830100467
- Part No: R412009038
- Part No: R412025968
- Part No: R976500149 - OEM/customized
- Part No: 0822030206/MNI-DA-10-0060-U-01-01-1-00-000-00
- Part No: 0821300349 / NL2-FRE-G014-GAU-060-PNB-AO-05
- Part No: 821300901
- Part No: 1827231015
- Part No: 5610219300
- Part No: 1825700085
- Part No: 1827010606
- Part No: 1834484260

- Part No: 2121006140
- Part No: 8941054044
- Part No: 8941054054
- Part No: 8941054324
- Part No: R412004817
- Part No: R412005795
- Part No: 5811290450
- Part No: 820057101
- Part No: 5226045000
- Part No: AS5-S0V-G034-024
- Part No: R412009250
- Part No: R412004423
- Part No: R414002009 / ED05-000-100-010-1M12A
- Part No: 490368604
- Part No: Code 1020100000
- Part No: RCM-06-090-SE-00-00
- Part No: 821300351
- Part No: 1827009314
- Part No: 821300911
- Part No: 821302501
- Part No: 5813170450
- Part No: 8940410612 / SN6-R2-DB09-048
- Part No: 5428110080
- Part No: R412010856
- Part No: 822010632
- Part No: 5813790650
- Part No: R412010717 / PM1-M3-G014-002-160-M12X1-NONE
- Part No: R412022872
- Part No: Gaskets for 00.580.3367/02 / for cylinder 00.580.3367/02 (OEM) alternative 0822033202
- Part No: 820023980
- Part No: 820023990
- Part No: 820035102
- Part No: 821305194
- Part No: 1105-20-000-1 obsolete
- Part No: 490431004

- Part No: 822033202
- Part No: R412020668
- Part No: R41200756
- Part No: R414004240
- Part No: R431003973
- Part No: 2518-1-9060-1
- Part No: 274H / M34 / 100/65/4100 / FS- S36198
- Part No: p/n: 5630201050, Type: ZZ99-3/2NC-PUS-ND4-POPPET
- Part No: AV0X-AES-D-BC-ECAT-ETHERCAT
- Part No: 820034002
- Part No: Compressed air preparation unit
- Part No: 0821300934 (NL4-SOV-G012-SOE-CON-SS)
- Part No: 821300367
- Part No: 821300350
- Part No: 830100373
- Part No: 5510100000
- Part No: 5510250000
- Part No: 5725650920
- Part No: 00.580.3367/02 OEM
- Part No: R480205752
- Part No: R416002226
- Part No: 0820060797 / TC08-5/2XX-AS-024DC-E-M8X1_4P-VTS
- Part No: 5226610500
- Part No: R412020942
- Part No: 5226035000
- Part No: 1025100000
- Part No: kit for A 3608955202
- Part No: R412022869 / ST6-R3-K03U-030
- Part No: R412006104
- Part No: 821303503
- Part No: 5631310100
- Part No: 5226020700
- Part No: P/N: 5727405280 Type: V740-5/2AR-230AC-07
- Part No: R480041122
- Part No: R412004751

- Part No: 1827231018
- Part No: 3610500600
- Part No: R961400141
- Part No: R415015780
- Part No: R422100974
- Part No: 821003021
- Part No: R412010565
- Part No: 821003050
- Part No: R415011103
- Part No: R480304869
- Part No: R412006368
- Part No: R412007959
- Part No: R480321486
- Part No: R415015560
- Part No: 5710200100
- Part No: R422003189
- Part No: 3843.AF9.216
- Part No: R412020074
- Part No: R412020087
- Part No: R412020079
- Part No: R422103007 / AV05-3/2CC-VT00-024VDC-NLC
- Part No: R412020071
- Part No: R412021778
- Part No: R422103004
- Part No: R422003185
- Part No: 821000004
- Part No: R422001078
- Part No: R422001097
- Part No: R412022859
- Part No: 822121007
- Part No: P/N: R412022861, Type: ST6-PN-M08U-030
- Part No: Repair Kit For R412007209
- Part No: 311 / 19 Mod. A obsolete/ replaced with VVAP-3/2NC-PUS
- Part No: 820024505
- Part No: R431005568

- Part No: R431004795
- Part No: 1020200000
- Part No: 581-32
- Part No: 581-21
- Part No: 820038126
- Part No: VO 21031448
- Part No: R431006083 (P-062572-00000)
- Part No: R431007321
- Part No: 820058126
- Part No: VVAP-3/2NC-PUS
- Part No: 5728400220
- Part No: 5776075302
- Part No: 049-035-150-7
- Part No: 0822010513 / KHZ-DA-016-0020-O
- Part No: 820019985
- Part No: R422103175 / ES05-5/2-SR-D8-24VDC-SGL
- Part No: R422102190
- Part No: 821300914
- Part No: 0821300930 / NL4-DIL-G012-NC4
- Part No: 821301501
- Part No: 821302500
- Part No: 820402019
- Part No: R431003042
- Part No: 1671-294-10
- Part No: 0821300911 / NL4-SOV-G012-SOM-MAN-SS
- Part No: ITS-DA-160-0200-2-2-1-3-7-073-00-000-ACC
- Part No: ITS-DA-160-0200-1-2-1-3-7-073-00-000-ACC
- Part No: ITS-DA-160-0200-1-1-1-3-7-073-00-000-ACC
- Part No: ITS-DA-160-0200-2-1-1-3-7-073-00-000-ACC
- Part No: 5610111000
- Part No: 5610113102
- Part No: EV03-005-060-020-SL1P
- Part No: 822306216
- Part No: 4441110000
- Part No: R412018225

- Part No: 5610214530
- Part No: 820235002
- Part No: 821303302
- Part No: REPAIR KIT FOR GMH 0080 T3 SAO 0150.9 HCO A2FE 56 KDN-K
- Part No: 821300924
- Part No: 5725475202
- Part No: 3730171100
- Part No: 5812672540
- Part No: 830100435
- Part No: 1827001626
- Part No: 1827003995
- Part No: 1827001605
- Part No: 5777050220 / CD04-5/2XX-AR-024DC-I-G018-G01
- Part No: R480145330
- Part No: ITS-DA-200-0270-2-2-1-1-8-000-0-MT4-ACC
- Part No: ITS-DA-200-0270-2-2-1-1-8-000-00-MT4-ACC
- Part No: 821302080
- Part No: repair kit for R422100600
- Part No: R402005737
- Part No: 2752135000
- Part No: 820060251
- Part No: R480041527
- Part No: R499001096
- Part No: G415018335
- Part No: R415004567
- Part No: 5630181100 (VR04-4/3EC-LEV)
- Part No: 822120003
- Part No: 168-580-316-0 obsolete, alternative PRA-DA-032-0160-0-2-2-1-1-1-BAS
- Part No: PRA-DA-032-0160-0-2-2-1-1-1-BAS
- Part No: 822032203
- Part No: 820055052
- Part No: R412007979
- Part No: R412012554
- Part No: 1827009619
- Part No: 821302555

- Part No: R440001900
- Part No: 490394818
- Part No: R414002403
- Part No: 361-050-750-01
- Part No: 0822010567 / KHZ-DA-050-0050-O
- Part No: 170-03 0800-1
- Part No: 3220621860
- Part No: R480606816
- Part No: 5634610100
- Part No: 5634610100 (CD07-5/2XX-SR-R-G014-G014-S)
- Part No: 1827231024
- Part No: 822122008
- Part No: 820230003
- Part No: 820230002
- Part No: 821401010
- Part No: 3610607700
- Part No: 3630040012
- Part No: 820056201
- Part No: AS5-ABVG034-MAN
- Part No: ENE-ET-10-NC-N-N-NN-G038-024DC
- Part No: CD02-5/2AS02ADC
- Part No: R412007352
- Part No: R412010713 (PM1-M3-G014-002-160-DINA-CON)
- Part No: 5634000100
- Part No: R414009321
- Part No: 3702008000 / 370-MA-M042-0080-N
- Part No: LS04 (R480270231)
- Part No: R412006273 / AS2-SSV-6038-FIA
- Part No: 5777060220
- Part No: R414002413
- Part No: 1021200000
- Part No: R412010264
- Part No: 821300917
- Part No: 821301502
- Part No: 821301806

- Part No: 821302404
- Part No: 821303505
- Part No: 821303812
- Part No: 5341124100
- Part No: 5813080000
- Part No: 821003028
- Part No: 820019980
- Part No: ES-ES05x12-DSUB25
- Part No: R976501075
- Part No: 0820 403 023-85427
- Part No: 1827 009 095-855
- Part No: 820403023
- Part No: 1820712084
- Part No: 3710760300
- Part No: 821003026
- Part No: R412007215
- Part No: 7472003001
- Part No: AV-AV03x6-DSUB25
- Part No: R412022865
- Part No: 820055502
- Part No: 830100303
- Part No: 1827020056
- Part No: D022/D030
- Part No: 0820051026 (CD01-5/2SR-VD01-024DC-AL)
- Part No: 822392010
- Part No: R412009120
- Part No: 820038652
- Part No: 1825503891
- Part No: 5776275302 (CD07-5/2XX-DO-NONE-I-G014)
- Part No: 1824210243
- Part No: 822122009
- Part No: 5813100000
- Part No: R412018751
- Part No: R412010324
- Part No: 5285010040

- Part No: R412006201
- Part No: 821401342
- Part No: 822391002
- Part No: 822392005
- Part No: 822931001
- Part No: 1822122025
- Part No: R422001237
- Part No: R 412 004 576
- Part No: R412019801
- Part No: 0820060126 (TC08-5/2XX-AS-024DC-I-FORM_C-S)
- Part No: R434000828
- Part No: 5811421000
- Part No: 131.064.5000
- Part No: NC -R480755832 ES-ES05X6-DSUB25
- Part No: R422102637 (ES05-2X3/2-CC-D8)
- Part No: 0822406340 \ KHZ-SA-032-0005-O
- Part No: R402003928
- Part No: R480962480
- Part No: R480962481
- Part No: R413000009
- Part No: 0830100366 / SN2-R2-K05V-240
- Part No: 19W26 0822 120 002
- Part No: R432013834
- Part No: R480665137
- Part No: socket for 1824210220
- Part No: 822397007
- Part No: R431005743 / P-061278-K0000
- Part No: R431005249 / P-059819-0000
- Part No: R431005745 / P-61289-10
- Part No: R412014628
- Part No: R412007344
- Part No: R480175941
- Part No: MSC-DA-020-0150HGHMHM02MSOOACC
- Part No: R412019006
- Part No: R480627374

- Part No: 0822066101 \ GPC-DA-050-0050-BV-BB
- Part No: R412009263
- Part No: R412009269
- Part No: R412009115
- Part No: R412009371
- Part No: R412009367
- Part No: CD07
- Part No: R480049027
- Part No: 5233030250
- Part No: 822122007
- Part No: 0820051504/CD01-5/2DS-VD01-024AC-AL
- Part No: R412006261 \ AS2-SOV-G038-MAN
- Part No: R41200185
- Part No: R412001343
- Part No: R412006269 \ AS2-SOV-G038-024
- Part No: R41200134 (pressure regulator)
- Part No: 1827009613
- Part No: 42122500
- Part No: R432006321
- Part No: R424E08312
- Part No: 5777770220 / CD07-5/3CC-DO-024DC-I-G014
- Part No: 5813490050
- Part No: 5812591650
- Part No: R480672839 D32 C100
- Part No: R412010373
- Part No: R480672839
- Part No: R412022873
- Part No: R432006124
- Part No: R800G02F
- Part No: R412009494
- Part No: 5610111100
- Part No: 566-201-000-0
- Part No: J653ASRD6C00A00
- Part No: G503AV3N300VMUF-G3ED103D0STD
- Part No: G503AV3J300VMUF-G3ED102D0STD

- Part No: G503AV3L300VMUF-G3DS204D0STD
- Part No: G503AV3N300VMUF-G3DS204D0STD
- Part No: 8503AMM22WA0010
- Part No: J653AR004R101H0
- Part No: A653A0000012615
- Part No: A653A0000012605
- Part No: 821300581
- Part No: 697-11-101
- Part No: 797-12-010
- Part No: 821303536
- Part No: 5631210530
- Part No: R434006664
- Part No: 493833103
- Part No: R412010208 / BCE-210-076-SB
- Part No: 20W33 0 822 121 001
- Part No: 820038152
- Part No: 5610102070 / EV07-001-060-010-2DIAN
- Part No: 5340051000
- Part No: 821003002
- Part No: R412006143 / AS2-RGP-G014-GAU-080
- Part No: 822010571
- Part No: 7350600000
- Part No: R414000240
- Part No: 5727415302 (V740-5/2DS-00000-07)
- Part No: R413000424
- Part No: 576 349 092 0
- Part No: 8856004950 (SUBSTITUTE T9CDL450 420 FROM REXROTH)
- Part No: R431005261
- Part No: 0821300062 / NLC-FRL-G034-GAU-100-PBS-MA-40,00
- Part No: 8940410602
- Part No: 0821300535 (NL4-ACD-G034-GAU-100-SSS-AO-05)
- Part No: 822406341
- Part No: 822121030
- Part No: R412019488
- Part No: R432036353

- Part No: 822344004
- Part No: 3230090600
- Part No: PM-23465.6
- Part No: R415009856
- Part No: TRB-DA-125-0400-0-2-2-1-3-1-ACC
- Part No: AS2 series
- Part No: R414008249 / EV03-000-060-420-SL1P
- Part No: R412010499
- Part No: 822353002
- Part No: AES-D-BD-EIP R412018222
- Part No: 57100000000000
- Part No: MNI-DA-25-0050-D-31-01-1-00-000-00/0822334503
- Part No: MNI-DA-25-0015-D-31-01-1-00-000-00/0822334537
- Part No: 821003025
- Part No: 822010654
- Part No: 821302440
- Part No: R412007269
- Part No: R402000250
- Part No: FD:18W22
- Part No: 822121018
- Part No: R412007209 /AS3 -FRE-8012-BAU
- Part No: F1CG-0111A-ADA4
- Part No: 5710400100
- Part No: 0821 000 010
- Part No: R412007009
- Part No: 822394200
- Part No: 1670620000 / 167-DA-063-0200-DM00SCWS0S
- Part No: 822334557
- Part No: 0821300776 / NL1-SOV-G014-SOE-024-SS
- Part No: 0821303718 / NL1-FLC-G014-PNB-HO-00,01
- Part No: 821300774
- Part No: R480141666
- Part No: R480960418
- Part No: R480960419
- Part No: R402003941

- Part No: R402003943
- Part No: R402003929
- Part No: R422002730 24 VDC
- Part No: R976500802
- Part No: 822394623
- Part No: 822393208
- Part No: 822394005
- Part No: 0822010552 (KHZ-DA-040-0015-O)
- Part No: 822120007
- Part No: 822394250
- Part No: R412006307
- Part No: 1829207061
- Part No: 820062052
- Part No: R961400144
- Part No: R424B06827
- Part No: 5500280000 \ 550-028
- Part No: 1834484187 / CN1-FORM_C-M12X1,5-2+E
- Part No: R432006436
- Part No: R431002947
- Part No: R412010608
- Part No: R480338734
- Part No: 1 825503 487
- Part No: 0 820 043 025
- Part No: 3610607600
- Part No: R433023957
- Part No: R433023958 P-106867 K0001
- Part No: 0822124005 / A-DA-080-0125-032211110000000000000000-B
- Part No: 8P-1S
- Part No: A-2-H
- Part No: 5811530000
- Part No: 5711100300
- Part No: 5652010000
- Part No: 822334502
- Part No: R404065065
- Part No: PACKAGING R404065065

- Part No: R432006079
- Part No: R432006290
- Part No: repair kit R433084025
- Part No: R433084025
- Part No: R432006441
- Part No: 5711100002
- Part No: 5711000002
- Part No: 3710200002
- Part No: 3630030022
- Part No: 3723520002
- Part No: 5710400002
- Part No: 5631020002
- Part No: 4342080000
- Part No: 5340170000
- Part No: 5341060002
- Part No: CNR481636527
- Part No: V K1827001291
- Part No: VKR413000828
- Part No: 0820402002 (VVST-3/2NC-ROL)
- Part No: R480154829
- Part No: R422001217 (CCI-DA-050-0060-00412241100000)
- Part No: 0820259002 (TC15-5/3EC-DO-E-SGL)
- Part No: R431003040
- Part No: R433022027
- Part No: R433041024
- Part No: R412010826
- Part No: AES-D-BC-DEV / R412018221
- Part No: 822010665
- Part No: R480062948
- Part No: R422002731
- Part No: 0822010524 / KHZ-DA-020-0025-O
- Part No: R431007966
- Part No: 822120008
- Part No: R414007421
- Part No: 822244009

- Part No: 0822419002 / BCP-165-054-SB
- Part No: 1827009337
- Part No: 822350003
- Part No: 822034204
- Part No: AS3-SOV?R412007388
- Part No: R412007388 / AS3-SOV-G012-3/2-PON-PVN
- Part No: R480051091
- Part No: R422003228
- Part No: NW5 G1/4
- Part No: R414000119
- Part No: A98- N 26747
- Part No: 5218565110
- Part No: 5220463442
- Part No: R4 12022827
- Part No: R414007383
- Part No: 822332503
- Part No: N 26747 - A98
- Part No: 821000010
- Part No: 830100464
- Part No: R434000736
- Part No: 0821300353 / NL4-FRE-G012-GAU-100-PNB-AO-05
- Part No: 5763810220
- Part No: R413000649
- Part No: 0822010573 / KHZ-DA-063-0020-O
- Part No: R412007185
- Part No: R412005101
- Part No: R412005036
- Part No: R432016585
- Part No: 822233005
- Part No: 822031208
- Part No: R422001218
- Part No: R480308317
- Part No: R431003429
- Part No: P/N: 0822332206, Type: MNI-DA-16-0125-U-31-01-1-00-00
- Part No: P/N: 1827001446, Type: CM1-AB3-012/016-M2-A

- Part No: P/N: 1827020298, Type: CB1-MNI-016-016-ST6
- Part No: R402003730
- Part No: R412010718 (PM1-M3-F001-002-160-DINA-CON)
- Part No: WV02-5/2AS-NONE
- Part No: 821302089
- Part No: 5813290650 / V581-5/2DS-024DC-I3-2CNO-LBX-AA-X-C-T0
- Part No: 820025602
- Part No: 820057001
- Part No: R412007184 (AS3-FRE-G012-GAN-080-PBP-HO-05)
- Part No: R412007261 / AS3-BAV-G012-MAN
- Part No: R412007027 (AS3-FLP-G012-PBP-HO-00,30)
- Part No: R412007063 (AS3-FLC-G012-PBP-HO-00,01-ICI)
- Part No: R412007269 (AS3-SOV-G012-024)
- Part No: R961400140
- Part No: 1834484204 (CN1-FORM_C-Z-2+E-3,00M-YE)
- Part No: R412009010
- Part No: 822334509
- Part No: 822391215
- Part No: R422001235
- Part No: 0822344005 (TRB-DA-080-0125-0-2-2-1-1-1-BA)
- Part No: 820024126
- Part No: R413000898
- Part No: p/n: 0822010721, Type: KHZ-DA-020-0010-O-NR
- Part No: 0822010541 / KHZ-DA-032-0010-O
- Part No: P/N 0820 038 126
- Part No: 822122018
- Part No: PRA-DA-032-0240-0-2-2-1-1-1-BAS
- Part No: TRB-PRX-032-ST
- Part No: 0822010522 (KHZ-DA-020-0015-O)
- Part No: 0820410110 / RA14-5/3CC-SR-HL
- Part No: G651AR001P250H0
- Part No: PRA/TRB-032-ST
- Part No: R424E19396
- Part No: 821000003
- Part No: R480657093

- Part No: R400003002
- Part No: R400003004
- Part No: R400003006
- Part No: H-2-X 0-125
- Part No: 820023126
- Part No: 1827009391
- Part No: 1827009389
- Part No: R412006000 (AS2-FLS-G014-PBP-HO-05,00)
- Part No: 822010551
- Part No: 0830100480 (SN2-PN-M008-030)
- Part No: CD01 -5/3EC
- Part No: R414002297
- Part No: 3710750002
- Part No: R412026772
- Part No: 822125008
- Part No: SEAK-06A4C-B1A2
- Part No: R976753227 oem
- Part No: 822406491
- Part No: 5811170650 (V581-5/2SR-024DC-I1-1CNO-LBX-A)
- Part No: 0820038126 (WV02-5/2AS-024DC)
- Part No: 0822343003 (TRB-DA-063-0080-0-2-2-1-1-1-BA)
- Part No: 0820038652 / CD02-5/2DS-024DC
- Part No: 0493833103 / 90606-5798
- Part No: 2650122020
- Part No: 0820019526 / DO30-3/2NC-CNOM-024DC
- Part No: 3236981000
- Part No: 8946202502
- Part No: 8946202032
- Part No: 3236990062
- Part No: 3236994162
- Part No: 5421330220
- Part No: 8941000302
- Part No: 1823391943 / QR2-S-RVA-DA10-DA10
- Part No: 5634461100 / CD07-3/2NC-PN-BU-G014-G014-S
- Part No: R431004996

- Part No: 822334503
- Part No: 822031202
- Part No: 0820400001 (VVAP-3/2NC-PLU)
- Part No: R412004800
- Part No: 0820052426 / CD01-5/3EC-VD01-024DC-AL-M12
- Part No: LIYCY-OB 5x 0,34
- Part No: R961400143
- Part No: R414008453
- Part No: 0830100466 / SN2-R2-M008-036 100 OHM
- Part No: R414001070
- Part No: C12P-63-AP-175-G-1- KS-A-J-L-N-20-39-2
- Part No: 1827414878
- Part No: R413000832 / PRA/TRB-125-HT
- Part No: R414010089 / ITS-DA-200-0150-1-2-1-1-5-MT4-ACC-MODI
- Part No: FD: 16W36
- Part No: 5285030080
- Part No: AS3-FRE-G012-GAU-080-PBP-AO-05.00
- Part No: AS3-FLP-G012-SSS-AO-00,30
- Part No: 0820403002 / VVAP-3/2NC-LEV
- Part No: 5794600220
- Part No: 5772072220
- Part No: 0822 011 002
- Part No: 5813080800
- Part No: MNR: 361-060-760-0
- Part No: PN: 0820056501 / Type: HF02 - 5/2DS - 024DC
- Part No: R412005241
- Part No: R480719794
- Part No: 1827414004
- Part No: 1827414006
- Part No: 5814080000
- Part No: 820023012
- Part No: 8919905512
- Part No: 1824210360
- Part No: 5763510220
- Part No: R412006115

- Part No: 1822124004
- Part No: 182022039 CD01-??
- Part No: R961400027
- Part No: 5791600220 (V579-3/2NC-DA08-024DC-04-RV2)
- Part No: 5763870820 / CD01-PL-5/3CC-024DC
- Part No: 5212086020
- Part No: R412010766 (PE5-PN-DA04-000-100-M12)
- Part No: R412007451 (EBS-PT-10-NN-N-N-NN-DA06-DA08-)
- Part No: 0830100365 / SN2-R2-K03V-240
- Part No: 820058601
- Part No: 820060001
- Part No: 820060401
- Part No: 1824210223 / 24V DC 4,7VA
- Part No: R412007231
- Part No: 822010525
- Part No: 5228039100 / MNI-SA-025-0300-803910-MODI
- Part No: SN:007820
- Part No: FD:21W46 / SN: 007820
- Part No: 820022986
- Part No: R412005098 / QR1-S-RVT-G012-DA16
- Part No: R412009272
- Part No: R412009176
- Part No: R412009258
- Part No: R412009226
- Part No: mount for R412009272 (AS5-SSV-G034-FIA)
- Part No: mount for R412009176 (AS5-FRE-G034-GAN-080-PBP-AO-05)
- Part No: mount for R412009258 (AS5-SOV-G034-PVC-CNOMO)
- Part No: mount for R412009226 (AS5-LBS-G034-PBP-MN)
- Part No: mount for R412009260 (AS5-BAV-G034-MAN)
- Part No: R434001453 / CERAM-ISO2-5/2DS-24VDC-I-LOW-TEMP
- Part No: MNR 0822342011
- Part No: 3750010300 / 30BAR-G3/8
- Part No: R480938200
- Part No: R480938201
- Part No: 0822010722 / KHZ-DA-050-0080-M

- Part No: R431008563
- Part No: R431003348
- Part No: R431002831
- Part No: ADVC-63-20
- Part No: R480145874
- Part No: 8652APJP2GA00HN
- Part No: 821301512
- Part No: R42200356
- Part No: 820025904
- Part No: R412006260
- Part No: 0830100371 / SN2-R3-K03V-042
- Part No: 0820055301 / HF03 - 3/2OC - 024DC
- Part No: Hf03-5/2
- Part No: 0820055102 / HF03 - 3/2CC - 024DC
- Part No: R412013391 / DO16-3/2NC-024DC-M12X1.75-ND
- Part No: 0822234003 (MNI-DA-25-0050-D-01-01-1-00-00)
- Part No: seal kit for R996001115
- Part No: 5340050010
- Part No: 0822406021 / KHZ-SA-012-0010-O
- Part No: R412019189
- Part No: 5727405302
- Part No: R432006211 / CERAM-ISO3-5/2SR-SS-120VAC-E
- Part No: R432006302 / CERAM-ISO4-5/2SR-SS-120VAC-E
- Part No: 5710400000 (CD07-3/2NC-SR-M014-M014-M010-S)
- Part No: 821302733
- Part No: 0822123001 / PRA-DA-050-0320-0-2-2-1-1-1-BAS
- Part No: R412010586
- Part No: 821302516
- Part No: 821303404
- Part No: 821303309
- Part No: 0821300901 / NL2-BAV-G014-SOM-MAN-SS
- Part No: 0822062404 // GPC-DA-020-0050-E-SB
- Part No: 5727475302
- Part No: 5228044250 / 522-SA-020-0025
- Part No: repair kit for 0822123001 / PRA-DA-050-0320-0-2-2-1-1-1-BAS

- Part No: R412006260 / AS2-SOV-G014-MAN
- Part No: 822341906
- Part No: R413000899 / PRA/TRB-040-ST
- Part No: 3420700220
- Part No: R480602823 / PRA 80-150
- Part No: 821300708
- Part No: 822334505
- Part No: R501A2B60MA00F1
- Part No: 822396504
- Part No: 3630103010, 4/3-NW7
- Part No: 5230033502 / CB1-523-032-063-RM6
- Part No: R412000823 / SN6-R2-DB09-024 ATEX 3GD
- Part No: 3355001990
- Part No: R432011989
- Part No: 5420890020
- Part No: R412006260 with gauge
- Part No: R412010569 (CC04-G018-DA06-2_1)
- Part No: CD07-5 / 2XX-SR-024DC-I-G014
- Part No: R412010245
- Part No: R412010247
- Part No: R412018167 / ITS-200-NBR
- Part No: 1827009907 / TRB-PRX-125-ST
- Part No: R412018165 / ITS-160-NBR
- Part No: 1827009569 / TRB-PRX-050-ST
- Part No: 5790500220 (V579-3/2NC-DA06-024DC-04-RV1)
- Part No: 5792500220 (V579-3/2NC-DA06-024DC-04-RV4)
- Part No: R480147069 / CCI-DA-040-0050-0041234110000
- Part No: 0821303808 / NL6-FLS-G100-PBS-HO-40,00
- Part No: 5610141310 / ED05-000-060-420-2DICA
- Part No: 5711000100 / CD12-5/2XX-AR-G012-G012-G018-S
- Part No: 3726522220
- Part No: R413000901 / PRA/TRB-063-ST
- Part No: 3750010072
- Part No: 3726562220
- Part No: 3220620022

- Part No: 0820 212 001
- Part No: R412006202
- Part No: KIT FOR REPAIR 0820260003
- Part No: R480610498
- Part No: 0822245002 / TRB-DA-100-0050-0-2-1-1-1-1-BAS
- Part No: KA132L36T1
- Part No: R480676621
- Part No: 5811421100
- Part No: 822334507
- Part No: 821302046
- Part No: TU1-S-PUR-8X1,15
- Part No: R431004541
- Part No: repair kit for R431004541
- Part No: R431004920 / (Old part# P-059155-00080)
- Part No: 0820038176 / CD02-5/2AS-024DC
- Part No: 0821300668 (NL1-RGS-G014-GAH-MAN-100-SS)
- Part No: 0821300922 / NL2-SOV-G014-SOE-024-DS
- Part No: R422103177 / ES05-2X3/2CC-D8-24VDC-SGL
- Part No: 5351230000
- Part No: 5351230010
- Part No: 0821758090 / VTS CHF02/FM1 Z
- Part No: R480687928
- Part No: R404066265
- Part No: R422001145
- Part No: R419801636
- Part No: 1827231039 / PG1-PAN-G014-SNL-D63P(0-16)
- Part No: glass bowls for 0821303808
- Part No: metal cages for 0821303808
- Part No: glass bowl seal for 0821303808
- Part No: bleed screws for the glass bowls for 0821303808
- Part No: 3224040000
- Part No: R413000236
- Part No: 821300878
- Part No: 5813130000
- Part No: R432016668

- Part No: R432038439
- Part No: R412000144
- Part No: 0820019501 (DO30-3/2NC-CNOM-024DC)
- Part No: 822010630
- Part No: R431000660
- Part No: AS2-RGS-G014-CAN
- Part No: 5791610210 (V579-3/2NO-DA08-012DC-04-RV2)
- Part No: OT-BRR070685
- Part No: 5811170050 / V581-5/2SR-NONE-I1-1CNO-LBX-AA-X-C-T0
- Part No: 5428457082
- Part No: R480672157
- Part No: STAMP KIT FOR R480672157 / PRA-125-900
- Part No: 3710760002
- Part No: R412015207
- Part No: 0821300258 / NL2-FRE-G014-GAU-100-PNB-HO-05
- Part No: 0821302705 / NL1-RGS-G018-GAN-MAN-030-SS
- Part No: R414005862
- Part No: MNR: R414005862
- Part No: 3712091000
- Part No: 3630000000000
- Part No: 5727400420 / V740-5/2AR-024DC-07
- Part No: 3630030100
- Part No: Repair kit for 167-08
- Part No: 3630030012
- Part No: R412015808
- Part No: 830100480
- Part No: 5226044500 (522-DA-020-0050)
- Part No: 5711100200 (CD12-3/2NC-SR-M022-M022-G018-S)
- Part No: 5634240100 (CD04-5/2XX-SR-HL-G018-G018-S)
- Part No: 5634040100 (CD04-3/2NC-SR-HL-G018-G018-S)
- Part No: 5727420220 / V740-5/2AR-024DC-07
- Part No: 5631311100 / VR07-5/3EC-LEV
- Part No: R417001969
- Part No: 5727970220
- Part No: 0821302441 / NL2-RGS-G038-GAN-MAN-100-SS

- Part No: 0821303442 / NL2-FLS-G038-SSS-HO-05,00
- Part No: FD819
- Part No: FD175
- Part No: FD176
- Part No: 0822332203 / MNI-DA-16-0050-U-31-01-1-00-00
- Part No: MNI-SA-025-0025-MODI
- Part No: 2996700017
- Part No: 1909041000
- Part No: Sealing Set FOR 206/125/50/70/STD/MP6/FS-BS
- Part No: R422102430
- Part No: R431004910
- Part No: R431005195 / RELAYAIR-H-5-D-3-200-140-15LB
- Part No: 1827008818
- Part No: 1827009333 / NL2-CBS-SSN
- Part No: 5811490450
- Part No: R422001109 / CCI-DA-080-0100-00412241100002
- Part No: 820224014
- Part No: 5630182100 / VR04-4/3CC-LEV
- Part No: R404064294
- Part No: 820055101
- Part No: R412010569
- Part No: 5790510220
- Part No: 5420930220
- Part No: 0822010694 / KHZ-DA-100-0025-M
- Part No: 2718320000
- Part No: 343 -5 MOD
- Part No: R480653388
- Part No: 820022981
- Part No: R431005000
- Part No: P-0593330000
- Part No: R412022866
- Part No: 821302421
- Part No: FD:403 (7290)
- Part No: CP1 1823376013
- Part No: CP1 1823376004

- Part No: 1823373000
- Part No: 7472860105
- Part No: 8652A3M04FA0000
- Part No: 8652ABAP4JA000N
- Part No: 8652ACDP4FA00GN
- Part No: 8652AD004TA0000
- Part No: 8652A5S84FA00F1
- Part No: R480150209 / RTC-DA-050-0750-BV-MBM00S00BLP000P0P0
- Part No: R412019688
- Part No: R412000230 / CD12-5/3EC-DO-230AC-I-G012-G012-EN175301
- Part No: G652A3M02011200
- Part No: P/N: R412006258, Type: AS2-SOV-G014-PVC-CNOMO
- Part No: 820402102
- Part No: R422102424
- Part No: R412006017 / AS2-FLS-G038-SSS-AC-05,00
- Part No: R415001094
- Part No: 0820061761 (TC08-5/3EC-DO-024DC-E-FORM_C-V)
- Part No: 0820060761 (TC08-5/2XX-AS-024DC-E-FORM_C-V)
- Part No: 0820058028 / TC15-5/2XX-SR-230AC-I-FORM_C-S
- Part No: R404054094
- Part No: R412007339 / AS3-CLS-X000-PBP-AO
- Part No: 1827008922
- Part No: 400962-297\Rev.E
- Part No: 400961-442\Rev.F
- Part No: 400921-297\Rev.R
- Part No: 400921-281\Rev.R
- Part No: 400921-197\Rev.R
- Part No: 400915-018\Rev.M
- Part No: 400915-017\Rev.M m
- Part No: 400914-548\Rev.AE
- Part No: 400914-542\Rev.AE
- Part No: 400914-448\Rev.AE
- Part No: 400914-444\Rev.AE
- Part No: 400914-242\Rev.AE
- Part No: 400913-142\Rev.M

- Part No: 400911-342\Rev.AA
- Part No: 400129-528\Rev.CA
- Part No: 400127-642\Rev.C
- Part No: 400127-225\Rev.C
- Part No: 400914-442\Rev.AE
- Part No: 0821301408 / NL2-LBS-G014-PNB-MN
- Part No: 822396013
- Part No: R413000900
- Part No: R412006184 / AS2-FRE-G038-GAN-080-PBP-HO-05,00
- Part No: 5812180000 / V581-5/2SR-I2-1CNA-AA-X-C-T0
- Part No: 5814481000 / V581-5/3CC-I4-2CNA-AA-X-C-T1
- Part No: 5763990220
- Part No: R480044485
- Part No: 8985121002
- Part No: 250H – 39 – 20 – STD17
- Part No: 820056601
- Part No: R432006382
- Part No: R412010850 / PE2-P1-G014-000-160-M012
- Part No: 5814230000
- Part No: R412007398 (AS3-SOV-G012-3/2-POS-024-M12)
- Part No: 0821302560 (NL2-RGS-G014-GAU-MAN-060-SS)
- Part No: 1829234070
- Part No: 2750151110
- Part No: CCL-DA-080-0050-IS-0210040211AB00000-BAS
- Part No: PRA-DA-050-0200-032211110000000000000000-B
- Part No: V581-5/2DS-024DC-I1-2P15-LUA-PP-X-C-T1
- Part No: PRA-DA-032-0050-032211110000000000000000-B
- Part No: PRA-DA-032-0160-032211110000000000000000-B
- Part No: TRB-DA-080-0100-012213110000000000000000-B
- Part No: KHZ-DA-040-0030-M
- Part No: PRA-DA-032-0100-032211110000000000000000-B
- Part No: R422001205 (CCI-DA-032-0050-00412241100000)
- Part No: 830100495
- Part No: R431005478
- Part No: PT-064104-01700

- Part No: R480627303
- Part No: 051BA4Z6MN00061
- Part No: 051BA4Z2MN00061
- Part No: R431008588
- Part No: R414007697
- Part No: R404058910
- Part No: 0820403005 (VVST-5/2DM-LEV)
- Part No: R480173688 / KPZ-M3-025-010-200-000-000-000
- Part No: 821300907
- Part No: 822330203
- Part No: R415009948
- Part No: R412014666 / AS1-SOV-G014-3/2-024-FORM C
- Part No: 493833308
- Part No: 2122006180
- Part No: 822010647
- Part No: 822010644
- Part No: 842900300
- Part No: 5610141330 / ED05-000-060-010-2DICA
- Part No: R412018226
- Part No: R422004007
- Part No: MH48747
- Part No: R422102427 / AV03-5/2DS-VT00-024VDC-NLC
- Part No: R422102431 / AV03-3/2CC-VT00-024VDC-NLC
- Part No: R480757198 / AV-AV03X4-DSUB25
- Part No: 277-025-080-0
- Part No: 822121010
- Part No: 97802346
- Part No: R431002825
- Part No: R431002912
- Part No: R431002640
- Part No: R431002645
- Part No: 1022200000