

ENDURA SUPPLY

AVTRON Product List

- Part No: AV56A 4.5
- Part No: AV685N1E8YXXV000
- Part No: HS35AY1FCU0XA000
- Part No: T447W
- Part No: AVTRON-M6-5S1XH51-T003
- Part No: HS35AY1CCU1EA000
- Part No: AV56A1CJE84XP000
- Part No: 491017
- Part No: 351885
- Part No: 324128
- Part No: HS35AG1UDU0UA000
- Part No: M6-5S3HX51-T005 obsolete replaced by M6C-5S8HX51-T005
- Part No: LPV-500
- Part No: HS35MYX6GWU0EA00
- Part No: LPV 20 Foot Cable Set
- Part No: 1DX1DXP013 typ M56,obsolete replaced by AV56
- Part No: AV56A1CDX6YXP000
- Part No: K875A
- Part No: K700D17571 1 KW
- Part No: K700D17571 2 KW
- Part No: K700D17571 3 KW
- Part No: K700D17571 9 KW
- Part No: HS25A
- Part No: DWG D33595
- Part No: AV30S1C135AIX000
- Part No: AHR8-1300
- Part No: M6-5S3XH51-T003 - old code, new code - M6C-5S8XH51-T003
- Part No: M6C-5S8XH51-T003
- Part No: M485L-51-HL1 12-15G' obsolete replaced by AV485NXS8Y8YL000
- Part No: AV485NXS8Y8YL000
- Part No: B15693
- Part No: M6 4S1HX51-T003 1024 PPR 5-24VDC. replaced by M6C-4S8HX51-T003

- Part No: M6C-4S8HX51-T003
- Part No: M6-5S3XH51-T005 REPLACED BY M6C-5S8XH51-T005
- Part No: M6-4S1HX51-W003 REPLACED BY M6C-4S8HX51-W003
- Part No: M6C-5S8XH51-T005
- Part No: M6-5S3HX51-T003 obsolete replaced by M6C-5S8HX51-T003
- Part No: M6C-5S8HX51-T003
- Part No: M6C-5S8HX51-T005
- Part No: XR850 (Part Number: XR850CEF5Y5Y4032)
- Part No: M485-48-LP1-LP1 MCA obsolete, replaced by AV485NXS8L8LP000
- Part No: AV485NXS8L8LP000
- Part No: M6-5S3HX51-W003 obsolete replaced by M6C-5S8HX51-W003
- Part No: M6C-5S8HX51-W003
- Part No: AV485NXS8Y8YA000
- Part No: M6C-4S1HX51-W003
- Part No: P/N B16690
- Part No: P/N B17839
- Part No: P/N 156015
- Part No: P/N 363099
- Part No: P/N 324282
- Part No: P/N 324997
- Part No: P/N 370125
- Part No: P/N 324496
- Part No: P/N 325035
- Part No: P/N 350980
- Part No: P/N 408304
- Part No: P/N B14711
- Part No: P/N 312413
- Part No: P/N 324393
- Part No: P/N 324346
- Part No: P/N 329682
- Part No: P/N 329681
- Part No: P/N 324771
- Part No: P/N 324985
- Part No: P/N 360589
- Part No: P/N 361873

- Part No: P/N 361874
- Part No: P/N 350525
- Part No: P/N 119311
- Part No: P/N D37527-11
- Part No: P/N 360772
- Part No: P/N 360379
- Part No: LPH60
- Part No: AVTRON-M6C-5S1XH51-T003
- Part No: AVTRON-HS35AY1CCU1EA000
- Part No: AVT-351885
- Part No: LPV-500 not available, alternative 2805 (Brand: Asco)
- Part No: M6-5S3XH51-T003
- Part No: M485L-51-HL1 12-15? obsolete replaced by AV485NXS8Y8YL000
- Part No: M6C4S8HX51-T003
- Part No: M6C4S8HX51--W003
- Part No: AVTRON-M6C-5S8HX51-T005
- Part No: B14711
- Part No: AVT-329681
- Part No: B14796
- Part No: 351687
- Part No: 338344
- Part No: 363220
- Part No: 4S1HX51-T003
- Part No: M6C-4S1HX51Z-T003
- Part No: LPH-80
- Part No: D27555-1
- Part No: AVTRON-M6C-4S8HH51-T003
- Part No: 363219
- Part No: M6C-5S1XH51-W003
- Part No: M6-5S8XH51-T003
- Part No: M6C-5S3XH51-T005 not available / M6C-5S8XH51-T005 alternative
- Part No: XR45
- Part No: XRB1 P/N: B35134
- Part No: HS35AY1CBU1EA000
- Part No: 324475

- Part No: HS40AET6M1A6W903S
- Part No: Modifications 003 - Include B28390 Torque Arm Kit
- Part No: 1024PPR
- Part No: AV4B51BCRA3AA000
- Part No: HS35AY1CDU1EA000
- Part No: AV850UPF8Y8LP004
- Part No: HS45F-1024-B10-OSW2450
- Part No: AV45-1024-SFT11-B+OWS2450
- Part No: HS9S1PX2FU2X0ZA
- Part No: AV25A43RIB45AA0F2
- Part No: M64S2HH51-T003
- Part No: AV25Y1BCA1XAA000
- Part No: AV56 THIN-LINE III
- Part No: 5S3XH51-T005
- Part No: AV56A 1TDX1YXG015
- Part No: AV56A1CBE8YXP000
- Part No: AV85A1CBE8WXP005
- Part No: AV485 / AVTRON-AV485NXS8Y8YL000
- Part No: AV6AL1CEEWA2A000
- Part No: AV850-1024CBL3
- Part No: B85-SMR9.00
- Part No: HS45 FAYAY8WDAZ04
- Part No: B16148
- Part No: 351060
- Part No: 370157
- Part No: B14795
- Part No: 324463
- Part No: 314128
- Part No: AV485NXS84XXG000
- Part No: K875A-2000Kw
- Part No: GT1800-400G-235
- Part No: AV485-N1S8S8SG000
- Part No: KITAV56ADXXX051
- Part No: KITAV56ADXXX050
- Part No: LPC100D47179

- Part No: FAYAY5GPA018004ZA
- Part No: M6C-4S8HH51-T000
- Part No: AVTRON-HS35AY1CDU1EA000
- Part No: C26386
- Part No: A320-EMM
- Part No: AV85A1CHT8YXP000
- Part No: HS25AY1NSE0UA00W
- Part No: AV32MGAYF9SAD000
- Part No: HS35M
- Part No: HS35A Y1CCU0XA000
- Part No: AV485N1S6P6PP000
- Part No: AV12-8Y400
- Part No: M6C-4S8XH51-W003
- Part No: HS35AY1CCU0FA000
- Part No: AV25F1CDA21AA000
- Part No: HS45FAYAY8PDA004
- Part No: HS25AY1CDE1EA000
- Part No: HS35AY1FBU0CA000
- Part No: AV850-UFF8Y8YP000
- Part No: M6C-4S1HX51-T003
- Part No: HS35M (1024PPR12MMW) S/N: 12856
- Part No: XP5-18AYA000
- Part No: B31514-CE
- Part No: 27750265MAB1C100
- Part No: 27050100MAB5C100
- Part No: 27550265MAB1C100
- Part No: XRB2
- Part No: XR45-G-AY-XX-F-W-T-B-905
- Part No: XR45-GAYXXFWTA905
- Part No: M6C-4S8HX51-W003
- Part No: HS4ZZ1Z2G50DA000
- Part No: HS4A41CWG50DA910
- Part No: XR45-G-AY-XX-G-H-T-A-908
- Part No: HS45FAYXX8WDA004
- Part No: HS4A41CWG50DA915

- Part No: XR45-G-AY-XX-G-H-T-A-000
- Part No: HS35A-Y1BAU0FA000
- Part No: AV32MGAYF9AD000
- Part No: AV85A- 1CJT8YXP000
- Part No: AV4AY1TAR33AA000
- Part No: HS35MY9FBU0UA00
- Part No: 606319
- Part No: B22519-32
- Part No: HS35AY1RBU0EA000
- Part No: AV32MGAYF3SAD000
- Part No: M6C 4S8HX51ZT000
- Part No: AV67A1CBE84XQ000