

ENDURA SUPPLY

Soldo Product List

- Part No: HWR012002A13A old code,new code HW01200-20W02SA3A
- Part No: SB01201-2
- Part No: SB01201-00W01A2
- Part No: SP012H0-EZW00R1
- Part No: SB01201-20W01A2.
- Part No: 0223135-0101
- Part No: SB73200-20W01B2
- Part No: SXC4200-20X31A3
- Part No: HWR29220-2-06103
- Part No: SP012A0-EZW00R1
- Part No: SXT12A0-10X31A3
- Part No: 0222006-0000-02
- Part No: SST12AE-20W01A6
- Part No: SB01300-20W01A2
- Part No: TB/BMN1
- Part No: GOR2450-70-70
- Part No: SQC420E-204400
- Part No: SQ7020E-1TX21A7
- Part No: SFT00A0-20W01A3
- Part No: SYT00A0-20X23A4
- Part No: SFC4200-20B60A3
- Part No: old code SIS3028E-2 new SS3028E-20A11A6
- Part No: SP012A0-EZW00R1 - obsolete, replaced by - ELR.SO.SP012A0-EZW00A1
- Part No: SP012A0-EZW00A1
- Part No: SX02200a ■20D31A3
- Part No: SB73200-2
- Part No: SB01201-0
- Part No: SB01200-20
- Part No: HWR032001A13A12000 old code, new code HW03200a ■10W02SA3A
- Part No: HW03200a ■10W02SA3A
- Part No: XABN1/NK1051 old code, new code SXN1200a ■10U87A3
- Part No: XABN1200E old code, new code SXN1200a ■10U87A3

- Part No: SF70220a ■20X11A3
- Part No: SP (SIP702L0-2H) old code, new code SP70240a ■EHA10A1
- Part No: SP70240a ■EHA10A1
- Part No: SXN1200a ■10U87A3
- Part No: ELR.SO.SM0120N-1HW00R2
- Part No: ELR.SO.SX01200-10X31A3
- Part No: ELR.SO.BMC411E-E1A23A5
- Part No: SKN120E-20D21A7 replaced by SQN120E-20D21A7
- Part No: SQN120E-20D21A7
- Part No: SB012
- Part No: ELR.SO.SB01200-20W01A2
- Part No: SM0120N-1HW00R2
- Part No: ELR.SO.SK1F200-10X23A3 - not available, direct replacement - ELR.SO.SK1F2A0-10X21A3
- Part No: SX01200-20D31A3
- Part No: ELR.SO.SK1F2A0-10X21A3
- Part No: HW01200-20W02SA3A
- Part No: ELR.SO.SB01201-20W01A2
- Part No: SB-17400-1
- Part No: SF01200-20W01A3 old code,ELR.SO.SF01200-20W01A3 new code
- Part No: HW01200-20W02SA5A
- Part No: SB01200-20W01A2
- Part No: SIB70221-2
- Part No: SS7022E-10L11A6
- Part No: SP012H0-2H
- Part No: SB70221-20A11A2
- Part No: ELR.SO.SP012A0-EZW00A1
- Part No: SB01201-2 old number, new number SB01201-20W01A2
- Part No: SP012A0-EZW00A1 (old ref. SP012H0-EZW00R1)
- Part No: SB01201-20W01A2. old code / new code SB01200-20W01A2
- Part No: SXC4200-20X31A3 old code / new code SKC4200-20X23L3
- Part No: 0222006-0000-02 old code / new code 2031801
- Part No: SFC4200-20B60A3 old code / new code SFC4200-20X01L4
- Part No: SP012A0-EZW00R1 old code/ SP01200-EHW00A1 new code
- Part No: SX02200-20D31A3

- Part No: HWR032001A13A12000 old code, new code HW03200-10W02SA3A
- Part No: HW03200-10W02SA3A
- Part No: XABN1/NK1051 old code, new code SXN1200-10U87A3
- Part No: SXN1200-10U87A3
- Part No: XABN1200E old code, new code SXN1200-10U87A3
- Part No: SF70220-20X11A3
- Part No: SP (SIP702L0-2H) old code, new code SP70240-EHA10A1
- Part No: SP70240-EHA10A1 old code / new code SP70200-EHA10A1
- Part No: 58711
- Part No: P/N: 57804, Type: ELR.SO.SB01200-20W01A2
- Part No: ELR.SO.HW01200-20W02SA3A
- Part No: SIB70221-2 old code, SB70221-20A11A2 new code
- Part No: SP012H0-2H old code, new code ELR.SO.SP012H0-EHW00R1
- Part No: P/N: 57527, Type: ELR.SO.SB70200-20X11A2
- Part No: ELR.SO.SP012H0-EHW00R1 (new code ELR.SO.SP01200-EHW00A1)
- Part No: ELR.SO.SFC4200-20A60A3
- Part No: MB.So.KN.XX
- Part No: 0223320-C401
- Part No: SWC420E-2HD23A6
- Part No: SP732H0-2 old code/new code ELR.SO.SP732A0-EZW00T1
- Part No: ELR.SO.SP732A0-EZW00T1 old code, ELR.SO.SP73200-EHW02B1 new code
- Part No: SP012H0-2
- Part No: ELR.SO.SP012A0-EZW00R1
- Part No: SP012H obsolete, alternative SP012A0-EZW00A1
- Part No: SP012A0 LS 2 Mech SPDT 1 M20 IP67 -20 80 GRP
- Part No: SP012H
- Part No: SIB60281-213 new type nr ELR.SO.SB60281-20A11A20008
- Part No: ELR.SO.SB60281-20A11A20008
- Part No: SX01200-10X31A3
- Part No: SB70220-10A11A2
- Part No: SK01200-20D21A3
- Part No: SWC420E-10X23A6
- Part No: SK03200-1 old code, new code SK03200-10X21A3
- Part No: SK03200-10X21A3
- Part No: KN07

- Part No: ELR.SO.SF70220-10C11A4
- Part No: SFC4281-20F11630028
- Part No: SFC4281-20H11630045
- Part No: SSC427E-20G11P6
- Part No: ELR.SO.SFC4200-20A60B4
- Part No: MB.SO.KN.XX Type Typ KNXX
- Part No: ELR.SO.SF01200-11UA7A3
- Part No: SP012H0-2 IP65 old code new code SP012A0-EZW00A1
- Part No: SX01201-2 old code, new code SX01200-20X31A3
- Part No: SX01200-20X31A3
- Part No: 57260 Type MB.SO.KN03.30x80.H30
- Part No: ELR.SO.SF10201-20A11A4
- Part No: SP012A0-EHW00A1
- Part No: SF70220-20A11A4
- Part No: SB70221-20G11A2
- Part No: KN01
- Part No: SB01201-2-01300 old code/new code SB01201-2NW01A2
- Part No: SB01201-2NW01A2
- Part No: SYN1200-8 old code / new code SYN1200-80X23A4
- Part No: SYN1200-80X23A4
- Part No: ELR.SO.HW01200-10W02SB5A
- Part No: SB73200-20W02B2
- Part No: SKC4200-2
- Part No: SQC420E-2 old code / new code SQC420E-20X21A7
- Part No: SQC420E-20X21A7
- Part No: SF01200-20A50A3
- Part No: old code SK C4 2 0 0 1 0 X 2 1 A 3 new code ELR.SO.SKC4200-10X21A4
- Part No: ELR.SO.SKC4200-10X21A4
- Part No: MB.SO.KN07.SK-SQ
- Part No: 2031801
- Part No: SFC 4100-2-3GD old code / new code SFC4100-20A60A4
- Part No: SFC4100-20A60A4
- Part No: SWC420E-10W87A6
- Part No: AM014A0-2H obsolete/alternative SM1F24AN-2HW00A2
- Part No: SXC4201-4 old code/new code C4200-40X31A3

- Part No: SM1F24AN-2HW00A2
- Part No: C4200-40X31A3
- Part No: 53913 , ELR.SO.SP012A0-EZW00A1
- Part No: Limit switch box
- Part No: NOVA V3 N1 old model, new model ELR.SO.ESN12A0-11X21A4
- Part No: ELR.SO.SF24221-20A11A3 (58373)
- Part No: MB.So.KN.XX (99999)
- Part No: MB.So.KN.XX (99999) - optional
- Part No: SIP 702L0-2 - old code, new code is ELR.SO.SP70220-EZA10R1
- Part No: SB01201-2 (new code SB01201-20W01A2)
- Part No: 58538 , ELR.SO.SP70240-EZA10A1
- Part No: SFC4221-10A11A3
- Part No: SFC4221-10A11A4
- Part No: SIS7022E-2 old code / new code SS7022E-20A11A6
- Part No: SS7022E-20A11A6
- Part No: SK012E0-21X21L3 old number / New number SK01200-21X23L3
- Part No: ELR.SO.SB01201-20W01A2 , 57263
- Part No: K1P-K2CFNMS (121899399)
- Part No: SK01200-20X21A3
- Part No: SIF24181-2-05600
- Part No: 83000 , MB.SO.KN.XX.SX.SH.SY.SW.SF.SB.SS
- Part No: 58710
- Part No: SQN120E-20I21A7
- Part No: SQN120E-20X21A7
- Part No: SYN1400-2 old code / new code SYN1400-20X23A4
- Part No: SYN1400-20X23A4 old code, new code SYN1400-20X23L4
- Part No: MB.SO.KNC05.30x130.H40
- Part No: NOVA V3 N1
- Part No: FXSP2012 old code / new code SP012A0-EZW00A1
- Part No: SP012H0-2H 16A
- Part No: SFN 1200-20W01A3
- Part No: SB01200-2 IP67 old code / new code SB01200-20W01A2
- Part No: SP012H0-EHW02R1 old code / new code SP01200-EHW02A1
- Part No: SP012H0-2HW00A1 old code / new code SP01200-EHW02A1
- Part No: SB01201-2 old code, new code SB01200-20W01A4

- Part No: SB01200-20W01A4
- Part No: SM0120N-2HW00A2
- Part No: SP70200-EHA10A1
- Part No: SPO12A0-EHW02A1 old code / new code SP01200-EHW02A1
- Part No: SKC4200-20D21A3 old code / new code SKC4200-20X23L3
- Part No: SF70221-2 old code, new code SF70200-20X11L4
- Part No: SF70200-20X11L4
- Part No: ELR.SO.SP01200-EHW00A1 (old code ELR.SO.SP012H0-EHW00R1)
- Part No: SF70221-20E11A4 old code, new code ELR.SO.SF70200-20X11E4
- Part No: SF70221-20D11A old code, new code ELR.SO.SF70200-20X11E4
- Part No: SWC820E-20X23A6 old code, new code ELR.SO.SWC820E-20X23L6
- Part No: ELR.SO.SF70200-20X11E4
- Part No: ELR.SO.SWC820E-20X23L6
- Part No: old code SB 73200-20W01A2- new code SB1201-20W01A2
- Part No: old code SB 73200-20X01A2- new code SB1201-20W01A2
- Part No: SB1201-20W01A2
- Part No: old code SS6228E-20C11A6- new code ELR.SO.SS6220E-20X11L6
- Part No: old code SS7022E-20B11A6- new code ELR.SO.SS7020E-20X11E6
- Part No: ELR.SO.SS6220E-20X11L6
- Part No: ELR.SO.SS7020E-20X11E6
- Part No: SP01200-DHW00A1
- Part No: 0212200-0000-01
- Part No: SF01200-20W01A4
- Part No: SF01200-20W01L4
- Part No: SFC4200-2-3GD B/N:1914/12
- Part No: SFC4200-2-3GD
- Part No: SQC420E-20D21A7 old version / new version SQC420E-20X23L7
- Part No: SQC420E-20X23L7
- Part No: SFC4200-20X11L4
- Part No: SP01200-EZW00A1
- Part No: old code SF01201-20A50A3- new code ELR.SO.SF01200-10A50L4
- Part No: ELR.SO.SF01200-10A50L4 (59212)
- Part No: KN
- Part No: KNC
- Part No: SP012H0-2H IP65 old code / new code SP01200-EHW02A1

- Part No: SP01200-EHW02A1
- Part No: SB32200-20W01B2
- Part No: SP012H0-2H-11500 old code,SP01200-EHW02A1 new code
- Part No: SX03200-20X31A3
- Part No: SQN120E-20D21A7 old code, new code SQN1200-20X23L7
- Part No: SQN1200-20X23L7
- Part No: SKC4200-20X23L3
- Part No: ELR.SO.SP01200-EHW00A1
- Part No: SIF 39 2 8 1-2
- Part No: SB31200-10W01B2
- Part No: SF70200-20X11E4
- Part No: SB32200-10W01B2 (32= P+F NBN4-12GM40-Z0)
- Part No: old code SIB70221-1-01300, new code ELR.SO.SB70221-20B11A2
- Part No: SP012H0-1H old code / new code SP01200-DHW00A1
- Part No: SB70200-1NX11A2
- Part No: ELR.SO.SB70221-20B11A2 same with SB70200-1NX11A2
- Part No: Display hats for SB 01200
- Part No: transparent housing caps for SB 01200
- Part No: SF70221-10A11A4 old code / new code SF70220-10X11A4
- Part No: SF70220-10X11A4
- Part No: SIF-24281-2 old code / new code SF24280-20X11A4 old code/ SF24200-20X11E4 new code
- Part No: SF24280-20X11A4 old code / SF24200-20X11E4 new code
- Part No: SB70200-20X11A2
- Part No: 0212099-0000-03 / 0212101-0000-04
- Part No: P/N: 59023, Type: SK01200-20X23L3
- Part No: SB23200-2
- Part No: SK1200-20X21A3 old code / new code SK01200-20X23L3
- Part No: SF86281-20G1163 obsolete
- Part No: SF01200-20A50A4
- Part No: SXC4400-20E31A3 old code, ELR.SO.SXC4400-20X31A3 new code
- Part No: ELR.SO.SXC4400-20X31A3
- Part No: KN02
- Part No: sp012ao-ezw00r1
- Part No: SB32200-20W01A2
- Part No: SP012H0-2H old reference, new reference SP012A0-EHW00A1

- Part No: SP01200-EHW00A1
- Part No: SKN3200-20X23L3
- Part No: SP012A0EZW001 old code / new code SP01200-EZW00A1
- Part No: 6K01200-1
- Part No: SKN 1200-1
- Part No: SP012A0-ENW02A1 old code, ELR.SO.SP01200-EHW02A1 new code
- Part No: SP01200-ENW02A1
- Part No: SWC420E-20D23A6
- Part No: SWC420E-20X23L6
- Part No: ELR.SO.SP01200-EHW02A1
- Part No: SX70220-10U77U3
- Part No: SM7320N-2HW00B2
- Part No: BMC41AE-E1E15P60028
- Part No: BMC41AE-E1G15P60028
- Part No: SWS1620EE old code , new code ELR.SO.SW0120E-20X23L6
- Part No: old code SKC4200-20X21A3 - new code ELR.SO.SKC4200-20X23L3
- Part No: ELR.SO.SK70200-10U77E3 (59567)
- Part No: ELR.SO.SB73200-20W01B2 (59187)
- Part No: MB.SO.KN.XX.SX.SH.SY.SW.SF.SB.SS
- Part No: ELR.SO.SKC4200-20X23L3 (59033)
- Part No: ELR.SO.SW0120E-20X23L6
- Part No: HWR29220-2-06104 (ELR.SO.HWR29220-2-06104)
- Part No: HWR29220-2-06102
- Part No: SB63281-20A11A2
- Part No: SP012A0-DHW00A1
- Part No: ELR.SO.SB01200-10W01A2
- Part No: SM0120N-1HW00A2
- Part No: SW0120E-10X23L6
- Part No: SP012A0-EHW02A1 old code, new code SP01200-EHW02A1 (IP67)
- Part No: SP01200-EHW02A1 (IP67)
- Part No: SX03400-1
- Part No: SF70221-20D11A4
- Part No: B02001-7E
- Part No: SK03200-10X23L3
- Part No: old code SQ0120E-20X21A7 new code SQ0120E-20X23L7

- Part No: SX03200-10U77E3
- Part No: SP732A0-EZW00B1
- Part No: SQ0120E-20X23L7
- Part No: SB01201-00W01A20018
- Part No: SIB02221-2
- Part No: ELR.SO.SP73200-EHW02B1
- Part No: REF-747582
- Part No: SYC8200-10E23A4
- Part No: SYC8200-10X23L4
- Part No: SYN1400-20X23L4
- Part No: SP732H0-2-00500
- Part No: SP73200-EHW00B1
- Part No: ELR.SO.SF63200-20X11E4
- Part No: P/N: 59664, Type: SFC4200-20A60L4
- Part No: TWM82260
- Part No: SF24281-20B11A3
- Part No: P/N: 59982, Type: ELR.SO.SK70200-20X23E3
- Part No: old code: SB01200-2, new code: ELR.SO.SB01200-20W01A2
- Part No: SF01200-20XD1L4
- Part No: SB0120D-0
- Part No: SFC4201-10UA7U3
- Part No: SFC4200-10UA7U3
- Part No: SB01200-10UA7A2
- Part No: ELR.SO.SBC4200-20X11A2/ 59632
- Part No: SP732AO-EHW0081
- Part No: SY012E0-10U77L4 old code / new code SY01200-10U77L4
- Part No: SY01200-10U77L4
- Part No: BMN1116-E1A23A60005
- Part No: SF70221-20A11A3
- Part No: SY83200-10X23L
- Part No: SXC4200-20X32A3
- Part No: SF01205-2HT3 old code / SF01200-20W01D4 new code
- Part No: SF01200-20W01D4
- Part No: SB01300-2BW01A2
- Part No: SFC4221-20G11N30028

- Part No: SF01200-2 IP67 old code/ SF01200-20W01L4 new code
- Part No: spigots for SB01200-20W01A2
- Part No: ELR.SO.SF01200-20A50L4 (59113)
- Part No: ELR.SO.SP70200-EZA10A1
- Part No: SP012A7-EHWC0R1 old code, new code SP01200-EHW00A1
- Part No: SX.SF.SY.SK.3D-Indicator-kit
- Part No: SK01200-21X23L3
- Part No: SIF24281-2 old code, new code SF24200-20X11E4
- Part No: SF24200-20X11E4
- Part No: SWC420E-10I23L6
- Part No: SF01200-10UA7E3
- Part No: SB73200-2 old code/ SB73200-20W01B2 new code
- Part No: SB822N1-50W0AA2 old code / SB822N0-50W0AA2 new code
- Part No: SFC 4200-20U97U3 old code/ SFC4200-20U97U3 new code
- Part No: Nr xx KNxy
- Part No: SB822N0-50W0AA2
- Part No: KNxy
- Part No: SFC4200-20U97U3
- Part No: Nr xx KNxy s
- Part No: Code: 8P012A0-EZW00R1
- Part No: SB01201-20W01A2 IP66/67 old code / new code ELR.SO.SB01200-20W01A2
- Part No: SB01200-02UA7A2
- Part No: SB01200-20UA7A2
- Part No: ELR.SO.SB01200-20G01A2
- Part No: SP012H-0-0 old code, new code SP01200-EHW00A1
- Part No: SB0121-2 IP67 old code/ SB01200-20W01A2 new code
- Part No: CAB01200E old code/ SB01200-10UA7A2 new code
- Part No: SYC4200-10G23P4
- Part No: ELR.SO.SB01200-20W01A2 (57804)
- Part No: SF03200-20X11L4
- Part No: ELR.SO.SQ0120E-20X23L7
- Part No: SP012A0-DZW00A1 out of production
- Part No: SB01200-10W02A2
- Part No: SF62200-20X11L4
- Part No: SXC4200-10X32A3

- Part No: SKC4200-10X23L3
- Part No: SP012AO-EHW00A1 old code/ SP01200-EHW00A1 new code
- Part No: SWC440E-7TU87L6