

ENDURA SUPPLY

Berthold Product List

- Part No: LB 440
- Part No: 40426-12
- Part No: 52592-050
- Part No: 004498-S
- Part No: 34787
- Part No: 40416-02 LB4441-02-0A-GD-E 40/35
- Part No: 40416-03 LB4441-03-0a-Gd-E 50/50
- Part No: 40421-02 LB4441-02-0A-GI-E 40/35
- Part No: 40426-06 / LB4405-06-0X-GI-E
- Part No: 40441-02 LB 440-02 obsolete/ replaced by LB 470-02-M
- Part No: 43433
- Part No: 45299
- Part No: 48452-11 LB 452 castXpert
- Part No: 52592-100 CONNECTION CABLE FOR GAMMACAST DETECTORS
- Part No: 65262 -100
- Part No: 817637-11
- Part No: 90a ■264 V. 50498
- Part No: AUTOLUMAT LB 953
- Part No: CASTXPRT LB452
- Part No: GHS-3172-1, 29891
- Part No: ID81287/LB3955
- Part No: LB 379
- Part No: 40444-01 LB 444-01-abgekAndigt und nicht mehr lieferbar, alternative LB 47x DuoSeries LB 474-02-M
- Part No: LB 491
- Part No: LB 565
- Part No: LB 566
- Part No: LB 567
- Part No: 48452-01 LB 452 castXpert
- Part No: LB 6739-01 Csl 40x50
- Part No: LB 6739-03
- Part No: LB386-1C (EXCEPT THE PART RADIOACTIVE SOURCE)

- Part No: LB4405-16-0X-SD-E
- Part No: LB-440 , 40441-42
- Part No: PFO MARK 5 PHOTOMETER
- Part No: SYSTEM:LB-323,LB-3940 06-03269 43174.06-951/2 800859-3465 obsolete
- Part No: Type Co-60 rod source for LB-440-M
- Part No: Type:LB4
- Part No: G_iG_a 60 63 MBQ (1.7MCI), L280
- Part No: LB 452 castXpert
- Part No: LB-4401-03
- Part No: LB-1236-H10 zur Messung der Umgebungs-A_{eff}äquivalentdosis H(10) Messbereich 0,05 IS/h bis 10 mSv/h Energiebereich 30 keV - 1300 keV Bestellnummer: 39581
- Part No: 40444-02 LB 444-02 Density Evaluation Unit (Master)
- Part No: 40444-03 LB 444-03 Density Evaluation Unit (Master)
- Part No: 40444-21 LB 444-21 Density Evaluation Unit (Master)
- Part No: 40444-22 LB 444-22 Density Evaluation Unit (Master)
- Part No: 40444-23 LB 444-23 Density Evaluation Unit (Master)
- Part No: 40444-41 LB 444-41 Density Evaluation Unit (Master)
- Part No: 40444-42 LB 444-42 Density Evaluation Unit (Master)
- Part No: 40444-43 LB 444-43 Density Evaluation Unit (Master)
- Part No: 37246
- Part No: 38477-110
- Part No: 38477-111
- Part No: 38477-120
- Part No: 38477-121
- Part No: 38477-130
- Part No: 38477-131
- Part No: 38477-150
- Part No: 38477-151
- Part No: 38477-170
- Part No: 38477-171
- Part No: 38477-190
- Part No: 38477-191
- Part No: 53214-005
- Part No: 53214-006
- Part No: 53214-008
- Part No: 47678-110

- Part No: 47678-111
- Part No: 47678-120
- Part No: 47678-121
- Part No: 47678-130
- Part No: 47678-131
- Part No: 47678-150
- Part No: 47678-151
- Part No: 47678-170
- Part No: 47678-171
- Part No: 47678-190
- Part No: 47678-191
- Part No: 53214-014
- Part No: 50040-110
- Part No: 50035-110
- Part No: 50035-171
- Part No: 50041-110
- Part No: 50036-110
- Part No: 50036-120
- Part No: 50036-170
- Part No: 50036-190
- Part No: 40425-06 LB4405-06-0x-Gd-E OBSOLETE- REPLACED BY LB4700-2K-1B-80-01-100 (56926-056)
- Part No: SZ 5 GHS-3171-1Gi , optional/alternative
- Part No: TYPE: LB 6639 BGO (25/25) obsolete
- Part No: LB 6739-03 Csl 25x50 mm
- Part No: 52592-150
- Part No: 52592-200
- Part No: 52593-100
- Part No: 52593-200
- Part No: 52594-050
- Part No: 52594-100
- Part No: 52594-150
- Part No: 52594-200
- Part No: 52595-150
- Part No: 52595-200

- Part No: 55249-050
- Part No: 55250-050
- Part No: 55250-100
- Part No: 55252-150
- Part No: CO-60 Type: LB4
- Part No: LB 452 castXpert 50498-01
- Part No: LB 452 castXpert 50502-01
- Part No: LB 452 castXpert 53799
- Part No: 04498-s
- Part No: 53772-S
- Part No: LB 6739-01 Csl 40x50 mm
- Part No: LB4441-01-0a-Gd-E 25/25
- Part No: LB 444-01
- Part No: LB124 SCINT
- Part No: LB 452 (47344-001)
- Part No: LB 452 (50498-01)
- Part No: LB 452 (50502-01)
- Part No: LB6651 ID:34868, PA-60015691 6037 alternative 48452-01
- Part No: 53144-S
- Part No: LB 452 castXpert 59553
- Part No: LB 452 castXpert 47344-001
- Part No: LB440-02
- Part No: LB 4710-080
- Part No: 40441-02
- Part No: 40413-03
- Part No: 31346
- Part No: 30673
- Part No: LB6739W
- Part No: PCF8582C-2
- Part No: LB 3941
- Part No: LB 6752-11
- Part No: 48452-13
- Part No: LB 4710-160
- Part No: SZ 5 GHS-3171-1Gd
- Part No: LB 6739 11 / Csl 40x50 mm

- Part No: LB 3940 obsolete
- Part No: 81696-5 LB323
- Part No: LB 6739-11 Csl 40x50 mm, (48452-11)
- Part No: LB6651 - obsolete , replaced by 48452-01, type LB 6739-01
- Part No: 48452-01, type LB 6739-01
- Part No: 58009
- Part No: LB6739-13-CsJ-25X50 (48452-13)
- Part No: LB 3543 11 MP (43617)
- Part No: 55249-100.
- Part No: 44563
- Part No: 41709-02
- Part No: 40167-080 (LB 4710-080 4TE)
- Part No: 29891 (GHS-3172-1)
- Part No: 29892 (GHS-3172-2)
- Part No: 31346 (SPGU 75/25)
- Part No: LB 6760-01
- Part No: 48452-13 , type LB 6739-13 Csl 25x50 mm
- Part No: LB 470-02-M
- Part No: 59477
- Part No: LB 474-02-M
- Part No: 56925-4BA2
- Part No: LB4405-06GB abgekündigt und nicht mehr lieferbar/ neuen Detektor LB 47x DuoSeries LB4700-2K-1B-80-01-100
- Part No: LB 47x DuoSeries LB4700-2K-1B-80-01-100
- Part No: 31346 Set of clamps (2 pcs.) SPGU 75/25
- Part No: LB4700-2K-1B-80-01-100 (56926-056)
- Part No: SPGU 75/25 (31346)
- Part No: 58802-100-S
- Part No: LB 474-01-M
- Part No: SZ 5 a " D1
- Part No: LB4700-11-1B-80-r1-100 (56926-006)
- Part No: Set of clamps (2 pcs.) SPGU 75/25
- Part No: Connection Cable for GAMMAcast Detectors 55249-100
- Part No: 61624
- Part No: 50498-001
- Part No: LB 4441-02

- Part No: 40444-01 / LB 444-01
- Part No: 47344-001
- Part No: 48452-01
- Part No: 48452-11
- Part No: 48452BA2
- Part No: 50498-01-s
- Part No: 50502-01 same as 50502-01-S
- Part No: 52592-100
- Part No: 53148-S
- Part No: 55067-050
- Part No: 55067-150
- Part No: 90-264 V. 50498
- Part No: LB 6739-11
- Part No: LB 6739-13
- Part No: 56085-S
- Part No: ??-60 63 MBQ (1.7MCI), L280
- Part No: LB-1236-H10 zur Messung der Umgebungs-Äquivalentdosis H*(10) Messbereich 0,05 µS/h bis 10 mSv/h Energiebereich 30 keV - 1300 keV Bestellnummer: 39581
- Part No: LB 6739-01
- Part No: 48452-03
- Part No: LB 6739-13 CsI 25x50 mm
- Part No: 52593-050
- Part No: 52595-050
- Part No: 52595-100
- Part No: 55067-100
- Part No: 55249-150
- Part No: 55250-150
- Part No: 55252-050
- Part No: 55252-100
- Part No: 50502-01-S
- Part No: 55653-S
- Part No: 64466-S
- Part No: LB440-02 obsolete, replacement LB 470-02-M +Terminal block
- Part No: 58803-100-s
- Part No: LB 3941 obsolete

- Part No: LB6752-11
- Part No: 52593-150
- Part No: 53437-S
- Part No: P/N: 61604-01 Type: LB 452 CastXpert
- Part No: LB4405-06GB abgekündigt und nicht mehr lieferbar/ neuen Detektor LB 47x DuoSeries LB4700-2K-1B-80-01-100
- Part No: LB4700-2K-1B-80-01-100
- Part No: 64576
- Part No: SZ 5 – D1 OBSOLETE- REPLACED BY LB4700-11-1B-80-r1-100 (56926-006)
- Part No: P/N: 56926-006 Type: LB4700-11-1B-80-r1-100
- Part No: 63283
- Part No: Terminal Block for LB 470-02-M
- Part No: 40440-02 obsolete, replacement LB 470-02-M +Terminal block
- Part No: LB 6752-11 / 48456-11
- Part No: 55282-S
- Part No: 40167-160 LB 4710-160
- Part No: LB4700-11-IC-80-R1-100
- Part No: SPGU 75/25 (Set 2 pcs.)
- Part No: 50498-01
- Part No: 33952-01 obsolete
- Part No: LB4710-180
- Part No: 40167-180
- Part No: 53779-S
- Part No: 53799-S
- Part No: 42816-012 B
- Part No: Csl 25/50
- Part No: 37625 (LB 7440-F-CR)
- Part No: ID:52593-150
- Part No: 53442-S
- Part No: LB 940
- Part No: LB4700-2L-IC-80-01-100
- Part No: LB 386-1C
- Part No: 53437
- Part No: LB4700-2J-IC-80-01-100
- Part No: 40167-090
- Part No: LB 474-01-M0

- Part No: LB4700-11-00-80-a1-100
- Part No: 54281-21
- Part No: LB 7442 D-CR
- Part No: 80796
- Part No: 32024
- Part No: 14658
- Part No: 45249
- Part No: LB 4700
- Part No: 65365
- Part No: 39246
- Part No: LB 440-21
- Part No: 55416-100
- Part No: 50637-S
- Part No: 36135-S
- Part No: LB 414
- Part No: LB4405-03
- Part No: 38478-121
- Part No: 55285-S
- Part No: 21324
- Part No: LB4700-12-00-80-a1-100
- Part No: 56926-039
- Part No: 56926-045
- Part No: 56926-008
- Part No: 56926-026
- Part No: 56926-009
- Part No: CS5-MDJB1
- Part No: 1170-85-5298
- Part No: BW 29/78
- Part No: LB 211
- Part No: LB 6739-13 Csl (48452-13)
- Part No: 65417-100
- Part No: 65416-100 (Open Ends)
- Part No: LB-440 Master-04
- Part No: LB 470-02-M0
- Part No: ST 3500800VD10

- Part No: LB 6739-01 Csl 40X50 (48452-01)
- Part No: 40441-23
- Part No: 40441-33
- Part No: 42855
- Part No: 47628
- Part No: Mounting Frame for LB 7410
- Part No: LB 2018-1
- Part No: LB 7440 DE-CR
- Part No: 41828
- Part No: LB480-2K-1C-12-01-000-L
- Part No: 52752
- Part No: 54281-14
- Part No: 56926-002
- Part No: 64402
- Part No: Part no: 48452-11
- Part No: Part No: 55252-100
- Part No: ST0800700D83517
- Part No: 2000200308
- Part No: LB4700-11-1B-80-a1-100
- Part No: MODEL: 55653-S
- Part No: BAI 9850-19/PINN
- Part No: LB115
- Part No: LB6411
- Part No: 6701M(100Sv)
- Part No: 6701H(1000Sv)
- Part No: 57268
- Part No: 56926-004: LB 4700-11-1B-80-01-100
- Part No: LB4700-12-00-80-r1-100
- Part No: 50636
- Part No: LB6752
- Part No: 56926-006
- Part No: LB4700-1A-1B-80-a1-100
- Part No: 68271
- Part No: 52592-200&57268
- Part No: LB 6739W

- Part No: ST 060+F1*V+D10
- Part No: P/N: 56926-050 Type: LB4700-2I-1B-80-01-100
- Part No: P/N: 56926-044 Type: LB4700-2E-1B-80-01-100
- Part No: P/N: 63284 Type: LB 470-01-M0
- Part No: P/N: 56926-081 Type: LB4700-15-00-80-r1-100
- Part No: LB4700-15-1B-80-r1-100
- Part No: 64607 19"-Rack, 84 HP / 3 RU
- Part No: P/N:64466-S
- Part No: P/N:53437-S
- Part No: P/N:53148-S
- Part No: P/N: 48452-13 Type: LB 6739-13 Csl 25x50 mm
- Part No: ST 2000300VD14
- Part No: 38907-008
- Part No: 6739-13-CSJ-25X50
- Part No: LB490-38477-15
- Part No: LB490-38477-150 obsolete
- Part No: LB4700-11-00-80-01-100
- Part No: 21326
- Part No: LB-4700-V-12-IC80-R1-100
- Part No: LB 474-02-M0
- Part No: 56926BA2
- Part No: LB4700-11-00-80-r1-100
- Part No: 81066BA2
- Part No: 27806
- Part No: 81066-4
- Part No: 81488
- Part No: 19513-01 DL00010
- Part No: 59832-S
- Part No: ST060-400V-92220/92220
- Part No: ST 2500250D8
- Part No: ST 0600400VD6
- Part No: ST 092220
- Part No: LB 480-31-2C-12-R1-000-L
- Part No: LB 474-22-M0-0 / 72066
- Part No: 72362

- Part No: 56926-219
- Part No: 61241
- Part No: cable for LB 6739-11 Csl 40/50 (52595-100)
- Part No: LB4700-11-FA-80-a1-101
- Part No: UniSENS LB 480, 1500mm (54733-C2762)
- Part No: 59030
- Part No: ST200+F1V+D8
- Part No: ST 1200700D8
- Part No: LB452
- Part No: 61604-11
- Part No: 74212-100
- Part No: ST 150+F1+D10
- Part No: N-55249-10
- Part No: LB 134
- Part No: LB 4401-01G
- Part No: 27528-06
- Part No: 41351
- Part No: 49274
- Part No: 65109-04
- Part No: 60737
- Part No: 55880
- Part No: 44545-26
- Part No: 44173
- Part No: 62869
- Part No: 63998
- Part No: 41028
- Part No: 38789
- Part No: 58067
- Part No: LB-490-91
- Part No: LB 440-12
- Part No: LB 4405-16-1X- GI-E
- Part No: 48452-01 LB 6739-01 Csl 40x50 mm
- Part No: LB4405-06-0X-Gd-E 2000 mm
- Part No: LB4700-1A-00-80-01-100
- Part No: 65416-100

- Part No: ID: 65416-100