

ENDURA SUPPLY

BFI AUTOMATION Product List

- Part No: P 106 EX
- Part No: Part.-No.S 730.3MY
- Part No: Part.-No.S 507.L
- Part No: S 506.3
- Part No: TYPE ORFEUS 3001 G601
- Part No: B512
- Part No: Type 2.0
- Part No: IRS3001 0CA11A13-SIM
- Part No: TYPE: 7.0/2 S507.5 MS
- Part No: 3001D
- Part No: FLAME SCANNER type: 2
- Part No: CFC2000IR1
- Part No: Type 8.70 (IR)
- Part No: LE-6773-A-1LE-6774-A-1 8.70
- Part No: LE-6773-A-2LE-6774-A-2 8.70
- Part No: LE-6773-A-3LE-6774-A-3 8.70
- Part No: LE-6773-A-4LE-6774-A-4 8.70
- Part No: LE-6773-A-5LE-6774-A-5 8.70
- Part No: LE-6773-A-6LE-6774-A-6 8.70
- Part No: LE-6773-A-7LE-6774-A-7 8.70
- Part No: S507H
- Part No: G601 - old code, new code 6020-3001-00 (3001)
- Part No: 507H
- Part No: S-507H
- Part No: ORFEUS 2 S 507-H
- Part No: Part.-No.S 507H (Type 2.0)
- Part No: BFI S508
- Part No: BFI3001
- Part No: 2.0 LA-SEC
- Part No: FLAME SCANNER 7.0 S 510.0
- Part No: NO G 601.D
- Part No: NO G 602

- Part No: S 510.0EXG
- Part No: G 601. D
- Part No: G 602
- Part No: Part no. S773
- Part No: 6020-3001-00 (3001)
- Part No: S710, obsolete replaced by 6050-9010-00
- Part No: S 730.7M, obsolete replaced by 5051-1070-00
- Part No: S 507.LA, obsolete replaced by 6010-2043-00
- Part No: 6050-9010-00
- Part No: 5051-1070-00
- Part No: 6010-2043-00
- Part No: G 601.D
- Part No: 6020-3001-00
- Part No: 6060-0561-65
- Part No: TYPE: 7.0/2 P/N: S507.5 MS
- Part No: FLAME SCANNER 7.0 S 510.0 (SERIAL NO -203552-L-2)
- Part No: S508 1
- Part No: Type 2 series SN: 202044 obsolete, replaced by 6010-2051-00
- Part No: 6010-2051-00
- Part No: 6010-2021-00
- Part No: 204487-L2
- Part No: CFC2000UV
- Part No: 6051-2100-00
- Part No: 6020-3002-10
- Part No: S 730.35M
- Part No: 6020-3001-00 Type 3001
- Part No: 7013-2072-00S Type CFC200IR1EX
- Part No: 6020-3001-20
- Part No: old code S 507H S/N:207825-L2 - new code 6010-2021-00
- Part No: 7010-3322-00
- Part No: 5051-3030-00 (X-IR, 3m Y-splitting)
- Part No: 6013-2031-00 (Type: CFC2000UV)
- Part No: 7010-7032-10
- Part No: 3007 (6020-3007-00)
- Part No: old code IRIS 5002, new code 5002

- Part No: 5002 (6020-5002-00)
- Part No: 6010-2033-00
- Part No: 6060-1000-00S
- Part No: 7010-3722-00
- Part No: old code ORFEUS.8.70, new code CFC200IR3
- Part No: CFC200IR3
- Part No: Typ 2.0L S/N 216041
- Part No: HT 899
- Part No: LLA 38 AS200
- Part No: G706.1
- Part No: G601.D
- Part No: 5052-1180-20
- Part No: CFC2000UVBFI
- Part No: CFC2000UV1EX
- Part No: 3001 (6020-3001-00)
- Part No: old code B512.1, new code 1598-0141-00
- Part No: 1598-0141-00
- Part No: flame scanner 2.0GT
- Part No: module 3001
- Part No: 2.0 Serial 204843-L2 old code, new code 6010-2051-00
- Part No: 6060-1000-00S KW5
- Part No: Type KW5/W
- Part No: P/N: 6010-2051-00, S/N: 1000109-2
- Part No: Repair kit for 2.0L SN 1006084
- Part No: 6010-2043-00 / 2,0LA GT-ABB
- Part No: old code: 6010-2013-00, new code: 6010-2043-00
- Part No: Type 2.0, s.n. 207079-L2
- Part No: AME1708
- Part No: CFC2000IR1 / 6013-2071-00
- Part No: 5051-1080-00
- Part No: CFC3000UV1
- Part No: 6010-3721-00
- Part No: G6013001 old code, 6020-3001-00 new code
- Part No: Type:2.0 SN:205452-L2
- Part No: SN 205581-L2 old code, 6010-2051-00 new code

- Part No: CFC2000IR
- Part No: 6051-1100-00
- Part No: 2.0L SN:214369