

# ENDURA SUPPLY

## Birkenbeul Product List

- Part No: 1074957
- Part No: 5AP-100L-6
- Part No: 5AP112M-4, HZ: 50/60
- Part No: 5AP132M-2V 11KW 2900 D/DK 12031.MOT32
- Part No: 5AP160M-12
- Part No: 5AP90S-2
- Part No: 5AP90L-4 460-480V , 1.5KW
- Part No: 6AP160M-04-LDZ
- Part No: 6AP200LK-04-HW
- Part No: 5AP112M-2s-HW-H
- Part No: 5AP90S 6 obsolete, replacement 6APE90S-6-IE2
- Part No: 1TZ992M-8
- Part No: 1TZ990L-6
- Part No: 5AP90L6
- Part No: 1TZ9112M-8
- Part No: 5A90L-6
- Part No: 5AP160M-8 M-Nr42619898300126 oem and obsolete
- Part No: 6APE90S-6-IE2
- Part No: LAfterflAgel aus Kunststoff fAr Motor 7AA160L-06
- Part No: 5AP132M a " 2V
- Part No: LAfterflAgel fAr Baugr. 112
- Part No: LAfterflAgel fAr Baugr. 160
- Part No: 6AP200LK-04-HW OEM, obsolete
- Part No: 6APE100L-4K
- Part No: Lüfterflügel aus Kunststoff für Motor 7AA160L-06
- Part No: 5AP132M – 2V
- Part No: Lüfterflügel für Baugr. 112
- Part No: Lüfterflügel für Baugr. 160
- Part No: 486-1614-001
- Part No: 8APE160M-6-IE3
- Part No: 8APE160L-4-IE3
- Part No: 8APE112M-4-IE3

- Part No: 5AP100L-4K-7AA
- Part No: 6AP80M-4K
- Part No: 6APE90S-4 IE2 ( Wellenmaß 24 x 47)
- Part No: 5AP100L-8 oem
- Part No: 8APE90S-6 IE3
- Part No: 8APE132M-2V-IE3
- Part No: 5AP132M-2V Nr 1040510 OEM and obsolete
- Part No: 8APE90S-2-0V
- Part No: back and front bearing shields for 8APE90S-2-0V
- Part No: back and front bearing shields for 5AP90S-2-0V
- Part No: 6APE80M-4K IE2
- Part No: 5AP160M-04-HW II OEM
- Part No: 8AOE90S-4
- Part No: 8APE 100L-4V
- Part No: 6APE100L-4 IE2 SWLH
- Part No: 8APE 225M-6 UL
- Part No: 8APE100L-2-IE3
- Part No: 8APE160M-2-HW-H OEM
- Part No: 6APE160M-6 IE2
- Part No: 8APE90S-4 IE3
- Part No: 6APE100L-4K-IE2
- Part No: 3AP804
- Part No: 3AP804 / 131672
- Part No: 8APE80M-4 IE3
- Part No: 8APE180L-6-IE3
- Part No: 8APE112M-2V-IE3