

ENDURA SUPPLY

Bonora Product List

- Part No: H71B/4 OP.64796
- Part No: H63B/4 - OEM
- Part No: S/N: 45276
- Part No: F71D/4
- Part No: 00091423APS30A0 (H 63C4)
- Part No: CR56/2
- Part No: 3CP90LE/2 (OEM)
- Part No: 3CP132MK1/2 (OEM for FPZ) - obsolete, replaced by - GR.132 - 15 HP 330/575-60 UR PREMIUM (Art. 4051+0107)
- Part No: GR.132 - 15 HP 330/575-60 UR PREMIUM (Art. 4051+0107)
- Part No: CS7 1C/4
- Part No: CS56B/4
- Part No: 3CP132SE/2 replacement for GR.132 - 2 POLI - 7.5
- Part No: GR.132 - 2 POLI - 7.5
- Part No: CSB71CX/4 (OEM)
- Part No: H112MA/6
- Part No: 3CP80D/2
- Part No: 13483 obsolete
- Part No: cs71a-4 (OEM)
- Part No: H53B/4
- Part No: 4051+0107
- Part No: 4051+0099
- Part No: H71B/4
- Part No: Bonora Ersatzmotor f. K05MS S/N: F59016
- Part No: 4050+0082
- Part No: 3CP132MG/2 obsolete, replacement 4077+0034
- Part No: 4077+0034
- Part No: Type: H100LA/2
- Part No: 75269
- Part No: HH90SC/2
- Part No: CSB71C/4
- Part No: 3CP90SC/2 obsolete, replacement 4071+0134

- Part No: 4071+0134
- Part No: H90LD/4
- Part No: H56B/4 - SN 48240 (OEM)
- Part No: CS871/4
- Part No: CS56B/2
- Part No: 4027+0065 (3CRB90LF/2)
- Part No: SR30MD00+0035 (SCL R30-MD)
- Part No: 2002 CSB71C/4
- Part No: BC 112MB/4
- Part No: 4071+0133
- Part No: H56B/4
- Part No: PJ 355/140J
- Part No: ARR112AF4P4
- Part No: SK05MS50+0154 (Type SCL K05-MS)
- Part No: MOTOR FAN FOR BONORA MOTOR
- Part No: (4051+0099)GR.132 - 2 POLI - 7.5 HP (5.5 kW) 200/400V 50Hz 208-230/460V 60Hz
- Part No: 3CP132SE/2
- Part No: Type: CR80D/2 OEM / OEM code: H80b/2
- Part No: 3CR100LB/2 OEM
- Part No: H80b/2
- Part No: Capacitor for MAB100LA/2
- Part No: H100LA/4
- Part No: 693006G01
- Part No: 3CR160LKS/2
- Part No: Brake disc for ARR100LB/2
- Part No: A501219
- Part No: 4071+0173
- Part No: 3CR160LP/2
- Part No: 692001G86
- Part No: CR56C/2 oem
- Part No: CS63A/4
- Part No: 4070+0077
- Part No: HE80F/4
- Part No: HE 160 MF/4
- Part No: HH90LE/2

- Part No: 3CP100LF/2
- Part No: HB90LD/2
- Part No: Capacitor for HB90LD/2
- Part No: SR30MD00+0042
- Part No: Motor terminal box gasket for 3CP100LD/2
- Part No: M56B/4
- Part No: SCL R30-MD
- Part No: 4027+0083
- Part No: 411000000000
- Part No: H56B/4 S/N A11084
- Part No: Type: 3CP100LJ/2
- Part No: KR0096
- Part No: 95618
- Part No: SK06TD00+0011
- Part No: 114344
- Part No: BS90C/4
- Part No: fan wheel for H71A/4
- Part No: SA47DRN71MS4
- Part No: M3100LA/2
- Part No: HH132MN/4
- Part No: H90LDX/2
- Part No: HE90LE-9-/2
- Part No: P/N: 5500+0303, Type: HH112MG/2
- Part No: 719269
- Part No: 4054+0051
- Part No: SK06MS50+0126
- Part No: CS90LS/2
- Part No: 3CP100LF/2 CC310B
- Part No: P/N: 4050+0098, Type: 3CR100LFS/2
- Part No: 3CP80B/2
- Part No: HE132SBS-3-/2
- Part No: SK04MS50+0240
- Part No: starter for H890LD/2
- Part No: Type: H90SA/2 No. 69361
- Part No: Capacitor for electric motor V220 / 1/60

- Part No: start capacitor for MAB100LA/2
- Part No: RUN capacitor for MAB100LA/2
- Part No: 4051+0097
- Part No: MOTOR FAN COVER FOR BONORA ENGINE
- Part No: CP80D/2
- Part No: HE132MJ/4
- Part No: seal for HE132MJ/4
- Part No: 4077+0039
- Part No: SK06TD50+0028
- Part No: 4073+0084
- Part No: HH90LE
- Part No: HH80D/2 S/N#4810
- Part No: H71C/4
- Part No: HB80CS/2 OEM
- Part No: H71C/4 (59661)
- Part No: SCL K10-MS / SK10MS00+0100
- Part No: ARR112MC/2
- Part No: 4051+0133
- Part No: TYPE. 3CP90LE/2
- Part No: CR80F/2
- Part No: 3CR90LE/2
- Part No: CS100LA/2
- Part No: 3CP100LF/2 sn: 70544
- Part No: 4050+0075
- Part No: I10596
- Part No: H90LB/2
- Part No: HE132HGS-3-/2
- Part No: MOTORE 2 POLI - MEC 132
- Part No: ARR90LB/4
- Part No: 4050005
- Part No: 4032+0047
- Part No: fan for HAB100LA/2
- Part No: fan cover for HAB100LA/2
- Part No: 3CP80F/2
- Part No: 2 POLI MEC 100

- Part No: 2 POLI - MEC 132 - 15.0 - 17.0 kW
- Part No: 2 POLI MEC 90
- Part No: fan blade of MEC 132
- Part No: HE100LF-3-/2
- Part No: 4073+0119 MOTORE 2 POLI MEC 90
- Part No: CS56B/4 0.09KW
- Part No: 4073+0105
- Part No: BC112C/4
- Part No: 3CP100LF/2 S/N 36818
- Part No: H112RV4
- Part No: H112B74
- Part No: HE56C/2
- Part No: SK07RMD00+0085
- Part No: SK05MS50+0220
- Part No: 4072+0136
- Part No: 4032+0059
- Part No: 4072+0133
- Part No: SK09MS00+0101
- Part No: HHX90SC/2
- Part No: MA63AA/4
- Part No: 3CP100LF/2 SN: 00852
- Part No: CR56C/4
- Part No: 3CR90LE/2 (s/n 28580)
- Part No: HE132MLT-3-/2