

# ENDURA SUPPLY

## Brusatori Product List

- Part No: 052302 SERIAL 29434/01 1,13 / 4 NM, 3000 MIN1 VN:172 V, 4,71 A ISOL.-KL. F, IP.54, BAUFORM: II/D
- Part No: 07630X
- Part No: BR076304
- Part No: BR51502
- Part No: DC MOTOR TYPE CC100L KW.2,2 RPM 2500
- Part No: DC MOTOR TYPE ML80M KW.3,37 RPM 2500
- Part No: DC MOTOR TYPE ML80P KW.4,59 RPM 2500
- Part No: MIMP21a~024V
- Part No: ML 80 L SN: 6559/02
- Part No: ML112M
- Part No: MP 44
- Part No: MP00460000029 MP46-170/3000-19/200-B5+ATEN6X10+KALTEN
- Part No: MP21 ,B14/71 14/105
- Part No: MP21, B14/56 9/80
- Part No: MP-46
- Part No: MP62-160/2000-24/200-B5+SDC20
- Part No: MPT202
- Part No: MPU24
- Part No: MPV24
- Part No: SERIES VT 100 P
- Part No: SPA004-001,TYPE L 50 R
- Part No: SPA004-002,TYPE L 107
- Part No: TYPE 1120
- Part No: Type MP 23, Cod.MP 0232603064 obsolete replaced by MPT202
- Part No: TYPE VT-100-P, CODE VT100P5000001, S / N 36156/03, P.N 7,3 KW
- Part No: Type: 1 R 60
- Part No: TYPE:051502 BR0515021CK500023
- Part No: VI112CL-4KW-4P-50HZ-230/400-B5+VF
- Part No: VT071L2U00059 B-VT71L-1,09-4P-4/6/87HZ-B5/14+VF601024L
- Part No: VT071L2I00035
- Part No: Z0150501 SDB60

- Part No: Z0180195,TYPE GM7
- Part No: VT090X4Z00018
- Part No: VT080L2Z00032
- Part No: 3780/2 obsolete, replaced by MPT202
- Part No: Z0340050
- Part No: V88-57001
- Part No: ML 112 M 01279 06-95 Serv S.1
- Part No: MP21, Cod: MP0212603027 obsolete, replaced by MPT50
- Part No: ML01800S00006
- Part No: MPT50
- Part No: ML 80S
- Part No: MP21 obsolete, replaced by MPT40
- Part No: COD:MP02 14235020 NO: 20529/33 obsolete, replace by MPT40 24 3000 9/56-B14
- Part No: MPT40 24 3000 9/56-B14
- Part No: 0323021A1MCK5S0000
- Part No: DB1-23
- Part No: SKYD-23-01
- Part No: BR077304
- Part No: 0723040H12EK1G0Z73
- Part No: ML00710L00008
- Part No: 112CL
- Part No: Typ 1 R 60 obsolete replaced by Z0150511
- Part No: Z0150511
- Part No: VT-71-L
- Part No: ML 80 L
- Part No: MP00460000045
- Part No: VT063L2T00001
- Part No: MP00620000010
- Part No: BRH772441V1XEKX00ZJ5
- Part No: ML80P
- Part No: MIMP21?024V
- Part No: ML80L
- Part No: MPT0500000008
- Part No: DB1-23 not available, replaced by SKYD-23-01
- Part No: VT-71-L OEM

- Part No: VT063L2T00001 OEM
- Part No: 0543040HHNDK100Z11
- Part No: brushes for ML180S
- Part No: CC 112 L-196/196/2000-28/250-B5
- Part No: CC100 L
- Part No: T112C L4 ( obsolete )
- Part No: RFCC080CXFK031001
- Part No: Z0180150
- Part No: MP00440000019
- Part No: VT071L2Z00066
- Part No: 0771540S11EK1G0Z00
- Part No: BR53202
- Part No: WINDED STATOR for V84304
- Part No: 82984-18
- Part No: 0533040P11DK100Z00
- Part No: BRV931441V1XXX2K@02P
- Part No: 49558/01
- Part No: VF 180 L IP23S oem
- Part No: OPDE-V-370 oem
- Part No: MT120 oem
- Part No: 0773040S11EK1G0Z00
- Part No: P00030PM00005
- Part No: terminal box for C.C. 100 L
- Part No: clipboard for C.C. 100 L
- Part No: speedometer for C.C. 100 L
- Part No: Z0180170
- Part No: MP0463679160 obsolete / new model MPQ205
- Part No: Brushes for ML 80 S
- Part No: Brushes for FDB 60
- Part No: Coupling for Brushes for FDB 60
- Part No: Coupling insert for FDB 60
- Part No: MPQ205
- Part No: CC00800C00002 obsolete
- Part No: VTDAM34
- Part No: Endbell for VU 132 P

- Part No: BR077304+RES
- Part No: BR075304+RES
- Part No: VT71L 2740
- Part No: BR077154 + ??????
- Part No: BRV78304
- Part No: BR073154+BRAKE
- Part No: BR073154
- Part No: Z0150501
- Part No: ML 100M
- Part No: VT63L2T00001
- Part No: VT71L1Z00024
- Part No: VT71L0L00001
- Part No: BR0742042QL VEK1GMZ00
- Part No: Type: 30PM010 IP44 DA9x26 56B14 CAVO 1mt
- Part No: P00030PM0,210243000XAALDXXXXXXXXX000XX0S
- Part No: C.C.112L
- Part No: ML00800M00084 / ML80M-290/330-2000-B35/28+VF+PT
- Part No: CA0100C0576001
- Part No: VT090L4H00033
- Part No: MPV63L
- Part No: VT090X4Z00018 old code, new code VT090X4Z00063
- Part No: VT090X4Z00063
- Part No: VT090X5T00064
- Part No: VF160M3U00009
- Part No: VT080L4H00058
- Part No: BR0773040511EK1G0000 old code / new code 0773040S11EK1G0Z00
- Part No: MP77M
- Part No: ML100S
- Part No: 0553040H11DK100Z00
- Part No: ML 71 M
- Part No: Z0180190
- Part No: FM0BC013U OEM
- Part No: 0772040U11EK100Z00
- Part No: ML100S ( 2.72kW, 1500 giri/1")
- Part No: ML100S (4.4kW, 3000 giri/1")

- Part No: MLS160M
- Part No: VT080S2P00043
- Part No: MLS180S
- Part No: ML 100 L
- Part No: EG313 12,5X32X40
- Part No: 1007728901002 OEM
- Part No: encoder for 1007728900002 OEM
- Part No: VT080S2P00027
- Part No: H422A953000E1
- Part No: 0843042D0688000 084304
- Part No: VT100P6E00029
- Part No: VT071M2P00015
- Part No: anchor for ML1320S00013
- Part No: carbon brushes for ML1320S00013
- Part No: coil springs for ML1320S00013
- Part No: BR0753040HHNEK100Z1I OEM
- Part No: 0513040P01M6M1F1A31001C0AG00FAAAA195A000
- Part No: ML01000P00003
- Part No: BRV782040H11K100000 old code, new code V782040H11EK100Z00
- Part No: BRV742040H11S100000 old code, new code V742040S11EK100Z00
- Part No: V782040H11EK100Z00
- Part No: V742040S11EK100Z00
- Part No: MPT205
- Part No: B-VT90X-8 -4P-2
- Part No: ML 132 SW - 80079701/02
- Part No: VU132P6F00004 OEM
- Part No: MLS160L
- Part No: FM0BA6821 SN: C358/01 OEM
- Part No: MPT202001,960903000XACCAUXXQXXX000XX0C
- Part No: VT071L2ZXX2C2C2XXD0X24078AEBB
- Part No: VT090P4P00062
- Part No: T80C A4
- Part No: VT100P6E00070 / VT100P6EXX2F4G2XXD24I4XXXA0BB
- Part No: R19 7x10x21 for MP 46
- Part No: J950 CARB Code 041205

- Part No: J950 CARB Code 41041205
- Part No: Vt080l4h00079
- Part No: MPV0560L00026
- Part No: V981041FN500C001 OEM
- Part No: BRV98104 OR 19 HK 2 2KO
- Part No: BR058204
- Part No: 0582040SGVDK1AKZ98
- Part No: VT90S
- Part No: MP-23 MP0233191060
- Part No: spare brushes kit for MP-23 MP0233191060
- Part No: Carbon brushes set for MP46 (18633/55)
- Part No: 0513040P11DK1A0Z00
- Part No: ML 112M N:21541/01
- Part No: VT071L0L00001 OEM
- Part No: 0782042WG1300I001 / 078204-2000/400-RES-24x50K/B5
- Part No: 30PM010 C 1MT
- Part No: CODE: VT080L4H0095 / TYPE: FM08A722 OEM
- Part No: BR0562040H11DK1000000 old code/ BR056204 new code
- Part No: BR056204
- Part No: 0553040H11DK100Z00 / 055304-3000/400-RES-19X40K/B5-CE
- Part No: TYPE: ML80L
- Part No: ML0080L081322