

ENDURA SUPPLY

Aerovox Product List

- Part No: 100279.39 270-300 MFD - OBSOLETE
- Part No: 400 VDC 1 POS-NEG Obsolete
- Part No: 80 MF 260 V AC
- Part No: ALC22A1039
- Part No: ALS31C 472 NP450
- Part No: ALS31C472NP450
- Part No: CGZ 6300 MFD 400 VDC
- Part No: H50K6608E-OBSOLETE (REPLACEMENT H50S6608A0BF21A)
- Part No: H50S6608A0BF21A
- Part No: N50H2511G30A4
- Part No: P50G3707YJ1-OBSOLETE Replaced with "Z50S3707N01N"
- Part No: Z50S3707N01N
- Part No: Z64S3740W85A1
- Part No: Z93S2848PN
- Part No: Z93S4430M02A3
- Part No: Z64S3740W04
- Part No: C103237300113 - no longer manufactured by Aerovox for 20 years
- Part No: Z94S5435MN
- Part No: Z50S3717N04A1
- Part No: Z50P3707N - alternative Z50S3707N01N
- Part No: QL422YW048V21C (1 Pack, 1x21 pcs)
- Part No: Z93S4824PN
- Part No: Obsolete Z24P3725E replaced with Z24D3725M01N
- Part No: Z24P3725E - Obsolete, replaced by Z23S3725M01N
- Part No: Z23S3725M01N - MOQ 200 pcs
- Part No: Z24D3725M01N
- Part No: AMP0020F33SHA
- Part No: H62S6620A0BH21A
- Part No: D83W4010M01H
- Part No: Z23S3720M01N
- Part No: 850-102MFD
- Part No: RBPS47496KB8GNZ

- Part No: HH62R1012E // 12 AµF 1000V 60HZ 70C - obsolete, replaced by H62S1012A0BF01A
- Part No: AEROVOX HH62R1012E // 16 AµF 1000V 60HZ 70C - obsolete, replaced by H62S1016A0BA01A
- Part No: H62S1012A0BF01A
- Part No: H62S1016A0BA01A
- Part No: N50H2385G21A3
- Part No: Z73S4010MN
- Part No: N50H1701Y33
- Part No: N50H2597G23A4
- Part No: Z93S4430M01A3
- Part No: Z93S5426P07N
- Part No: 9440 1238
- Part No: N5OR1001SK (obsolete)
- Part No: N50H2511G24B3
- Part No: N50H2180G25A3
- Part No: N50H2514G22E3
- Part No: condenser for RUDH 90618 R 004915738
- Part No: Z94S5232JN
- Part No: N50H2112GO2R
- Part No: Z93S4830PN
- Part No: QL422YW048V21C
- Part No: N64H3082G
- Part No: Z93S4824MN/2779-MF
- Part No: PART NO. 369229, 48MFD +/-3% 280VAC 60HZ 105C MAX ; INT. RES. 0.57 MEGOHM
- Part No: QL232EW195V
- Part No: H62S6620A0BH
- Part No: HH62R1012E // 12 µF 1000V 60HZ 70C - obsolete, replaced by H62S1012A0BF01A
- Part No: AEROVOX HH62R1012E // 16 µF 1000V 60HZ 70C - obsolete, replaced by H62S1016A0BA01A
- Part No: Z94S5232J07N same as Z94S5232JN
- Part No: N50H2112GO2R replaced by N50H2112GO2R
- Part No: H62S4660A0GE21A - obsolete, replaced by - H62S4660A0GF21A
- Part No: ALS31C472NP450 alternative ALS31A472NN450 Kemet
- Part No: H62S4660A0GF21A
- Part No: ALS27A 1029MF
- Part No: H26S6645A0CH21A

- Part No: H93S6620A0BH21A
- Part No: ALS41A222MF350 Alternative
- Part No: ALS31C332MF350
- Part No: ALS31A152KF350
- Part No: RBPS30571KR7GNZ
- Part No: ALS20A1255MF oem
- Part No: Z74S4826M21R old P/N, Z74S4826M new P/N
- Part No: Z76S4830M21R old P/N,Z74S4830M new P/N
- Part No: Z74S4826M
- Part No: Z74S4830M
- Part No: RBPS30591KR7GNZ
- Part No: H62S4660A0G
- Part No: ALS60A 1001 DA oem
- Part No: ALS60A 1000 DA oem
- Part No: Z93S3348MN
- Part No: ALS31C 1016 xx 66779/1 OEM
- Part No: Z93S4828MO1A3 (pack=12pcs)
- Part No: 161 A 193 MFD
- Part No: QL232EW195V (1 pack= 21 pcs)
- Part No: D22C4005C01H
- Part No: CP53B1KE105K1
- Part No: Z93S3624PN
- Part No: Z26S6045MT5A4
- Part No: Z26S6045M50N
- Part No: N50H2511G24D3
- Part No: N50H2596G21G3
- Part No: Z73S4024MN
- Part No: Z50S3710M01N
- Part No: Z93S4024MN
- Part No: C103237300110
- Part No: Z26S5592MT5A4
- Part No: Z26S5846M50N
- Part No: Z74S4824MN
- Part No: Z91S3707N01A3
- Part No: old code 2776-MF, new code Z93S5226NN

- Part No: Z93S5226NN
- Part No: z26s6045m21
- Part No: Z50S6605M01N
- Part No: Z93S3624P01N
- Part No: N50H2511GR
- Part No: N50H2596GR
- Part No: Z50P3705M46
- Part No: Z26S3770M43
- Part No: Z26S3770M
- Part No: Z94S5232J07N
- Part No: A16GEN4C11
- Part No: VC32052GDTR RM267
- Part No: MMP0225X12MT
- Part No: CY 213215-G5
- Part No: old pn H64R6615E29 / new pn H64S6615A0BF21A
- Part No: PN X129-62-54
- Part No: old pn H50R661DE22/ new pn H50S6610A0BF21A
- Part No: H50S6610A0BF21A
- Part No: H64S6615A0BF21A
- Part No: Z93S4430PN
- Part No: S50H1501T23A1
- Part No: Z26S3775M50N
- Part No: RBPS 0735 .68 UF/K 1000VCD
- Part No: RBPS68491K-B7-G
- Part No: 2387179
- Part No: D83W4015M01H
- Part No: Z93S4824P021N
- Part No: QL422YW048D22A
- Part No: Z93S4830MN
- Part No: Z26S3775M
- Part No: Z50S3704M01N
- Part No: N50H42510G45R
- Part No: MMP0150J33
- Part No: MP4-444
- Part No: 14217771

- Part No: PLCR24400D
- Part No: D84W4024M01H
- Part No: Z26S3775M25
- Part No: QV232EW195N
- Part No: MMP0133X3550P
- Part No: Z24S3730W05N
- Part No: H64S6618A0BF21A
- Part No: 180 MFD 110
- Part No: H64S6620A0AF
- Part No: N64H3082G21E4
- Part No: N64H3082G24A4
- Part No: PSU16115
- Part No: PSU18915A
- Part No: Z73S4010MN (2uF)
- Part No: Z73S4010MN (20uF)
- Part No: Z73S4010MN (30uF)
- Part No: Z73S4010MN (50uF)
- Part No: SFT37T15K238B-0000
- Part No: Type Z93S4824P021N
- Part No: Z94S5232N
- Part No: Z50S3707N
- Part No: SFA37T17.5K3888-0000
- Part No: Type Z93S4824PN
- Part No: H62S4660A0GA