

ENDURA SUPPLY

ABAC Product List

- Part No: 6211475800
- Part No: 8973015419
- Part No: B 7000 10HP
- Part No: BF ABAC
- Part No: STO ABAC
- Part No: THERMOSTATIC VALVE ????
- Part No: VR ABAC
- Part No: piston rod for compressor FC2-50 CM2 REDLINE CF
- Part No: crank mechanism for compressor FC2-50 CM2 REDLINE CF
- Part No: 9056322 (obsolete-replaced by FLK16-01213)
- Part No: 9618035 (obsolete - replaced by FLK04-01338)
- Part No: 692110B
- Part No: P/N: 1110215, Type: KS-L-1296
- Part No: LD 200
- Part No: 8973015417
- Part No: 0079500000 G120
- Part No: Model TP 25 I (serial number TP 25 C)
- Part No: BD1
- Part No: BD1/30 FM1 SIL
- Part No: B5900B
- Part No: VEC25-I
- Part No: APM-I
- Part No: APM-B
- Part No: B7000/500
- Part No: genesis 7,510
- Part No: OS15P
- Part No: 9056176 wrong code- new code SP.3076
- Part No: B5900B/500CT5.5
- Part No: 2236108748
- Part No: 2203034100
- Part No: MTINX465
- Part No: VAA-B50M-300-I B

- Part No: N/P: 9056113
- Part No: 8973035121
- Part No: 2236105773 \ DF58100
- Part No: 2236105734 \ DF58130
- Part No: 2236105790 \ DF58158
- Part No: 2236106186 \ DF58226
- Part No: Model VA175 IT
- Part No: VRS251
- Part No: 2258290102
- Part No: B 5900B-90 CT5,5 V440-60 obsolete
- Part No: VM150M-IT
- Part No: 8973037630
- Part No: Repair kit for VAA-B50M-300-I B
- Part No: gasket set for LT 27 B 600-270 FT
- Part No: 6211471900
- Part No: B6000
- Part No: compressor unit with drive/fan wheel for compressor B 6000-270 FT 7,5 400 CE AIRB0
- Part No: 6229028500
- Part No: 4116020190
- Part No: valve plates with seals for PRO B5900B 270 VT5.5
- Part No: 4116000235