

ENDURA SUPPLY

ACI Product List

- Part No: CY0408409000
- Part No: ??5055 ??? 2015 ASI/US100 - obsolete,IM5118 - replacement
- Part No: IM5118
- Part No: TS2106-GH-10-AA (OEM - alternative is 10K OHM 77 DEG)
- Part No: TS2108-GH-10-AA (OEM - alternative is 10K OHM 77 DEG)
- Part No: 10K OHM 77 DEG
- Part No: 10176377
- Part No: NY14224
- Part No: A/TT100-R-4-EXPL - not available , alternative - TA2105
- Part No: # 130183
- Part No: 604M
- Part No: S30025S
- Part No: A/MLP2-005-W-U-A-C-0P
- Part No: A/MSC
- Part No: A/MSCS
- Part No: C105
- Part No: C0630012R
- Part No: C0400012R
- Part No: C1250012R
- Part No: A/CP-SBS
- Part No: A/RH2-R