

ENDURA SUPPLY

Checkline Product List

- Part No: CF-4H
- Part No: DTW 1200 I
- Part No: MEASURES CABLES: 3/16" a " 1"OD (5MM a " 25MM) CAPACITY: CTM-2000 a " 2000 LB / 10 KN / 1000 KG CTM-10000 a "
- Part No: MTT03-100E / 133317
- Part No: PLT-5000
- Part No: T-042-2000
- Part No: TI-25M
- Part No: Probe for TI 25 M, 250 HR 7.5 MHZ
- Part No: ELE-DT-315A
- Part No: ELE-DT-315A-2
- Part No: 126135
- Part No: BTM-400 Plus
- Part No: TI-007GT
- Part No: TI-007
- Part No: 126097 TICC-M Nylon Schutztasche
- Part No: I -25 LTX
- Part No: CPS-4
- Part No: MEASURES CABLES: 3/16"– 1"OD (5MM – 25MM) CAPACITY: CTM-2000 — 2000 LB / 10 KN / 1000 KG CTM-10000 —
- Part No: 126500 / BTM-400PLUS
- Part No: DTX-500
- Part No: DX2-1000
- Part No: DX2 – 10K
- Part No: AWS-QC
- Part No: P/N:130313; Type: ELE-PK2X
- Part No: ELE-PK2X-OT
- Part No: ETX-500
- Part No: TI-25DLX
- Part No: ZEF-100
- Part No: 130041
- Part No: CDT-2000HD

- Part No: ETX-100
- Part No: 20251
- Part No: TI-25LTX
- Part No: 130550 / HP-10F
- Part No: 136622 / TI-25MX
- Part No: TI-007X
- Part No: DAW-340N
- Part No: TSD-50/20000214
- Part No: TSD-50 /20000233
- Part No: TSD-400 /20000180
- Part No: TSD-400 / 20000185
- Part No: 133099 / TSD-50
- Part No: 132918 TSD-400
- Part No: CPS-20
- Part No: CPS-60
- Part No: F-1000-30
- Part No: 133009 for F-1000-30
- Part No: DX2-400 Tension Meter 20-400 cN
- Part No: DX2-200 Tension Meter 20-200 cN
- Part No: DX2-5000 Zugspannungsmesser 400-5000cN
- Part No: DX2-1000 Tension Meter 50-1000 cN
- Part No: probe for TI-25MX
- Part No: CAP-TT01-50
- Part No: J-40-T
- Part No: WT-100
- Part No: 135040 / TI-MVX
- Part No: ITI-10 1/4
- Part No: ITI-100 3/8"
- Part No: TT-QC-750i-3/8
- Part No: Cap parts for 132918 / TSD-400
- Part No: 138201 DTL-TSD
- Part No: TSD-BC
- Part No: FB-150
- Part No: OH-1
- Part No: ZF2-10

- Part No: DTL-100I
- Part No: probe for TI-PVX