

ENDURA SUPPLY

Adda Product List

- Part No: 2TB16L4300007 TFCP 160L L-6 11KW 960 DEV/DAK 400/690 VOLT 50HZ
- Part No: 3323 100
- Part No: 664-AD2512MS - OBSOLETE, FOLLOWER -664-AD2512MS-LF
- Part No: 664-AD2512MS-LF
- Part No: 664-D0624HBA72GLLF
- Part No: AB0612MB-A03
- Part No: AB7205HX-GC3
- Part No: AD 624 HB-A71 GL
- Part No: AD0412HB-G70(TJ)
- Part No: AD0424LS-C50
- Part No: AD0612HBGA0GL-LF
- Part No: AD0612MX-G76-T-LF
- Part No: AD0624HB-A71GL
- Part No: AD1212LB-A70GL
- Part No: AD1212LB-A71GL
- Part No: AD1224UB-F52-LF
- Part No: AD1224UB-F52(FNCU)
- Part No: AD1224UX-A73GL
- Part No: AD7515MB
- Part No: AK1782HB-AT
- Part No: BRUSHLESS DC 24V 0,40A
- Part No: FRL-W-160 SERIE T BG 160 4 LOCH 230/400 VOLT
- Part No: MFR PN: AD0612MX-G76(T)-LF
- Part No: Model B14
- Part No: AD1212MF-A72GL DC 12V 0,33A
- Part No: C 315 M-6
- Part No: C 180 MT-4
- Part No: AD0912UX-A7BGL
- Part No: AQ1224HB-F51(FN21)
- Part No: TB09L2100002
- Part No: 6113127 - obsolete-replaced by 4TT16M6200001
- Part No: 7153138 -obsolete-replaced by 4TT16L4200001

- Part No: 4TT16M6200001
- Part No: AB7005HX-ABB OBSOLETE
- Part No: IEC 34-VDE0530
- Part No: T532/3403 obsolete/replaced by TFC 90 L-4
- Part No: TFC 90 L-4
- Part No: FC 90L-4 obsolete/replaced by TFC 90 L-4
- Part No: 1010-052302
- Part No: AA1281US-AW
- Part No: AD0424MB-G70(T)
- Part No: AA1282UB-AT(CF)
- Part No: 24V DC-LÜFTER 60x60x25 IP55
- Part No: AA1752HB-AW
- Part No: FC90S-2-B5, 3-PHASE
- Part No: AG12024HB257100
- Part No: 2150766
- Part No: AD17224DB-5159M0(OCW)
- Part No: S A49 69F 220
- Part No: AP0505HX-J90
- Part No: AK1782HB-AT-LF
- Part No: AK1782HB
- Part No: AD1224HB-F51
- Part No: AD1212UB-F51
- Part No: AD0912US-A70GL
- Part No: AD1224UB.F51.FN obsolete/alternative AD1224UB-F51-LF
- Part No: AD1224UB-Y51
- Part No: AD1224UB-F51-LF
- Part No: AD0505HB-G76
- Part No: AD0505HB-G76-LF
- Part No: AD0724HB-D72
- Part No: 3TT09S2100003
- Part No: AD0924HB-A71GL
- Part No: AD0424HB-G76
- Part No: AD0812UX-A76GL
- Part No: AK1781HB-AW
- Part No: VAAK1781HB-A

- Part No: K9D
- Part No: AD0812XR A73GL
- Part No: AD0824XB-F71DS
- Part No: AD0924HB-Y71GL(NA21)
- Part No: TFC90LA-4
- Part No: AD0524HB-G70(BT1)
- Part No: AD0912UX-A71GL(N961)
- Part No: AD1212UB-F51(N)
- Part No: AD1212UB.F51.FN
- Part No: AB05012DX200600
- Part No: FCP80-4
- Part No: MLB:1PC14231CB690AC8-Z
- Part No: AD0824HB-D71 obsolete
- Part No: AD0824MB-D92 obsolete
- Part No: AD082UB-A73GL
- Part No: AD0924HS-A70GL (T)
- Part No: AS12024HB389100
- Part No: AD0924HB-F99DS
- Part No: AD0912HB-Y71GL(N)
- Part No: AD1224UX-A73GL(21)
- Part No: AD1212MB-F51
- Part No: AD0605LB-G70
- Part No: AQ1224MB-F51(FN219T)
- Part No: AD17224DB5159M0 3 POLE
- Part No: AD1224UB-F51
- Part No: AD912US-A70GL
- Part No: AD0912UX-A7BGL-LF
- Part No: AS12048HB389300
- Part No: AD04024UB285102
- Part No: CA90L4FECC
- Part No: AD07012LX257B00
- Part No: AD1224UB-A71GL
- Part No: AD08024UB257104(00 H3)
- Part No: AG06024HX257003(00L5)
- Part No: AG03012HB105100

- Part No: 4TT18L6200003
- Part No: 6TT18L6200003
- Part No: AD09224HB-F99DS