

# ENDURA SUPPLY

## Adler Spa Product List

- Part No: 11.02.2023
- Part No: 3"-FP3
- Part No: 3"-FP3(NP511526-A105-N170A)
- Part No: ASR322
- Part No: DN 40 FJ2
- Part No: DN 40 FM2
- Part No: FP3 1/2"
- Part No: FT4-DN80-PN10
- Part No: ITC-C-54
- Part No: ITC-C-56
- Part No: ITC-C-62
- Part No: ITC-C-67
- Part No: ITC-C-68
- Part No: ITC-C-69
- Part No: ITC-C-70
- Part No: ITC-C-71
- Part No: ITC-C-72
- Part No: ITC-C-73
- Part No: ITC-C-74
- Part No: ITC-C-75
- Part No: ITC-C-76
- Part No: ITC-C-77
- Part No: ITC-C-78
- Part No: RSTSTPF1040
- Part No: RSTSTPF1050
- Part No: RSTSTPF1080
- Part No: TPF1050
- Part No: type FA2 DN 50 A300 UNC TV ES.CRIO 304+420
- Part No: VT5CC040DTP-X-BOHRUNG
- Part No: 10X90.NP22A 2006 K3
- Part No: A511605
- Part No: AP X 110 SE/SERIE: A511605

- Part No: ADLER FA2
- Part No: FB1CC050IUTPSL
- Part No: APR 085 SESpring 10Cr322950 Series12/07913/0001/x Obsolete, replaced by FP3CC040DTPSWEQPIS + APM164SE050BCDG
- Part No: FP3CC040DTPSWEQPIS + APM164SE050BCDG
- Part No: FX2BB100CTVCA1EQ
- Part No: ADLER 15A
- Part No: APX127DE Obsolete, replaced by APM214DE
- Part No: APM214DE100
- Part No: FA2 BALL VALVE 304+304 ND 65 PN16
- Part No: FA2 BALL VALVE 304+304 ND 80 PN40
- Part No: RSTSTVFZ4032
- Part No: FB1BB050DTPSL
- Part No: FA1AB050DTPSL
- Part No: HWR012002A13A - from Soldo, Adler Spa alternative - ASM-312
- Part No: DN50 (2")
- Part No: ASM-312
- Part No: FG2CC100LTV
- Part No: RSTSTVF2100
- Part No: APM148SE
- Part No: APM242SE050A
- Part No: EVD11T24DC
- Part No: 15/01339/0002
- Part No: FA2 DN80
- Part No: APM164 KIT
- Part No: APM214 KIT
- Part No: APM305 KIT
- Part No: DN50-GK PTFE
- Part No: DN80-GK PTFE
- Part No: DN150-GK PTFE
- Part No: TVF2100
- Part No: 18/04444/0007 2"
- Part No: 18/04444/0007 2 1/2"
- Part No: FP3CC040DTPSWPI
- Part No: FP3CC050DTPSWPI

- Part No: FP3CC065KTPSWPI
- Part No: B052667
- Part No: APM123SE
- Part No: APM214SE
- Part No: APM242SE080C
- Part No: VT5 DN 50
- Part No: FM2-5066TP-NB1
- Part No: FM2-5066TP-NB2
- Part No: VT5 DN50 + ACTUATOR
- Part No: RSTSTVF2040
- Part No: RSORAPM186
- Part No: RSTSTVF2025
- Part No: RSORAPM164
- Part No: RSTSTVF2015
- Part No: RSORAPM148
- Part No: RSTSTVF2020
- Part No: RSTSTVF2050
- Part No: RSORAPM214
- Part No: FE2 BALL VALVE A105 + 316 DN 25 A150 BALANCE HOLE + STRIPPLABLE VARNISH
- Part No: FE2 BALL VALVE A105 + 316 DN 65 A150 BALANCE HOLE + STRIPPLABLE VARNISH
- Part No: FB1-NTN-PLS-DN80/PN40
- Part No: FB1BB080DTP
- Part No: 8384
- Part No: BGL70VNA00987
- Part No: BGL70VNA00988
- Part No: BGL70VNA00990
- Part No: BGL70VNA00992
- Part No: APM164SE
- Part No: FT4AB080DTPSL
- Part No: APM186DE050
- Part No: FP3AC040DTGFG
- Part No: EVN31 / EVN33
- Part No: FT4AB050LTVL
- Part No: APM105
- Part No: FA1AB050DTP

- Part No: FP3AB025DTPFGSL APM164SE025A
- Part No: FB1BB040DTPASO
- Part No: FB1BB040DTPSLASO
- Part No: A508618
- Part No: APM305SE100C
- Part No: FS2AB015ETPFN
- Part No: F07-PN25-98
- Part No: Sealing set for F07-PN25-98
- Part No: FP3AC010FTVFGSL
- Part No: FA2-DN100-ANSI150-316L-N445920
- Part No: rebuild kit for FA2-DN100-ANSI150-316L-N445920
- Part No: FA2CC100ITP
- Part No: RSTSTPF2100
- Part No: FP2CC015ETPFN
- Part No: FP2CC025DTPFN
- Part No: APM242SE
- Part No: APM123DE025