

# ENDURA SUPPLY

## Colvern Ltd Product List

- Part No: 17/542/2584 4K 15M 9229.ES 144
- Part No: 17/542/2684 4K 15 M 9229. ES 144
- Part No: 3001/115 250RK
- Part No: 4001/22 a “ 1 Isl© a “ 9043 - 5W
- Part No: 4001/22, 2KOK, 0019
- Part No: 7001/29 2KOK 7818
- Part No: 7319H CLR5001/ M40 5kl©
- Part No: cp10/006 0206
- Part No: CP16110/M50 5KM
- Part No: CP 16110 / M 50 - 5 Kohm
- Part No: CP17/319/2630ES130
- Part No: LM10 / 3M29
- Part No: LM10/3M29 5KOM 0819
- Part No: LM10-3/29
- Part No: LM10-3M29 5KOM 173 11
- Part No: 4501/22 200RK 7947
- Part No: 4001/11S 10 KOHM
- Part No: 4001/M50 5
- Part No: 4001/115
- Part No: LMI0/3M29
- Part No: LM10/3M295KOM TO ES AW
- Part No: COLVERN LM10/3M29,240072
- Part No: LM10/3M295K
- Part No: CP16001/15S-5KOHM
- Part No: CLR 1106/M50 1K+-10% (11060M50001KKAA)
- Part No: CP.16/001/M165
- Part No: CP16110/M50 5KOK 9747
- Part No: CLR 4001/11S,10KOhm
- Part No: 4K 15M ES 133
- Part No: 10KOHM-4001/11S
- Part No: LM 10/ 3M29 a “ 10K, A±20%
- Part No: CP16/110/M50

- Part No: CLR 4000
- Part No: LM10/3M29 5KOM
- Part No: CLR 3001/9S, obsolete, replacement CLR 4001/ 9S 50 RK
- Part No: CLR 4001/11S 5K + - 10% (4001011S005KAA) AB#:3104001160
- Part No: CLR 4001/ 9S 50 RK
- Part No: LM 10 / 3M29 - 5 Kohm +-20% Lin
- Part No: 4001011S250RCAA 3104001125
- Part No: 4001011S050RCAA 3104001105
- Part No: 4001/11S 250R+-10%
- Part No: 4001/11S 50R+-10%
- Part No: LM10/3M29-5 KOHM
- Part No: CP 17/ 583-2 AS
- Part No: CT.1319/M255 obsolete replaced by C 18 - 4,7 KOHM
- Part No: C18-4,7 KOHM 25mm ABcode: 2101802840 obsolete,replaced C18-4,7 KOHM 15mm ABcode:2101802845
- Part No: CP 16110 / M 50
- Part No: LM 10 / 3M29 - 5 KR
- Part No: CLR 4001/22-2K0K
- Part No: CLR 4001/22-1K0K
- Part No: 4517/ 25S 100RK
- Part No: CLR 1232/15S 3101232170
- Part No: CLR 1232/268
- Part No: CP 16110 41150 02470
- Part No: CLR 4517/25S 3104517210
- Part No: LM 10 / 3M29 4114902400
- Part No: LM10/3M29 1K0M 06413
- Part No: CLR1232/15S/5K
- Part No: CLR1232/268/10K
- Part No: 3104001170
- Part No: 310450122
- Part No: CLR3001/9S 5R Obsolete Replaced by CLR 4001
- Part No: CLR 4001/ 9S
- Part No: CP 16110 / M 50 4115002470
- Part No: 31011 06940 1106/9S
- Part No: 3101232xxx

- Part No: 4501/15S 31045 01170
- Part No: LM 10/ 3M29
- Part No: CP.16/501/M255
- Part No: CLR 4001/ 11S 10KK
- Part No: 4027/M22
- Part No: CLR 1106/9S 10K+-10% (1106009S010KKAA)
- Part No: C18-4,7 KOHM 15mm ABcode:2101802845
- Part No: CLR 4501 / 22 200R K
- Part No: CLR 4001/ 11S -5 KOHM
- Part No: CT.1319/M25S 5KOM 8026 - obsolete
- Part No: lm10/3m29 5KOM 9725
- Part No: 4517/ M25S 100RK
- Part No: CLR 4001/11S 10K
- Part No: LM24/3M29
- Part No: CLR 4001/22 2K,+10%
- Part No: CP 16110/ M 50 - 5 K0hm
- Part No: LM10/3M29 10KOM
- Part No: 8939.E3I03 Obsolete
- Part No: CP 17/225 / 2584 4K15M to ES 103
- Part No: CLR4517/15S 10KJ
- Part No: CLR4517/M25S 100RK
- Part No: CP 16110 / M 50 5KOK ES84 9813
- Part No: CP 16110 / M 50 - 5 Kohm (30+ pieces)
- Part No: CP 16110 / M50
- Part No: CP 10/010
- Part No: CLR 4001/22 2K+-10% (40010022002KKAA)
- Part No: CLR 4001/22 2K+-10% (40010022002KKAA) (5-10 pcs)
- Part No: CLR 4001/22 2K+-10% (40010022002KKAA) (10+ pcs)
- Part No: CP110/M50