

ENDURA SUPPLY

Airtech Product List

- Part No: ASC0080-1MT250-6
- Part No: ASC0140-1MT700-6
- Part No: ASC0080-1MT400-6
- Part No: AAC20125 PC-401.00019
- Part No: ASC0315-1MT301-6
- Part No: Nr. PC-100.00025 Type ASC0140-1MT700-6
- Part No: ASC0080-1MT250-6 PC-100.00020
- Part No: VSC0315-1MT301-6
- Part No: VSC0080-1MS370-5 - old name, new name - ASC0080-1MS370-5
- Part No: ASC0080-1MS370-5 (PC-100.00006)
- Part No: ASC0140-1MT131-6
- Part No: VSC0210-2ST301-6 old code / new code ASC0210-2ST301-6
- Part No: ASC0210-2ST301-6
- Part No: VSC0415-1MT161-6 HMA - obsolete/ replaced by 70-603190501
- Part No: ASC0415-1MT161-6_HMA (70-603190501)
- Part No: AAC00125
- Part No: AAC32125
- Part No: AAC11125
- Part No: AAC10125 obsolete/ replaced by AAC11125
- Part No: ASC0315-1MT301-6 #005
- Part No: ASC.....T301-6 #001
- Part No: VSC0080-1MT250-6 old description(Vacuvane),ASC0080-1MT250-6 new description(Airtech)
- Part No: VSCO-2ST301-6 old code/new code ASC0210-2ST301-6
- Part No: VSC0530-1MB401-1_K3G
- Part No: ASC0530-1MB401-7_K3G
- Part No: ASC0080-1MS370-5
- Part No: ASC0530-1MD401-7-K3G
- Part No: ASC0210-1MT161-6
- Part No: PC-100.00182 // ASC0315-2ST431-6
- Part No: VSC0315-2ST431-6 old code, new code ASC0315-2ST431-6
- Part No: AAC20200

- Part No: AAC11200
- Part No: VSC0210-1MP151-6
- Part No: VSC0210-1MT161-6
- Part No: ASC0210-1MP151-6
- Part No: VSC0315 -2ST4731-6 old code, new code ASC0315-2ST431-6
- Part No: ASC0280-1MT161-6
- Part No: VSC0415-1MT161-6 HMA old code, ASC0415-1MT161-6_HMA new code
- Part No: ASC0415-1MT161-6_HMA
- Part No: VSC0140-1MT 131-6 old code, ASC0140-1MT131-6 new code
- Part No: 46768310
- Part No: 74040001
- Part No: 46750400
- Part No: old pn VSC0530-1MT551-7 / new pn ASC0530-1MT551-7
- Part No: Repair kit for VSC0530-1MT551-7
- Part No: Fan blade for VSC0530-1MT551-7
- Part No: ASC0530-1MT551-7
- Part No: VAC 00125
- Part No: ASC1050-1MT122-7
- Part No: (V)ASC0315-1MT221-6
- Part No: PC-600.00014
- Part No: ASC0530-2ST112-7 / PC-100.00193
- Part No: ASC 0530-1MT551-7 Z
- Part No: ASC0315-2ST551-7
- Part No: ASV0027
- Part No: 3BA1900-7AT36
- Part No: ASC1050-1MT182-7
- Part No: ASC1050-2ST252-6
- Part No: 35509 Combo Overhaul Kit L160C
- Part No: 3BA1910-7AT46
- Part No: VSC1050-2ST252-6 old code, ASC1050-2ST252-6 new code
- Part No: VSC0530-S-551-7
- Part No: 3BA1430-7AT26
- Part No: 3BA1630-7AT06
- Part No: ASC0415-1MT401-6 / PC-100.00055
- Part No: ASC0315-1MT221-1

- Part No: ASC0210-1MT221-6
- Part No: TEFLEASE MG2
- Part No: ASV0027-1MB110-2_Z
- Part No: 3BA1900-7AT06
- Part No: PC-102.00103
- Part No: 3BA1630-7AT16
- Part No: 3BA1800-7AT26
- Part No: VSC 0315 – 1 MT401-6
- Part No: ASC0315-1MT401-6
- Part No: AQD 500TF | AT5507
- Part No: AQD 500TF PLUG
- Part No: Nr. PC-401.00111 Type AAC41150-1-0-0-B
- Part No: MAX 2000 (20L)
- Part No: 3BA1600-7AT26
- Part No: AQD-500TF-1/4
- Part No: ASC0315-2ST431-6
- Part No: Motor terminal board for VSC0530-1MT551-1_DISA
- Part No: AQD500TF