

ENDURA SUPPLY

Alpha [Wittenstein] Product List

- Part No: ALPHA 580F CH: 414; 433.900MHZ
- Part No: ALPHA 580F CH: 422; 434.100MHZ
- Part No: SP 140S - MF1 - 10 - 1G1 - 2S
- Part No: ALPHA 580F CH : 407; 433,2250 MHz-obsolete-replaced by ALPHA 612E-2, CH : 407; 433,2250 MHz
- Part No: ALPHA 580F CH : 424; 434,1500 MHz-obsolete-replaced by ALPHA 612E-2, CH : 424; 434,1500 MHz
- Part No: ALPHA 580F CH : 428; 434,2500 MHz-obsolete-replaced by ALPHA 612E-2, CH : 428; 434,2500 MHz
- Part No: ALPHA 580F CH : 404; 433,1500 MHz-obsolete-replaced by ALPHA 612E-2, CH : 404; 433,1500 MHz
- Part No: ALPHA 612E-2, CH : 407; 433,2250 MHz
- Part No: ALPHA 612E-2, CH : 424; 434,1500 MHz
- Part No: ALPHA 612E-2, CH : 428; 434,2500 MHz
- Part No: ALPHA 612E-2, CH : 404; 433,1500 MHz
- Part No: ALPHA 612B
- Part No: ALPHA 3000D2
- Part No: 100423 Ersatz-Sender für: ALPHA 604A
- Part No: 100100 Ersatzsender für ALPHA 580A
- Part No: 4008-3S
- Part No: SPK+ 075S-MF2-12-2E1-1K01
- Part No: DF74990668
- Part No: LP 090S-MF1- 10-0G1
- Part No: SP210SMF1
- Part No: ALPHA 580F - 433,250 MHz – channel 408
- Part No: ALPHA 580F - 434,025 MHz – channel 419
- Part No: ALPHA 580F , channel 407
- Part No: TK025F-MF1-10-5H1 1TK
- Part No: SP140S-MF2-16-0K
- Part No: LP090-M01-10-100-000
- Part No: ZST400-HE6-X
- Part No: SK 075S-MF1-10 -1H1-1K00
- Part No: ALPHA LP090-MO2-100-110

- Part No: NP025S-MF2-15-1E1
- Part No: NP 025S-MF2-100-1_1
- Part No: 2889177
- Part No: 5899995
- Part No: 5665299
- Part No: NP005S-MF1-10-1B1
- Part No: Type:SP-100S-MF-1-10
- Part No: LP120-M01-5-110
- Part No: LP120S-MF1-3 1/1
- Part No: LP 090-M02-25-110-000
- Part No: RLU 300-PU-18R1-030
- Part No: SN: 2881311 Type LP 090F-MF2-25-1G1-35 obsolete / replaced by NP 025F-MF2-25-1E1
- Part No: LP070-M02-025-111-000 obsolete / alternative NP015S-MF2-25-1_1
- Part No: LP090-M02-025-111-000 obsolete /alternative NP025S-MF2-25-1_1
- Part No: NP 025F-MF2-25-1E1
- Part No: NP015S-MF2-25-1_1
- Part No: NP025S-MF2-25-1_1
- Part No: lp 070-mo2-50
- Part No: NP 025S MF2 - 30 - 1E1
- Part No: SP 140S - MF2 - 20 - 1K1 - 2S
- Part No: SP140S-MC1-5-1K1-2K
- Part No: NP 015F MF1 - 07 - 1E1
- Part No: TP 050S MF1 - 10 - 011 - 2S
- Part No: LP120-M02-15-111
- Part No: LP090-MO1-010-111-PGG
- Part No: SP 060S - MF2 - 28 - 1C1 - 2S
- Part No: CP 005S - MF1 - 10 - 1B1-2S
- Part No: CP 005S - MF1 - 04 - 1B1-2S
- Part No: CP015S-MF2-70-1E1-2S
- Part No: ECM0708 YO0017CT
- Part No: ECM0708 YO0017FR
- Part No: TP 050S MF2 - 91 - 0G1 - 2S
- Part No: TP 010H-MA2-38, 5-0 E1-25 DMF-46/16 i=38.5 S/N 3789269
- Part No: NP025S-MF1-10-1H1
- Part No: TP 010H-MA2-38,5-0E1

- Part No: TP 110S MF2 - 25 - 011 - 2S (20032309) RAC
- Part No: SP 100S - MC1 - 05 - 1K1 - 2K
- Part No: NP 005S MF1 - 05 - 1B1-1S
- Part No: SP140S-MF2-70-0G0
- Part No: 10021522
- Part No: CP 025S - MF1 - 10 - 1E1-2S
- Part No: 50532 DR 1896C
- Part No: SP 060S - MF1 - 03 - 0C1 - 2S
- Part No: NP 025S MF1 - 10 - 1E1
- Part No: NP025S-MF1-10-1D1-1S
- Part No: LP-050S-MF2-50-1B1
- Part No: ELC-00020-A
- Part No: NP025S-MF2-50-1D1-1S
- Part No: LP 070-M01-003-1
- Part No: EC200300AA32001430
- Part No: RP040S-MF1-7-3K1-2S
- Part No: RP-050S-MA2-38.5-3K1-2S
- Part No: TP025S-MF1-10-0G0
- Part No: NP005S-MF2-IE-1C1
- Part No: LP 090-M02-50-111-000 SERVO
- Part No: SK+ 075S - MF1 - 04 - 1E1
- Part No: TYPE TP0255-MF2-61-OE1-25
- Part No: TP 025S MF2 - 61 - 0E1 - 2S
- Part No: LP 070-MO2-15-110-000
- Part No: LP 090-M01-5-111-000
- Part No: TPC+010S-MF2-20-0E1-1K_____RAC 20063511
- Part No: SK+100S-MF2-35-1E1
- Part No: CP 060-MO1-10-111
- Part No: CP 015-MF1-10
- Part No: CP 015S - MF1 - 10 - 1C1-2S
- Part No: SP 100L-MC1-7-1G1-2K
- Part No: NP 025S MF2 - 50 - 1E1
- Part No: TP 025V MF1 - 10 - 0G0 - 2S
- Part No: RD1601F-20F1-15K-B10K-6F36
- Part No: SP 100S - SF1 - 10 - 011 (20041261) RAC

- Part No: RP 050S - MA2 - 022 - 3K1
- Part No: 4012
- Part No: CP060-MO1-10-111 (PIN: 5271120)
- Part No: NPR 025S -MA2-40-1E1-1S
- Part No: SP 075S -MF2-25-1E1-2S