

ENDURA SUPPLY

Bardiani Valvole Product List

- Part No: 2.5" VVF418B212
- Part No: 2.5" VVF418X212
- Part No: 24VDC.
- Part No: 98-??/? 06657 ERSATZVENTIL TYPBBZP
- Part No: ASI-BUS
- Part No: B925 DN 11851 TYP TT AISI 316L (1.4404) DN50 (2") 4-90°TT
- Part No: B925 TT VITON DN80
- Part No: B925 TT VITON SMS63
- Part No: B925 TT VITON SMS67
- Part No: B925, DOPPELSITZVENTIL TT, DN 21/2" ODER DN65, EPDM,
- Part No: BAMBBF300BEAD
- Part No: BAPACF200BEAC
- Part No: BAPACF300BEAC
- Part No: BATABF212BEAA
- Part No: BBZK –L TYPE DN40
- Part No: BBZK –L TYPE DN50
- Part No: BBZK –L TYPE DN80
- Part No: BBZM-L TYPE DN80
- Part No: BBZOG
- Part No: BBZOG TANK BOTTOM VALVE 2 POSITIONS 11/2"
- Part No: Ersatzteile für Ventile BBZP
- Part No: BBZP DN 11851 TYP L AISI316L (1.4404) DN25-32 (1") EPDM
- Part No: BBZP – DN50-NO
- Part No: BBZP DN 11851 TYP LL AISI316L (1.4404) DN80 (3") EPDM
- Part No: BBZP DN 11851 TYP LT AISI316L (1.4404) DN125 (5") EPDM
- Part No: BBZP DN 11851 TYP P7-TL AISI316L (1.4404) DN50 (2") EPDM
- Part No: BBZP DN 11851 TYP T AISI316L (1.4404) DN50 (2") EPDM
- Part No: BBZP LL VITON SMS63
- Part No: BBZP LL VITON SMS67
- Part No: BBZP, KEGELVENTIL, DN 21/2" ODER DN65, LEPDM
- Part No: BBZPM
- Part No: BC1ABF212BEAA

- Part No: BCWADF300BEAA
- Part No: BCWANF200BEAA
- Part No: Type: ZVF PN: BEAAAE050BEBA
- Part No: BEAAAE065BSBF
- Part No: BEAAAL200BEBB
- Part No: BEAAAL200BEBE
- Part No: BEAAAL300BEBH
- Part No: BUTTERFLY GASKET FOR RVFB001668 VALVE
- Part No: DICHTUNGSATZ ANTRIEB
- Part No: DICHTUNGSATZ VENTILGEHAUSE
- Part No: DN 25 ZVF BUTTERFLY VALVE MAINTENANCE KIT
- Part No: DN 40 ZVF BUTTERFLY VALVE MAINTENANCE KIT
- Part No: DN 50 ZP THREE-WAY VALVE MAINTENANCE KIT
- Part No: DN 50 ZVF BUTTERFLY VALVE MAINTENANCE KIT
- Part No: DN100 EPDM VVF-DIN AISI316 DIN11851
- Part No: DN25 EPDM AISI316 ZVF-DIN DIN11851
- Part No: DN25 EPDM VVF-DIN AISI316 DIN11851
- Part No: DN32 EPDM VVF-DIN AISI316 DIN11851.
- Part No: DN32 EPDM ZVF-DIN AISI316 DIN11851
- Part No: DN40 EPDM ZVF-DIN AISI316 DIN11851
- Part No: DN40 EPDM VVF-DIN AISI316 DIN11851
- Part No: DN50 EPDM VVF-DIN AISI316 DIN11851
- Part No: DN50 EPDM ZVF-DIN AISI316 DIN11851
- Part No: DN50MM
- Part No: DN65 EPDM VVF-DIN AISI316 DIN11851
- Part No: BEAACC065BEBF
- Part No: DN65 EPDM ZVF-DIN AISI316 DIN11851.
- Part No: VVF418B065
- Part No: DN65 VVF418X065
- Part No: DN80 EPDM VVF-DIN AISI316 DIN11851
- Part No: DN80 EPDM ZVF-DIN AISI316 DIN11851
- Part No: EPDM 226
- Part No: EPDM 47
- Part No: EPDM 55
- Part No: EPDM 57

- Part No: EPDM DN 63.5
- Part No: EPDM DN65
- Part No: FLANGES IN AREAS WHERE THE SEALS AND IN THE SHAFT SEALS (FOR YQ1065BP300FA MATR NO: ONA 000100 PRE
- Part No: GUIDING BUSHING 130
- Part No: GUIDING BUSHING 168 PTFE
- Part No: GUIDING BUSHING 28
- Part No: Guiding Bushing 120
- Part No: PNEUMATISCHES SCHEIBENVENTIL, DN 2 1/2" ODER DN65, SCHWEIßENDE, EPDM, ANTRIEB MACH98, NC (FEDER SCHL
- Part No: QNCAA108002
- Part No: QNW000038PSA
- Part No: QNXAAAAAEDFAA
- Part No: QNXAAAAEEFAA
- Part No: QNXAAAABDAAAAJ
- Part No: QNXAAAABEDFAA
- Part No: QNXBAAAAEBFAA
- Part No: QNXBAAAAEEFAA
- Part No: QNXBAAAABDAAAAB
- Part No: QNXBAAAABEBFAA
- Part No: SEALING RING 14
- Part No: SERVICE KIT DN50
- Part No: Shutter Nut 28
- Part No: TPHGM06203
- Part No: TPHGM08003
- Part No: TPJGM05106
- Part No: TTAYQ065P2
- Part No: TTAZD050V
- Part No: TTCBAA040E
- Part No: TTCZP040V
- Part No: TTCZP050V
- Part No: TTEZP156G
- Part No: VDX2D3115015
- Part No: VDX2D3115020
- Part No: VDX2D3115025
- Part No: VDX2D3115040

- Part No: VDX2D3115050
- Part No: VITON DN63.5
- Part No: VITON DN65
- Part No: VVF-DIN: AISI316, DIN11851, DN25, EPDM
- Part No: VVF-DIN: AISI316, DIN11851, DN100, EPDM
- Part No: VVF-DIN: AISI316, DIN11851, DN32, EPDM
- Part No: VVF-DIN: AISI316, DIN11851, DN50, EPDM
- Part No: VVF-DIN: AISI316, DIN11851, DN65, EPDM
- Part No: ZAW, DN 65, PN 10
- Part No: ZQDN50 STAINLESS STEEL PRESSURE ADJUSTING 0 - 80BAR (WITH: 2 X REDUCED THREADED SOCKET 2 X CYLINDER)
- Part No: ZVF DN 11851 AISI 316L (1.4404), EPDM DN 50 (2")
- Part No: ZVF –DN 80-FLANGED (PN6)
- Part No: ZVF –DN100-FLANGED (PN6)
- Part No: ZVF DN80
- Part No: ZVF SMS51
- Part No: ZVF VITON DN80
- Part No: ZVF VITON SMS38
- Part No: ZVF VITON SMS63
- Part No: ZVF VITON SMS67
- Part No: ZVF-DIN: AISI316, DIN11851, DN25, EPDM
- Part No: ZVF-DIN: AISI316, DIN11851, DN32, EPDM
- Part No: ZVF-DIN: AISI316, DIN11851, DN40, EPDM
- Part No: ZVF-DIN: AISI316, DIN11851, DN50, EPDM
- Part No: ZVF-DIN: AISI316, DIN11851, DN65, EPDM,
- Part No: ZVF-DIN: AISI316, DIN11851, DN80, EPDM
- Part No: QNC400083AA A00 CIL.MACH 83 S.E.FARF 304
- Part No: VVF418B025
- Part No: VVF418B040
- Part No: VVF418B050
- Part No: TYPE: ZVF CODE: BEAABT080BEBF
- Part No: EPDM MIX B925
- Part No: 115 DN65-80 NBR MIX B925
- Part No: ZVF Pneumatic Butterfly Valve
- Part No: 134
- Part No: 134 (25MM)

- Part No: 133 (32MM)
- Part No: BEAABU080BEBH
- Part No: QNXBAAABDAAAA
- Part No: QNXAAAABBAAAA
- Part No: BEAAAA050BNBA QNXAAAABBAAAA
- Part No: Electronic PCB for RVFB007926 obsolete, replacement QEF000022PSA0
- Part No: SN: ONB 008590,BAAACA050AEAA
- Part No: 21665
- Part No: BAPAAC050BEAA BBZP VALV.PNE DN 50L
- Part No: QNXAAAABEBAAA GIOTTO-TOP 2PNP
- Part No: YQ3 065BPAA0T
- Part No: BAQ ABB050BEAA
- Part No: VF16VVF41 8B100(EPDM)
- Part No: VVF- DN 125
- Part No: VVF- DN 80
- Part No: VVF- DN 40
- Part No: VVF- DN 25
- Part No: ZVF-DN40
- Part No: BBZP-L Type DN 65-NC ,EPDM
- Part No: ZVF-DN100
- Part No: BBZK DN65-I SS VITON 316 LIN SE NO
- Part No: TTCBAP050E
- Part No: TYPE:BBZP, SN: BB 0001303
- Part No: RVFB 0009024 DN40
- Part No: RVFB 0009030 DN80
- Part No: VVF418B080
- Part No: TTCBAA050P
- Part No: TTCBAA065P
- Part No: TTABAA080E
- Part No: TTAZD050E
- Part No: TTAZD065E
- Part No: TTAZD080E
- Part No: TTABGA050P
- Part No: TTABGA065P
- Part No: TTABFA040P

- Part No: TTABFA100P
- Part No: TTEZD156G
- Part No: BACABA050BVAC
- Part No: BEAAB100BEBI
- Part No: Pos. No. 14 For YPA 50 Divert
- Part No: Pos. No. 213 For YPA 50 Divert
- Part No: BAPACB025BEAG QNXBAAACEADAA
- Part No: BEAAB025BEBR QNXBAAACEADAA
- Part No: BAPACB025BEAA QNXBAAADEAAAAAB
- Part No: BEAAB025BEBA QNXBAAADEAAAAAB
- Part No: SERVICE KIT PRODUCT SIDE FOR VALVE VVF418S065
- Part No: Kit for 98 NBR TTEBEA098G
- Part No: BEAABU050BVBA
- Part No: QNXEAAAAEAFAA
- Part No: ONA 0000097
- Part No: TPJGM01706
- Part No: RAAGM4131
- Part No: TOJ002016TAA
- Part No: TPGGM0161
- Part No: RAAGA121
- Part No: RAAGA3087
- Part No: BCWADA050
- Part No: QNXDAAABEBFAA
- Part No: QNXDAAABEBEAA
- Part No: TTABCW050E
- Part No: TTEBCW093G
- Part No: VVF418S050
- Part No: TTEBEA083G
- Part No: Gasket Set For ZVF
- Part No: Repair Kit For ZVF
- Part No: TTEBAP083G
- Part No: TTCBAP040E
- Part No: BAPACA040BEAB
- Part No: TTCBAA065E
- Part No: TTCBAA050E

- Part No: TTEZP083G1
- Part No: BEAAAA050BSBA
- Part No: TTEBEA098G
- Part No: BCAADA065BEAA new code B925-TT
- Part No: B925-TT
- Part No: BFFAAA050BEAC
- Part No: ??????050?
- Part No: 02-ON/A 05469
- Part No: 02-ON/A 01949
- Part No: 02-N? 00689
- Part No: BAPABA080BEAA
- Part No: QNXDAAACEAFAA
- Part No: SERIAL N.:2013ONA0000296 - YQ2112BM200DA
- Part No: BEMAAD065BPAA
- Part No: BGEAAB050BPAB
- Part No: BAPACJ200BEAA
- Part No: ZVF V.FARF.DN 40 F/F MACH83 DE 316 EPDM
- Part No: ZVF V.FARF.DN 50 F/F MACH83 DE 316 EPDM seals
- Part No: ZQ1050BM100LA
- Part No: BGEAAA040BEABD
- Part No: BAAAAA080BEAA Pos.006-019 TTEZP130G1
- Part No: BAAACA040BVAA Pos.006-019 TTEZP083G1
- Part No: BAPACA032BEAB Pos.010-017 TTEBAP083G
- Part No: BAAACA040BVAA Pos.014-108-138-156-157 TTCBAP040E
- Part No: BAPACA03BEAB Pos.014-108-138-156-157- EPDM TTABAA080E
- Part No: BAAAAAA080BEAA Pos.014-108-138-156-157 TTABAA080E
- Part No: BAPACJ100BEAA
- Part No: QNE400098LAA
- Part No: RFVB007739
- Part No: RFVB007739 2 INCHES
- Part No: VVF418B100
- Part No: TPJGM04106
- Part No: TTAZQ050P2
- Part No: BGEAAR040BEAC
- Part No: TTABAP050V

- Part No: RVFB003629
- Part No: TOJTE01815
- Part No: TTCZQ100P3
- Part No: TTCBAP065P
- Part No: TTABAP080P
- Part No: TTAZY0575P
- Part No: TTCBAQ100P
- Part No: TTAYQ080P3
- Part No: BKBAAF200BPAH
- Part No: QNXDAAABAAAAA
- Part No: QNXG1AABEBAAA
- Part No: QNXF1AABEDAAA
- Part No: BEAAAB025BEBD
- Part No: QNXEAAABAAAAA
- Part No: TOFBB065002
- Part No: BBZQ
- Part No: TTABAP040E
- Part No: TTEBGE083G
- Part No: DN25 BBZS5
- Part No: DN20 BBZS5
- Part No: DN50 BBZS5
- Part No: BEAAAB065BEBI
- Part No: QNWPS0100
- Part No: Type: ZWF PN:BEAAAB065BEBF old code, new code BBZP DN65 LT EPDM W/W
- Part No: Type: ZP PN: BAAAEA065BEAB old code, new code ZVF DN65 EPDM W/W
- Part No: BBZP DN65 LT EPDM W/W
- Part No: ZVF DN65 EPDM W/W
- Part No: Repair kit for QNXEAAABAAAAA
- Part No: QNXE1AABAAAAA
- Part No: BEAAAL112BEBE
- Part No: TTABEA050E1
- Part No: BGDAAB050BEAE
- Part No: TTEBAP134G
- Part No: GIOTTO TOP 360
- Part No: QNCAA083001

- Part No: BEAAB050BEBA
- Part No: QNXEAADEBFAAA
- Part No: BCWANA050BEAAG obsolete / replaced by BCWANA050BEAA + QNXDAAABEAFAA
- Part No: TTEBCW138G
- Part No: TYPE B925
- Part No: BCWANA050BEAA
- Part No: QNXDAAABEAFAA
- Part No: TTABCW100E
- Part No: TTABAP080E
- Part No: TTABAP100E
- Part No: QNXD1AABEAFAA
- Part No: VVF418X025
- Part No: VBAA3CAA0C021
- Part No: BKAAAA025BMAAD
- Part No: VVF418B300
- Part No: VVF418B212
- Part No: VVF418X050
- Part No: VVF418X040
- Part No: VVF418S040
- Part No: BAPACB040BEAC
- Part No: Type: BBZ81EX Code: BGDAAA065BPAJ
- Part No: Kit for valve Type: BBZ81EX Code: BGDAAA065BPAJ
- Part No: TTABAP050E
- Part No: TTABAP065E
- Part No: TTABCW065E
- Part No: TTCBAP065E
- Part No: TTCBAP080E
- Part No: VVF418S025
- Part No: QNXE1AADEBFAAA
- Part No: BCWANA065BEAA
- Part No: B915PMO 4-90° TT 2
- Part No: B915PMO 4-90° TT 3
- Part No: TTEBKA207G
- Part No: QRD600050BBAE
- Part No: BEAACCC050BEBA

- Part No: QNXDAAABEDFAA
- Part No: QNXEAAAEBEFAA
- Part No: QNXDAAAADAFAA
- Part No: BC6ANX200BEAAAA
- Part No: BC6ANX300BEAAAA
- Part No: Seal kit for BBZP DN 50
- Part No: BGDAAB040BVAA
- Part No: TTABEA040E1
- Part No: TTCYQ050M2
- Part No: TTEZP130G1
- Part No: QNXAAAABAAAAA
- Part No: QNXA1AABAAAAA
- Part No: BGEAAB065BEAC
- Part No: TTABGA065E
- Part No: TTEZS083G
- Part No: Type: BBYP /BB 0002535
- Part No: BAQAAA050BPAA
- Part No: sealing for RVF8:0018404
- Part No: rubber for valve 99-01/A 03907
- Part No: Service Kit of Product Wetted Seals for High Pressure Valve DN40 LL-TT-LT-TL, TTCZQ040P2
- Part No: KIT GUARN CIL.130--156 PN.PRESS./PNE DN 80-100 NBR, TTEZP130G1
- Part No: S/N: ONA 000018 / ZQ3040BP322NA
- Part No: BKAACB040BPAP
- Part No: QNXDAAACEEFAA
- Part No: DN40 LL-TT-LT-TL
- Part No: PNE DN 80-100 NBR
- Part No: BBZP BB 0006404
- Part No: BAPAAJ200BSAA
- Part No: TTABAP050S
- Part No: CIL.108-156
- Part No: QNXDAAABBAAAA
- Part No: BBZPM-CLAMP-1+1/2"-BRK-ATEX II 2G Ex
- Part No: BBZPM-CLAMP-1"-BRK-ATEX II 2G Ex
- Part No: BAVAAA040BEAAA
- Part No: TTABCI080E

- Part No: TTABAP065P
- Part No: BEAAAB032BSBA
- Part No: BEAAAB065BSBF
- Part No: BAAAAB050BEAC
- Part No: BAPAAB050BEACC
- Part No: seal 142 for ZVS DN10--65
- Part No: BEAACI050BEBA
- Part No: TTABAP150E5
- Part No: 801491042
- Part No: BEAAX0 50BSBA
- Part No: BKAACB065BPAA