

ENDURA SUPPLY

Benzlers Product List

- Part No: 2245 5195
- Part No: A46314-2
- Part No: A46334-1
- Part No: AS 4.5-FLEXIWARP X1-5R-10
- Part No: BD58-H-N-2-50-MCH WITHOUT MOTOR
- Part No: BS 40 AL-TT 3,5:1 RH
- Part No: BS 50 42:1 43097 7
- Part No: BS 71-F-TT 28:1 LH
- Part No: 90056-0164
- Part No: BS112/63
- Part No: BS40
- Part No: BS40 AL-TT
- Part No: BS40 AL-TT 3,5:1 RH FOOD
- Part No: BS40 OSB 80 B/6 EXCH ,HTNR. 008F033799 MENGE:1 LAGERPLATZ:CT49E48&49
- Part No: BS40-6,67-M2AA71A4
- Part No: BS40-ENV-IEC71B14
- Part No: BS40F-00-VM-3-IEC 63-B14A
- Part No: BS71A
- Part No: BS71K-0-0-2
- Part No: GEARBOX BTM72-3-K-H2-0-BV (CONNECTING MOTOR 18.5KW, 1450RPM)
- Part No: J100 RL
- Part No: J100 RO
- Part No: J100 RR
- Part No: J71/72 RL
- Part No: J71/72 RR
- Part No: J71-J72 RO
- Part No: A46314-1
- Part No: REPLACEMENT FOR 10+ BS 40, 40:1
- Part No: REPLACEMENT FOR 10+ BS 40, 60:1
- Part No: TA25
- Part No: TA30
- Part No: TA400

- Part No: J52A-15- - 060 – 2 BH (Ø 60 mm H7 - Ø 38 mm)
- Part No: A48784-6 + A46314-2
- Part No: A48784-5
- Part No: BS63 D 00 P 2
- Part No: MULTIFLEX 13 20/50
- Part No: B94624-M2
- Part No: J12B
- Part No: J12B-15- - 045 – 2 --
- Part No: BD40 L U 2 220 B SM
- Part No: BS40 C IEC71 B14
- Part No: BS40 6.67
- Part No: BD66 H N 1 1100 B LS MCH90 / B14
- Part No: BS50FX
- Part No: J125-20 2 K125
- Part No: J52A/BS71
- Part No: M052245.BGC
- Part No: M052245.BACQ1 SPEC
- Part No: BS50 C O0 2
- Part No: MSBCCL90L4
- Part No: BS50 I O0 P 2
- Part No: TV021SPEC1 obsolete / alternative J21A--5—045-H2
- Part No: J21A--5—045-H2
- Part No: M073256.BGCK1
- Part No: MULTIFLEX 13 (587130001)
- Part No: B92362-1
- Part No: B92413-1
- Part No: MSBCCL90L4 + brake
- Part No: B92743-1
- Part No: J22A-C76983
- Part No: UAA248-100LB4 / BG251-MT100LB4B3
- Part No: M082228.BGCF1
- Part No: A53783 DS7
- Part No: Coupling complete for BG247
- Part No: M072220.BGCK1
- Part No: M073256.BGCK

- Part No: R002/180/A/63/EOE/N/V6.62.109.20
- Part No: K3-18HN1 63
- Part No: M052232.BGCH1
- Part No: MULTIFLEX 13 - composed of 2x A46314-1 and 1x A46334-1
- Part No: BS71 K OH-B P 3 IEC80/B14
- Part No: BA 71B4 S/N: 00061212
- Part No: BS71 K OH-A P 3 IEC80/B14
- Part No: BA71B4
- Part No: 62129
- Part No: BS40 ENV K 00 P3 IEC71/B14
- Part No: K103110.BGHC1
- Part No: A61153-1
- Part No: A43983-1
- Part No: 317090HA
- Part No: 252096005
- Part No: MS71A2 – IECB14
- Part No: BS5071B-4
- Part No: Cap for M0822-BMC-1
- Part No: 491134-007
- Part No: J110/-/15/--/110-2
- Part No: B40/BA/ IEC80B14
- Part No: BD27 L U 2 30 SM according to 5001249.005
- Part No: K073212.BMCC1A7.5A
- Part No: WAF 161M4 BRRHAR100 TF SH FL
- Part No: BDL40-L
- Part No: 644750-1/BG 244-04
- Part No: A46314-3
- Part No: A46314-4
- Part No: A48784-1
- Part No: A48784-3
- Part No: A48784-4
- Part No: A48784-6
- Part No: BTMF12 T3A90L4 B14
- Part No: BA 100LB4
- Part No: BAX112MB4/B5

- Part No: F100LB4/B5
- Part No: Outlet support adapter for BA 100LB4
- Part No: BDL40
- Part No: BD66 H N 4 80 SM MCH/BTM03-E
- Part No: 63 7.75 : 1
- Part No: BS63 A
- Part No: BD58 H U 2 250 B -MCH 100/B14
- Part No: J100-05--100-2
- Part No: BS71 K 0H-B P3 IEC80/B14
- Part No: 651169
- Part No: J100-15-?080-2
- Part No: TV72 (G10594)
- Part No: J72A-15—70-2
- Part No: J72B
- Part No: TV152 out of production
- Part No: BS40 G 00 P 2
- Part No: BD40/9868797 1
- Part No: BS88 J 30H P 2
- Part No: BD40 L U R4 150 OB PR
- Part No: BS50SPEC I 0H-A P 2
- Part No: F0642 0.37 KW
- Part No: a cut part of the shaft for 851648
- Part No: B40483-1
- Part No: 317670HA
- Part No: BD66-L-N-3-220
- Part No: BD 58-L-U-2-250-SM-SP
- Part No: BS40 K IEC71/B14
- Part No: J110-20-110-2
- Part No: MULTIFLEX 13
- Part No: J52A-15-060-2-2
- Part No: MULTIFLEX 13 (50mm)
- Part No: M13P
- Part No: C072156.FGH1
- Part No: couplings for BA 90LA4 / 06413044