

# ENDURA SUPPLY

## Ber-Mar Motors Product List

- Part No: Type:BA80AA
- Part No: Type: S712-4-B5B
- Part No: MS 711-4-B5
- Part No: Type:MS562-4-B14
- Part No: S..801-4-B5 CSA/UL 2
- Part No: S..90S-4-B5
- Part No: S..802-4-B5 CSA/UL 2
- Part No: AF.90LS4.5FBC
- Part No: AF.80.S4.5FBC
- Part No: Type:AF90LL45FBC
- Part No: AF.90SC4.5FBC
- Part No: SVF 712-4-B5 34
- Part No: SVC.71.L4.4150
- Part No: MS632-4-B14
- Part No: PAU3.71.A2\*00B
- Part No: 31.43.0051.B
- Part No: 30.08.0090.A1
- Part No: 10.05.G37255
- Part No: VS.90LS2.S000
- Part No: AF3-802-4-B5 4
- Part No: BM132V2.CAR400
- Part No: 16110197
- Part No: TB 12 FLTE
- Part No: KF 11211C34.55 H750/60 I.11F4CM34
- Part No: SVFX.802-4-B5.T651
- Part No: S..90S-2-B5CSA/UL 2
- Part No: S..632-4-B5 CSA/UL 2
- Part No: SC.112M-6-B5 CSA/UL 2
- Part No: S..90L1-2-B5CSA/UL 2
- Part No: MS 712-4-B
- Part No: S..712-4-B14 8
- Part No: PAU3.71.A2-00

- Part No: MS2 90L1-4-B5 IE2
- Part No: 10.47.3302.SW
- Part No: SX.71.S4.7065 old code / new code SX.712-4-B14
- Part No: SX.71.S4.4065 old code / new code SX.712-4-B14
- Part No: SX.712-4-B14
- Part No: SVC.90LS4.552
- Part No: AF.80.S4\*5P44
- Part No: PAU3.71.S2\*51
- Part No: SVF132M-4-B5 33ASR
- Part No: S..90L1-4-B3 7
- Part No: S3 112M-4-B3DX
- Part No: S3 100L1-4-B3DX
- Part No: S..632-4-B14 P
- Part No: AF-160LS4.5L50 KTY
- Part No: mechanical seal for PAU1.90SC2.50
- Part No: counterface for PAU1.90SC2.50
- Part No: MS100L3-4-B5
- Part No: S2.802-4-B5 PTC PA
- Part No: BN 90 S 4 FA R
- Part No: S..712-4-B5 PTC PA
- Part No: AF.802-4-B5PTCSO
- Part No: S..711-4-B5 PA
- Part No: AF.801-6-B5PTCSO
- Part No: AF.80.S4.5FBC 9
- Part No: AF.80.S4.5FBC.G
- Part No: S..801-4-B5 PA
- Part No: S..632-4-B5 PTC PA
- Part No: Mec 100
- Part No: VS80C2.0009 ISF IP54 SERS1
- Part No: SN: 1805029
- Part No: SN: 1706658
- Part No: 10.47.3003.SW
- Part No: SVF.90LC4.758
- Part No: BRAKE FOR SFV.90LC4.758 HZ.50/60
- Part No: S..801-4-B34

- Part No: ZZRA440SBR
- Part No: R080105BM
- Part No: 090MLDS001
- Part No: AF-712-4-B14 3
- Part No: VS.71.S2.0000
- Part No: S..802-4-B5 PTC PA
- Part No: PAU1.90LS2.01
- Part No: S3.132S-4-B3
- Part No: SVFC112MC4.55
- Part No: SX3..90L1-2-B5 7
- Part No: NF020-AU24-F250-90B2-SA-GI
- Part No: T2A 713-4-B5
- Part No: SV.100L-6-B3573
- Part No: 10.47.3004
- Part No: S712-414 UL2
- Part No: 251BMS632-4B14
- Part No: GV..07404E1F.70
- Part No: S..632-4-B14 V
- Part No: AF3-90L-4-B5 OCR P
- Part No: SF112L-45 UL6 AC
- Part No: VS.90LS2.V000
- Part No: S633-25 UL 36
- Part No: SVF132LL4.558S19
- Part No: electric brake for SVF132LL4.558S19 old code/ 11.063811H024 06.38.11H 24V. D.28 90 NM new code
- Part No: PAV..71.S4.00
- Part No: 11.063811H024
- Part No: 11.063811H024 06.38.11H 24V. D.28 90 NM
- Part No: MS 90L2-4-B5 not available
- Part No: S..90L2-4-B5
- Part No: SC.71.S4.4150
- Part No: MS712-4-B5
- Part No: T2A 712-4-B5
- Part No: S 712-4-B5
- Part No: 10.47.3009.2
- Part No: SVC100LS4.5058

- Part No: seal for PAU2 71.S2.00 out of production
- Part No: S3..90S-2-9601
- Part No: MS 90S-2-B5
- Part No: S 80LG4.7050
- Part No: S.100L1-2-B5
- Part No: G..06404GA3FT
- Part No: SC.71.L4.4150
- Part No: 10.47.3004.M
- Part No: SC.80.S2.7050
- Part No: SPM.90SP41500.B5
- Part No: D100LC2/4.561
- Part No: S100L2-45 R UL 2
- Part No: SVF100L2-414 BHNK