

# ENDURA SUPPLY

## BFT Product List

- Part No: BFT BGV 4.5 ARM BARRIER 230 V AC WITH 1300 RPM MOTOR COMPLETE SET
- Part No: BFT COMPASS CARD READER COMPATIBLE WITH BFT COMPASS 485 - D113704
- Part No: CAPRI TCA-RIC SN:11068002184
- Part No: CELLULA 50
- Part No: EFOR 1380 S MLN8930/10/057 ROIITF-28
- Part No: BFT TYPE"EOS120"
- Part No: Mitto B Rcb 02 R1
- Part No: Mitto B Rcb 02 R1 transmitter
- Part No: Mitto B Rcb 04 R1
- Part No: MOTEUR BFT TYPE "PHOBOS N"
- Part No: P111273 Cellula 130 receiver
- Part No: REDUCER OF BARRIER MOOVI 50
- Part No: SHOULDER FOR MOOVI 50
- Part No: SIRIO TMA
- Part No: VEGA 60/12 CSI 60NM,12RPM,230V,240W
- Part No: SUB-ER-SC-LEFT
- Part No: CELLULA130 obsolete no repl
- Part No: Intensifier 1100049-222
- Part No: TYP EFOR 1380 S 30
- Part No: D000039
- Part No: N728022
- Part No: N728038
- Part No: DEIMOS BT A400
- Part No: I100074 10001
- Part No: D573003
- Part No: B LTA 024 R1
- Part No: DESME A.15
- Part No: B EBA WI-FI GATEWAY (P111494)
- Part No: Moovi 30 BT
- Part No: toothed rack for Type DEIMOS
- Part No: DEIMOS AC A800 SL DN - 230V
- Part No: COMPACTA A20-180

- Part No: P910044 00002
- Part No: Moovi 30 S
- Part No: 1215847
- Part No: KIT REDUCTION I099708
- Part No: P4.5
- Part No: P/N: D573003
- Part No: P/N: P925207 00001, Type: SP3500
- Part No: N9400007
- Part No: D111906
- Part No: P111782
- Part No: D226041 wrong code, correct code P111782