

ENDURA SUPPLY

Convum Product List

- Part No: PCG-20-S
- Part No: PFG-3.5A-SE
- Part No: MC5-E
- Part No: PBYK-110
- Part No: PBYK-50
- Part No: NAPFTS-25-6-S-O
- Part No: MPS-V23C-NGA
- Part No: MPV3S2NVG24BL
- Part No: CVA2-15HSVDN4AL
- Part No: VF-5
- Part No: PFG-15-F
- Part No: PFTK-10-F
- Part No: PFG-3.5A-F
- Part No: CV-05HS-200BL
- Part No: SC2S05HSzzS
- Part No: MPS-V23C-C
- Part No: CSV110-4L
- Part No: CV-10HS
- Part No: MVS- 030- A W
- Part No: PCYK-60-NBR
- Part No: 10.003.040.01, D= 3,5 mm schwarz
- Part No: 10.003.040.01AS, D= 3,5 mm, schwarz antistatisch
- Part No: CONVUMB CVB-09HSCKB
- Part No: CV-20 HSG
- Part No: CV-20HS
- Part No: CV20HSCK
- Part No: CVA-15HS24AL (24AL)
- Part No: CVA-V (8326)
- Part No: CVX-1378MC22
- Part No: MC2S10HSABSM24B5R
- Part No: MC4S05HS
- Part No: MCS2S10HS

- Part No: MPS-R23C-NGA
- Part No: MPS-V23R-NGA
- Part No: MPS-V34R-NGA
- Part No: MPS-V9C-NGA
- Part No: MS6-01
- Part No: MSV-030AB-R
- Part No: MVS-030AB-R
- Part No: MYOTOKU CV30AHS
- Part No: VACCUM FILTER _ VF-3
- Part No: V-CV15HS
- Part No: VF-3 MYOTOKU/9F00034RF
- Part No: VF-3K
- Part No: VF-5 (8415)
- Part No: VF-5E
- Part No: VFL 44
- Part No: MC22S10HSABSL4BLR0610
- Part No: CKV010-4E
- Part No: MPS-78E-NC
- Part No: MPS-P3RC-GA
- Part No: SCW-4.5x3 FNN
- Part No: MC22S10HSABSL4BLR
- Part No: SC3S 15S V9P DFS WT
- Part No: MC72S25HS21C4WLR-P
- Part No: MVS 3011 063
- Part No: MPS V9C PCA obsolete, replaced by MVS-V9AC-PCA
- Part No: CKV0104E (stock)
- Part No: LV290-4E
- Part No: PJG-10-SE
- Part No: TKY-H6X8
- Part No: PB60-NBR
- Part No: MPS-V3F5-G (V3SRC-G) - not available-alternative MPS-V4F5-G
- Part No: MPS-V4F5-G
- Part No: PNG-131-N
- Part No: 10.026.032.02A
- Part No: 10.026.032.03/40

- Part No: CVB-09HSCK24BL
- Part No: MC10MPRGS404
- Part No: MC10-M4
- Part No: PBG 50 S
- Part No: PBG 75 N
- Part No: PBG 110 N
- Part No: PFG 03.5A S
- Part No: PFG 03.5A N
- Part No: PFG 05A S
- Part No: PFG 05A N
- Part No: PFG 60 S
- Part No: PFG 60 N
- Part No: PFG 80 S
- Part No: PFG 80 N
- Part No: PFG 95 S
- Part No: PFG 95 N
- Part No: PJG 60 S
- Part No: PJG 60 N
- Part No: PJG 70 S
- Part No: PJG 70 N
- Part No: PJG 80 S
- Part No: PJG 80 N
- Part No: MSL -02
- Part No: MSL -01
- Part No: MC72S25HS21C4BLG
- Part No: PS5 CM
- Part No: PS7 CM
- Part No: PS5 CF
- Part No: PS7 CF
- Part No: MSM-01
- Part No: MSS-01
- Part No: MC72S25HS21CSWLR-P 4x13
- Part No: SCW-S10
- Part No: MPS-R2M5-G
- Part No: PKG -135A-W

- Part No: PAG-20A-N
- Part No: MVS-V9AC-PCA
- Part No: PJG-50-N
- Part No: MC72S25HS21C4WLR
- Part No: CVA-V6722
- Part No: CVA-V
- Part No: PJG-15-S
- Part No: 2060058 OEM for TOYO
- Part No: MPS C35R-PCA
- Part No: PC-90
- Part No: PCG-90-N
- Part No: SGB-20-S4
- Part No: SGB-30-S4
- Part No: CVA-DN
- Part No: MC72S25HS21C4ALR-P
- Part No: MC7-E
- Part No: CVK-S
- Part No: MC72S25HSZSC4ALR
- Part No: MC72-S-25-H-S-21-C-4-B-L-R
- Part No: MC7-U
- Part No: CVK2-C201-W
- Part No: CA3-V4-6
- Part No: CA2-V4-6
- Part No: SC3-T-A
- Part No: PCG-7-SE
- Part No: CKV010-4Z
- Part No: PFTK-80-N
- Part No: PCG-7-S
- Part No: CV-15LS
- Part No: CVA2-10HS4AL
- Part No: CVA2-10HS100AL
- Part No: CVF-1-10LS
- Part No: 218000109
- Part No: CVF-E
- Part No: CV-10LS

- Part No: VF-3
- Part No: CVF-1-10LS discounted, replaced by CV-10LS +VF-3
- Part No: 218000242
- Part No: YNA0242379
- Part No: MPS-P35R-PCA
- Part No: MC22S10HSVGL4BLR
- Part No: MPS-71EA-NGHA-V
- Part No: CVF-F
- Part No: MPS-V35R-PCA#
- Part No: MC10MPRGS101CONVUM
- Part No: PFG-6A-SE
- Part No: 312700405
- Part No: PNG-116-S
- Part No: MPS-V35G-PCA
- Part No: PFG-5A-SE
- Part No: PJG-4-SE
- Part No: MCV-10HR-88
- Part No: MPS-V9AC-NCA
- Part No: NAPJYS-15-10-S-O