

ENDURA SUPPLY

Alerton Product List

- Part No: BACKTALK
- Part No: BCM ETHERNET MODULE BCM-ETH
- Part No: BCM-ETH
- Part No: BCM-ETH 715000100
- Part No: BCM-MDM 715000200
- Part No: BCM-MS/TP
- Part No: BCM-PWS 715000000
- Part No: LTBT-VLC-444
- Part No: VAV-SD2A
- Part No: VLC 1600 INPUT MODULE
- Part No: VLC-1188 (BACnet MS/TP-Feld Controller 11 UniversaleingAnge und 8 TRIACDigitalausgAnge, 8 AnalogausgAnge)
- Part No: VLC11-88
- Part No: VLC-1600 (BACnet MS/TP-Feld Controller 16 UniversaleingAnge)
- Part No: VLC16160 (BACnet MS/TP-Feld Controller 16 UniversaleingAnge und 16 TRIACDigitalausgAnge)
- Part No: VLC-16160 16 UNIVERSALEINGA,,NGE UND 16 TRIAC-DIGITALAUSGA,,NGE
- Part No: VLC-444
- Part No: VLC-550
- Part No: VLD-362-FF-W
- Part No: VLD-362W
- Part No: VLC 853 (BACnet MS/TP-Feld Controller 8 UniversaleingAnge, 5 TRIACDigitalausgAnge und 3 AnalogausgAnge)
- Part No: VLC 1000
- Part No: TCH024AVF30CRBS
- Part No: Type fan coil with 4 pipe
- Part No: Comunication Port 715000100 BCM-ETH
- Part No: Power supply module 715000100 BCM-ETH
- Part No: VLD-362
- Part No: VLD-362-FF
- Part No: MS-2000-BT
- Part No: STI-NTC10-01
- Part No: VLC-660R

- Part No: DTB/10K3
- Part No: SE25M24
- Part No: ADV7
- Part No: MVS-38-NP-24
- Part No: VLC-1188
- Part No: VLC-16160
- Part No: VLCA-1688
- Part No: 715000200
- Part No: 715000100
- Part No: 715000000
- Part No: VLC 651 R
- Part No: VLC-1600
- Part No: A/CP-D-4-GD
- Part No: EXP-2200
- Part No: BCM-PWR
- Part No: 715000300
- Part No: ACM
- Part No: A/TTM1K(50-100F)-RA-12"-4-GD
- Part No: EXP-10-12-0
- Part No: ACM010
- Part No: NTA020-040
- Part No: MS-2000H-BT
- Part No: COMPASS-1-SM
- Part No: ACM032
- Part No: VLC-444E
- Part No: ACM global controler
- Part No: SCT-NCT 10-01
- Part No: TS-1101-WA-10-AA
- Part No: BCM PWS
- Part No: TS-2108-MH-10-AA
- Part No: TS-2104-MH-10-AA
- Part No: TS-2008-PD-10
- Part No: RH-153P-NA-MA-AA
- Part No: VLC-1188-E
- Part No: VLC-1600-E

- Part No: VLC-16160-E
- Part No: TS-2012-MD10-AA
- Part No: MS4-TH
- Part No: TS-2004-FB-10-AA
- Part No: ACM064-2MS TP
- Part No: ACM064-2MS TP - since 2020 replacement for BCM-PWS, BCM-ETH and BCMMS/TP
- Part No: VLC-550E
- Part No: VLC-660RE
- Part No: VLC-853-E
- Part No: SCNT-NCT-10-01
- Part No: VAV-SD2A-E
- Part No: VAViH-SD
- Part No: H800
- Part No: X050BAA
- Part No: FLG-MODBUS
- Part No: VLC-550/D
- Part No: LU84-5101-B
- Part No: PM-590
- Part No: NG2DW1500B
- Part No: H8036-2400-4
- Part No: VLX
- Part No: MT212-2
- Part No: X100CBE
- Part No: VXIO-322-HOA
- Part No: VIP-363-HOA
- Part No: A/CO2-DUCT-C
- Part No: A/RH5-D
- Part No: A/CR-24AC
- Part No: VLC-651R-E
- Part No: MS-2100H-MSTP
- Part No: ACM032-2MSTP
- Part No: AXM-22-0-0
- Part No: VAV-SD-E
- Part No: AXM-10-12-0
- Part No: VLC-1616OZ /5234

- Part No: RH-155P-NA-MA-HT
- Part No: TS-3006-OA-10-AA
- Part No: TS-2004-GD-10-AA
- Part No: BCM-MDBS
- Part No: VAV-SD2A-E-F
- Part No: 362 FF
- Part No: TS 1050