

ENDURA SUPPLY

Alpha Product List

- Part No: 3000D2
- Part No: 025-MX1-7-050-002
- Part No: 10012179
- Part No: 10026219
- Part No: 10026299
- Part No: 220 C
- Part No: 580 D CH:414 ID:D1.10010110
- Part No: 580 D+1
- Part No: 580D WITH HANDHELD
- Part No: 604 A IN DER FREQUENZ 434 2500 MHZ
- Part No: 6159351050-77
- Part No: A 1500 EPDK
- Part No: A06B-6110-H055
- Part No: A06B-6111-H026-H550 AMP ISP26 TYPE A
- Part No: A06B-6114-H106 AMP ISV-1-150 FSSB
- Part No: A06B-6114-H211 AMP ISV 2-160 FSSB
- Part No: A4008-3S 433 MHZ
- Part No: AA4004 NC
- Part No: Alpha 580C-1
- Part No: ALPHA 607BT
- Part No: ALPHA NO 050-2,I 35
- Part No: ARTIKEL-NR. 6159351050-77 ALPHA D5
- Part No: AWR75
- Part No: HG+140 S-MF1 3-5K1-1 K00
- Part No: LK050-M01-1-111
- Part No: LK90
- Part No: LP 070S-MF1-10-1D1-3S
- Part No: LP 090-M01-10-111-000
- Part No: LP 090-M01-5
- Part No: LP 090-MO1-10-111-000
- Part No: LP 120 M01-3 111-000
- Part No: LP 120-M01-3-111

- Part No: LP_120-MF1-10-111/1FK7060-5AF71-1UGO
- Part No: LP070-MO1-5-120
- Part No: LP090 M02 50 111 000
- Part No: LP-090-M01-10-110-000 RATIO:10
- Part No: LP090-M01-10-111-000
- Part No: LP-090-M02-15-111-000 RATIO : 15 DMIL : 22
- Part No: LP090-MO1-5-110
- Part No: LP120-M01-3-111-000
- Part No: LP120-MO1-10-111
- Part No: LP155-M01-10-111-000 - replaced by LP155S-MF1-10-1L1-3S/MPL-A4540F
- Part No: LP155-M02-25-111-000
- Part No: LPB 120 MO1 10 111
- Part No: P/N TR368
- Part No: RSP 075 A02-6E25-018
- Part No: SERIE: ALPHA 600 230VAC
- Part No: SK+100 S-MF1-03-0H1-1K00
- Part No: SK0755-MF1-4-2E1
- Part No: SP + 140MC I = 5.
- Part No: SP 075S-M2-40-1C1-2K
- Part No: SP 075S-MF2-35-1C1-2S RATIO:35 SERIAL:1870112
- Part No: SP 100S-MC1-5-0G1-2K Serial No:1987537
- Part No: SP 1-40MF1-10-121-000
- Part No: SP 140-MX2-90-00/110S02
- Part No: SP+ 075-MF2-100
- Part No: SP+140-MS
- Part No: SP060S-MF1-10-0C1 / 1FT6031-XAK7X
- Part No: SP07SS-MF1-7 1C1-2S
- Part No: SP140L-600M3
- Part No: SP140M3Z-22
- Part No: SP140-MF1-041-000
- Part No: SP140MSI-5
- Part No: SP140S-MF1-10-1G1
- Part No: SP140S-MF1-3-0M1 / SGMGH-1AA _A61-11.0 KW
- Part No: SP140S-MF1-5
- Part No: SPK100-MF2-5-041

- Part No: SPK180-MF2-5-071
- Part No: STEP-500
- Part No: TK.050S-MF2-20 -5G1-1S10
- Part No: TK+050S-MF1-10-5K1
- Part No: TP 025S - MF1 - 10 - 0G1
- Part No: TP 025S-MF1-1O - 0G0-
- Part No: TP 050S-MF2-20-0E1
- Part No: TP 110-MF1-10-070/20002896
- Part No: TP025S-MF1-10060-2S
- Part No: TP025S-MF2-31-0E0
- Part No: TP025S-MF2-50,F=43,I=50,DMF 3/13
- Part No: TP025S-MF2-61-0E1 / SH100 20025644
- Part No: TP050S-MF1-5-0I1/1FT6084
- Part No: TP050S-MF1-7-0G0 GEM. SERIENNR. 2006800 ARTIKELCODE 20032034
- Part No: TP05S-MF2-35-OG1-2S SERIAL:1870125
- Part No: TPK 110S-MF2-28-OK1-1K01
- Part No: TPK010-MF2-20-041-000
- Part No: TPK025S-MF2-40-0E1/1FK704
- Part No: TPR-050S-MF2-52-OK1-1K01
- Part No: Transmitter for Alpha 580C-1
- Part No: VAG1542
- Part No: VDH 050
- Part No: ZST-200-PA5-500-012-R1
- Part No: reducer for VDH-050-MF1-28-031-0C1
- Part No: ALPHA 580B - obsolete, replaced by ALPHA 612B+100415
- Part No: PROTECTION RUBBER CAP for ALPHA-500
- Part No: TP025S-MF2-61-OE
- Part No: XP040K-MF2-16-2K1/1FK710
- Part No: 2466 SL001 / 30,5m
- Part No: 100069
- Part No: OM-5100 62Sn/36Pb/2Ag
- Part No: ID:D101010010 CH:402 FR:433.1000MHZ
- Part No: 2466 SL001 / 152m
- Part No: TP 050S-MF-10-0K0-2S
- Part No: W5 WM110

- Part No: TP025MX110
- Part No: SP 075S-MF1-7-0C0-2S
- Part No: 100415
- Part No: SP 100-MF1-7-031-000
- Part No: C-604
- Part No: Type: alphira 060-1
- Part No: TP 025S-MF1-10-0G1-2S
- Part No: TP 025Z-MX2-91 -0E0-VAC
- Part No: TK- 004S-MF2-40- 5B1-1S10
- Part No: SK-060S-MF2-16 -0C1-1S10
- Part No: TK-004S-MF1-3-5C1-1K00
- Part No: 5076C SL005
- Part No: SP100S-MF1-i10 1G1 (603700986)
- Part No: SP100.MF2-I20-1G1 (603700926)
- Part No: 612D
- Part No: 560S obsolete, replaced by ALPHA 608B
- Part No: 20029654
- Part No: SPK 060-MF2-10-131-000 Art: 20012337 SN:1226135
- Part No: 475CC
- Part No: 500
- Part No: SPK-100-MF2-10-141-00
- Part No: Type: LP 090-M02-100 111-000
- Part No: SP Lp 120S-MF-5 -111-3S , Y3850030602
- Part No: 580D-1 obsolete, replaced by ALPHA 612D
- Part No: SP 100S-MF2-16 -1E0-2S
- Part No: ALPHA 612D
- Part No: pH2000D
- Part No: 4323331
- Part No: AME816 02009
- Part No: CH063 (14MM)
- Part No: CH063-SR 6/6 (14MM)
- Part No: RX7000
- Part No: SK075S-MF1-4-2E1
- Part No: SP180-MF2-16-041-000
- Part No: 580C-2 obsolete, Comparative model ALPHA 612C-1

- Part No: ALPHA 612C-1
- Part No: P/N:SK 100S-MF2-25-4G1-1S10
- Part No: CP080-M02-50-111
- Part No: LP155S-MF1-10-1L1-3S/MPL-A4540F, Art code: 10026235
- Part No: LP 090-MO1-10-110-000 obsolete replaced by LP090S-MF1-10-1x1-000
- Part No: LP090S-MF1-10-1x1-000
- Part No: DCGK009
- Part No: DCGK010
- Part No: DCGK011
- Part No: DCGK012
- Part No: DCGK017
- Part No: 100423 Ersatz-Sender fAr: ALPHA 604A
- Part No: 100100 Ersatzsender fAr ALPHA 580A
- Part No: 541336
- Part No: SP100S_MF1_5_1G1_2S
- Part No: SP100_MF1_5
- Part No: SP100S_MF1_5
- Part No: SP100S_MF1_10_1K1_2S
- Part No: TP050S_MF2_50_0K1_2S
- Part No: A050S-MF1-10-3G0-2S
- Part No: SP 140 M1-10-141
- Part No: TPMA050S-027M-6KB1-155D-W1
- Part No: Typ: SPK+1405-MF2-20-0K1-1K01
- Part No: SP140-SF1-7