

ENDURA SUPPLY

HITACHI Product List

- Part No: VBLF-110
- Part No: VS50-40
- Part No: VS60-40
- Part No: VTFO-HKK 4P
- Part No: EHTD10A
- Part No: LQX a “ 200
- Part No: LQY a “ 100
- Part No: EH-OP05
- Part No: EH-OP10
- Part No: WF165 ZDFG-200WH ATH80D
- Part No: WF167ZDFG320WH ATH80D
- Part No: WJ200-015LF330
- Part No: WR18DBDL
- Part No: Y904582
- Part No: 467-MCBA4196
- Part No: GX22G332YD115
- Part No: KP-D20BP 1/2"
- Part No: EH-OP20
- Part No: EH-OP30
- Part No: EH-TP50
- Part No: EH-TP10
- Part No: EH-TP20
- Part No: LQY a “ 200
- Part No: EH-TP30
- Part No: EH-TP45
- Part No: EH-TP60
- Part No: EH-TP70
- Part No: LQP-510, 510V
- Part No: LWP040 PLC
- Part No: CFI-H
- Part No: SJ200-037LFR OBSOLETE
- Part No: HN10K-SG-1/2B

- Part No: EH-IOCH2
- Part No: HN10K-SG-18
- Part No: HN10K-SG-1B
- Part No: HN10K-SG-3/4B
- Part No: 4F620-20-L-DC24V-ST
- Part No: 11K4P
- Part No: NEW-HITACHI
- Part No: PX14C11VM1CAB
- Part No: 752017
- Part No: HIT326240
- Part No: RXE-4150
- Part No: 33029590-2 CPU
- Part No: DF-F700-ATE400R
- Part No: DF-F700-ATE250R
- Part No: DF-F700-ATE250LR
- Part No: DF-F600-AEF146
- Part No: EH-CB10A
- Part No: DF-F600-AEF72
- Part No: DF-F600-ATE250
- Part No: DF-F500-AAF72
- Part No: DF-F500-ACF18
- Part No: DKC-F710I-900JCM
- Part No: DKC-F710I-600JCM
- Part No: EH-CB20A
- Part No: EH-AX8I
- Part No: EH-AX8V
- Part No: EH-AX8H
- Part No: DKC-F710I-300KCM
- Part No: DKC-F710I-146KCM
- Part No: DKC-F710I-3R0H3M
- Part No: DKC-F710I-2R0H2M
- Part No: EH-XD32
- Part No: DKC-F710I-1R6FM
- Part No: DKC-F710I-400SCM
- Part No: DKC-F605I-600KS

- Part No: DKC-F605I-450KS
- Part No: DKC-F605I-400JS
- Part No: DKC-F605I-300KS
- Part No: DKC-F605I-300KM
- Part No: EH-XD64
- Part No: DKC-F605I-300JS
- Part No: DKC-F605I-146KS
- Part No: DKC-F605I-72KS
- Part No: DKC-F605I-2R0HS
- Part No: EH-CU
- Part No: EH-CUE
- Part No: EH-AY4H
- Part No: DKC-F605I-1R0HS
- Part No: DKC-F605I-200S1
- Part No: DKC-F605I-146S1
- Part No: 06931520, 17C78326 A
- Part No: DKC-F605I-72S1
- Part No: E405AHD-36D2 (R410A)
- Part No: EH-YTP32
- Part No: E605DH-59C2Y
- Part No: KIT MAINTENANCE FOR RX-S1
- Part No: KP-D20BP
- Part No: DKU-F505I-400JSR
- Part No: EH-XD16
- Part No: DKU-F505I-300KSR
- Part No: DKU-F505I-300JSR
- Part No: LCD PANEL (OF TX14D11VM1CAA)
- Part No: LMG 7420 PLFC- X, 6041 T
- Part No: SP14Q002
- Part No: SP14Q005
- Part No: SX14Q002ZZA
- Part No: SX14Q004 6053T
- Part No: DKU-F505I-146KSR
- Part No: DKU-F505I-146JSR
- Part No: 202628 (38-55700040-0|01):

Endura Supply Industrial Parts Supplier If the part you are looking for is not in the product list, please send us an e-mail or call us. Phone: +1 862 783 0519 Email: info@endurasupply.com

- Part No: DKU-F505I-72KSR
- Part No: TBOLQ-KK-31KW-4P 31KW
- Part No: TNM 5000
- Part No: TX14D11VM1CAA
- Part No: DKU-F455I-146J1
- Part No: TX14D11VM1CAA 6053T 15422
- Part No: TX14D11VM1CAA Obsolete
- Part No: DKU-F455I-72K1
- Part No: EH-YTP16
- Part No: EH-LNK
- Part No: U-2900/ PART # LH-57
- Part No: U7117 0097 003 001 5M
- Part No: EH-TP45A
- Part No: DKU-F455I-72J1
- Part No: U7117-0097-00 2.0M
- Part No: DKU-F405I-180H1
- Part No: DKU-F405I-72J1
- Part No: DKU-F405I-18J1
- Part No: U7117-0098-018-00 9.0 M
- Part No: DH45MEY 1500W
- Part No: Universal rail kit
- Part No: (2PNCT-T) T3C30X3.5
- Part No: 101091802
- Part No: 150A, 3P, AC 380V, 50 HZ, 30KA TYPE: F-225F ODER TYPE: FXK250-S
- Part No: LMG5278XUFC-00T
- Part No: 175223 (LMG5278XUFC-00T LCD SCREEN DISPLAY REV D)
- Part No: 175231 890-2430
- Part No: 175237
- Part No: 175246, F8T5
- Part No: 175247 / TX14D11VM1CAA
- Part No: 17CO7051-B
- Part No: 17CO7052-2
- Part No: 250 - 500 - 1000 - 2000 HOURS PERIODIC MAINTENANCE FILTER (FOR ZX 350)
- Part No: 250 - 500 - 1000 - 2000 HOURS PERIODIC MAINTENANCE FILTER (FOR ZX 450)
- Part No: 2PNCT

- Part No: 310S379-300-6
- Part No: 310SA01-151-7
- Part No: 326727
- Part No: 361016903
- Part No: 361093410
- Part No: 4129280
- Part No: 4TB SAS 7.2K RPM HDD LFF
- Part No: 503DH-80C2,R22
- Part No: 6.6KV / 415 V MVA POWER TRANSFORMER
- Part No: 600GB SAS 10K RPM HDD SFF
- Part No: 6264BLP10L JAPAN004801303
- Part No: 74005
- Part No: 74006
- Part No: 78001
- Part No: 8C38143-B
- Part No: 999923134
- Part No: 999953403
- Part No: A66L-0001-0286
- Part No: ABPF20S20WE
- Part No: ABPF-20S20WE
- Part No: ADA3 LM SERIES LINEER MOTOR DRIVERS ADA3-R5ML2
- Part No: AGP520A
- Part No: BS 024C obsolete replaced by BS104E
- Part No: contactor H50
- Part No: CR4-50A
- Part No: CY7C167A-35PC 0031 F 02 631203
- Part No: D740 839
- Part No: DV18DBL (2LSCK)
- Part No: DV18DBL (NN)
- Part No: DV18DL
- Part No: DWG NO:K1-31655 ITEM NO:20
- Part No: EB 1220BL 12V2.0AH - obsolete (replaced by EB12M)
- Part No: EB 1226HL 12V2.0AH - obsolete (replaced by EB1230HL)
- Part No: EB1230HL
- Part No: EB12M

- Part No: EH-150
- Part No: EH-150 (16 DIGITAL INPUT,17 DIGITAL OUTPUT)
- Part No: HITEH-PSA
- Part No: F6045GB
- Part No: F6045GR
- Part No: FL7M-3T7HD PROXIMITY SWITCH FOR REDUCTION
- Part No: G100 2-10 MPA
- Part No: G20 0.2-2 MPA
- Part No: G500 10-50 MPA
- Part No: GZGH80W 511J
- Part No: H375400/2100
- Part No: PTC STARTER FOR FETOSAT EKOVAAT (EKOVAAT 1 HP) H4820M
- Part No: H65
- Part No: HD647180XUCP8L
- Part No: HFV 110V
- Part No: HM1 106B FOR BLACKBOX (LEG LOAD WEIGHING SYSTEM) TYPE 235-034
- Part No: HM1106 for Blackbox (LEG Load Weighing System) Type 235-034
- Part No: HN27C256AG-12
- Part No: HN27C256AG-15
- Part No: HN27C256HG-70
- Part No: HN27C4096AG-10
- Part No: HN58C1001P-15
- Part No: HPV 091DS RE 18 A
- Part No: CP1270F2
- Part No: IL-SJ300E 2B026798-5
- Part No: IOC-01H 3JFEH
- Part No: JD40X32B-51.5D 1.5KW 380V 3.4A MOTOR + PUMP
- Part No: JD40X32L-50.4K
- Part No: VB-060-E2
- Part No: LMG7520RPFC OBSOLETE- REPLACED BY LMG7520RPFC-J
- Part No: LMG6382QHFR
- Part No: LMG7380QHFC (8541091A)
- Part No: LMG7380QHFC
- Part No: LMG7380-QHFC
- Part No: LMG7402PLFF

- Part No: LMG7420PLFC-X NACHFOLGER - SP 14 N02L6ALCZ / 12006171
- Part No: LQO120 S10 MINI CPU-D.
- Part No: LQP010-S10-MINI -DISCONTINUED- REPLACED BY: LQP512
- Part No: LQP120-S10-MINI -DISCONTINUED- REPLACED BY: LQP512
- Part No: LSPCT 193-230395 (16-03-02-00)
- Part No: M1-1HX
- Part No: M1-1HX S/N 960135
- Part No: M6-NFB6 / VTF0-K
- Part No: Module da TMextension Drive Box - LFF 2U x 12
- Part No: PTC STARTER FOR EKOVAAT (EKOVAAT 1 HP) MTRP 3501 T723
- Part No: PART NO:4683111
- Part No: PGM 12,5V HN27C256 HG-70
- Part No: PGM 12,5V HN27C256 HGU-85
- Part No: PO-7.5EC5
- Part No: Power Unit
- Part No: PROGRAMING UNIT _ IP8011-20
- Part No: PVD-1B-32P-11G5-4665A
- Part No: RX-S1
- Part No: HITACHI RX-SD260W
- Part No: SAE02999013357 BKO-C1730H22
- Part No: SJ300 READER HEAD + 2M CABLE
- Part No: SKU 12031464727, F10T8BL - REPLACEMENT (UNBRANDED)
- Part No: SP14N02L6ALCZ
- Part No: SP12N002 Obsolete
- Part No: ZCFW 160 R 0,5 PTH08M - (UNKNOWN TYPE)
- Part No: ZDFG200-ST ATH80D
- Part No: HL6545MG
- Part No: LMG420plfc-x
- Part No: CPU, LPU500
- Part No: DIF, LFI 500
- Part No: SDIO, LSU 500
- Part No: 6264BLP10L
- Part No: BXF-08-10-A-93
- Part No: Model No : E405AHD-36D2 VRF 410A
- Part No: SJ200-002NFEF

- Part No: MBF 28A 1F06A 852 380-053E MODEL: RAS-4HVRNE OBSOLETE, replaced by RAS-4HVNC1E
- Part No: EH-PT4
- Part No: GSS42-CS45 for GR-CH5025W
- Part No: T3C30CX3.5
- Part No: EA1200VX
- Part No: RAS-4HVNC1E
- Part No: DH 24 PB 3 OBSOLETE
- Part No: DH 24 PC 3 OBSOLETE
- Part No: DH 26 PB
- Part No: DH 26 PC
- Part No: Model: e405ahd-36d2 410
- Part No: SX14Q004 (8540276A)
- Part No: LMG7410PLFC obsolete, replaced by SP 14 N02 L6 ALCZ / 12006171
- Part No: Aloka UST-677P
- Part No: Aloka UST-9123
- Part No: LMG7420PLFC-X Rev. D (obsolete-limited availability)
- Part No: F8T5
- Part No: F8T
- Part No: LQE702
- Part No: LQE775 OEM
- Part No: 467-MCBA4189
- Part No: 467-MCBA4191
- Part No: 467-MCBA4195
- Part No: G18SH obsolete replaced by G18UBY
- Part No: AMS2500 SN 1 : 87050535
- Part No: Brocade DCX-4S
- Part No: SJ700-055HFEE
- Part No: NB616XB SJ-FB
- Part No: G18UBY
- Part No: Stop Lever for H 65 SB
- Part No: Spatmeissel
- Part No: Rotor for H 65 SB
- Part No: TBOLQ-KK-31KW-4P
- Part No: TBOLQ-KK-1KW-2P
- Part No: 3282390-C

- Part No: TFO - KK
- Part No: 451037
- Part No: DF-F850-9HGSS
- Part No: DF-F850-6HGSS
- Part No: DF-F850-4HGDM
- Part No: DF-F850-3TNL
- Part No: DF-F800-AMF600
- Part No: DF-F800-AKH600
- Part No: DF-F800-AKH450
- Part No: DF-F800-AKF400
- Part No: DF-F800-AKH300
- Part No: DF-F800-AKH146
- Part No: DF-F800-AVE3K
- Part No: DF-F800-AVE2K
- Part No: DF-F800-AVE1K
- Part No: DF-F700-AGF400
- Part No: DF-F700-AGH300
- Part No: Brushes and charcoal kit for DH 40 MR
- Part No: DF-F700-AGF300
- Part No: DF-F700-AGH146
- Part No: DF-F700-AGF146
- Part No: DF-F700-AGH72
- Part No: DF-F700-ATE1KR
- Part No: DF-F700-ATE750R
- Part No: DF-F700-ATE500R
- Part No: Model: LNC 500 oem
- Part No: 5524239-C
- Part No: GPF4-1S
- Part No: TBOLQ-K1.0KW 2P
- Part No: 090Z003
- Part No: 932.517.56 Type: WR 22SA
- Part No: TYPE: TFOA-FK 6P, MFG NO: D221158
- Part No: TYPE: TFO, FORM: KK, MFG NO: G8063009,
- Part No: LMG7420PLFC-X 5,7"
- Part No: HD647180X0CP6

- Part No: 05-0011-01
- Part No: TX14D11VM1CAB (OBSOLETE)- REPLACED BY TX14D11VM1CPD
- Part No: MPE012A
- Part No: MPE710A
- Part No: MPE411A
- Part No: MPE111A
- Part No: MPE412A
- Part No: MPE310A
- Part No: TX14D11VM1CPD--- OBSOLETE- replaced by TX14D24VM1BAA
- Part No: BS-022C2
- Part No: MS8S-HBA
- Part No: BS-022B(Obsolete, replaced by BS-022C2)
- Part No: SAE04829020330
- Part No: R6 EPM374 ETM-4120-20
- Part No: R6 EP1585-EP5M-4120-36-R0.5-W-PN
- Part No: R2 FH531 ASRM 2025-R-4
- Part No: R2 WF233 EPMT-0603TN-8 JS4060
- Part No: R10 EPSM-4200-60-R1.0-W-PN
- Part No: R3 EP371 ETM-4060-15
- Part No: R10 BCF-2018S25S
- Part No: CY9020-ZCET100CE
- Part No: CY9020-ZCET100SE
- Part No: R8 ABPF-16S16W
- Part No: ATH80D ZPFG-160-GH
- Part No: R5 EP862-EPBTS-2100-TH
- Part No: R3 EPB-EPBTS-2060-TH
- Part No: 250-141 ET175
- Part No: 261-141
- Part No: 581-144 ET156
- Part No: HUS 130, PN 3282390-C
- Part No: Optischer Sensor mit Halterung Accessorie
- Part No: Kopfhalterung komplett fAr Ink-Jet Accessorie
- Part No: Encoder/Geschwindigkeitsgeber 1024er Accessorie
- Part No: Edelstahl Wagen fAr Ink Jet Accessorie
- Part No: Fahrstrecke CIJ Installation

- Part No: AZ 060 CIJ Installation
- Part No: AcœP Installation
- Part No: YTFO
- Part No: I8981354622
- Part No: HH4629117
- Part No: HF-42211-25-H
- Part No: LQV000
- Part No: LQP527
- Part No: NCP-F LNC500
- Part No: LMG7420PLFC-X obsolete/replaced by SP14N02L6ALCZ
- Part No: LQZ500
- Part No: LWV461
- Part No: JDMT070204R JM4060
- Part No: ASMM-0732R-8
- Part No: SJ700-150HFEF2
- Part No: LWP000-CPU
- Part No: 06954204, 17C87452 A
- Part No: 17B34864A
- Part No: LQP512
- Part No: k20n-ep(obsolete. replaced by HS25-1a1b/HS25-2a2b)
- Part No: HS25-2a2b
- Part No: SX14Q006
- Part No: HS25-1a1b
- Part No: HH-4496 643 210-220-250
- Part No: HH-4683 331 210-220-250
- Part No: HYA-10501-32354-J 210-220-250
- Part No: 425-1577 210-220-250
- Part No: 263G673191 LHE 210-220-250
- Part No: TX14D11VM1CBA
- Part No: ATC-1/ITEM NO:24
- Part No: 310Q401-053
- Part No: 05-0011-00
- Part No: Halcom B1 (grease)
- Part No: MPE112A.
- Part No: MPE210A

- Part No: A160E
- Part No: JD40X32B-51,5D
- Part No: TX14D24VM1BAA
- Part No: LMG7520RPFC-J
- Part No: BS204C
- Part No: SHW73TC9G
- Part No: LQX300-Z OEM
- Part No: LQP010-Z OEM
- Part No: LQV000-Z OEM
- Part No: LQX130-Z OEM
- Part No: P/N#16/10Sa ■134a ■537
- Part No: E655DH-65D2Y
- Part No: 4387931
- Part No: ZX800 9212745
- Part No: 4449084
- Part No: SJ200-007-HFEF2
- Part No: H2T3201672S7
- Part No: TX23D12VM0CBA - OBSOLETE
- Part No: TXD11VM1CAA obsolete
- Part No: HPV116C
- Part No: 3HGSS 3282390-C 300GB 10KRPM DISK for HIS130 (alternative is 3282390-A)
- Part No: Joystick repair kit For:zax 160 lc 2005
- Part No: 870/4659548/JFP777409
- Part No: 870/JFP777414/4459548
- Part No: 3282390-A
- Part No: JD40x32B-E51,5 Motor 1,5kw 380v
- Part No: LQE720 OEM
- Part No: LQP-510, S10V
- Part No: LQP-520
- Part No: LQP525
- Part No: HSC-1540
- Part No: HSC-1580
- Part No: HSC-1021
- Part No: HSC-1041
- Part No: HSC-1081

- Part No: HSC-1281
- Part No: LQV100
- Part No: LQV020
- Part No: LQE520
- Part No: LQE530
- Part No: LQE510
- Part No: LQE515
- Part No: LQE500
- Part No: LQE502
- Part No: LQE550
- Part No: LQE560
- Part No: LQE565
- Part No: LQE540
- Part No: LQE545
- Part No: LQE546
- Part No: LQE570
- Part No: LQE575
- Part No: LQE770
- Part No: LQE740
- Part No: LQE701
- Part No: LQZ700
- Part No: LNC 500
- Part No: PLC R700 LNC 500 NCP-F OEM
- Part No: A58L -0001-0339
- Part No: NCP F LNC 500 oem
- Part No: BS104E
- Part No: YTS48AH
- Part No: RPMW1003MOEN JP4020
- Part No: 9136529
- Part No: FT-3KM F140100
- Part No: LQS a “ 200
- Part No: WJ200-015LFDN330
- Part No: JRB120-3
- Part No: SJ700-150LFF2
- Part No: WJ200-007LFDN311

- Part No: SJ-DN
- Part No: MB2-08-S
- Part No: JDMT100308R-FW-JP4120
- Part No: HN27C101AG-10
- Part No: MBM200HS
- Part No: SJ200-004NFEF2 obsolete
- Part No: HN27C256AG-10
- Part No: HN27256G-25
- Part No: E405AHD-36D2
- Part No: JD40X32A-50,75D-obsolete, replaced by JD40x32A-E50.75
- Part No: VLB-110
- Part No: Model: 32HXC01
- Part No: JD40X32M-60.4K
- Part No: JD40X32M-50.25K
- Part No: JD50X40M-50.4K
- Part No: JD40x32A-E50.75
- Part No: JD40x32B-E51.5
- Part No: JD40x32B-E52.2
- Part No: JD50x40L-E50.75
- Part No: JD50x40A-E51.5
- Part No: JD50x40B-E52.2
- Part No: JD50x40C-E53.7
- Part No: JD50x40C-E55.5
- Part No: JD65x50M-E50.75
- Part No: JD65x50L-E51.5
- Part No: JD65x50A-E52.2
- Part No: JD65x50B-E53.7
- Part No: JD65x50C-E55.5
- Part No: JD65x50C-E57.5
- Part No: JD80x65L-E51.5
- Part No: JD80x65L-E52.2
- Part No: JD80x65A-E53.7
- Part No: JD80x65B-E55.5
- Part No: JD80x65B-E57.5
- Part No: JD80x65C-E511

- Part No: JD100x80A-E55.5
- Part No: JD100x80A-E57.5
- Part No: JD100x80B-E511
- Part No: JD40x32L-E60.75
- Part No: JD40x32A-E61.5
- Part No: JD40x32B-E62.2
- Part No: JD40x32B-E63.7
- Part No: JD50x40M-E60.75
- Part No: JD50x40L-E61.5
- Part No: JD50x40A-E62.2
- Part No: JD50x40B-E63.7
- Part No: JD50x40C-E65.5
- Part No: JD50x40C-E67.5
- Part No: JD65x50M-E61.5
- Part No: JD65x50L-E62.2
- Part No: JD65x50A-E63.7
- Part No: JD65x50B-E65.5
- Part No: JD65x50C-E67.5
- Part No: JD65x50C-E611
- Part No: JD80x65L-E62.2
- Part No: JD80x65L-E63.7
- Part No: JD80x65A-E65.5
- Part No: JD80x65B-E67.5
- Part No: JD80x65B-E611
- Part No: JD100x80A-E67.5
- Part No: JD100x80A-E611
- Part No: 43743569121
- Part No: E655DHD-65D2Y
- Part No: N144200000
- Part No: EH-TP45C obsolete/ replaced by EH-TP45A
- Part No: EH-CBM03 alternative EH-32XZ04
- Part No: EH-BS11A
- Part No: EH-PSA
- Part No: EH-CPU548
- Part No: EH-CPU516

- Part No: EH-MEMP
- Part No: E656DHD-65D2YG
- Part No: HCG FA
- Part No: 4700 MFD
- Part No: EH-32XZ04
- Part No: TFO-K 0,65 KW 4P 200V Btype
- Part No: HFV 110A
- Part No: HSC6853
- Part No: T0-K 4P
- Part No: 6117ALSP-20
- Part No: LMG7525RPFF
- Part No: LMG7420PLFC-X
- Part No: 2M - T75
- Part No: RX2-SD160W
- Part No: DFS60B-S4PM10000
- Part No: MWB5RU
- Part No: 2200U 400V
- Part No: SX14Q004
- Part No: SDS-UV280
- Part No: 3285262-A DF-F850-2HGDM
- Part No: 3282390-A DF-F850-6HGSS
- Part No: MODEL:EPR-N6L
- Part No: LPU 500
- Part No: LFI 500
- Part No: LSU 500
- Part No: LPE 500
- Part No: G7C00159A
- Part No: G7B00100A
- Part No: G7B00116F
- Part No: EH-TP60 HMI
- Part No: ZS1120S1
- Part No: DS1836S1
- Part No: DS2244V1
- Part No: ZS1120S1 ACCS P1
- Part No: DS1836S1 ACCS P1

- Part No: DS2244V1 ACCS P5
- Part No: eTop 312-W
- Part No: 890-2430
- Part No: LPU-500, CPU
- Part No: LPE-500, PS
- Part No: LFI-500, DIF
- Part No: LSU-500, SDIO