

# ENDURA SUPPLY

## AO Smith Product List

- Part No: DEL-10
- Part No: DEN-40
- Part No: F42DS8A01
- Part No: SER 12MA UC17039/F
- Part No: DE2F6104K
- Part No: 48-4-100/2DS
- Part No: 6UA UC17039/F MOD AA1R5160K 240V 50HZ 0.75A 2700 RPM
- Part No: single motor fan for F42DS8A01
- Part No: AJRM35HD
- Part No: Motor fan, Double shaft for F42DS8A01
- Part No: HD46GK460
- Part No: 07408GB UC17039, MOD AA1R5160K 240V, 50HZ, 0,75AA, 2700 RPM replaced by 33-2-35ADV
- Part No: 33-2-35ADV,.
- Part No: 327P665 (OEM)
- Part No: Ser.11U U/Mod.JA2M440N
- Part No: 644108-4-01
- Part No: 644106-4-01
- Part No: JE1F034NS obsolete, replacement 33-2-100ATEFV
- Part No: 33-2-100ATEFV
- Part No: 3VH 100 LL
- Part No: SER.048106M
- Part No: F48L32A50
- Part No: 517002-091
- Part No: 511946-1
- Part No: JB2R075N
- Part No: SER. 19S U MTR MOD JE1E032NS
- Part No: 511438-008
- Part No: 512369-24
- Part No: 789806+169106
- Part No: Model:3PM 132SS 6
- Part No: (F4-S1-A1), P/N 8901-1 /

- Part No: 12407GB UC17039, MOD AA1R5160K obsolete, replaced by 33-2-35ADV
- Part No: UC17039/F MOD AA1R5160K 240V 50HZ 0.75A 2700 RPM obsolete/ replaced by 33-2-35ADV
- Part No: 22343700
- Part No: 33-2-35AD
- Part No: 512059-1
- Part No: 517153-0-91
- Part No: 7-181793-21
- Part No: 9SA UC17039/F MOD AA1R5160K.
- Part No: AA1R5160K
- Part No: AA1R5160K REPLACED BY 33-2-35ADV
- Part No: F42DS8A01, single
- Part No: MOD AA1R5160K
- Part No: Model:2624D
- Part No: S 548C54C28
- Part No: S/N UC 4833/F
- Part No: 517231-001
- Part No: 9A-BDP-U-1-BL-L-6
- Part No: 511875000
- Part No: 9241326023
- Part No: 3PM 132SS 6
- Part No: 324162-004
- Part No: 5K48MN4295x
- Part No: Water Heater 15 Gallons
- Part No: Control unit for ADM 90 J
- Part No: Reset button for ADM 90 J
- Part No: Electrode for ADM 90 J
- Part No: JA2Y030N
- Part No: F48H03A01 replaced by CENTURY D1036
- Part No: S48C54C28
- Part No: 120G TALL 750K MBH NG WHTR PWR
- Part No: 12-10173-1
- Part No: 7-193501-01
- Part No: 514374-1
- Part No: 516536-1
- Part No: 512116

- Part No: 516341
- Part No: DEL-30-5
- Part No: DEL-40-6
- Part No: JB2R077N
- Part No: F48H282B81
- Part No: JA2Y056N
- Part No: propeller for 3PM 132SS6 / 420505
- Part No: ?JB1R048N
- Part No: F48B46A50
- Part No: P56A18A19
- Part No: F48L74A50
- Part No: ECT120 obsolete
- Part No: F48G34B10
- Part No: 788700-002
- Part No: P56B62A50
- Part No: F48AB23A01
- Part No: MOD DA3J067N# 4KA48
- Part No: F48T32A50
- Part No: 8-1655364-23?SN:BW10-185 oem
- Part No: 80962
- Part No: filters for 5002059
- Part No: BFC 100 D
- Part No: 0099383005(S)\*
- Part No: 3VH 100LL 2 (833599)
- Part No: 8-966498-40 / CI4D
- Part No: EA 2-000702
- Part No: 511516-1;MODEL: D10M5A
- Part No: JF1G6726K
- Part No: F48L63A50
- Part No: F48B20A05