

# ENDURA SUPPLY

## Banner Engineering Product List

- Part No: D12SP6FVQ
- Part No: EA5E300Q ARTIKEL-NR.: 3075424
- Part No: EA5E450Q ARTIKEL-NR.: 3075425
- Part No: EA5R300PIXMODQ ARTIKEL-NR.: 3077528
- Part No: IVUTGPR25
- Part No: 3075376 Type: K50APFF100GREQP
- Part No: K50APTGRQCQ
- Part No: K50LBWXP (3087153)
- Part No: K50LGRA1YP
- Part No: K50LGRXPPB2Q
- Part No: K50LGRYNQ
- Part No: K50LGRYPPB2Q
- Part No: K50LGXXP (3077956)
- Part No: K50LGXXPPB2Q
- Part No: K50LRXXP (3077958)
- Part No: K50LRXXPPB2Q
- Part No: K50LYXXP (3077957)
- Part No: K80LGRA2YPQ
- Part No: LS10-EQDH
- Part No: LS10RQDH
- Part No: LX3ESRQ
- Part No: LX3RSRQ
- Part No: M186EQ
- Part No: M18SP6RQ
- Part No: MAQDC-815
- Part No: MQDC-415RA
- Part No: OASBFV
- Part No: OTC-1-YW
- Part No: PBPS46TMB5 ARTIKEL-NR.:3070863
- Part No: Q25-A8K
- Part No: Q25SP6FF100
- Part No: Q45 ULIU64ACR, 5-24V

- Part No: Q456EQ5
- Part No: Q45BB6LLPQ6
- Part No: Q45BB6LLPQ6, 3041033
- Part No: Q45BB6RQ5
- Part No: Q45ULIU64ACR, 3047551
- Part No: Q85BB62DLT9B
- Part No: QDE-875D
- Part No: QS186EQ8
- Part No: QS18EP6DB
- Part No: QS18VP6DQ8
- Part No: QS18VP6FF100Q8
- Part No: QS18VP6RQ8
- Part No: QT50ULBQ6
- Part No: R55FVWQ
- Part No: S186EQ ARTIKEL-NR.: 3029507
- Part No: S18SP6RQ ARTIKEL-NR.: 3029510
- Part No: SA-E12M30
- Part No: SA-M30M30-75
- Part No: SKU 13000003672
- Part No: SKU 14000003672
- Part No: SM312DQD,3026834
- Part No: SMB 30FVK
- Part No: SMB30 RAVK
- Part No: SME312D
- Part No: SOP-E12-150SS
- Part No: SSA-EB1MLGRP-12ED1Q8
- Part No: SSA-MBK-EEC1
- Part No: STBVP6Q5
- Part No: TL50BLBGYRQ 3019280
- Part No: TL50BLYALSQ 3019744
- Part No: TL50GRAQ
- Part No: TL50GRQ
- Part No: TL50GYRAQ
- Part No: TL50RAQ
- Part No: TL50RQ

- Part No: TL50RYGQ SKU 12024896581
- Part No: UC-LS10
- Part No: VTBP6Q
- Part No: WAK4-5/S90
- Part No: WWAK4-5/S90
- Part No: Q45ULIU64ACRQ6
- Part No: SM2A31RQD
- Part No: SM2A312LV
- Part No: 3027285
- Part No: PPROCAM 74937
- Part No: PLUS P4 Edge
- Part No: Presence PLUS P4 Edge 1.3
- Part No: MAE4816 & MAR4816
- Part No: BMHE4A- C/BMHL4G- C- 77380 77380
- Part No: SLSP30-750Q88
- Part No: K50LGXXPQ
- Part No: K50LWXXP
- Part No: K50LYXXP
- Part No: K50LRXALSXP
- Part No: 3066452
- Part No: MQDC-406
- Part No: SLSR14-450Q8
- Part No: SLSE14-450Q8
- Part No: OPBT3QDH
- Part No: Q25SN6FF100Q
- Part No: M18SP6DLQ
- Part No: 3032953 / MQAC-415RA
- Part No: K50RPFF100GREQP (3076007)
- Part No: 3076046 / K50APFF100YREQP
- Part No: Q45BB6LLP
- Part No: TL50GYRQ
- Part No: 68888
- Part No: 3090971 Type: IVU2PRBXC
- Part No: 3088098 Type: WLS28-2XW145DSQ
- Part No: 13893

- Part No: 18400
- Part No: 3029512 Type: RDM35
- Part No: 11335
- Part No: 28673
- Part No: 3082482 Type: LEDGB150X150PW2-XQ
- Part No: 79871
- Part No: 3064179 Type: STBVP6
- Part No: BWA-USB1WIRE-001
- Part No: 3047558 Type: Q45ULIU64BCRQ6
- Part No: 3032723 Type: SMB30A
- Part No: BRT-40X23B
- Part No: BRT-100X18A
- Part No: BRT-80X50CM
- Part No: BRT-42
- Part No: BRT-42A
- Part No: BRT-2A
- Part No: DBQEZLPTL
- Part No: QS18VP6LPQ8
- Part No: BRT-84
- Part No: BRT-2X2
- Part No: VS25EVQ
- Part No: VS2RP5RQ
- Part No: 3070230 Type: QS30LD
- Part No: TL50GYRAOSQ
- Part No: K50LGRYPQ
- Part No: MBCC-412
- Part No: T30SN6RQ
- Part No: 3091681 Type: LE250IQ
- Part No: Q25AW3LPQ3
- Part No: MQAC-406RA
- Part No: QS18VP6LPQ5
- Part No: QS30DQPMA
- Part No: 3033420 Type: T186EQ
- Part No: 3033422 Type: T18SP6RQ
- Part No: ARTIKEL-NR.: 3052519

- Part No: ARTIKEL-NR.: 3079022
- Part No: AT-FM-2A
- Part No: BT13S
- Part No: D10IPFP (62388)
- Part No: DX70N2X6S4P4M2M2 Obsolete, replaced by DX80N2X6S-PM2
- Part No: DX70G2X6S4P4M2M2 Obsolete, replaced by DX80G2M6S-PM2
- Part No: DX80N2X6S-PM8
- Part No: DX80G2M6S
- Part No: QS18VP6LDQ8 (3073045)
- Part No: R55CG1QP
- Part No: LS2TP30-450Q88
- Part No: QDE-850D
- Part No: SM312LVQD
- Part No: IA1.53SMTA
- Part No: BRT-THG-1-100
- Part No: BT210SM8M900 3024858
- Part No: T306EQ
- Part No: DX70G2X6S4P8
- Part No: DX70N2X6S8P4
- Part No: QM42VT1
- Part No: DX80N2Q45VT
- Part No: K80LGRYB4NQ
- Part No: MQDC1-530
- Part No: Q25SP6LPQ
- Part No: Q40SP6FF400Q
- Part No: SMBQ4XFAM10
- Part No: Q4XTILAF300-Q8 3094797
- Part No: IVU2RGR12
- Part No: RD35
- Part No: SBF1 BANNER MULTI-BEAM
- Part No: PBP BANNER MULTI-BEAM
- Part No: LM3 BANNER MULTI-BEAM
- Part No: NO5-Q08-AP7X2
- Part No: KOS2-ME-UND6X
- Part No: DX80G2M6S-PM2.

- Part No: 3087097 Type: DX80N2X6S-PM2
- Part No: QS12VP6DQ obsolete/alternative Q12AB6FF50Q or QS18VP6DQ8
- Part No: Q12AB6FF50Q
- Part No: R58ECRGB1Q
- Part No: 3075044 Type: R58ECRGB2Q
- Part No: LT30S1TQ (OEM)
- Part No: 3087105 Type: DX80N2X6S-PM2
- Part No: 3GA5-14
- Part No: 3061648 Type: QS18VP6CV45
- Part No: SM312LVMHS-50248
- Part No: QM42VT2
- Part No: MQDEC2-550RA
- Part No: SL030VB6YQ-65377
- Part No: 3076420 Type: T8LGRXPQP
- Part No: 3033200 Type: SMB18A
- Part No: QS18VN6LP (61627)
- Part No: SM30PRLBW/30
- Part No: SLSR14-300Q8
- Part No: LM4-2
- Part No: SBDL1
- Part No: PBT
- Part No: LM4-2M.1
- Part No: 3052519
- Part No: 3079022
- Part No: p/n: 3075424, Type: EA5E300Q
- Part No: 3075425 / EA5E450Q
- Part No: P/N: 3075376 Type: K50APFF100GREQP
- Part No: 3024983 / K50APTGRQC
- Part No: K50LGRA1YPQ
- Part No: LS10-EQDH ( 10004368 / 25092783 )
- Part No: MQDC-415
- Part No: 3031941 / Q25SP6FF100
- Part No: 3066460 / QS18VP6DQ8
- Part No: QS18VP6LLPQ8
- Part No: QS18VP6LVQ8

- Part No: 3002728 / QT50ULBQ6
- Part No: 78414 / SA-E12M30
- Part No: SMB30MM
- Part No: SU923QD
- Part No: SMA31EQD
- Part No: SM30SRL
- Part No: DS3-LD-045
- Part No: M12PDQ8
- Part No: K50RPF100GREQ
- Part No: 10487549 / 54592000
- Part No: SBRXF1
- Part No: SMA30PEL
- Part No: BWA-QD5.5
- Part No: SMBAMS70AS
- Part No: T18GRYN
- Part No: T18GRXN
- Part No: T18GRXNQ
- Part No: T18GXYNQ
- Part No: S18SN6D W/30
- Part No: PBP46UM2.5
- Part No: PIF66UMVFA
- Part No: RPA-C1-10
- Part No: PIT46UM5
- Part No: VS25EVQ-69237
- Part No: NI35-CP40-AN6X2
- Part No: EZS-1200
- Part No: EZA-MBK-13
- Part No: EZA-MBK-14
- Part No: EZA-MBK-15
- Part No: IT23P
- Part No: PBPF26UMB
- Part No: PBPS66U
- Part No: QS18EP6FPQ8
- Part No: CL50YXXPQ
- Part No: EZSS-1650

- Part No: Q126E-81524
- Part No: MQDC-530RA
- Part No: MQDC2S-815RA
- Part No: STP-MAQDC-806
- Part No: VSM4RP6R
- Part No: QDC-515C
- Part No: EZS-1350
- Part No: T18GRYNQ
- Part No: VS4RN5R
- Part No: APG30S
- Part No: T18RP6LP
- Part No: QDU-515C
- Part No: SI-QS75MC
- Part No: M186E W/30
- Part No: SI-LS83SD
- Part No: SI-LS83SRAD
- Part No: SI-LS83SE
- Part No: SI-LS83SRAE
- Part No: T86EVQ5
- Part No: Q12AB6R
- Part No: Q12AB6RQ
- Part No: Q12RB6RQ
- Part No: Q12RP6RQ3
- Part No: Q12AP6RQ3
- Part No: TL50HGQP
- Part No: K30LMXXPPB2
- Part No: K30LRXXPPB2Q
- Part No: K30LBXXPPB2Q
- Part No: K30LMXXPPB2Q
- Part No: PBPS46UMT
- Part No: DS18AP6LPQ8-79909
- Part No: MQVR3S-530
- Part No: MQDC20-530
- Part No: MQAC-450
- Part No: MQDEC-450SS

- Part No: MQEAC-630
- Part No: TL50ALS
- Part No: Q25SP6R W/30
- Part No: PIT26UHF
- Part No: S18RW3R W/30
- Part No: PIT46UM14TL
- Part No: Q10RP6RQP2
- Part No: PIL46UHF
- Part No: Q10AP6RQP2
- Part No: QS18VP6RQ5-19637
- Part No: QS18VP6RQ5
- Part No: VS25EQ
- Part No: FLX30-DM30
- Part No: SMBP4RAS
- Part No: M18GRBPQ
- Part No: DELP-1150E
- Part No: T30RGX8PQ8
- Part No: IVURDM-QDK-803
- Part No: DBQ5
- Part No: Q10AN6D
- Part No: Q10AN6DQ
- Part No: Q10RN6D
- Part No: Q10RN6DQ
- Part No: Q10AP6D
- Part No: IVU LICENSE BCR
- Part No: CSB-M1240M1241
- Part No: PIT420U
- Part No: DEC2-505C
- Part No: Q452EQ25
- Part No: PIFM46UHF
- Part No: PIF26UMFL.200
- Part No: PIF26UMFL.315
- Part No: EZA-QDR-8
- Part No: K30LXXGPQP-17559
- Part No: T30SP6R

- Part No: PIL430U
- Part No: M18GRXN
- Part No: M18GRXNQ
- Part No: IT2.83SM6
- Part No: LCF04
- Part No: PBP46UHF
- Part No: PBPF215U
- Part No: PBF26UHF
- Part No: SMBPVA16AB
- Part No: EZS-1500
- Part No: 3087097 / DX80G2M6S-PM2
- Part No: P/N: 3031934 Type: Q25SP6LPQ
- Part No: 26836 / SM312FQD
- Part No: P/N: 3087097 Type: DX80N2X6S-PM2
- Part No: P/N: 3090971 Type: IVU2PRBXC
- Part No: P/N: 3088098 Type: WLS28-2XW145DSQ
- Part No: P/N: 3029512 Type: RDM35
- Part No: P/N: 3082482 Type: LEDGB150X150PW2-XQ
- Part No: P/N: 3064179 Type: STBVP6
- Part No: P/N: 3047558 Type: Q45ULIU64BCRQ6
- Part No: 3032723 / SMB30A
- Part No: BRT-51X51BM
- Part No: 3066452 / QS18VP6LPQ8
- Part No: 3040071 / BRT-2X2
- Part No: P/N: 3070230 Type: QS30LD
- Part No: P/N: 3091681 Type: LE250IQ
- Part No: P/N: 3033420, Type: T186EQ
- Part No: P/N: 3033422 Type: T18SP6RQ
- Part No: SM312W
- Part No: P/N: 3075044 Type: R58ECRQB2Q
- Part No: 3087105 / DX80N2X6S-PM2
- Part No: P/N: 16557, Type: 3GA5-14
- Part No: P/N: 3061648 Type: QS18VP6CV45
- Part No: P/N: 3076420 Type: T8LGRXPQP
- Part No: P/N: 3033200 Type: SMB18A

- Part No: P/N: 3078860 Type: DX80N2X6S0P0M4M4
- Part No: MQDC2S-815
- Part No: P/N: 3800137 Type: DXM100-B1R3
- Part No: P/N: 3095667 Type: DX80N2X6S-P6
- Part No: P/N: 94597 Type: QM42VT1
- Part No: P/N: 95664 Type: BWA-BK-001
- Part No: PIT26U
- Part No: PKG6Z-2
- Part No: P/N: 67380 Type: LT3BDLV
- Part No: P/N: 96352, Type: QT50R-EU-AF2Q
- Part No: 3801918 / Q4XTKLAF600-Q8
- Part No: WLB92X1100PBQ
- Part No: XS2RO
- Part No: M12FTH4Q
- Part No: DXM100-B1R3
- Part No: BWA-BK-001
- Part No: DX80N2Q45TH-NB
- Part No: DX80N2Q45VT-NB
- Part No: Q4XTULAF300
- Part No: P/N: 94773, Type: LMBWLS27SP
- Part No: P/N: 3036393 Type: S186ELDQ
- Part No: TL50CGYRAQ
- Part No: MQDEC3-530SS
- Part No: BWA-BK-008 (802370)
- Part No: QDE-815D
- Part No: SMBWLS28RA
- Part No: LTF12IC2LDQ
- Part No: P/N: 3029409, Type: S186E
- Part No: P/N: 3029408, Type: S18SN6R
- Part No: P/N: 3033421, Type: T18SN6RQ
- Part No: 87489
- Part No: 87490
- Part No: Q453E
- Part No: 80458
- Part No: OTBA5QD

- Part No: MSR4024Y
- Part No: MSE4024Y
- Part No: MQDEC2-415
- Part No: 20 FT
- Part No: S22AMTSGHT
- Part No: 85068
- Part No: 805002
- Part No: 72154
- Part No: SOK-TL50-150SS
- Part No: 18348 / AHC2158496
- Part No: 807139
- Part No: 807138
- Part No: 2879
- Part No: TL700YRA
- Part No: 32311 / PVL500PQ
- Part No: Q3XTBLD-Q8
- Part No: 25620
- Part No: 10137 / SA-M30TE12
- Part No: 10443 / SOP-E12-150A
- Part No: 37628 / Q45AD9DLQ
- Part No: 32470 / T18SP6FF50
- Part No: 26892 / SM312WQD
- Part No: WLS28XW285XQ
- Part No: 3029988 / SSA-EB1PLXR-12ED1Q8
- Part No: 3085064 / XS26-2DE
- Part No: 29510 / S18SP6RQ
- Part No: 801976 / PGIRS66U-100
- Part No: 87576 / DF-G3-PS-2M
- Part No: 20065 / IAT23PMSS
- Part No: SX5-B
- Part No: QS18VP6LLPQ5
- Part No: PBA
- Part No: SC10-2ROE
- Part No: Q12RB6RQ5
- Part No: Q126EQ5

- Part No: 3077763 / Q20NLP
- Part No: SMBQ20L
- Part No: SLLP23-420P88
- Part No: 61631 \ QS18VP6LPQ
- Part No: 89583 \ SLLP40-910P55
- Part No: B-TL70-Q8
- Part No: MQDC1-506
- Part No: 3087105 / DX80G2M6S-PM2
- Part No: AB60D100
- Part No: K30LGRYP
- Part No: SLSP14-1500P88
- Part No: SLSP14-450P88
- Part No: K30LGRXPQ
- Part No: 3025366 / QT50R-EU-AFH
- Part No: 3061636 / QS18VP6LV
- Part No: P/N: 71817, Type: LX24RQ
- Part No: P/N: 71802, Type: LX24EQ
- Part No: SME312LPCQD
- Part No: 3072132 / Q12RB6LPQ
- Part No: BRT-44X29A6
- Part No: OPBT2QDH
- Part No: 3071817 / LX24RQ
- Part No: 3071802 / LX24EQ
- Part No: 45LM58
- Part No: Q45BB6FQ5 (38667)
- Part No: IAT23S
- Part No: SSA-EB1P-02
- Part No: TL50B-GYRAQBSZ
- Part No: SMBQ4XFAM12
- Part No: MAR4816PX485Q
- Part No: WLH60XW640B
- Part No: T30R-1515-KIQ
- Part No: EZ-SCREEN TYPE 2
- Part No: BWA-BK-013
- Part No: P/N: 71561, Type: QS30EXQ

- Part No: MQDC-4506SS
- Part No: RSD1QP
- Part No: LTF24IC3LDQ
- Part No: BRT2\*2
- Part No: MQDC2S-815 \ 3070976
- Part No: 3076959 / K50LGRYBWPQ8
- Part No: 3070976
- Part No: SI-MAGB2SM
- Part No: QCM50
- Part No: 79217 / SLM20B6
- Part No: 3002661 / LX3EQ
- Part No: TL50BLW1G1B1Y1R1Q
- Part No: STP-14 - 30 MM
- Part No: SM312D
- Part No: LT3PUQ-79783
- Part No: SM912LVAG
- Part No: QDEG-8100D
- Part No: OTBVN6
- Part No: P/N: 58979, Type: BRT-84
- Part No: MQDEC2-515
- Part No: T30SN6R W/30 EZ-BEAM
- Part No: T306E W/30 EZ-BEAM
- Part No: LTF12IC2LDQ-M
- Part No: MQDEC2-506
- Part No: K50L2RGBKQ
- Part No: K30APT2FXBF2QP
- Part No: S18-2VPDL-Q8
- Part No: 88407
- Part No: SM312FQD
- Part No: MPC3
- Part No: TL50B-GYRQBSZ
- Part No: VSM-2M5APD100-2M
- Part No: 27060 / SE61RNCMHS
- Part No: 25971 / SE61EMHS
- Part No: TL70BGYRAPQ

- Part No: SOK-TL70-150A
- Part No: MAQDC-830
- Part No: MAQDC-8125
- Part No: STBVR81 / 64190
- Part No: QS18EP6XLPCQ5
- Part No: EA5E600Q
- Part No: EA5R600PUXMODSRLCQ
- Part No: 45LM5
- Part No: 3092336 / TL70GYRQ
- Part No: FIC-M12F4
- Part No: S18SP6DLQ
- Part No: 3002667 / LX3RQ
- Part No: 3077761 / Q20PLP
- Part No: 810628 / S15C-I-MQ
- Part No: 812240 / DXMR90-X1
- Part No: 812041 / R45C-B22-SQ
- Part No: 3096764 / K50APT2GRYF2Q
- Part No: 3097183 / VELC85-BG
- Part No: 3097184 / VELC85-PC
- Part No: TL50
- Part No: 3047553 / Q45ULIU64ACRQ
- Part No: PTL110S-FF100TD3-QP150 / 805482
- Part No: DELPE-81D
- Part No: LPA-MBK-11
- Part No: WLB32-1130PBQ
- Part No: 3087484 / WLB32C1130PBQ
- Part No: NV5-Q08-ANY-73194
- Part No: TUR3802557
- Part No: S30SP6RQ
- Part No: S306EQ
- Part No: 51127 / AHC1929749
- Part No: 83214 / AHC1965454
- Part No: 4 per ■EC 61496
- Part No: SMB30SC
- Part No: T18-2NAELIR-Q8

- Part No: T18-2VPRL-Q8
- Part No: T186EQP
- Part No: T18SP6RQP
- Part No: 3029508 / S18SP6DQ
- Part No: 3053981 / Q45VR3LV
- Part No: MBCC2-506
- Part No: SM91RFQD
- Part No: 65963
- Part No: 36150
- Part No: 25530