

ENDURA SUPPLY

Beta Sensorik Product List

- Part No: R3V-PR1C-60-100-S
- Part No: 13B-Q10TSI-PS6K
- Part No: 16B-Q10TSI-PS6K
- Part No: D9284/1004
- Part No: DW3040-RG3-S2-DW27232
- Part No: EW-M3-O-M
- Part No: EW-M5-O-M
- Part No: GLSL 80 BDP-OBSOLETE REPLACED BY "OE27131"
- Part No: I4B-BM12CI-PS6K-S
- Part No: LO00610 VDC-G1-SA
- Part No: LO02010 TYP:KS19-G-3
- Part No: LO02012 TYP: KM19-G-3
- Part No: M120A-BM12CI-PS6K-S. (BS22027)
- Part No: M120A-M18CI-PS6K-S OR M120A-BM12CI-PS6K-S
- Part No: M120A-M18CI-PS6K-S obsolete replaced by M120A-BM12CI-PS6K-S
- Part No: M90A-BM12CI-PS6IK-S/TA200
- Part No: M90A-BM12CI-PS6K-S/TA 200
- Part No: M90A-M12A-N-S-DB/1M/5POL obsolete, replaced by M90A-BM12A-N-S-DB/0,8m/5pol
- Part No: MMZ9999
- Part No: NM22454 M3V-A8A-PS6K-S/K53
- Part No: TYP: VLK08-2 ARTNR.: Z770023
- Part No: V8BP02
- Part No: V9BP
- Part No: VLK50-5
- Part No: VLK51-5
- Part No: ZU50077
- Part No: 09264/1104
- Part No: Cabels for 09264/10004
- Part No: M3V-PR1C-PS6K-S (NM22252)
- Part No: 7003833 obsolete replacement M3V-PR1C-PS6K-S
- Part No: VLK50-20
- Part No: SKI-FSA-M30-P-nb-X-PBT-Y2

- Part No: M3V-KET-PS6-S/500
- Part No: NM22454 Type: M3V-A8A-PS6K-S/K53
- Part No: M90A-BM12A-N-S-DB/0,8m/5pol
- Part No: OE070907 Type: EWM-M3-0-M
- Part No: RLV74BHPRT78 obsolete, replacement OT27047 Type: RT-78-0-MHP
- Part No: OT27047 Type: RT-78-0-MHP
- Part No: IPS4-S1PO25-3U8
- Part No: IPS4-S06PO25-3U8
- Part No: I1,5B-6,5TSI-PS6K/44
- Part No: VDC-AP-S obsolete, replaced by VDC-AP1-S
- Part No: VDC-AP-M obsolete, replaced by VDC-AP1-M
- Part No: V9BP - 01
- Part No: DP2-42E
- Part No: GLS-120BP/R
- Part No: GLS-50BP/R
- Part No: NI21561 - I40B-Q80CI-PA6K-S
- Part No: M3V-KEA-PS6-S
- Part No: BS22036 Type: M90A-BM12CI-PS6K-S
- Part No: EW-M3-0-M/500mm