

ENDURA SUPPLY

Binks Product List

- Part No: 101-1145
- Part No: 102-1716
- Part No: 102-1759
- Part No: 102-1765
- Part No: 102-1766
- Part No: 102-1780
- Part No: 102-1803
- Part No: 102-1807
- Part No: 102-1808
- Part No: 102-2202
- Part No: 107071
- Part No: 107-1181
- Part No: 114-01108
- Part No: 140 B
- Part No: 183G
- Part No: 192294
- Part No: 192626
- Part No: 20 - 6257
- Part No: 20-2369-5
- Part No: 2101-4307-9GW
- Part No: 250636
- Part No: 250640
- Part No: 250645
- Part No: 250647
- Part No: 31-396
- Part No: 41-10279
- Part No: 41-10285
- Part No: 41-13831
- Part No: 41-13835
- Part No: 41-13852
- Part No: 41-13880
- Part No: 41-13887

- Part No: 41-1456
- Part No: 41-1531
- Part No: 41-1538
- Part No: 45GPM-19 11 64 45 GPM
- Part No: 54-5447
- Part No: 5454-4960
- Part No: 71-133 (GO7021) 1/2" ID
- Part No: 80-651 not available for sale in EU, no ATEX
- Part No: 81-810
- Part No: 818831
- Part No: 83C-210-B
- Part No: 841001 - UNKNOWN MODEL
- Part No: 84-345
- Part No: 84-407
- Part No: 86-949
- Part No: 873 611 + 873 612
- Part No: 873076
- Part No: 873077
- Part No: 873086
- Part No: 873087
- Part No: 873106
- Part No: 873107
- Part No: 873241
- Part No: 873351
- Part No: 873352
- Part No: 873353
- Part No: 94507
- Part No: 95-A
- Part No: A260220 - UNKNOWN MODEL
- Part No: A260880 - UNKNOWN MODEL
- Part No: AB70 90L 4 - unknown product
- Part No: DX70R3-CG
- Part No: E2-15/162850
- Part No: E2-15/192829
- Part No: E2-30/192680

- Part No: E2-40&30 /162600
- Part No: E2-40/192755
- Part No: ES TC 13-9-1590
- Part No: EXTENSION EAX 84a ■ (J2XAA1)
- Part No: MACH 1A HVLP AUTOMATIC AIR SPRAY GUN A~2,3MM
- Part No: MACH 1SL HVLP SPRAY GUN A~2,3MM
- Part No: N26070021 - UNKNOWN MODEL
- Part No: PAINT GUN
- Part No: PRESSURE CUP FOR MACH 1SL
- Part No: PTL 412 K8
- Part No: QMS 444 CE
- Part No: QMS 445 CE
- Part No: QS-5003
- Part No: QS-5012
- Part No: QS-5012-CE
- Part No: F-QS-5012-CE
- Part No: 95 1/4" NPSM HOSE CONN
- Part No: 104010
- Part No: 104009
- Part No: 104053-C-C
- Part No: Repair kit for 104053-C-C
- Part No: Repair kit for 104009
- Part No: Repair kit for 104010
- Part No: 103027 / Model 460
- Part No: 250576
- Part No: 250567
- Part No: DVP-515
- Part No: KK-4630
- Part No: 114-01516
- Part No: AA44U10MB - unknown product
- Part No: MX 4/32 - incomplete model
- Part No: 88-423
- Part No: 818836
- Part No: 862004
- Part No: 862045

- Part No: 873138
- Part No: 873295
- Part No: 873412
- Part No: DX70R3-PF
- Part No: DX70R3-PFA
- Part No: SRIPRO-100-HS-K
- Part No: SRIPRO-200-10-K
- Part No: SRI-478-K12
- Part No: SRI-3-K
- Part No: SRI-401-K
- Part No: SRI-402-K
- Part No: GTI-213-12-K
- Part No: GTI-413-K
- Part No: GTI-404-K
- Part No: 2465-16HV-32S0-E
- Part No: 2465-18HV-32S0-E
- Part No: 2466-18HV-32SG
- Part No: 1466-12HV-CS1-E
- Part No: 2465-18HV-32SO
- Part No: 2465-16HV-32SO
- Part No: 192668
- Part No: 84-409
- Part No: E2-30
- Part No: 114-01306
- Part No: 191192
- Part No: 862040
- Part No: 250610
- Part No: 84330
- Part No: DX 100 (alternative is DX70N-FF-2)
- Part No: DX70N-FF-2
- Part No: 161994
- Part No: 160513
- Part No: 171788
- Part No: 192382
- Part No: 2K-2080 OBSOLETE

- Part No: Diaphragm Repair Kit For:41-818831
- Part No: 818822
- Part No: 862020
- Part No: 862003
- Part No: 862025
- Part No: GEMINI I-1" SS
- Part No: Typ: m1g OBSOLETE- ALTERNATIVE ADV-G513-20 (BRAND: DeVILBISS)
- Part No: 1-Liter Beccher fAr m1g
- Part No: Reparatur set fAr m1g
- Part No: Ersatznadel fAr m1g
- Part No: ErsatzdAse fAr m1g
- Part No: ErsatzsprAhkopf fAr m1g
- Part No: ES TC 13-9-1550
- Part No: 72-1681
- Part No: 162662
- Part No: DR205E-MX2206D0PRU-2-S05MEB-MX22060PU-SMB OUTFIT
- Part No: 72-1333
- Part No: 250626
- Part No: 250628
- Part No: 250627
- Part No: 183S-210-CE
- Part No: Model 61 obsolete, alternative model 21
- Part No: 6220-8118-5 - 21 GUN 59BSS-252
- Part No: 6220-8219-1 - 21 GUN 59CSS-262
- Part No: 192633
- Part No: 192579
- Part No: 41-3300
- Part No: 41-3304
- Part No: 193476
- Part No: 194596
- Part No: 193624
- Part No: 193623
- Part No: 192939
- Part No: 0110-009132
- Part No: 0114-014530

- Part No: 0114-014734
- Part No: 0114-018597
- Part No: 0114-016006
- Part No: 191179
- Part No: 80-601 not available for sale in EU, no ATEX
- Part No: 80-619
- Part No: 105-1084-2
- Part No: 861075 Repair Kit
- Part No: lid for gun Type M1 a "G HVLP
- Part No: FX88PU-CMH
- Part No: 162781
- Part No: 193478
- Part No: 193685
- Part No: 161451
- Part No: 193164
- Part No: 193166
- Part No: MACH 1A HVLP Obsolete Replaced by CBA1-513-12
- Part No: PT-78-K60
- Part No: 140-B (6530-0000-1)
- Part No: 114-01314
- Part No: 207902BF obsolete, alternative 207902 BF-W
- Part No: 207902 BF-W
- Part No: 83C-211-CE
- Part No: 2101-4307-9
- Part No: 41-818831
- Part No: 83C-210CE
- Part No: Part No: 84-345
- Part No: 6469-2800-7
- Part No: EXTENSION EAX 84" (J2XAA1)
- Part No: MACH 1A HVLP AUTOMATIC AIR SPRAY GUN Ø2,3MM
- Part No: MACH 1SL HVLP SPRAY GUN Ø2,3MM
- Part No: QS-5012 obsolete, replaced by 31-452
- Part No: Repair kit for 104053-C-C - not available
- Part No: Repair kit for 104009 - not available
- Part No: Repair kit for 104010 - not available

- Part No: DVP-515 Obsolete
- Part No: 1-Liter Beccher für m1g
- Part No: Reparatur set für m1g
- Part No: Ersatznadel für m1g
- Part No: Ersatzdüse für m1g
- Part No: Ersatzsprühkopf für m1g
- Part No: lid for gun Type M1 –G HVLP
- Part No: 350188
- Part No: 843000
- Part No: 336191
- Part No: 83-2099
- Part No: 83-3032
- Part No: 83-2111
- Part No: 83-2110
- Part No: 83-2107
- Part No: 250625
- Part No: DXK-288
- Part No: DXK-287
- Part No: DXK-286
- Part No: DXK-289
- Part No: DX200
- Part No: 250768
- Part No: 250686
- Part No: 250687
- Part No: 250603
- Part No: 46-6020
- Part No: 45-6701
- Part No: 47-768
- Part No: 104010-N
- Part No: 104050P-C-C
- Part No: 72577
- Part No: DXK-222
- Part No: DXK-223
- Part No: DXK-224
- Part No: DXK-225

- Part No: 192822
- Part No: 192629
- Part No: 165972
- Part No: 192628
- Part No: 183S-510
- Part No: (old) 818822 has been superseded by P/N 41-818822 (new)
- Part No: 41-818822
- Part No: GEM2-D2D1D11
- Part No: 202-55-4
- Part No: Cover for GEM2D-2D1D11
- Part No: 104016
- Part No: 41-4456
- Part No: 250681
- Part No: 250620
- Part No: 250608
- Part No: 250619
- Part No: 250618
- Part No: 41-718855
- Part No: 41-718856
- Part No: 41-718857
- Part No: 104017 (EU number)
- Part No: 102-3602
- Part No: 20-4542-K5
- Part No: 20-6473-K5
- Part No: 20-6296-K5
- Part No: 20-6474-K5
- Part No: 102-2448
- Part No: 102-2421-K5
- Part No: *207-11196-1-K25
- Part No: 104018-32
- Part No: 104-058
- Part No: 0115-010219
- Part No: Nozzle for MACH 1 HVLP
- Part No: Cap for MACH 1 HVLP
- Part No: KK-4631

- Part No: KK-4633
- Part No: KK-4634
- Part No: 204043
- Part No: 107732
- Part No: 162570
- Part No: 250461
- Part No: 250472
- Part No: 162584
- Part No: 167184
- Part No: 191163
- Part No: 187020
- Part No: 191504
- Part No: 191180
- Part No: 250442
- Part No: 204233
- Part No: 162284
- Part No: 6100-1808-9
- Part No: 80-617
- Part No: 250483
- Part No: 250529
- Part No: 250446
- Part No: 162702
- Part No: 183S-523
- Part No: PTL-408-K20
- Part No: 104048
- Part No: 0115-010337
- Part No: DX200SN
- Part No: DX200AN1
- Part No: 6-272
- Part No: 31-452
- Part No: 72-83030
- Part No: repair kit for AA4400A
- Part No: High pressure filter for AA4400A
- Part No: 114-01516T
- Part No: QS-576-H

- Part No: 54-744
- Part No: 54-3009
- Part No: 54-2524
- Part No: 54-759
- Part No: 54-760
- Part No: 54-753
- Part No: 85-470
- Part No: 102-2138
- Part No: 71-7687
- Part No: Ref. No. 31
- Part No: Reference No. 33 / QMS-447
- Part No: Reference No. 39 / KK-5042
- Part No: Reference No. 40 / QMS-5
- Part No: QMS-431-CE
- Part No: 83C-220
- Part No: 0114-013448
- Part No: 46-6002
- Part No: DX200 /diaphragm set
- Part No: 873098
- Part No: QS-4016
- Part No: diaphragm damper for 104009
- Part No: TYP 250620
- Part No: 192631
- Part No: 192632
- Part No: DXK-202
- Part No: DX70N-FM-1
- Part No: DXK-1
- Part No: DXK-2
- Part No: DXK-3
- Part No: DXK-4
- Part No: DXK-14
- Part No: DXK-15
- Part No: Disposable container for 183S-15XX
- Part No: rebuilt kit for 107052
- Part No: QS-PS75TP30K

- Part No: 160285
- Part No: 160320
- Part No: 161607
- Part No: 166000
- Part No: 187994
- Part No: 189736
- Part No: 502373
- Part No: 502514
- Part No: 502375
- Part No: 502891
- Part No: 502509
- Part No: 502928
- Part No: 502681
- Part No: 502682
- Part No: 502512
- Part No: 502511
- Part No: 502814
- Part No: 192765
- Part No: ITW104010
- Part No: 41-818830
- Part No: P/N: 41-718855, Type: repair kit for 41-818822
- Part No: 83-2923
- Part No: 250020
- Part No: 181066
- Part No: 181065
- Part No: 71-7797
- Part No: 71-2732
- Part No: 207-10161
- Part No: 207-10699
- Part No: 207-10176
- Part No: 207-10338
- Part No: 207-10195
- Part No: 237-296
- Part No: PT-418-CE
- Part No: 250535

- Part No: 187576
- Part No: 250563
- Part No: 2100 GW
- Part No: 71-7797 H
- Part No: 814410
- Part No: HAR-511
- Part No: 192392
- Part No: 192862
- Part No: 6220-5123-7
- Part No: 41-718854
- Part No: 41-718861
- Part No: 861070
- Part No: 20-1820
- Part No: 41-298
- Part No: 250524
- Part No: KK-4632
- Part No: 52-2410
- Part No: 04PV120-093VP
- Part No: 11B 106855
- Part No: 04PV150-093VP
- Part No: 04PV120-053VP
- Part No: 04PV090-093VP
- Part No: 46-2302 - 302SS
- Part No: 20-5052-5
- Part No: 20-3600
- Part No: 54-723-5
- Part No: 102-347
- Part No: 54-2418
- Part No: 54-2419
- Part No: 54-722-5
- Part No: 2-28-5
- Part No: 237-94
- Part No: 237-101
- Part No: 237-103
- Part No: 237-105

- Part No: 237-90
- Part No: 237-86
- Part No: 237-88-K5
- Part No: 71-1201
- Part No: 71-1203
- Part No: 71-7686
- Part No: set of nozzles for larger fraction (200,500,800) for model 105-1084
- Part No: DXK-216
- Part No: DXK-213
- Part No: DX200AN
- Part No: 107757-Y-Y
- Part No: HGB-509-5-R38
- Part No: DXK-203