

ENDURA SUPPLY

BODINE ELECTRIC Product List

- Part No: 22B3BEBL/SR-Z3
- Part No: 33A3BEPM-Z2
- Part No: B23801002
- Part No: B26800103
- Part No: B26801036
- Part No: B49200048
- Part No: B51421781
- Part No: B51421802
- Part No: B57400008
- Part No: B59300008
- Part No: BE0850
- Part No: J06550020,24A4FEPM-Z4
- Part No: COUNTER SPRING FOR 42Y4FEPM-E2
- Part No: TYPE NSE-13,S/N Z00240096
- Part No: MODEL NO:850
- Part No: 22B2BEBL-D3 (BE3329)
- Part No: SN: K5K0005D0015 (OEM)
- Part No: 9175CQ0026
- Part No: 33A3BEPM-5R
- Part No: BE0865
- Part No: BE0866
- Part No: 77820 215 D/C 9849 obsolete
- Part No: PN : '0187 24A-D
- Part No: 33A5BEPM-GB
- Part No: 42R6BFPP-FX3
- Part No: 24A2BEPM-D3
- Part No: BE0866 Type: UPM-3318C
- Part No: L5K0012L0032 OEM
- Part No: Typ: UPM-3318C Artikel-Nr.: BE0866
- Part No: KYC-24A2 OEM
- Part No: 42A5BEPM-5N

- Part No: Type 42D3BEPM-E4, Serien-Nr. 173KD6067 obsolete, alternative BE5047 Type: 42A5BEPM-FX4
- Part No: BE5047 Type: 42A5BEPM-FX4
- Part No: 42R5BFCI OEM
- Part No: NSH-11 D3 obsolete
- Part No: KYC-24.
- Part No: Type: 42A7BEPM-F2 S/N: 4190PPKN0013 - obsolete, alternative - Typ: 42A5BEPM-FX2
- Part No: Type: 42A5BEPM-FX2 (Art. Nr. BE5041)
- Part No: Type 42A5BEPM-E3 obsolete, replaced by 42A5BEPM-FX3
- Part No: BE5044
- Part No: 22B3BEBL/SR-Z3 oem
- Part No: 33A3BEPM-Z2 Art. Nr. BE6165
- Part No: REPLACEMENT COUNTER SPRINGS FOR S/N Y0583D0052 TYP 42Y4FEPM-E2
- Part No: 193
- Part No: P/N: BE0866 Type: UPM-3318C
- Part No: Type 42D3BEPM-E4, Serien-Nr. 173KD6067
- Part No: P/N: BE5047 Type: 42A5BEPM-FX4
- Part No: 30R2BECI-D3
- Part No: S/N: 0666NXLH0012 obsolete, alternative BE2253
- Part No: BE2253
- Part No: 42R6BFPP-F2 see identical in construction P/N: BE2262 Type: 42R6BFPP-FX2
- Part No: P/N: BE2262 Type: 42R6BFPP-FX2
- Part No: 57400008
- Part No: 5043
- Part No: V138576.B01
- Part No: 22B4BEBL/SR-3N oem
- Part No: 30X1BECI-D6 OEM FOR MUNTERS CARGOCAIRE
- Part No: 33A3BEPM-Z2 (V5K0083D0070 - P/N 397-92427)
- Part No: 49200048
- Part No: S57400008
- Part No: 33A5BEPM-5F
- Part No: 34R4BFPP-FX1
- Part No: 24A2FEPM
- Part No: 33A5BEPM-W2
- Part No: 34R6BFCI
- Part No: 33A3BEPM-Z3

- Part No: 2250 Type: 34R4BFPP-E4
- Part No: 42A-FX
- Part No: UPM-3318C
- Part No: 42R5BFSI-FX3
- Part No: BSL 722
- Part No: 42X5BFCI-E2 OEM
- Part No: 24A4BEPM-D3
- Part No: 49300034
- Part No: B49201010
- Part No: B49301001
- Part No: 494 01156
- Part No: 6168
- Part No: KYP-26
- Part No: 49200032
- Part No: 49300037
- Part No: P/N: 6167, Type: 33A3BEPM-Z2
- Part No: 48X5BFCI-F2
- Part No: 24A4BEPM-3F
- Part No: 6037
- Part No: 42A5BEPM-FX4
- Part No: 187
- Part No: 34R6BEPP-Z3
- Part No: 6738
- Part No: N2253
- Part No: MODEL 6016
- Part No: 42R6BFCI-FX4
- Part No: 33A5BEPM-WX2
- Part No: 33A5BEPM-WX2 / 180 RPM
- Part No: 42R6BFPP-5N
- Part No: 42A5BEPM-FX4 Model: 5069
- Part No: TYPE: 34R4BFCI-3F
- Part No: N1671
- Part No: N1669
- Part No: 6024
- Part No: 6034

- Part No: TYPE 42X3BFSI-5L
- Part No: Type 42A5BEPM-E3 (S/N:4183KWIJ0024)
- Part No: Nr. BE5044 Typ: 42A5BEPM-FX3
- Part No: 2-A2BEPM-D3
- Part No: 5681
- Part No: 0655 1/6HP 28RPM, 115V
- Part No: 42A3BEPM-E4
- Part No: Art-Nr.: BE5049 Type:42A5BEPM-FX4
- Part No: BE5045 42A5BEPM-FX3
- Part No: p/n: 2673, Type: 42R-5L/H
- Part No: V-10R / U0422043 OEM
- Part No: 42X5BF-C1E2
- Part No: 34R4BFCI-Z3 #12805
- Part No: TYPE NSE-13
- Part No: BE3863
- Part No: 42A5FEPM-FX3
- Part No: 42A5BEPM-E2
- Part No: 32D5BEPM-5F / 4142VQ1074
- Part No: Typ: 42A5BEPM-FX3
- Part No: P/N: BE0627, Type: 42R4BFCI-5L
- Part No: BE0049
- Part No: P/N: 3495, Type: 34B4FEBL-5N
- Part No: Brushes for 42A5BEPM-FX1
- Part No: 49201031
- Part No: 24A4BF-M-D3
- Part No: KCI-24T4
- Part No: 6016JTTCG0025
- Part No: 5044
- Part No: Typ: 42R6BFPP-FX1
- Part No: Typ: 24A4BEPM-3F
- Part No: model #5049
- Part No: 1061 OEM for Kollmorgen
- Part No: 0855 OEM for Kollmorgen
- Part No: 48Y5BFCS-5H
- Part No: 30R1BECI-D4

- Part No: 493 01001
- Part No: 574 00008
- Part No: 492 00047
- Part No: Type 42A5BEPM-E3 (S/N:4182BTFF0025) oem
- Part No: HBT444-19
- Part No: TYPE 34R6BFCI-W2
- Part No: B50ELC
- Part No: 24A0BEPM
- Part No: 24A2BEPM serial.num U0495B0010 OEM
- Part No: 34R4BFCI-5R OEM
- Part No: 663
- Part No: 33A7BEPM-GB/H OEM
- Part No: 24A4FEPM-3RD OEM
- Part No: 42Y5BEPM-F3 OEM
- Part No: TYPE.33A3BEPM-Z2 SN. S03750027 OEM
- Part No: 33A5BEPM OEM
- Part No: S49201032
- Part No: S49300034
- Part No: 4116ANETO137
- Part No: 2856TJFC0004
- Part No: 33A5BEPM-W3
- Part No: SN. 0187FVIT0010 TYPE. 24A4BEPM-D3
- Part No: 189
- Part No: 42A7BEPM OEM
- Part No: 42A5BEPM-GB
- Part No: 664
- Part No: TYPE 42Y6BFPP
- Part No: SN.T760273 TYPE. 33A3BEPM-Z3 OEM
- Part No: 159
- Part No: 466
- Part No: 49401054
- Part No: 42A5BEPM-E4
- Part No: BE4275
- Part No: S/N.X760097 TYPE. 42A4BEPM-5L OEM
- Part No: 654JL9096

- Part No: 45Y5BEPM-F3 OEM
- Part No: 907950003 / 92485-01
- Part No: WPM2137E1
- Part No: S/N. 0255TLPG0009 TYPE.42R5BFSI
- Part No: 33A5BEPM-WX3
- Part No: 724
- Part No: OEM 42Y5BEPM-F3 SN:No.X0344D0039
- Part No: 24Y2FEPM-D5 - OEM
- Part No: B49200047
- Part No: BE6144
- Part No: 6737
- Part No: BE3304 Typ: 22B4BEBL
- Part No: 24A4BEPM 115V
- Part No: 5266
- Part No: 42R6BFPP-FX3 / 2860
- Part No: 80856441
- Part No: 6165
- Part No: N2474
- Part No: PN: BE3309 / Type: 34B6BEBL
- Part No: 30R2BEYC-D3 OEM
- Part No: 6169
- Part No: 49401075
- Part No: BE0196 / 24A2BEPM-D4
- Part No: N2637
- Part No: N2671
- Part No: 5303
- Part No: 3983
- Part No: 42R5BFSI
- Part No: N6737
- Part No: Type: 24A4BEPM volts - 130v
- Part No: Model 0663
- Part No: S/N: 0187ZAQE0029 / 24A4BEPM-D3
- Part No: 494 01015
- Part No: 33A3BEPM-Z2 (H5K0089E-0002) OEM
- Part No: 443-90037

- Part No: B49201028