

ENDURA SUPPLY

Brinkmann Product List

- Part No: 20236264
- Part No: 020236264 SNGTI36264
- Part No: 14.SM.020-4410
- Part No: 2 CM PROBE TIP, STAINLESS STEEL
- Part No: 2023820-0 FOR PC-950
- Part No: 30 INCH FIBER OPTIC W/PINS
- Part No: 3DISE0AA-S00068
- Part No: 4LARA0MS-F03654
- Part No: 570 NM
- Part No: BFS 364/50+001
- Part No: COLORIMETER FILTER, 40% NEUTRAL DENSITY
- Part No: COLORIMETER FILTER, FOR WAVELENGTH 450 NM
- Part No: COLORIMETER PROBE TIP, PYREXA®, 1 CM LIGHT PATH
- Part No: COLORIMETER PROBE TIP, STAINLESS STEEL, 2 CM LIGHT PATH
- Part No: Colorimeter PC950
- Part No: FILTER,520NM W/HOLDER
- Part No: KITPC950
- Part No: KIT-TIPC950
- Part No: PC-950
- Part No: REF:STA304/270 +001
- Part No: SAL605/560 +001
- Part No: SB 20+001
- Part No: SK-97
- Part No: SNG-TI31122
- Part No: SNGTI31173 570NM CYANIDE MEASUREMENT FILTER
- Part No: SNGTI36001 30 INCH FIBER OPTIC W/PINS
- Part No: SNGTI36264
- Part No: STA303/370+001
- Part No: STE 143/420
- Part No: TA302/170-X+142
- Part No: TAL 401/570+001
- Part No: TAS 401/460-MV+210

- Part No: TB100/270+001
- Part No: TB100/270-Z+280
- Part No: TB100/350
- Part No: TC 160/430 BX+361
- Part No: TC160/430-BX
- Part No: TC63/350-750 W9F+074
- Part No: TFS 364/50+001
- Part No: TFS 460/60+001
- Part No: TH 90-470-OBSOLETE, REPLACED BY TH618A590
- Part No: TH45/690-W9FX+432
- Part No: TH618A590
- Part No: TH90/290-690-MV+210
- Part No: Probe for SNGTI 36264
- Part No: SFL1550/440 +001 7,5 kW F IP 55 IE3 I" 3x400V, 50Hz, fAr Y/I" - Anlauf Zolltarif-Nr.: 8413 70 59
- Part No: 1: 800-1900-0/ Q-BEAM
- Part No: STA902/500 + 001
- Part No: TFL650 Q40-SFC
- Part No: TC 63/440 +001
- Part No: TA250/200-65+003
- Part No: TA160S200+001
- Part No: STA902/500 / -A+180
- Part No: P 5-25 V 1-0311-1001
- Part No: TC160/430-BX+537
- Part No: TC160/430-B60X+360
- Part No: TC160/430-B60X+562
- Part No: TH628A790 +100
- Part No: SFL850/330+001
- Part No: STA402/400+001
- Part No: SGL801/450+001
- Part No: SAL 1002/860+001
- Part No: TB 40/170
- Part No: SAL1301/780+001
- Part No: STA902S820
- Part No: KTF 83/340

- Part No: Part #60502130
- Part No: STA306/690 +001
- Part No: GGG 40 B01
- Part No: TFS574/20-N+160
- Part No: TH 180 / 760 - replaced by TH1120A760
- Part No: 6RIWE0VI-K05144
- Part No: TH1120A760
- Part No: BFS260/70 -61KBT5Z+415
- Part No: SXC2824/440-R+001 - the design is currently revised
- Part No: 1116812863-40640/2
- Part No: 13F5G1D-390A
- Part No: STE143/270 + 001
- Part No: TB 16/ 90 +001
- Part No: TC 63/560 +100
- Part No: SNGTI31171
- Part No: TS 12/250
- Part No: TA400/270
- Part No: 3DISE0AA-B00067
- Part No: TH1120A760+100
- Part No: TH1411B660-Z+300
- Part No: SB25-65BZX+435
- Part No: KTF152/180 +001
- Part No: FH209A29
- Part No: TH608A290
- Part No: BFS250/30-KBT5N+167 obsolete, replaced by BFS250/30+-KBT5N+184
- Part No: KIT-TIPC950220V
- Part No: SNG-TI38200
- Part No: SNG-TI38267
- Part No: BFS250/30-KBT5N+184
- Part No: STA402/400 +001
- Part No: FH1403A28+001
- Part No: 6PUSP4BS-025000-G
- Part No: STC160/580-2M+505
- Part No: SNGTI31173
- Part No: KITPC950220V

- Part No: 6UMZU0AA-K07324
- Part No: 512426
- Part No: SNG-TI36264
- Part No: 3DISE0AA-B00068
- Part No: COLORIMETER PROBE TIP, PYREX®, 1 CM LIGHT PATH
- Part No: ROWPC950KIT
- Part No: TC160/430-BX+36
- Part No: SFL1550/440 +001 7,5 kW F IP 55 IE3 ? 3x400V, 50Hz, für Y/? - Anlauf Zolltarif-Nr.: 8413 70 59
- Part No: TFL650 Q40
- Part No: TA160S200 +001
- Part No: TB 40/170 +001
- Part No: SAL1301/780 +001
- Part No: KTF 83/340 +001
- Part No: 4LARA0GS-F04654
- Part No: SXC2824/440-R+001
- Part No: 520NM W
- Part No: UH614A49 + 001
- Part No: UH618A59 + 001
- Part No: STC 25/260-56+028
- Part No: STA402/490+001
- Part No: SNGTI36001
- Part No: SNGTI09208
- Part No: TC260/920+001
- Part No: STA405/750 -A+180
- Part No: BFS260/60 -KBT5N+184
- Part No: STA601/560 -52GXZ+1139
- Part No: SGL801/320 -52XZ+1116
- Part No: FFS364/70
- Part No: TFS364/70 -GF+353
- Part No: KTF 53/290 -56S+029
- Part No: TC 63/350 +001
- Part No: STA607/520-W9+052
- Part No: KTF152/410+001
- Part No: TA400/270-G+131
- Part No: STA 604/410+001

- Part No: 3LASE0SI-B00080
- Part No: STA404/27062GXZ+1049
- Part No: 4LARA0MS-F03655
- Part No: SAL 602/370+001
- Part No: 4LARA0MS-F03760
- Part No: 4LAAX1SC-F03697
- Part No: SAL404/440 -MV+211
- Part No: SXC2824/440 -CM5RXZ+3063
- Part No: SBA402+001
- Part No: SAL 403/320-52GX+421
- Part No: SNG-TI38291
- Part No: SFL1150/230-X+109
- Part No: TH1115A570-MV+211
- Part No: SAL301/370 +001
- Part No: SAL301/370+001 118027661-1
- Part No: TA250/550 +001
- Part No: STA608/1010 +001
- Part No: FFS348/80+001
- Part No: SAL602/450-MVZ+1022
- Part No: TB 40/350 +001
- Part No: 09.F5.B3A-390A
- Part No: 3TH360/380-650 -ZX+404
- Part No: 4PUSP3FS-510000 +B
- Part No: 6UMFR1AA-093-387
- Part No: TA160/200 +001
- Part No: 6LARA0PO-K04189
- Part No: TA302/490 +001
- Part No: KC60-012 /0801015539
- Part No: BZ5-OP240
- Part No: M 317 711 0300
- Part No: TS 22/150 -B634Y+552
- Part No: TC 63/350 -42W2X+246
- Part No: TL141/470 -Z+002
- Part No: H3177110301
- Part No: H3160600153

- Part No: SBF 1350
- Part No: 20237317
- Part No: FH407A29 +001
- Part No: SGL801/320 -MV+1032
- Part No: BOM-TIPC9X0CBL
- Part No: BFS232/30-K -61Z+037
- Part No: TFS348/70 -KBT5N+184
- Part No: 3BFS232/30-K -61Z+037
- Part No: 4PUSP4BK-023200
- Part No: STA904/960 +001
- Part No: STA406/800 +001
- Part No: STA304/270 +001
- Part No: 3LASE0SI-B00081
- Part No: GB1018H1
- Part No: SB60 -40+110
- Part No: TC160/740-AZ+370
- Part No: KTF152/180 -61+024
- Part No: 71L/2 (M71b2)
- Part No: SAL302/420 -GMVZ+1947
- Part No: TB 40/170-Z+002
- Part No: STA902/820 -X+176
- Part No: ZS112140-M+250
- Part No: STA1302/1070 +001
- Part No: SAL1301/460 -Z+002
- Part No: STA604/760+001
- Part No: BFS238S70+001
- Part No: 6411-631
- Part No: TC 25/340 +001
- Part No: TH431A690 -IL+131
- Part No: TC 63/440 -BX+532
- Part No: 3DISE0AA-B00056
- Part No: TA160/200-G1+130
- Part No: SGL801/570 +001
- Part No: SGL801/320 -Q40MV+367
- Part No: MUS-SNGTI3112 2

- Part No: TB 25/220+001
- Part No: SAL604/350-MVXZ+817
- Part No: FFS 348/xx (4PUSP4FS-034800)
- Part No: B501-F -Z+006
- Part No: TH422S690
- Part No: TC 63/440 +100
- Part No: TC160/430 +100
- Part No: TC 63/350-750+001
- Part No: TS 22/300 +001
- Part No: KC31 -Z+002
- Part No: TB 63/350 +001
- Part No: TA80S170+001
- Part No: Type: STA402/400+001
- Part No: 20236001
- Part No: 20231173
- Part No: 20238267
- Part No: KTE141/200-60ZX+471
- Part No: 6DEFU0PO-K04181 for TA 160
- Part No: TB 40/170 -G1Z+382
- Part No: TE142/300 +001
- Part No: TE142/300+001 1.1 KW-
- Part No: SAL901/450 -Z+800
- Part No: FFS250/70 +001
- Part No: FFS348/50+001
- Part No: TC160/430 (s)
- Part No: TC160/430 +001
- Part No: STC160/430 +001
- Part No: SNG-TI36001
- Part No: TAL200/220 +001
- Part No: SFL1350/560 -CM1+132
- Part No: STA902/820+001
- Part No: 3KUPL0AA-B00024
- Part No: STH414A390-MVZ+237
- Part No: STC63/440-MVX+314
- Part No: STH1105A380-MVZ+237

- Part No: STH420A490-MVZ+237
- Part No: SGL781/450-MV+700
- Part No: STH611A490-MVZ+237
- Part No: SBG781-MV+700
- Part No: TA160/440-MV+211
- Part No: TS 21/110-61+024
- Part No: BFS250S40KBT5N+167
- Part No: KC31 +001
- Part No: TB 40/170 -03Z+703
- Part No: PC 950/800
- Part No: FH431A79 +001
- Part No: KTF 152/410
- Part No: TH431A690+001 / 0120814535-17481 002
- Part No: TC 63/560 +001
- Part No: 1000000184
- Part No: Nr. 1000000183
- Part No: 1000000167
- Part No: 1000000168
- Part No: 1000000169
- Part No: 1000000170
- Part No: TC 63/750 -65+003
- Part No: TYPE TC 63/750-65
- Part No: SFL1350/440+684
- Part No: TC160/430 -BX+531
- Part No: SGL1101/460-MV+211
- Part No: BFS238/70+110
- Part No: BFS238/70 +001
- Part No: BMK4 -6156XZ+767
- Part No: SBA402+001 1.5KW FIP55
- Part No: TA 303/3
- Part No: TES232/70-KH-61XZ+851 70 oem
- Part No: TFS232/70-KH-61XZ+851
- Part No: BMK3 -56XZ+766
- Part No: 6UMZU0AA-K07323
- Part No: STA403/850

- Part No: 1PC950
- Part No: STA404/270+001
- Part No: TB 16/170+001
- Part No: BFS250/90-K -GZ+333
- Part No: KTF 52/200-65ZX+262
- Part No: KTF301/290-X+053
- Part No: BFS140/30-61Z+1131
- Part No: STA902/500-AZ+370
- Part No: TS 12/190 +001
- Part No: 4PUSP3FS-612000
- Part No: 2023820-0
- Part No: TC 40/430-B508+542
- Part No: STA 604/330-Z+002
- Part No: TC 40/430 B 508
- Part No: SFC1150 (4CRCI1SM-F05786)
- Part No: TH1402S280 -61Z+090
- Part No: 59712
- Part No: KTF 16/120-X+505
- Part No: STA1003/920-XZ+837
- Part No: STA1302/1070 -XZ+1353
- Part No: STH1412A900-Z+800
- Part No: TAS / STS301... ? 1001
- Part No: SBA142+001
- Part No: BFS250/70-K -FZ+240
- Part No: Type TH 45/690-X+193 / 0902060031
- Part No: TGL801/320-MV+210
- Part No: SAL 1303/940
- Part No: KTF 81/270-ZX+261
- Part No: SAL 1301/580+001
- Part No: TC160/330-580-Z+250
- Part No: TB 63/120-X+190
- Part No: 20236213
- Part No: 20209208
- Part No: TA160S270-G+131
- Part No: KTF153/220-TF+418

- Part No: TFS232/70-KH-61Z+850
- Part No: ZT071085-MC+250
- Part No: KTF 51/170-06ZX-449
- Part No: FFS238/20+001
- Part No: 4SUPU0AA-B01656
- Part No: Type: TAL302/190-MVX+520
- Part No: TC 40/430-B508+542 // 0205000581
- Part No: Type TC 63/440-BX
- Part No: SGL502S300+001
- Part No: SFL550-1150
- Part No: TH609B490 -MVZY+463
- Part No: SAL603/280 -Z+095
- Part No: KTF 81/120+001 / 0716012080-28023 048
- Part No: TC25/430+001
- Part No: STA901/430-W9MV+218
- Part No: KTF303/370-Z+617
- Part No: Type BFS250/60-Z+320 No. 0213001971
- Part No: FH609S34+001
- Part No: BFS250/70-K+110
- Part No: SATE0AA-B00185
- Part No: VRBK0AA-B01062
- Part No: 4CUZY0GG-FF0090
- Part No: KTF 153/220-TF+418D
- Part No: FFS 376/xx (4PUSP4FS-037600)
- Part No: ZS090120-MF+250
- Part No: TYPE:SAL402/270-Z+002
- Part No: KTB200/270-6156X+573
- Part No: 59719040
- Part No: 59719712
- Part No: TH425A590 +001
- Part No: TFS 496-N
- Part No: 6UMFR1AA-D05097
- Part No: BFS238/90 K GZ+11
- Part No: TFS574/40-GZ+1004
- Part No: STE145/590-Z+002

- Part No: SAL401/220-Z+002
- Part No: SAL401/220-Z+095
- Part No: TC 63/440-65B+352
- Part No: 260760020
- Part No: TH416B390-61Z+090
- Part No: TA160/270+001
- Part No: STA 1302/1070+1353
- Part No: TB 40/170-B4ZX
- Part No: 20236507
- Part No: SFL1550/560+001
- Part No: TS 22/110-X+191
- Part No: 1-0211-1008
- Part No: SBM450-62Z+090