

# ENDURA SUPPLY

## Brooks Instruments Product List

- Part No: MT3809/G
- Part No: 0104090270058/001
- Part No: 0104090270059/004
- Part No: 1020-I-1"-C1-M7
- Part No: 1350/D1F33A1A5B00
- Part No: 1350EZ192.
- Part No: 1355/D-2-H-5-A-1-B-6-C-0-0
- Part No: 2-5 ML / MIN
- Part No: 3809EB2BBKAAAA1 - obsolete, replaced by MT3809/G
- Part No: 3809EZBBBBTAEBA
- Part No: 5836N
- Part No: 5850 E/B1
- Part No: 5850E/B1A1A30
- Part No: 5850S
- Part No: BROOKS TOTALIZER MODEL 4253 PARTS FOR TOTALIZER MODEL 4523 6 DIGITS E D DISPLAY a " PART NO. 273-L-0
- Part No: DS-VA-MT3809-3819-ENG
- Part No: FR 2A14 S V VT
- Part No: FR2A15SNVT
- Part No: FR2A15SVVT
- Part No: 2510A2A29SVVT
- Part No: FR-4500-4A70 - ObsoleteReplaced with "2530A4A70SVVT"
- Part No: FR-4500-4A73
- Part No: FR4A36BLBN.
- Part No: FR4A42BVBN
- Part No: FR4A42SVVT
- Part No: FR4L71BNDN
- Part No: FRA36BLBN
- Part No: GT1350.
- Part No: MC1000-I-2"-C1-M1-H5-T22-Z12-2000/2100
- Part No: MC1000-I-2"-C1-MX-H5-T22-Z12-2000/2140
- Part No: MODEL MR3000

- Part No: MODEL: 3809EAADADDAEAA
- Part No: MR3A12BNBN
- Part No: MR3A14SVVT
- Part No: MR3A14SVVT WITH MAXIMUM FLOW VON 5 LPM AIR
- Part No: MR3A15SVVT WITH MAXIMUM FLOW VON 10 LPM AIR
- Part No: PROTECTION COVER OF GLASS FOR G/T 1000 V60722/01
- Part No: QMBC
- Part No: SLA5851
- Part No: T15CAB1FA1AAC
- Part No: S122-30-PSI/BAR-NPT
- Part No: 1350/D2D3D1B5B000- obsolete, replaced by 1350GAK3BBJU1AAA
- Part No: 1350GAK3BBJU1AAA
- Part No: Type 810
- Part No: 3809EB1BADAA1N1 obsolete, replaced by 3809GBA07BFBF1A00A00
- Part No: 3809EB1ABDAA1N1 obsolete, replaced by 3809GBA07AGBF1A00A00
- Part No: nd7 0.125 A8 BU Y1
- Part No: 3809GBA07BFBF1A00A00
- Part No: 3809GBA07AGBF1A00A00
- Part No: V37786/10 M/T3750A
- Part No: MR3L11
- Part No: 2530A4A70SVVT
- Part No: MT3809EB2C1DTAEAA obsolete replaced by 3809GAA08DFBF1D3B0C0
- Part No: 3809GAA08DFBF1D3B0C0
- Part No: SLAMF63S2EBA0G2A2
- Part No: 3750CC2A11BEAAAAA0
- Part No: FR-2A13-S-N-VT
- Part No: MR-2A13-S-N-VT
- Part No: 5851S/BD1KA1AA0AA1B1 obsolete, replacement SLA5851
- Part No: SLA5851S1TAB1B2A1
- Part No: SLA5851SJ1AB1C2A1
- Part No: 1350EP2AAHV5A/8900A3B1C0A1A1 obsolete, replacement 1350GAM3AAJN5AAA
- Part No: 1350GAM3AAJN5AAA
- Part No: 5850S/BC1KA1BB3BA1B1 obsolete, replaced by SLA5850S1TAB1C2A1
- Part No: SLA5850S1TAB1C2A1
- Part No: SLA5850

- Part No: FR2000 2L11 obsolete, replacement 2510A2L11SVVT
- Part No: 2510A2L11SVVT
- Part No: MF64S/AS4DA0BB3KA1B1 obsolete, replacement SLAMF64S4DAA0G2A1
- Part No: SLAMF64S4DAA0G2A1
- Part No: SLA5850S1JAB1C2A1
- Part No: 5850S/BC1KA1AA0AA1B1 alternative SLA5850ST1AB1B2A1
- Part No: SLA5850ST1AB1B2A1
- Part No: 925J741WAA
- Part No: 5860IA13DA2EA
- Part No: SLA5860S1GAA0C2A1
- Part No: 5860IA13DF2EA Replacement for 5860IA13DA2EA
- Part No: 229-00-602-25
- Part No: 3809GAA12CFBB1A00000
- Part No: 5850S/BC1KA1AD0AA1B1 obsolete replaced by SLA5850P1TAB1B2A1
- Part No: SLA5850P1TAB1B2A1
- Part No: 5850S/BC1HA1AB3BA1B1 Obsolete Replaced by SLA5850S1HAB1B2A1
- Part No: 3809GBA10DFBB1A00B00
- Part No: 3809GBA08BFBB1A00B00
- Part No: QMBC2L1B2A1A2A1CX1D7A 1AA
- Part No: QMBC2L1B3E1A1AKB8H7A1AA
- Part No: QMBC4L1B3E1A1A1KB8H7A1AA
- Part No: 1350
- Part No: BROOKS TOTALIZER MODEL 4253 PARTS FOR TOTALIZER MODEL 4523 6 DIGITS E D DISPLAY – PART NO. 273-L-0
- Part No: C
- Part No: MR 3A15 S V VT
- Part No: PTFE
- Part No: P/N: 1350/D2D3D1B5B000- obsolete, replaced by 1350GAK3BBJU1AAA
- Part No: SLA5860S\_1/4NPT F\_4-20mA
- Part No: 1350G (Modellnummer 1350GAL3EBCA1AAA)
- Part No: 3809GAA08AFBB1A00B00
- Part No: 2530A4A73SNVT
- Part No: 2540A5A53PI
- Part No: GT1355/D9D3D1B1C02
- Part No: 3809GBF08BEBB3D3C000
- Part No: 834M138ZZA

- Part No: 834-M-105-ZZA
- Part No: GF040CXXC-0008050L-R2PVS4-XXXXAX-00C
- Part No: R-8M-75-1 S925J208AAA
- Part No: 3809GAD10BABB1A00000
- Part No: SLA5850SG1AB1C2A1
- Part No: SLA5810S1HAB1C2A1
- Part No: 1355/D2D301B5B00
- Part No: 1355/D26301B5B00
- Part No: 1355/D1e501B5B00
- Part No: SLA5863S2GAA0C2A1
- Part No: 2510A2A15SNVT
- Part No: 5850EC4BW3TD2A
- Part No: MT3809EBBAADQAAA1
- Part No: 3819B
- Part No: SLA5851S1JAB1B2A1
- Part No: M31086-002
- Part No: SLA5850SJ1AB1C2A1
- Part No: 2540A5A54SV
- Part No: SLA585011TAB1A2A1
- Part No: 2510A2A17SVVT
- Part No: 5860IA13DA2DA
- Part No: SLA5850 AIR 10 NLPM
- Part No: 2540A5A51SV
- Part No: 1350/D1D3E1D5AC00
- Part No: 1350GAL3DBFG1AAA
- Part No: DLIHVP2A6CD2AA
- Part No: QMBC4L1B2A1A1A1CY1A7C1DA
- Part No: 2510A2A14BVBN 01B83702225
- Part No: 3809GCC000GBE3D3C0A0
- Part No: 1308-09Z2Z1Z02
- Part No: 3750CA2A11BEAAAAA0
- Part No: 1255AR1072MRQVV
- Part No: 1350G
- Part No: 1350GAH3CBFA1AAA
- Part No: MT3809

- Part No: 3809GBA07CGBF1A000A0
- Part No: 8-1307-6800
- Part No: SLA5850SH1AB1C2A1
- Part No: 5700AL1A1AA
- Part No: GT1600
- Part No: GT1600 - Large Glass Meter N2
- Part No: SLAMF64S4AAA0E2A1
- Part No: MT3809 (SN:V25246/02)
- Part No: 1355GAF3JDJA1AAC
- Part No: 0254AB2B11A
- Part No: 124Y057AAA
- Part No: 5850S/BC1GA5BA0AA1B1
- Part No: 8601D2D4AB
- Part No: GT1355
- Part No: 5850EC4BD3EF2A
- Part No: 1250AD6092ALAVB
- Part No: F4715101001
- Part No: SLA5863S\_3/4"
- Part No: SLA5863S2EAA0C2A1
- Part No: 1350/D1G3G1D5C000
- Part No: SLA5850 REV B
- Part No: M20-2763
- Part No: SLAMF64S3NAA0G2A1
- Part No: 1355GAD3ABRT5AAA
- Part No: GF040CXXC-0008050L-R2AVS4-XXXXAX-00C
- Part No: Model 1350/1355
- Part No: 3809GBA12DGCB1D30000
- Part No: SLA5851SJ1AB1B2A1
- Part No: SLA5851ST1AB1C2A1
- Part No: MR3L11SNVT
- Part No: 3750CA2F11BEAAAAA0
- Part No: 3750CA3F11CEAAAAA0
- Part No: 3750CZ474
- Part No: 3809/G Size 12
- Part No: 1307AZ1002

- Part No: sensor for 1307AZ1002
- Part No: 8601D
- Part No: 1355G
- Part No: 1350GZ-105527
- Part No: 2530A4A70BVBN
- Part No: 8601D2D1AB
- Part No: F22481-004
- Part No: 1640AA6A1AA13D02A
- Part No: SLAMF61S
- Part No: 1350GAL3ABJU1ATAXY605+RC15-14-N3
- Part No: 1350GAM3CBJV1AAA-XY605
- Part No: MF64S
- Part No: S/N: F10534-002 MODEL:5850S/BC1KA1AA0AA1B1
- Part No: SLA5853S (4820-01-685-8808)
- Part No: SLA5850A1GAB1C2A1
- Part No: SLA5863S
- Part No: GT1350 L 8800 VD2 / TB R-2-65-DG FS / 1/4 NPT F
- Part No: DLT316832
- Part No: SLA5850S\_1/4"NPT avec filtre\_0-5V
- Part No: 8601D2D4AA
- Part No: MR3A15SNVT
- Part No: 3809GBD08ABBF1A00000
- Part No: 1350GAJ3BBFA1AAA
- Part No: 3809GBD030ABA3D3A000
- Part No: 1250AR6013MRAVB
- Part No: LPM AIR
- Part No: SLA5850SG1AF4C2A1
- Part No: 1355 I / TB R215BG / FI / RC1014N3 / ¼ NPTF
- Part No: 5850E
- Part No: SLAMF53S\_1/2"BSP\_4-20mA
- Part No: SLA5853S2DAB3C2A1
- Part No: MR3A13SNVT
- Part No: 1350GAK3BAJU1AAA
- Part No: SLA5851S
- Part No: MT 3809/ DN25

- Part No: MT 3809/ DN15
- Part No: cylindrical glass panes for 375B113QTA
- Part No: SLA5860S1BAA0B2A1
- Part No: 8601D-2C5BA
- Part No: 8000B (1")