

ENDURA SUPPLY

Cantoni Motor Product List

- Part No: 1106C004015H0 SEMH 063C-4
- Part No: 13110000A00000
- Part No: 1,7976931348623157E+308
- Part No: 13110000G10000
- Part No: 1311M004435HS
- Part No: 2SIE315M-6A
- Part No: 2SIEK 160 M-2B
- Part No: 2SIEK 215TC-2
- Part No: 2SIEK80B2
- Part No: 2SIEK 090L-2
- Part No: 3SIEL 160 M-2B
- Part No: DUTYS SH 71-6B
- Part No: LR0060W11JE00
- Part No: M27500-22ML2T08.
- Part No: M2SG280S4/2W
- Part No: M2SIEK112M-6
- Part No: M81044/12-20-0-9 TP
- Part No: M81044/12-22-0.
- Part No: SC.180L2/4 22.8 KW 2940RPM/M - 16.2KW 1480RPM/M
- Part No: SEHR90-4SF
- Part No: SEMG56-4
- Part No: SG180L-8
- Part No: SIE215TC-2
- Part No: SKG 63 -2A
- Part No: SKH 080A-4
- Part No: TYPE: 2SG 280M4 S/N A45232(NOT OFFERED REPLACED BY 2SIE 280M-4)
- Part No: SKC 50-2A
- Part No: SKH 063B-2 0,25kW B5 230/400V-50Hz
- Part No: 1310LA04425IE2
- Part No: 984.62556.03 (REPLACED BY) 2SIE132S-2B (112027)
- Part No: 2SIE132S-2B (112027) V440/60HZ 7,50 KW Poles 2 Shape B3 Volt/Hz 400 T 50 U.M Pz
- Part No: 2SIE 90 L-2

- Part No: SH-90-L4 OBSOLETE REPLACED BY 2SIE 90L-4
- Part No: 2SIE 090L-4
- Part No: EExe II T4
- Part No: 2OG.40A30V0AG0000- replaced by 2SIEL 132SA-2
- Part No: 2SIEL 132SA-2
- Part No: 080B-4 0,75kW
- Part No: A48954 DE 365T-4
- Part No: A48954 NDE 365T-4
- Part No: 603-645-8610
- Part No: PSSG 132 M-4
- Part No: 1313S004435IE2
- Part No: SLh90L2
- Part No: 2SIE 160L-6
- Part No: 2SIE 100L-4B
- Part No: SLH 56X-4C2 REPLACED BY STLH56XC-4 B3/B14A (1105XC04225H0)
- Part No: STLH56XC-4 B3/B14A (1105XC04225H0)
- Part No: 2SIE 90L-4
- Part No: SKH71A-2 1107A002625H0
- Part No: IEC071 11070000A32A
- Part No: IEC 071 (B03) 11070000O72H0
- Part No: 1313S004135IE2B
- Part No: B 5 SG 63
- Part No: R C2125OUO2A-401 DA2 B3
- Part No: Typ Sg 63-8B
- Part No: SKG 63-8B
- Part No: SKH 80 X-6C
- Part No: 2SLg225M-4
- Part No: 2SIEK90L2 AC400V 2.2kw
- Part No: 2SIEK 132 S-4
- Part No: SSKG 180 L-4
- Part No: 2SIE180M2
- Part No: SKH 71 X-6C
- Part No: 2SIEK 080B-4 0,75kW B5 230/400V-50Hz IE2
- Part No: SKh 80-4B obsolete, replacement 2SIEK 80-4B
- Part No: 2SIEK 080B-4 0

- Part No: SKH 080B-6
- Part No: 2SIEK 90 S-4
- Part No: DS-Motor 3 SIEL 132 M-4
- Part No: SKH 90 S-4 obsolete, replacement 2SIEK 90 S-4
- Part No: SSG 160 obsolete, replaced by 1316L006035IE2B, 3SIE160 L-6
- Part No: 1316L006035IE2B
- Part No: SIE286TD4
- Part No: SIE324TDZ4
- Part No: SIE326TDZ4
- Part No: SIE365TDZ4
- Part No: 1108A002425IE2
- Part No: SKH 90L-4 T116113 obsolete, replaced by 2SIEK 90L-4
- Part No: 2SIEK 90L-4
- Part No: 2SIEK 200L-4C
- Part No: 2SIE1 60L6 obsolete, replacement 3SIE160 L-6
- Part No: 3SIE160 L -6
- Part No: 1311M002025IE2B
- Part No: 13110000O72H0
- Part No: 1108A00F045H0
- Part No: SKh 80-8BHPS in B5
- Part No: SKHr 080B-8 HPS
- Part No: 99444
- Part No: 99443
- Part No: HPS 16.34 180VDC 80Nm d35
- Part No: SKg 71-4B2 obsolete/ replaced by SKh 71-4B
- Part No: SKH 071B-4
- Part No: SKH 71-2A
- Part No: 13100000O28HE
- Part No: 2SIEL 180M-2 22kW B3/B5 400/690V-50Hz IE2
- Part No: 38118
- Part No: SKH 063B-4
- Part No: 99-040320-009
- Part No: 1311M002435IE2
- Part No: SIE256TC4
- Part No: 2SIEK 90 S-2

- Part No: IP56 Execution IEC090
- Part No: 2SIEA180M-4 old Nr/ new Nr II3D 2SIE 180M-4
- Part No: Type: 2SIE280M2 - obsolete, replaced by - 3SIE 280 M-2
- Part No: II3D 2SIE 180M-4
- Part No: Type: 3SIE 280 M-2
- Part No: SLH 080A-4
- Part No: 2SIE 112M-6
- Part No: Skg 1- 1 2M-4 - obsolete, alternative - 2SIE 112 M-4 or 2SIEK 112 M-4
- Part No: 2SIE 112 M-4
- Part No: 2SIEK 112 M-4
- Part No: 2SIE 90 S-4
- Part No: SH 071B-4
- Part No: SH 071A-2
- Part No: 2SG 180L-12 7,5kW B3 (V6) 400/690V-50Hz, IP56
- Part No: SEKhR 90-4MF FX
- Part No: 6309 2RS C3
- Part No: SKG16043
- Part No: SSKG 180L-8/4
- Part No: 2SIEK 80-2B replacement 2SIEK 080B-2 1,1kW B5 230/400V-50Hz IE2
- Part No: 2SIEK 080B-2
- Part No: 2SIEL 132M-4
- Part No: IEC071 (B01)
- Part No: SEMLH 080B-4
- Part No: 2SIEK 090L-6
- Part No: 2SIE 160L-4
- Part No: 2SIE 280S-4
- Part No: 2SIE 225S-4
- Part No: IP56 Execution IEC280
- Part No: IP56 Execution IEC225
- Part No: 2SIE 280M-4.
- Part No: 2SIE 225M-4
- Part No: 2SIEK 080XC-2
- Part No: 2SIE160-MA4 obsolete , replaced by 3SIE 160 M-4
- Part No: 3SIE 160 M-4
- Part No: SG 280 M-4

- Part No: 1309L008025H0
- Part No: SH 056B-4
- Part No: 1105B004225H0
- Part No: 1105B004125H0
- Part No: 1105B004325H0
- Part No: 2SIEK 50-4B