

# ENDURA SUPPLY

## ADVANCED ENERGY Product List

- Part No: 3858550
- Part No: 3858570
- Part No: 3858580
- Part No: 3749150
- Part No: 3858540
- Part No: 3858490
- Part No: THYRO A 2A 400 130 HRL1 obsolete, replaced by Thyro-A 2A 400-130 HRL3
- Part No: Thyro-2A 400-100 HRL1 obsolete, replacement Thyro-A 2A 400-100 HRL3
- Part No: Thyro-2A 400-60 HRL1 obsolete, replacement Thyro-A 2A 400-60 HRL3
- Part No: Thyro-A 2A 400-100 HRL3
- Part No: Thyro-A 2A 400-60 HRL3
- Part No: Thyro-A 2A 400-130 H RL3
- Part No: Thyro-A 1A 400-30 HRLP3
- Part No: 2000001015 Obsolete!! Replaced by 2A 400-100 H3
- Part No: 2A 400-100 H3
- Part No: Thyro-A 2A 400-100 HRLP3 (2.000.324.208)
- Part No: Thyro-S 2S 400-130 H RLP3 (2.000.224.209)
- Part No: 2000000846
- Part No: Thyro-A 2A 400-100 HRL3 (2.000.314.208)
- Part No: 2A 400-100 H3 / PN 2.000.304.208
- Part No: 1A400-16 HRL1 KO
- Part No: IMPAC IPE 140
- Part No: 3887520
- Part No: 2000000841
- Part No: Thyro-A+ 1A 230-280 HFRLP4
- Part No: Thyro-A + Display cabinet installation kit (frame + cable)
- Part No: Thyro A+ Display
- Part No: SD card for Thyro-A + display
- Part No: PC Software Thyro-Tool Family / Pro
- Part No: Bus module
- Part No: Thyro-A+ 1A 500-60 HRLP4
- Part No: 3874570

- Part No: 3909010
- Part No: 2000314209
- Part No: 2000000848
- Part No: 2000325305
- Part No: Thyro-S 1S 400-60 HRLP3 (2.000.224.107)
- Part No: IMPAC IN 300
- Part No: P/N:2.000.312.104, Type: Thyro-A 1A 230-16 HRL3
- Part No: P/N: 2.000.315.104, Type: Thyro-A 1A 500-16 HRL3
- Part No: 2000003741 / ZME 5
- Part No: 2000314313
- Part No: 2000190002
- Part No: 2000190013
- Part No: Typ: Solvix LF / Mn: 3152070-040
- Part No: 2000302105
- Part No: Thyro-A 1A 230-30 H3 / 2000302105
- Part No: Thyro-A+ 2A 500-280 HFRL4 (2.000.765.211)
- Part No: 2A-500-30-H-F-RL3
- Part No: 3A-500-30-H-F-RL3
- Part No: Thyro-A 3A 500-30 HRL3
- Part No: Thyro-A 2A 500-30 HRL3
- Part No: Thyro-A 1A 400-30 H3
- Part No: ■MPAC IS 50-LO/GL 600-1800C
- Part No: 3 820 660
- Part No: 3 835 300
- Part No: 3 835 310
- Part No: 3 835 400
- Part No: 3157601-101
- Part No: Thyro-A 2A 400-280 HFRL3
- Part No: Thyro-A 2A 400-130 HRL3
- Part No: 3 856 530
- Part No: 8000001020
- Part No: THYRO-A 400/100 HRL1
- Part No: THYRO-A 400/60 HRL1
- Part No: Thyro-A 1A 400-100 HRLP3
- Part No: Thyro-A 1A 400-16 HRL3

- Part No: 6C24-P125-I10
- Part No: 4C24-N60
- Part No: 1PX500-170 H