

# ENDURA SUPPLY

## Ametek Pittman Product List

- Part No: 61000062
- Part No: 1,42E+231
- Part No: 14203B371
- Part No: 14205E247-R1 oboslete repl by GM14205E247-R2
- Part No: 14205E247-R2
- Part No: 14207 SERIES E320
- Part No: 14207D537 30,3 V 200 CPR (OEM)
- Part No: 14237E093 38.2 VDC
- Part No: 3501D74H01
- Part No: 3504D26G03
- Part No: 101-728-003
- Part No: 8224S006
- Part No: 8224S006-R1 oem
- Part No: 8324S006-R1- obsolete - replacement - 8224S006-R1
- Part No: 86922A034-R2
- Part No: 9234S006-R1
- Part No: 9236E110-R1 OEM
- Part No: 9236E837
- Part No: E6-2000-156-I-D-D-D-B 800.736.0194
- Part No: GM14633E270-R4 Y4611 12 VCD oem
- Part No: GM712J140
- Part No: GM8724G482-R1 - OEM/customized
- Part No: GM9213-5
- Part No: GM9234E235-R1
- Part No: GM9234E496 316D10042 256 CPR 24VDC 65.5:1 RATIO (OEM)
- Part No: GM9236S020
- Part No: GM9236S026-R1
- Part No: GM9236S026-R1-SP
- Part No: GM9413F277 oem
- Part No: GM9414H764
- Part No: GM9434F990-R2
- Part No: GM9636L024-R4 OEM

- Part No: HR2
- Part No: HR3.
- Part No: M14436A195 OEM
- Part No: 5130-168-0003
- Part No: MCG 2242-ME2834 OEM
- Part No: MGM 9234 A143 24 VOLT 127,7/1 RATIO
- Part No: MGM9234A143-R1
- Part No: MGM9537A075
- Part No: MGM9537A078-R03 48VDC (OEM)
- Part No: MOTOR -507D2D788B GM9234E496 24VDC 65.5:1 RATIO 256 LINE - OEM PRODUCT, CAN'T OFFER
- Part No: MT9414C934 - OEM/customized
- Part No: MT9414C934, 3501D74H01 .. REV.G, 19.1 VDC, 10-1-87
- Part No: PART # 3501D74H01
- Part No: Part n° 2233-mt3142 cod-0084150826
- Part No: T9234C321, OEM!!!
- Part No: 134603
- Part No: T9234C321-R2 15.3 V/KPRM 10.10.11. OEM
- Part No: T9234C321-R8 15.3 VDC/KRPM 01-10-13 (OEM)
- Part No: PART. No 2451-M4146-1 OEM
- Part No: GM9213C400-R2 (OEM)
- Part No: 14237E093- Product os OEM.
- Part No: PLG52 RATIO 4.5-1
- Part No: Part no:M543 12 70 0806 04 MPU Serial no:000043 Type:A2852
- Part No: 117416-03
- Part No: 9236E879 109512 REV B OEM!!!
- Part No: 9412C436-R2
- Part No: 2451-m4146 OEM!!
- Part No: DC054B-4 (14204)
- Part No: 14204 (DC054B-4)
- Part No: G40A
- Part No: MT9414C934,3501D74H01 - (OEM\*)
- Part No: M9234A222 OEM!!
- Part No: DC026C-3 (8693) (proprietary) OEM
- Part No: 14203B371-R1 (OEM)

- Part No: 329A813H02
- Part No: 9412C436 500 731 obsolete, replacement 9412C436-R2
- Part No: 9234C140-R5
- Part No: DC040B-3 OEM!!
- Part No: BGE6050 OEM!!
- Part No: 4411E059-R3 oem
- Part No: LO-COG 24V dc
- Part No: MT9414C934. (OEM\*)
- Part No: 9234E751
- Part No: 2451-M4146 (proprietary)
- Part No: M/N: 14202D746 (OEM)
- Part No: M/N: 9434K350-RI (OEM)
- Part No: M/N: GM8712J110 (OEM)
- Part No: GM9234E496
- Part No: MT9414C944 (OEM)
- Part No: MGM9537A078-R3 OEM!!
- Part No: 9234-24.0V-G51A-38.3-0000-B30A-24V OEM!!
- Part No: DC040B-5 (9236) (OEM)
- Part No: Rotor for 9236E837
- Part No: GM8712F191
- Part No: M14436A178 OEM!!
- Part No: 9236C238-R5 + K80.720.P9000 OEM!!
- Part No: GM9213C400-R2 - OEM/customized
- Part No: DC054B-3000-A25
- Part No: D? 054 B2 -2 , 19,1 A
- Part No: GM94LT2
- Part No: 2234-MBE5288 OEM
- Part No: 14631
- Part No: TT0953
- Part No: GM9236S015-R1
- Part No: 9234E828 (OEM)
- Part No: GM14205E247-R2
- Part No: GM8224S024 - SP
- Part No: M9234A204 OEM!
- Part No: 14436

- Part No: 9236E837-R1 obsolete
- Part No: 2232-M3991 OEM!!!
- Part No: 2151-M5411 OEM for Draeger Medical Systems Inc
- Part No: I9234C321 OEM!
- Part No: GM8712-41 (obsolete - replaced by GM8212-41)
- Part No: GM8212-41
- Part No: SE+119620001
- Part No: GM 8212-31
- Part No: 9237S010-R1-SP
- Part No: GM9214C440-R1
- Part No: OEM
- Part No: H5530F1
- Part No: GM9236S014-R1
- Part No: M9234A222-R1 OEM!!!
- Part No: 14207S008
- Part No: 7246516
- Part No: GM8224S028
- Part No: GM8722G206-R10 OEM!
- Part No: MGM9233A138 OEM
- Part No: GM14902E332 OEM
- Part No: GM9234E471-R2 OEM
- Part No: TT0953 (21200305)
- Part No: GM14901E299 OEM
- Part No: M9237S106
- Part No: T9234C321-R2 OEM
- Part No: 14207D537-R3 OEM
- Part No: 2451-M4146-1 OEM
- Part No: GM9232E447-R1 OEM
- Part No: MT0916 OEM
- Part No: MT9414C934 (3501D74H01) (OEM\*)
- Part No: DC026C 26mm OEM
- Part No: DC030B 30mm OEM
- Part No: 9234S004-R1
- Part No: 14203 15.2 V
- Part No: 14203 24.0 V

- Part No: M9237A020-R2
- Part No: 9236C238-R4 OEM
- Part No: coal for GM8713G220 oem
- Part No: 9236E837 old code, new code 94745004
- Part No: G42441253 oem
- Part No: GM9236S020-R1
- Part No: GM82 2D392
- Part No: GM8712C693 oem
- Part No: 9236C238-R5 OEM
- Part No: A5930 M543 1270 0808 03MSU OEM
- Part No: 8692A034-R6 - OEM
- Part No: Reducer for MT9414C934,3501D74H01 - (OEM\*)
- Part No: 2451-M5411 oem
- Part No: 9236E110-R1 7305D-028
- Part No: SE+119620001 (OEM)
- Part No: M9234A141-R1
- Part No: GM9433L255 oem
- Part No: GM8222D342
- Part No: A2824
- Part No: 4443S013
- Part No: 3482-MAC5114 oem
- Part No: P/N: 5484-875
- Part No: 964741924 oem
- Part No: GM8224S022
- Part No: GM9234S023-R1-SP
- Part No: GM14904S015-R1-SP
- Part No: 4202D123-R1 OEM
- Part No: GM923E471-R2
- Part No: P/N:2233-MT3142 oem
- Part No: 14237A164-R1 OEM
- Part No: 9237E248-R4 oem
- Part No: GM9213C494-R1
- Part No: 92-14W-1
- Part No: GM9213C400-R2 490199100-4 - OEM/customized
- Part No: GM9833C003-RA oem

- Part No: 14202D123-R1 oem
- Part No: Brushes for 14202D123-R1 oem
- Part No: 604704014
- Part No: GM9234C542 oem
- Part No: 869A034-R7 MT200
- Part No: GM9213C494-R1 (OEM)
- Part No: A4180-1
- Part No: GM14902D550-R8
- Part No: Brushes for M543 1270 0808 03 MSU
- Part No: GM8224S025
- Part No: 2242-ME2834 Mfg code: 28246-11 04 OEM
- Part No: AMETEK Motor 9434K350-R1 oem
- Part No: M9232A205 oem
- Part No: 9232S001-R1
- Part No: T9234C321 15.3 V/KRPM
- Part No: GM14902E332
- Part No: GM14633E270-R5 Y4611
- Part No: 2393-ME4614 OEM
- Part No: GM8214J389
- Part No: MBE5288-2234
- Part No: EM011502
- Part No: GM9233E990
- Part No: 9236E79-R1
- Part No: DC030B-2
- Part No: GM9434L280
- Part No: M9234A115-R1
- Part No: 8692A034-R7
- Part No: magnet for 2451-m4146
- Part No: GM9432J216-R2 OEM
- Part No: T9234C321-R2 15.3 VDC/KRPM
- Part No: GM9234S017-R1
- Part No: P/N: 15 180 0200 00
- Part No: P/N: 15 180 0201 00
- Part No: P/N: 15 180 0202 00
- Part No: K6917

- Part No: PG6612A119
- Part No: DC083A-20E0-A04
- Part No: 9237S010-R1
- Part No: A4180 (M586 0585 0606 12 TBV)
- Part No: T9234C321-R8 15.3 VDC/KRPM 11-18-13 OEM
- Part No: GM14904C516
- Part No: 9236E879-R1 OEM
- Part No: GM92\*E663-R2
- Part No: GM8713G948
- Part No: 103944-1
- Part No: brush gear for 9236c238-r2 (OEM)
- Part No: GM14902E030-R2
- Part No: GM9234S032-R1
- Part No: 4443S013 ( 24 VDC)
- Part No: dc040b-5000-a05-1
- Part No: 82000432-7-1
- Part No: M642 0860 1208 04TPZ
- Part No: 4411E059-R2
- Part No: GM9413C295 31124 obsolete
- Part No: 80-223902-90
- Part No: B3-ID23004-Q3
- Part No: Q3/C
- Part No: GM9236E009-R3
- Part No: P/N: 1013723000-PKG, Type: 101-028-050
- Part No: 8692A033 / R5 oem
- Part No: GM9414 B362
- Part No: GM9236S014
- Part No: MGM833A120-R1
- Part No: GM8822G109-R2
- Part No: GM9236E882 OEM
- Part No: 2234-MT2416
- Part No: ID23004
- Part No: E0005400
- Part No: GM92365015-R1
- Part No: 9412C436-R2 /5650163

- Part No: coal for 9412C436-R2 /5650163
- Part No: GM9236S014-R1-SP
- Part No: MT14205C546-R3
- Part No: M542 1100 0806 05 MPU ( OEM )
- Part No: M540 0741 0606 14 MPU ( OEM )
- Part No: 8692A033-R5 48V
- Part No: GM140904E523-R1
- Part No: 5484-803 D-FG001
- Part No: GM9636E980-R7 OEM
- Part No: GM8212S030
- Part No: GM9236E349-R2 OEM
- Part No: 42441253 OEM
- Part No: GM14904E523-R1
- Part No: DC040B
- Part No: contact carbon for GM9232E447
- Part No: GM9232E447
- Part No: GM9413-4
- Part No: 601101
- Part No: EC042B-1
- Part No: PLG42S 200:1
- Part No: 2232-M3991 (code 51633)
- Part No: reductor below the MT9414C934
- Part No: ?gm9236e157-r
- Part No: GM9236E157-R1
- Part No: EC083A-40C0-A13 OEM
- Part No: CH/C SN:190527127
- Part No: 3504D26G07
- Part No: GM8212D122-R2
- Part No: 9234S007-R1-SP
- Part No: B30A-002
- Part No: DC040B-3M00-A04-0
- Part No: B30A-002 DC19 33
- Part No: GM8222D577
- Part No: GM87125030
- Part No: MTC 3160 / 005038-02

- Part No: 329A813H04
- Part No: 9236C238-R5 + K80 S/M
- Part No: 2234-M4875
- Part No: GM9213-2
- Part No: ROCMT0001
- Part No: 9237-248-84
- Part No: 14232A107-R2
- Part No: M540 0741 0606 11MBU
- Part No: GM8212S242
- Part No: GM8224S017
- Part No: 100060 21 17
- Part No: GM8542S049-SP
- Part No: GM8542S049
- Part No: GM9213-1