

# ENDURA SUPPLY

## Ametek Windjammer Product List

- Part No: 117637-51
- Part No: 119152-01
- Part No: 150372-50
- Part No: 150372-50 Type K - OEM for TEKA
- Part No: Circuit board for 117459-04 G2.179.1501/04D
- Part No: 117459-04 G2.179.1501/04 not available/alternative 117459-05
- Part No: 119155-03(obsolete replaced by 119155-06)
- Part No: 119155-06
- Part No: P/N: 117459-23, obsolete, replacement 117459-05
- Part No: 117459-05
- Part No: 150908-50
- Part No: 119153-54
- Part No: AMETEK 117416-03
- Part No: K 150372-50 OEM/customized
- Part No: M-1136
- Part No: 119155-03 obsolete/replacement 119155-06
- Part No: 117459-04 obsolete/alternative 117459-05
- Part No: 119155-52
- Part No: 117630-03
- Part No: 117459-04 obsolete/replacement 117459-05
- Part No: 117416-03 obsolete, alternative 117416-51
- Part No: 119379-52
- Part No: 117638-03 not available/alternative 117638-53
- Part No: 117638-53
- Part No: 150158-009(obsolete/OEM)
- Part No: 0126MAE02X6
- Part No: AR508 / S 150372-50 Art.Nr: 150372-50
- Part No: 11741651
- Part No: 117642-00
- Part No: 117642-52
- Part No: 117459-55
- Part No: 117459-00

- Part No: 117459-01 old model, new model 117459-05
- Part No: 117459-03 not available/alternative 117459-05
- Part No: 119155-59 OEM
- Part No: 117630-06
- Part No: 117641-46
- Part No: 119101-01
- Part No: 116638-08
- Part No: BBA14-222HEB-80
- Part No: 150437-50
- Part No: 117632-52
- Part No: AC113S-1ACABC2E1DT-290
- Part No: 119153-51
- Part No: 8529548
- Part No: 119155-59 oem for Trotec 42335
- Part No: G2.179.1501/02
- Part No: 6060120014
- Part No: 117459-01 / type 01979 01 010396X6
- Part No: 119153-57
- Part No: 117637-51R / 08541235
- Part No: 3965900
- Part No: 117643-52
- Part No: 8544392
- Part No: 119153-53
- Part No: 8544391
- Part No: 119153-70 // 08569710
- Part No: 117459-05R