

ENDURA SUPPLY

Bitzer Product List

- Part No: 4CES9Y 40S
- Part No: 4DES-7Y-40S 400V
- Part No: 1001116296, 107023
- Part No: 101.0000
- Part No: 101.1629
- Part No: 101.1630
- Part No: 101.1682
- Part No: 101.1683
- Part No: 101.381654
- Part No: 101.381724 / SE-E1
- Part No: 101.383922
- Part No: 101.3913 343 014 02
- Part No: 101.3945
- Part No: 101.4281 LH104/S4N-8.2Y
- Part No: 101.4284 LH135/S6H-20.2Y
- Part No: 101.4802 2JES-07Y-40S
- Part No: 101.4812 2CES-3Y-40S
- Part No: 101.4957
- Part No: 101.7155
- Part No: 101.7262 LH44/2FES-3Y
- Part No: 101.7266 LH64/2DES-3Y
- Part No: 101.7268 LH84/2CES-4Y
- Part No: 101.7270 LH84/4FES-5Y
- Part No: 101.7274 LH104/4DES-7Y
- Part No: LH114/4CES-9Y
- Part No: 101.7277 LH104/4TES-9Y
- Part No: 101.7278 LH114/4TES-12Y
- Part No: 101.7279 LH114/4PES-12Y
- Part No: 101.7280 LH135/4PES-15Y
- Part No: 101.7282 LH135/4NES-20Y
- Part No: 101.7283 LH135/4JE-15Y
- Part No: 101.7284 LH135/4JE-22Y

- Part No: 4HE-18Y
- Part No: 101.7286 LH135/4HE-25Y
- Part No: 101.7287 LH135/4GE-23Y
- Part No: 101.7288 LH135/6JE-25Y
- Part No: 101.7289 LH135/6HE-28Y
- Part No: 101.7725
- Part No: 103-6081
- Part No: 2120102 OR 361322-03
- Part No: 2200120
- Part No: 2DES-2Y-40S
- Part No: 2GES-2Y-40S VD
- Part No: 2KC- BIS 2FES
- Part No: 301 109 50
- Part No: 302 297 93
- Part No: 302297-92
- Part No: 305 231 01
- Part No: 308001-61
- Part No: 343 014 02
- Part No: 343 427 01
- Part No: 346 720 43 BITZER EIBAUMOTOR
- Part No: 347 017 10 101.3947
- Part No: 347027-01
- Part No: 347320-33
- Part No: 361315-11
- Part No: 362 003 01
- Part No: 362 004 02
- Part No: 362 016 02
- Part No: 372 316 07
- Part No: 372 421 06
- Part No: 372010 90
- Part No: 374 017 03
- Part No: 4 EC 4.2
- Part No: 4 FC.3.2
- Part No: 4 G-20.2
- Part No: 4DES-7Y-40S (101.4819 Bitzer halbh. Verdichter CE3 400V)

- Part No: 4EES-4Y-40S
- Part No: 4EES-4Y-40S 400V/3/50HZ
- Part No: 4FC-3,2 Y
- Part No: 4G-30.2
- Part No: 4H-15.2Y-40P (Obsolete replaced by 4HE-18Y-40P)
- Part No: 4HE-18Y-40P
- Part No: 4N-20.2
- Part No: 4NCS-12.2 obsolete/repleacment 101.4957
- Part No: 4PC7.2
- Part No: 4PE-12Y-40P
- Part No: 500059-10
- Part No: 531.0128
- Part No: 6B5406PL-2NU
- Part No: 6H-35,2
- Part No: 6H-35.2Y
- Part No: 80001347
- Part No: 80035681
- Part No: 80064655
- Part No: 80064656
- Part No: 80064658
- Part No: 80064661
- Part No: 860-3003-01
- Part No: 892-1140-02
- Part No: Art.Nr. 101.7156
- Part No: B 320 SH
- Part No: BSE 170 Kanne 10L 531.0125
- Part No: CSH 6563-40Y400V
- Part No: CSH 7573-90Y400V/3/50HZ o.Ventile
- Part No: CSH 8563-125Y400V/3/50HZ
- Part No: CSH 9571 180Y 40D
- Part No: CSH7571-90Y-40D
- Part No: ESH736-40S
- Part No: ESH743Y-25S
- Part No: GROUPE LH114-4TES-12
- Part No: HSKC 7471-90

- Part No: K 4803 TB-4
- Part No: LH135/S6H-205.2Y
- Part No: S6J-16.2-35P
- Part No: MADENI YAG B5.2
- Part No: 374 015 02 (101.382972 Bitzer Wellenabdichtung)
- Part No: SE-B2 F.2EL-8FC
- Part No: 22A613
- Part No: 6F-50.2Y-40P 101.4144 400V PW-3-50Hz
- Part No: 6FE-50Y-40P
- Part No: 4EES-6Y-40S 400V ARTIKEL 101.4817
- Part No: Type: VSK3161-15Y Ser. No: 15620220 OEM!!
- Part No: 304 055 03
- Part No: 304 054 02
- Part No: 4 TES-12Y
- Part No: 4 NES-20Y
- Part No: 4 JE-22Y
- Part No: 4J-13.2Y-2NU - Obsolete!!Replaced with "4JE-13Y-40P"
- Part No: 4TCS-802Y-40P - Obsolete!! Replaced with "4TES-9Y-40P"
- Part No: 4PCS-15.2Y-2NU - Obsolete!!Replaced with "4PES-15Y-40P"
- Part No: 4JE-13Y-40P
- Part No: 4TES-9Y-40P
- Part No: 4PES-15Y-40P
- Part No: K203HB-2/4
- Part No: SPB-1800
- Part No: 343 218 02 CSH/W 85.. bis 95
- Part No: CSH 7581-80Y-40P
- Part No: CSH8591-140C-40 D
- Part No: Type: 6f-50.2-40P, SN: 1674311433 - Obsolete!!Replaced with "6FE-50Y-40P"
- Part No: 6FE-50Y-40P 400V
- Part No: 361815-01
- Part No: 101.381689
- Part No: SE-B2
- Part No: 4G.2 obsolete, replacement 4G.2Y
- Part No: No. A-78
- Part No: 4G.2Y

- Part No: 311 100-08
- Part No: 320 500 08
- Part No: 301 007-07
- Part No: 302 297-40
- Part No: 382 300-58
- Part No: 382 310-25
- Part No: 305 125-03
- Part No: 311 100-04
- Part No: 320 500-07
- Part No: 362 503-02
- Part No: 325 000-34
- Part No: 372 812-02
- Part No: 303 602-11
- Part No: 382 112-01
- Part No: 381 214-01
- Part No: PN:34794901 obsolete/replaced by 101.5593
- Part No: 101.5593
- Part No: 4EES-4Y
- Part No: 101.4818
- Part No: W-4H-15.2 obsolete/ replaced by 4HE-18Y-40P 400V
- Part No: 4HE-18Y-40P 400V
- Part No: LH135E/4PES-15Y 400V
- Part No: Type: 6F-50.2 Y, SN: 662502306 obsolete/replaced by 6FE-50Y-40P
- Part No: LH135E/4PES-12Y 400V
- Part No: OSKA 8591-K NH3
- Part No: OSKA 8571-K NH3
- Part No: OSKA 7471-K NH3 obsolete/replaced by OSKA 7472 NH3
- Part No: 4NSL-30K-40P 400V
- Part No: 4DSL-10K-40S 400V
- Part No: Spare parts for OSKA 8591-K NH3
- Part No: Spare parts for OSKA 8571-K NH3
- Part No: Spare parts for OSKA 7471-K NH3
- Part No: Spare parts for OSKA 7441-K NH3
- Part No: Spare parts for OSKA 4NSL-30K-40P CO2
- Part No: Spare parts for OSKA 4DSL-10K-40S CO2

- Part No: 6F-50.2Y-40P obsolete/replaced by 6FE-50Y-40P 400V
- Part No: OSKA 7472 NH3
- Part No: 300 028 07
- Part No: 374 027 01
- Part No: 384 102 01
- Part No: 346 331 51
- Part No: 372 811 09
- Part No: 372 421-02 obsolete replacement 372 422 01
- Part No: 372 124 01
- Part No: 372 120 01
- Part No: 6F-50.2Y-40P,S/N:1674104795 obsolete replacement 6FE-50Y-40P
- Part No: CSH 7561-80-40P obsolete replacement CSH 7563-80Y400V
- Part No: Spare parts for Compressor CSH 7561-80-40P
- Part No: 372 422 01
- Part No: 4TC-12.2Y-40P
- Part No: CSH 7563-80Y400V 101.7710
- Part No: Typ 8FC-70.2-40P S.Nr.1681104955
- Part No: CSH 8561-125Y OBSOLETE, REPLACEMENT 101.7720 / CSH 8563-125Y!!!
- Part No: 305054-02-unavailable
- Part No: 101.6805 / 304-055-01
- Part No: 101.7720 / CSH 8563-125Y
- Part No: 362 002 06
- Part No: 360 504 01
- Part No: 101.4832 / 4NES-14Y-40P 400V
- Part No: 343219-04
- Part No: 060B0171/T
- Part No: 372 001 07
- Part No: 372 003 19
- Part No: 372 903 01
- Part No: 386 100 03
- Part No: 386 100 07
- Part No: 386 200 03
- Part No: 386 200 04
- Part No: 386 200 06
- Part No: 386 300 02

- Part No: 374 015 04
- Part No: 4DES-5Y-40S 400V
- Part No: 4TCS-12.2Y-40P - obsolete (replaced by 4TES-12Y-40P 400V)
- Part No: 4TES-12Y-40P 400V
- Part No: CE2S 2CES-3Y-40S 400V/ 101.4812
- Part No: BZ 03N7471k
- Part No: BSE 170 Dose 1L 531.0122
- Part No: 320 500 06
- Part No: 304 051 03
- Part No: 372 511 11
- Part No: 372 812 01
- Part No: 347602-03 obsolete, replacement 347 600 03
- Part No: 374011-03 obsolete, replacement 374 017 03
- Part No: 372704-02 obsolete, replacement 372 712 01
- Part No: 101.3937
- Part No: 372 712 01
- Part No: 4EES-4Y-40S 400V
- Part No: 4CES-6Y-40S 400V
- Part No: 101.381742
- Part No: 346 670-43
- Part No: 347 019 04
- Part No: CSH8573-140Y
- Part No: Typ:4G-30.2Y-40P, SN:1678912646 obsolete/replaced by 4GE-30Y-40P 400V
- Part No: 4GE-30Y-40P 400V
- Part No: 101.3823
- Part No: 101.5647
- Part No: 302 297 37
- Part No: 372 816 02
- Part No: 301 007 10
- Part No: 4H-15.2Y-40P 3PH - obsolete, replaced by 4HE-18Y-40P 400V
- Part No: 347 949 01
- Part No: 2KC-05Y - obsolete, replaced by 2KES-05Y-40S 400V
- Part No: 6H-35,2 Y - obsolete, replaced by 6HE-35Y-40P 400V
- Part No: 301 168 52
- Part No: 101.4801 / 2KES-05Y-40S 400V

- Part No: 6HE-35Y-40P 400V
- Part No: 361 329 06
- Part No: 101.4632
- Part No: OSKA8571-K / 101.2522
- Part No: 347 019 02
- Part No: 4DC-5.2-40S - obsolete, replaced by 4DES-5Y-40S 400V
- Part No: 101.4818 / 4DES-5Y-40S 400V
- Part No: 6J-33.2Y-40P 400V PW-3-50Hz
- Part No: 302 297 46
- Part No: 382 300 46
- Part No: 382 310 13
- Part No: Piston for 6J-33.2Y-40P 400V PW-3-50Hz
- Part No: Rings Set for 6J-33.2Y-40P 400V PW-3-50Hz
- Part No: 4J,6J 302 297 46
- Part No: K2923TB-4
- Part No: SET OF GASKET for 2N.2
- Part No: 101.6807
- Part No: 2CES-3Y-40S 400V (101.4812)
- Part No: 210 0076
- Part No: 4H,6H,4H.2,6H.2 304 051 02
- Part No: P/N: 101.6807, Type: 2FC-2.2/3.2 304 055 03
- Part No: 372 937 03
- Part No: 311104-04
- Part No: 315 100-07
- Part No: 315 107 11
- Part No: 302 105 01
- Part No: 382 300 37
- Part No: Nr. 36200101
- Part No: 374 010 05
- Part No: INT69 B3
- Part No: CSH 9583-210Y 400V BSE170 o.Ventile
- Part No: CSH 9593-240Y 400V BSE170 o.Ventile
- Part No: 151.7242 / K203HB-2/4
- Part No: CE3S 4DES-5Y-40S 400V
- Part No: Type IV 315 107 03

- Part No: 370 000 19
- Part No: 304 055 04
- Part No: seal kit for 500059-10
- Part No: 4TES-9Y-40P 400V
- Part No: GSD 80385VAB46J OEM
- Part No: 101.4633
- Part No: OLC-K1 (101.4633)
- Part No: 4H 252Y 40P REPLACED BY 4HE-25Y-40P 400V (101.4839)
- Part No: 4G-20.2Y obsolete replaced by 4GE-23Y-40P 400V
- Part No: 4GE-23Y-40P 400V
- Part No: 4HE-25Y-40P 400V (101.4839)
- Part No: CSH8583-125Y (101.7723)
- Part No: 321 105 07
- Part No: 302 298 79
- Part No: 311 135 03
- Part No: 372 841 28
- Part No: 372 823 01
- Part No: 301 129 50
- Part No: 304 063 12
- Part No: 362 004 04
- Part No: 372 704 01
- Part No: 372 704 05
- Part No: 321 105 03
- Part No: 302 298 61 (101.383981)
- Part No: 311 125 01
- Part No: 372 835 21 (101.382881)
- Part No: 372 702 03 (101.384172)
- Part No: 301 168 50 (101.380212)
- Part No: 304 059 07 (101.380657)
- Part No: 362 012 02 (101.382257)
- Part No: 347 501 05
- Part No: 361 106 06
- Part No: 361 106 02
- Part No: 372 002 02
- Part No: 360 212 02

- Part No: 382 231 26
- Part No: 312 036 02
- Part No: 313 000 29
- Part No: 384 902 03
- Part No: 384 902 01
- Part No: 380 306 52
- Part No: 380 306 51
- Part No: 372 021 35
- Part No: 372 998 01
- Part No: 34900607
- Part No: 372 836 01 (101.382885)
- Part No: 30026901
- Part No: 343217-01 obsolete, replacement 101.3859
- Part No: OVERHAULING GASKET FOR S6J-16.2
- Part No: PISTON AND PIN PACKAGE FOR S6J-16.2
- Part No: CONNECTING ROD PACKAGE FOR S6J-16.2
- Part No: PISTON RING FOR S6G-16.2
- Part No: PISTON RING BOTTOM FOR S6J-16.2
- Part No: OIL FILTER STRAINER FOR S6J-16.2
- Part No: TRUSTWASHER FOR S6J-16.2
- Part No: 101.3859
- Part No: 34731806 obsolete, replacement 34733403
- Part No: CSH 9563-210(Y)
- Part No: 34702701 obsolete, replacement SE-B2 f.2EL-8FC 347 028 01
- Part No: 34733403
- Part No: 4ncs-20.2y-40p - obsolete, replaced by 4NES-20Y-40P 400V
- Part No: 4NES-20Y-40P 400V
- Part No: XGBI9999W Type CSH95103-280Y-40D
- Part No: 382300-46
- Part No: 382310-13
- Part No: 311 100 05
- Part No: 320500-07
- Part No: 372314-03
- Part No: 32050006
- Part No: 382403-04

- Part No: 361338-01
- Part No: 372415-02
- Part No: 302297-46
- Part No: 374027-01
- Part No: 325910-01
- Part No: 372303-01
- Part No: 372003-15
- Part No: 370 004 01
- Part No: 370004-02
- Part No: 372704-01
- Part No: 372200-04
- Part No: 304051-01
- Part No: 362003-01
- Part No: 372811-02
- Part No: 373 704 05
- Part No: OPT-CR11-230V
- Part No: OPT-CKCH-140230
- Part No: 6GE-34Y-40P 400V
- Part No: 101.384157
- Part No: 37401802
- Part No: 31000101
- Part No: 302 003 01 obsolete, no replacemnt
- Part No: 30223904
- Part No: 30405004
- Part No: SE-B1 f.2KC-4NC 347 019 01 (22A607)
- Part No: GSD80485VAB4-2
- Part No: GSD80385VAB4-2
- Part No: S4N-8.2Y
- Part No: S4G-12.2Y
- Part No: S6G-25.2Y
- Part No: 301 007 16
- Part No: 372 301 03
- Part No: 372 511 07
- Part No: 370 004 03
- Part No: 302 297 43

- Part No: 347035-01
- Part No: CSH7563-80Y
- Part No: HSK7451-70-40P
- Part No: CE3S 4EES-4Y-40S 400V
- Part No: K4803TB(2PASS)
- Part No: OLC-D1 34794901 (AYBI1949A)
- Part No: CSH 6563?60Y
- Part No: 4DES-5Y-40S
- Part No: CSH9593-240Y
- Part No: S6F-30.2Y-LS
- Part No: 4GE-23Y
- Part No: 4PES-12Y
- Part No: 6GE-34Y
- Part No: 343213-12
- Part No: repair kit for 6F-50.2Y-40P
- Part No: 6B5406PH-4PU
- Part No: 372 817 01
- Part No: LH135E/4PES-15Y-40P 400V
- Part No: 34794901
- Part No: 2CES-3Y
- Part No: K203HB/2CES-4Y
- Part No: 151.7244
- Part No: 4VES-7Y
- Part No: S6J-16.2Y-40P 400V
- Part No: CSH 9591 -240Y-40D L403939
- Part No: CSH6563-60Y-40P
- Part No: ABBI5350D
- Part No: 34431001
- Part No: B-IY
- Part No: 6HE-28Y-40P 400V
- Part No: 4CES-9-2DU-1D wrong code- new code XGBI9999W
- Part No: XGBI9999W
- Part No: 6DTE-50K-40P
- Part No: 915 101 11
- Part No: 347318-06

- Part No: 6FE-44Y
- Part No: 343 208 34
- Part No: 343 208 23
- Part No: 389 002 01
- Part No: ABBI4133E
- Part No: ABBI5351E
- Part No: XGBI9999W CSH9583-280Y
- Part No: 347 013-03
- Part No: ABBI2150E
- Part No: ABBI3130E
- Part No: CSH 9553-180Y 400V BSE170 o.Ventile
- Part No: 34703401
- Part No: 4PES-12Y-40P
- Part No: K2923TB-2
- Part No: 372301-03
- Part No: 372303-02
- Part No: 305064-02
- Part No: 372112-03
- Part No: 305069-05
- Part No: 375014-04
- Part No: 372113-03
- Part No: 4FES-5-4SU
- Part No: 2DES-3-4SU
- Part No: 2FES-3-4SU
- Part No: ACBI1230A
- Part No: 101.4815/CE3S 4FES-5Y-40S 400V
- Part No: F202H
- Part No: 343 219 01
- Part No: 347 600 01
- Part No: 347 023 03
- Part No: AW55855
- Part No: STAS-485T
- Part No: CSH6553-50Y
- Part No: CSH7573-90Y
- Part No: CSH8593-140Y

- Part No: 311 104-08
- Part No: 311 104-09
- Part No: 310 003-01
- Part No: 374 008-04
- Part No: 315 107-04
- Part No: 302 239-06
- Part No: 304 050-06
- Part No: 372 800-06
- Part No: 372 835 21
- Part No: 302 298 61
- Part No: 101.2880
- Part No: 101.3886
- Part No: 101.1858
- Part No: 101.3819
- Part No: OLC-S1
- Part No: 372 811 03
- Part No: 6F-50.2Y-35P
- Part No: 6FE-50-3PU-2D
- Part No: 4FES-3Y
- Part No: CSH8571-140Y-40P
- Part No: VSK 3161-15Y-40P
- Part No: CE1S 2FES-3Y-40S 400V
- Part No: CSH8573-140Y-40P
- Part No: 302 268 91
- Part No: 91511505 / BSE 170 / NDBI2001A
- Part No: 37402208
- Part No: K813HB-4
- Part No: 372 823 02
- Part No: 372 837 01
- Part No: 302 575 04
- Part No: 302 574 60
- Part No: 374 100 12
- Part No: 374 100 11
- Part No: 386 604 01
- Part No: 382 403 05

- Part No: 372 001 10
- Part No: 382 500 03
- Part No: 361 106 05
- Part No: CSH6563-60Y-4PU
- Part No: OSNA8571-K
- Part No: 347004-03
- Part No: LH 135/ 4 NES 20 Y
- Part No: 343 309 02
- Part No: 375 068 01
- Part No: 347 020 03
- Part No: 347 032 01
- Part No: 347 505 02
- Part No: K2923T-2
- Part No: K2923T-4
- Part No: AFBI3455A
- Part No: 382 500 01
- Part No: 374 022 07
- Part No: GSD80295VAB432
- Part No: VSK3161-15Y-40S / PN: 101.0000
- Part No: AFBI3140A
- Part No: CHS6563-40Y
- Part No: GSD60154VAB2-2
- Part No: GSD60182VAB2-2
- Part No: 347043-08
- Part No: K 1053HB
- Part No: 2GES-2.EY
- Part No: GSD80485VAB4
- Part No: 4GE-30Y 30HP(R407C)
- Part No: TYP. 6FE-50Y-40P SN.1600506109
- Part No: 6GE-40Y-40P
- Part No: 4EES-4-4SU-1D
- Part No: Oil level sensor for CSH 8591-140Y-40P
- Part No: 347 962 01
- Part No: 361 315 18
- Part No: 2HES-2Y

- Part No: 2FES-2Y
- Part No: 362 105 02
- Part No: 360 110 06
- Part No: 361 110 01
- Part No: 302 298 69
- Part No: 304 063 35
- Part No: 347 600-003
- Part No: BSE 170 L
- Part No: SN: 1171000558
- Part No: 4VES-10Y
- Part No: 361 100 35
- Part No: 361 100 26
- Part No: 302 977 01
- Part No: 311 004 02
- Part No: JAFPR007001
- Part No: OSNA 7472 NH3
- Part No: OSNA 7471
- Part No: 4NE-20Y-2NU
- Part No: 343256-03
- Part No: 32500068
- Part No: OA9111A
- Part No: OAS3088
- Part No: 4EES-6-2DU-1D
- Part No: CSH8563-90Y-4PU
- Part No: 4NE-20-4PU-1D
- Part No: HSK 7471-90
- Part No: BLUE-1.250
- Part No: CSH85 71-110Y
- Part No: 37402312
- Part No: 91511502 / BSE 170
- Part No: S6H 20.2Y
- Part No: HSK7451-70-35P
- Part No: Type: 4P,4P.2 (30405202)
- Part No: GSD80385VAB562
- Part No: 343213-04