

# ENDURA SUPPLY

## Britool Product List

- Part No: AVT1200A
- Part No: EVT 600A - 1/2
- Part No: DRIVEN SLOT FOR EVT3000A
- Part No: E100109B
- Part No: E340 T
- Part No: ETM250E
- Part No: EVT1200A
- Part No: EVT-1200A
- Part No: EVT-2000A
- Part No: EVT3000A
- Part No: EVT3000A MODEL 70-330 NM
- Part No: GVT8400
- Part No: HVT 7200
- Part No: HVT5000
- Part No: RPSEVT6H
- Part No: AVT 300A - 3/8
- Part No: EVT3000A 70-330Nm
- Part No: 1/2" Square Drive for EVT3000
- Part No: EVT 600A
- Part No: BRIEVT2000A
- Part No: IMPACT UNIVERSAL JOINT 1/2" TO 1/2"
- Part No: IMPACT UNIVERSAL JOINT 1/2" TO 3/4"
- Part No: IMPACT UNIVERSAL JOINT 3/4" TO 3/4"
- Part No: IMPACT UNIVERSAL JOINT 3/4" TO 1/2"
- Part No: BXEEVT1200A
- Part No: AVT100A
- Part No: BRIEE189867B
- Part No: ETV2000A
- Part No: DSR2037-6 - discontinued
- Part No: AB562 - discontinued
- Part No: DH344
- Part No: EB500 - discontinued

- Part No: XBRKSDEVT3000
- Part No: AVT 100A - 3/8
- Part No: E100104
- Part No: E031805B
- Part No: EVT3000APB
- Part No: FRAMEWORK THROUGH 1/2 of mod. EVT 3000A
- Part No: EVT600A
- Part No: BRIE031805B
- Part No: K0301
- Part No: AVTR 600 obsolete,replaced by AVT600
- Part No: EVTR 1200 obsolete,replaced by EVT1200A
- Part No: EVTR 3000 obsolete,replaced by EVT3000A
- Part No: AVT600
- Part No: UCTSF 70 obsolete,replaced by E100106
- Part No: UCTSF 100 obsolete,replaced by E100107
- Part No: UCTLF 200 obsolete,replaced by E100108
- Part No: E100106
- Part No: E100107
- Part No: E100108
- Part No: Spare part for EVT 1200A
- Part No: AVT300A
- Part No: AVT330-A
- Part No: AVT 100 EVT 600A AT-2503
- Part No: 486-C070N
- Part No: 748254
- Part No: D46
- Part No: AVT 300 A - 5-33 Nm
- Part No: AVT 600A
- Part No: EVT600
- Part No: EVT2000A 1/2
- Part No: HVT 5000
- Part No: 2000A
- Part No: AVT 300
- Part No: BR■TOOL 300
- Part No: BR■TOOL 600

- Part No: BR■TOOL 1200
- Part No: BR■TOOL 2000
- Part No: BR■TOOL 3000
- Part No: ewt 6000 a
- Part No: EVT 2000