

# ENDURA SUPPLY

## Broadcom (Avago Technologies) Product List

- Part No: 630-HEDS-5500 C06 HP
- Part No: 630-HFBR-4533Z MFR. #:HFBR-4533Z
- Part No: AFBR-57D7APZ-ELX OBSOLETE
- Part No: ASSR-1530-005E
- Part No: AT25DQ321-SH-B - NOT AVAILABLE
- Part No: HDLX-2416
- Part No: HEDL-5505#I13
- Part No: HEDL-5540#A11
- Part No: HEDL-5540#I11
- Part No: HEDL-5600#A06
- Part No: HEDL-5600#H06
- Part No: HEDM-5500#B14
- Part No: HEDS 5500 C11
- Part No: HEDS-5500#A14
- Part No: HEDS-6140#B10
- Part No: HEDS-5500#C13 (pack 1x100)
- Part No: HEDS-5500#A02
- Part No: HEDS-5500#A13
- Part No: HEDS-5645#H14
- Part No: HEDS5701-G
- Part No: HEDS-9100#A00
- Part No: HEDS-9100-A-00-1112
- Part No: HEDS-9140#A00
- Part No: HEDS-9200-300
- Part No: HFBR-1414 - OBSOLETE, SIMILAR PRODUCT HFBR-1414Z
- Part No: HFBR-1414Z
- Part No: HFBR-14E4
- Part No: HFBR-2412
- Part No: HFBR-24E2
- Part No: HLMP-EL1G-Y10DD
- Part No: SFH551/1-1V
- Part No: SP000063855

- Part No: SP000063858
- Part No: SSH551V
- Part No: HEDS-5645 A06
- Part No: AFBR-5715PZ-NT1
- Part No: AFBR-5715PZ-GB1
- Part No: AFCT-5715PZ-NT1
- Part No: AFCT-5715PZ-GB1
- Part No: HEDS-5540#A11
- Part No: HEDS-9100#B00
- Part No: ASSR-1510-003E
- Part No: HFBR-4535Z
- Part No: HFBR-4531Z
- Part No: AFBR-703SDZ-IN1(Obsolete replaced by 630-AFBR-709SMZ)
- Part No: AFCT-701SDZ-IN1(Obsolete)
- Part No: ABCU-5710RZ,1000BASE-T SFP (Obsolete replaced by 630-ABCU-5740RZ)
- Part No: hedm-5500 j14 (stock)
- Part No: AFBR-700SDZ - obsolete
- Part No: ABCU-5710RZ - obsolete, similar product ABCU-5740RZ
- Part No: HEDS-5540#C11
- Part No: HEDS-5540#E06
- Part No: HEDS-5540#A01
- Part No: HEDS-5540#A02
- Part No: HEDS-5540#A06
- Part No: HEDS-5540#A14
- Part No: HEDS-5540#A12
- Part No: HCNW3120 - incomplete model
- Part No: ACPL-C87B-000E
- Part No: AFCT-5715PZ
- Part No: AFCT-701SDDZ
- Part No: HEDL-5645#A13
- Part No: AT-30511-TR1G
- Part No: HEDS-9100#E00
- Part No: HEDS-5600 G06
- Part No: H 9720 L 0949
- Part No: ALMD-EG3D-VX002

- Part No: ALMD-CM3D-XZ002
- Part No: HLMP-EG1B-Z10DD
- Part No: HLMP-CM3A-Z10DD
- Part No: HFBR 57E0PZ 0952
- Part No: HFBR 57E0PZ 0951
- Part No: HFBR 570PZ 1001
- Part No: AFBR-5710PZ
- Part No: 128C930H01
- Part No: EDS-5500#S13
- Part No: AFBR-5701LZ
- Part No: CAN1/205W/DM
- Part No: LSI00197
- Part No: LSI00264
- Part No: iSAS-7373-HT - SFF-8087
- Part No: TO SFF-8087
- Part No: HFBR-1522 obsolete/replaced by HFBR-1522Z
- Part No: HFBR-2522Z
- Part No: HFBR-4533Z
- Part No: HFBR-1522Z
- Part No: AELT-5000-S16 obsolete
- Part No: bcm5751
- Part No: AFBR-709DMZ
- Part No: HEDS-9100#S00
- Part No: HEDL-5540#A14
- Part No: HEDM-5500#B11
- Part No: HEDS-5640#A06
- Part No: AEDR-8500-102
- Part No: HEDS-9100#C00
- Part No: HFBR-4506Z
- Part No: ACPL-H312-000E
- Part No: A3101,DIP-8
- Part No: HEDS-9700#E50
- Part No: ACPL-H312-560E
- Part No: HEDS-5600#C06
- Part No: HEDS-9200#360

- Part No: HEDS-9200#Q00
- Part No: ACPL-217-50BE (pack 1x3000)
- Part No: AFBR-700SDZ
- Part No: AFBR-703SDZ-IN1
- Part No: AFCT-701SDZ-IN1
- Part No: HCPL-0453-500E (reel of 1500 pcs)
- Part No: HEDS-5605#A13
- Part No: AEDR-8502-102
- Part No: AEDR-8600-100
- Part No: AEIC-7272-S16
- Part No: HEDS-5500#C13
- Part No: ACPL-247-500E
- Part No: HFBR-EUS100Z (roll x100 meters)
- Part No: HEDS-9730#Q50
- Part No: HEDS-9730#150
- Part No: HEDS-9731#Q50
- Part No: HEDS-9731#150
- Part No: AFBR-57D7AMZ-QL
- Part No: HSMG-C280 (1 x 4000 pcs.)
- Part No: HSMC-C280 (1 x 4000 pcs.)
- Part No: HSMY-C280
- Part No: HEDS-9100#F00
- Part No: HSMG-C280 (pack x4000)
- Part No: H5-25412-00
- Part No: BCM5761
- Part No: HRPD-AD32#54C
- Part No: QFBR-5751APZ
- Part No: HCNW4504
- Part No: HFCT-721XPD obsolete/alternative XFP-10GLR-31 (10GBASE-LR XFP) (FiberStore)
- Part No: HEDS-9140#H00
- Part No: HCPL-181-00BE (pack x3000)
- Part No: BCM-95722A2202G
- Part No: AEAT-6600-T16
- Part No: HFBR-4593Z
- Part No: HFBR-RUD100Z

- Part No: HFBR-4532Z
- Part No: HFBR-2528Z
- Part No: HFBR-1528Z
- Part No: HCPL-314J
- Part No: HCPL-314J-500E
- Part No: HCPL-314J-500E (pack 1x850 pcs)
- Part No: HEDS 9140-200 E
- Part No: HFBR-EUS500Z
- Part No: HFBR-EUD500Z
- Part No: HEDS-9730
- Part No: HEDM-5500#B02
- Part No: HEDL-5540#A12
- Part No: HEDL-9140#A00
- Part No: P/N: HFBR-2402 obsolete, available RoHS version HFBR-2402Z
- Part No: P/N: HFBR-1402 obsolete, available RoHS version HFBR-1402Z
- Part No: HFBR-2402Z
- Part No: HFBR-1402Z
- Part No: HFBR-57E0PZ
- Part No: HSMS-2812-TR1G obsolete
- Part No: AFBR-703SDZ
- Part No: HEDS-5500#F02
- Part No: H9730
- Part No: AEDT-9810-J00 (pack x200)
- Part No: AEDT-9811-J00 (pack x200)
- Part No: AEDR-8712-102
- Part No: SAS3108
- Part No: HFBR-4533 Z
- Part No: HFBR-4535 Z
- Part No: HCPL-7800A-000E
- Part No: BCM2836RIFBG
- Part No: HCNW4504-300E (pack of 2 pcs)
- Part No: HCNW2611-500E (1 package-5 pcs)
- Part No: HSMG-C170
- Part No: HDLG-2416
- Part No: ACPL-064L-060E

- Part No: HEDS-5500 I 14
- Part No: PEX8619-BA50BC G
- Part No: 1238 A
- Part No: HEDS-5500#A11?
- Part No: HEDS-5500#A12
- Part No: AS38-H39E-B13S
- Part No: ASSR-1530
- Part No: HCPL-3120-300E
- Part No: HEDS-5500#F12
- Part No: HEDS-9701#C54
- Part No: HEDS-5540 I11
- Part No: Shaft for HEDS-5500#F12
- Part No: HEDS 5600 A06
- Part No: HFBR-4513Z
- Part No: H0113D0059C2/06
- Part No: HEDS-5505#A13
- Part No: T-1505A
- Part No: R-2505AZ
- Part No: HEDS-5645 A12
- Part No: HCPL-181-00BE
- Part No: HEDL-5500#A02
- Part No: 05-25420-17
- Part No: AFBR-79EBMZ
- Part No: ACPL-P484-000E
- Part No: HCNW4506
- Part No: A786J
- Part No: ACPL-C87A-000E
- Part No: HEDL-5540#A13
- Part No: HEDS-5120#C13
- Part No: HEDS-5500#S13
- Part No: 1412TZ TX 1049
- Part No: HEDS-5500-C13 2048A
- Part No: HCPL-2300
- Part No: HFBR-END020
- Part No: AFBR-4594Z

- Part No: HFBR-2532Z
- Part No: HFBR-1532Z
- Part No: HFBR-4503Z
- Part No: HFBR-4516Z
- Part No: HFBR-4526Z
- Part No: HEDS-5120#A11
- Part No: QFBR 5750 APZ
- Part No: ACPL-K376-500E
- Part No: ACPL-024L-000E
- Part No: AFBR-57G5MZ-ELX
- Part No: Part no: H0113D0059C2/06
- Part No: HEDL-5540#A02
- Part No: SFH757V -SP000063858
- Part No: AFBR-57F5MZ-NA1 16 GFC SFP+ SWL
- Part No: 33-00279R6+A2 10G SFP+ SWL
- Part No: HEDL-5605#A06
- Part No: HLMP-EJ08-WZ000
- Part No: ACSL-6420-00TE
- Part No: ADT7461AARMZ-R
- Part No: CNY17-3-300E
- Part No: ACSL-6400-00TE
- Part No: H9731
- Part No: HLMP-EG08-Z2000
- Part No: HEDL-5540-111
- Part No: HEDL-5540#A01
- Part No: AFBR-5903AZ
- Part No: AFBR-786BEZ
- Part No: AFBR-776BEZ
- Part No: HEDS-9040#T00
- Part No: HEDS-9040#J00
- Part No: HEDS-9040#B00
- Part No: HFBR-2506AMZ
- Part No: HFBR-2506AFZ
- Part No: HSME-C191
- Part No: BCM5709C

- Part No: HEDS-5500#A06
- Part No: AFBR-S10PS010Z
- Part No: AFBR-S10PS011Z
- Part No: ACPL-217-500E
- Part No: 05-50077-01 / 9560-8i
- Part No: HEDS-9000/9100
- Part No: HEDS-51X0/61X0
- Part No: LSI HBA SAS 9300-8e
- Part No: HCMS-3917
- Part No: ACPL-214-500E
- Part No: AFBR-S10TR001Z
- Part No: QFBR 5751APZ GBIT