

ENDURA SUPPLY

Clampco Product List

- Part No: 5050100
- Part No: 94100-0300 C410C-75-300-S
- Part No: 94100-0350 C410C-75-350-S
- Part No: 941YL-0200
- Part No: 941YL-0300
- Part No: 941YL-0400
- Part No: 941YL-0500
- Part No: 995XJ-0484
- Part No: BEQC83011
- Part No: CLAMP-NSA8603-587
- Part No: F1019M0200
- Part No: F1019M0250
- Part No: F1019M0300
- Part No: F1019M0400
- Part No: F1019M0500
- Part No: MUSA-10122-001
- Part No: O-RING FOR CLAMP-NSA8603-587
- Part No: SEGD48B32
- Part No: SEGS12B10
- Part No: SEGS23200K
- Part No: SEGS23P2K
- Part No: SEGS23P2K_EX3
- Part No: SEGS24B10
- Part No: SEGS24B32
- Part No: SEGS2B32
- Part No: SEGS48B10
- Part No: SEQC83051
- Part No: SP_SPL023B32
- Part No: SP_SPL024A32
- Part No: V0135200M-0588-S2
- Part No: V01-3-81-00-N-0606-S2
- Part No: V02-3-53-00-N-0239-S1

- Part No: V02-3-53-00-N-0415-S1
- Part No: V02-3-61-00-N-0438-S1
- Part No: V07-3-42-00-M-0286-S3 WITH SAP
- Part No: V07-3-42-00-M-0336-S3 WITH SAP
- Part No: V07-3-42-00-M-0386-S3 WITH SAP
- Part No: V07-3-42-00-M-0486-S3 WITH SAP
- Part No: V07-3-42-00-M-0586-S3 WITH SAP
- Part No: 994CY-1024 A97 D = 250
- Part No: SEMO230A
- Part No: 94100-0300
- Part No: SP_SPL023200K
- Part No: V01-1-54-00-W-0314-S14
- Part No: 321A01YB
- Part No: 998EZ-0367
- Part No: 998EZ-0540
- Part No: 998EZ-0934
- Part No: 998EZ-0642
- Part No: 995ML-0236
- Part No: 04552 oem
- Part No: BC-03
- Part No: 94101-1060
- Part No: 94101-1075
- Part No: 94101-1088
- Part No: 94101-1200
- Part No: 94101-1222
- Part No: 94101-1275
- Part No: 94101-1425
- Part No: 94101-1625
- Part No: 94101-1750
- Part No: 94101-0250
- Part No: 94101-0275
- Part No: 94101-2000
- Part No: 94101-0312
- Part No: 94101-0350
- Part No: 94101-0450

- Part No: 94101-0541
- Part No: 94101-0616
- Part No: 94101-0675
- Part No: 94101-0766
- Part No: 94101-0878
- Part No: 99506-0525
- Part No: VO2-3-82-00-M-1213S
- Part No: 998JQ-0562 H05
- Part No: V0238200N-0912-S2
- Part No: C410YLW-75-884-S14
- Part No: 9953W-1056
- Part No: 43 2 810 085
- Part No: 998EZ-0367 OEM
- Part No: T-Schrauben für 998EZ-0367 118151
- Part No: Ersatz-Mutter für 998EZ-0367 118151
- Part No: 94100-0425
- Part No: 802502-008
- Part No: V02382EZN-0367-H
- Part No: Wooden box for SEGS23P2K_EX3
- Part No: V band for 998EZ-0484
- Part No: V band for 995XJ-0634
- Part No: V band for 995XJ-0534
- Part No: 941 WG-1178 C12
- Part No: 998EZ-0484 OEM
- Part No: FP 30x12.7 W4 250.1247.00
- Part No: FP-K2 W4 250.0047.1270
- Part No: F1020M0175
- Part No: F1020M0200
- Part No: V01-1-82-00-W-281-S
- Part No: V01-1-82-00-W-258-S
- Part No: Esyl54 (54mm)
- Part No: Esyl60 (60mm)
- Part No: 941UJ-4300
- Part No: C410YLW-75-400-S14
- Part No: C410YLW-75-450-S14

- Part No: 996BP-0527 (NSPP)
- Part No: SCSG00120 obsolete, replaced by SCSG_HDGS
- Part No: SEGS23C2K_15
- Part No: SCSG_HDGS
- Part No: FG- 5050100
- Part No: V0136246N - 1 box = 10 pcs.
- Part No: 951FM-0475
- Part No: C410N-75-750-S4
- Part No: 94100-0750
- Part No: SEGS23B10
- Part No: 94100-0388
- Part No: 994FM-1024
- Part No: 998NT-0975 old code, BC-03 new code
- Part No: 94106-0750
- Part No: SEGS23A32
- Part No: SEGS23A3213
- Part No: 996HY-067 L11 OEM
- Part No: 996HY-0670 L11 OEM
- Part No: 995XJ-0534 N/S 045181 oem
- Part No: 995XJ-0634 N/S 044181 oem
- Part No: 998EZ-0367 N/S 290181 oem
- Part No: 995XJ-0484 N/S 290181 oem
- Part No: V07-3-63-00-N-0623-56
- Part No: 955XJ#0484 290181 oem
- Part No: 955XJ #0322 263171 oem
- Part No: 994CY-1024 B96
- Part No: 994CY-1024
- Part No: SEGS23HFLOOD
- Part No: 90016-0500
- Part No: SEQC88061_EXB
- Part No: SEGD23B32_1_EX3
- Part No: SEI1230AC_EX4
- Part No: GPS_ANT_EX4
- Part No: SCSD04_Eexe
- Part No: SCSD05_Eexe

- Part No: SCCES00425_EX_HT
- Part No: SCCES01025_EX_HT (from stack"s base to lamp)
- Part No: SCCES01025_EX_HT (from Control Board to stack"s base)
- Part No: BC-02
- Part No: V0138200W-0985-H8
- Part No: 941MG-0950
- Part No: V01-3-71-00-N-0304-S2
- Part No: V01-3-71-00-N-0418-S2
- Part No: V01-3-71-00-N-0548-S2
- Part No: V01-3-71-00-N-0757-S2
- Part No: 94106-0256
- Part No: 94106-0125
- Part No: SEGS23P2K_13
- Part No: 94143-0350
- Part No: 94143-0400
- Part No: 998QA-1700 203162 oem for Solberg
- Part No: V07-4-52-00-N60482
- Part No: 952KE-0531
- Part No: SEGD23P2K_1_15 / MIOLB-M1_23D
- Part No: SEGD23B32
- Part No: SEQCxy02x
- Part No: SEI1230AC_M
- Part No: SCCES0515
- Part No: SCCES0415 / FG16OH2R
- Part No: SCCE00510
- Part No: FG16OR16 / 3G1,5
- Part No: C370c-62-523-S1
- Part No: 6LCO-C-CLAMP (6-6345)
- Part No: V0234100N-1721-S2
- Part No: 994KC-0890 D07 oem for Solberg
- Part No: V0336300W-0335-S2
- Part No: 996FL-1764 oem
- Part No: 998BT-0636
- Part No: V03352XJN-0634-H OEM
- Part No: V03352XJN-0534-H OEM

Endura Supply Industrial Parts Supplier If the part you are looking for is not in the product list, please send us an e-mail or call us. Phone: +1 862 783 0519 Email: info@endurasupply.com

- Part No: V03352XJN-0484-H OEM
- Part No: V02382EZN-0484-H OEM
- Part No: SEQC88061
- Part No: SEQC88061_EX3
- Part No: 998EZ-0484-C03
- Part No: 998EZ-0540-A04
- Part No: 998EZ-0642-K03
- Part No: 998EZ-0367-C02
- Part No: 995XJ-0534-F02
- Part No: 995XJ-0634-M02
- Part No: 998EZ-0934-C02
- Part No: V03T.4.42.00M.0596.55
- Part No: 941YL-0550
- Part No: 78962
- Part No: 94100-0400
- Part No: 9960P-1730
- Part No: 94100-0800
- Part No: 94100-1200
- Part No: 58695
- Part No: LIOLB-P1_23S
- Part No: SEGS23P20K_15
- Part No: SEGS23P20K_13
- Part No: 941WG-1178
- Part No: 93603-2120 / 252141
- Part No: 94100-0200
- Part No: 94100-0500
- Part No: SP SEI230AC
- Part No: BA09-Y
- Part No: MIOLB-M1_23S
- Part No: 999KZ-1512 OEM for Sunwell in Woodbridge Ontario
- Part No: 94100-0772
- Part No: 94100-0397
- Part No: 941QB-0460
- Part No: 99949-1100
- Part No: 93601-0444

- Part No: 93716-0523 D12
- Part No: 93716-0681
- Part No: 93716-0405 C08
- Part No: 93716-0360 D12
- Part No: 93716-0320 D12
- Part No: 996RL-1012 OEM - 9219700240
- Part No: 995L5-0662-L06 OEM
- Part No: MC844-185
- Part No: 995xj-0322
- Part No: 995vh-0512 / 150605
- Part No: SPL0MB-E1_48DSH
- Part No: SPL0DCB32_15
- Part No: V0935400N-1040-S4
- Part No: SEG23P2K_15
- Part No: SEGD23A10_1_13
- Part No: 94100-0212
- Part No: 94100-0256
- Part No: 408646
- Part No: 95130-0762 320211
- Part No: 94106-0388
- Part No: 251 0047 1270
- Part No: 9416H-1525
- Part No: C511N-88-850-S2 / 95177-0850
- Part No: 99429-0638
- Part No: 94106-0425
- Part No: 94100-0225
- Part No: V01-3-54-00-M-61812-S3
- Part No: 995KH-0900
- Part No: 998AD-0780
- Part No: 999ES-1423
- Part No: 998 EZ 0540 088221
- Part No: 993BC-0232
- Part No: 99800-0481
- Part No: 998YK-1880
- Part No: V0139200A-0533-S1

- Part No: V0135100M-0525-S2