

# ENDURA SUPPLY

## Clarke Product List

- Part No: AF1980
- Part No: JU4H-UF34
- Part No: TK 6HNL 60
- Part No: ZP 513
- Part No: Solenoid for DQ6H-UFAA50
- Part No: Gland Packing for DQ6H-UFAA50
- Part No: Loctite -casing gasket for DQ6H-UFAA50
- Part No: Gasket rocker cover for DQ6H-UFAAA50
- Part No: V-Ring for DQ6H-UFAA50
- Part No: Thermostat for DQ6H-UFAA50
- Part No: Alternator Belt for DQ6H-UFAA50
- Part No: Shaft seal ring for DQ6H-UFAA50
- Part No: Oil seal front for DQ6H-UFAA50
- Part No: Oil Seal Rear for DQ6H-UFAA50
- Part No: 69102013
- Part No: C07477
- Part No: C071883
- Part No: JU6H C071883
- Part No: 6090HF484A.B.C.D- R556310
- Part No: JW6HUF50- 193988
- Part No: C05806
- Part No: CO7475
- Part No: C072011
- Part No: ju4h-uf22
- Part No: JU6H-NLABL8 OBSOLETE; REPLACEMENT BY JU6H-NLM8
- Part No: JU6H-NLM8
- Part No: C123644
- Part No: C051847
- Part No: C07476
- Part No: JX6H-UFAD88/ C04615
- Part No: JX6H-UFAD88 / C02770
- Part No: JX6H-UFAD88/ R133142

- Part No: C071245
- Part No: C071243
- Part No: C071244
- Part No: C03396
- Part No: C05626
- Part No: JX6H-UFAD88 / C04592
- Part No: JX6H-UFAD88 / C03595
- Part No: JW6H-UFAD70
- Part No: DDFP-L6FA-8399
- Part No: DDFP 04AT 7428
- Part No: C070490
- Part No: C122191
- Part No: C07478
- Part No: DT2H-1JFAA60
- Part No: GPDFM-N-12-W-BCE-10-220
- Part No: C02550
- Part No: JU6H-UF84 # C04521
- Part No: JU6H-UF84 # C03396
- Part No: JU6H-UF84 # C02550
- Part No: JW6H-UF60 obsolete
- Part No: JU6H-UF54
- Part No: 00C002550
- Part No: R504836 (C04521)
- Part No: 00C02550
- Part No: 00C04521
- Part No: CPP3000B PART No. 7210102
- Part No: REPAIR KIT FOR DR8H-UFAA40
- Part No: heater element for C123644
- Part No: PU158TI-AC1
- Part No: C071222
- Part No: C07853
- Part No: C07826
- Part No: C07827
- Part No: C07828
- Part No: C051851

- Part No: C121920
- Part No: C071001
- Part No: 00C03396
- Part No: F007A4
- Part No: 0C071963