

ENDURA SUPPLY

Airtec Product List

- Part No: 0181-04-712 MN-06-511-HN
- Part No: 1321-11
- Part No: 1660-11
- Part No: 1660-21
- Part No: 18-T-23-011-30
- Part No: 23-M-09-17-412-R
- Part No: 23-M-09-17-442-R
- Part No: 23-M-09-19-432-R
- Part No: 23-M-09-19-462-R
- Part No: 23-SP-011-427 VALVE+ BOBBIN
- Part No: 28-ST-01
- Part No: 400M 2F T
- Part No: 400M 3F T
- Part No: 400M 7F T
- Part No: 40-452-060-60
- Part No: 40-452-085-60
- Part No: 4551-433-T18513 (Obsolete)
- Part No: 4M310-10 24V
- Part No: KM-10-510-HN-500
- Part No: 4V1008-CTT01718 4V310 24V
- Part No: 8-2 210-08
- Part No: BM-02-310-HNR-462
- Part No: BSP-040
- Part No: COIL FOR SOV OF MODEL:4V220-08
- Part No: CS1-A
- Part No: ER 25-310
- Part No: KF-10-520-HNR-442
- Part No: KN-05-511-HN-432 [24V = 2,2 W]
- Part No: KN-05-511-HN-EX
- Part No: KN-063-DRH
- Part No: ME-05-511-HN-412
- Part No: ME-05-511-HN-442

- Part No: MI a “ 01 a “ HN a “ 16 AAA404
- Part No: MI 03 530-HN
- Part No: P-07-520
- Part No: SERIAL NUMBER 2012-008 ORDER C0312 0053 MODEL BART LINE
- Part No: T-30-310
- Part No: VAC VALVE 402
- Part No: VS-06-511
- Part No: ZS-5700
- Part No: ZX-40-KG-0625-01
- Part No: ZX-40-SG-0900-01
- Part No: ZX-50-KG-0350-01
- Part No: ZX-25-SR-1500-02
- Part No: M-05-510-HN-442
- Part No: MN-06-511-HN-442
- Part No: KN-10-510-HN-442
- Part No: HF-14-510
- Part No: BM-02-510-HNR-156
- Part No: FF4-4 DAH
- Part No: J/0003-4176-000
- Part No: PT100 0004-4382-000
- Part No: Q2E160L2D
- Part No: GM 160 L4
- Part No: 2007-8821
- Part No: 2007-8447
- Part No: 2007-8811
- Part No: 2007-8907
- Part No: 281-611/281/417
- Part No: 2007-8891
- Part No: BF 2000
- Part No: MO-07-310-HN-442
- Part No: XL-125-0300-050
- Part No: XLB-125-02
- Part No: 23-ST-2456-01
- Part No: NO:4551-361
- Part No: Alternative: BM-01-510-HNR-462

- Part No: 23-SP-011-412
- Part No: M-22-530-HN-412
- Part No: MN-06-510-HN-442
- Part No: 4V410-15 replaced by M-22-510-HN-427
- Part No: M-22-510-HN-427
- Part No: 23-SP-016-727
- Part No: EL-18-510
- Part No: MSV86522R --- alternative EL-18-510 by AIRTEC
- Part No: DZ1 - 160 - B/320
- Part No: XG-160-0320-050 - Alternative for DZ1 - 160 - B/320
- Part No: LCD-TYPE 1
- Part No: 961024
- Part No: 961038
- Part No: 451050
- Part No: KN-05-510-HN
- Part No: KN-05-310-HN-442
- Part No: L-25-520
- Part No: 4v430c-15 alternativ 86-MV-5-12-530-M42
- Part No: KF-46-210/2-HN-S12
- Part No: KN-05-510-HN-442
- Part No: 2636000
- Part No: XLVK-100-01-0250
- Part No: 28-ST-06-127
- Part No: ER-18-310
- Part No: MG-07-510-HNX-XXX OEM
- Part No: 23-SP-011-427
- Part No: RB-3160
- Part No: KN-05-530-HN-442
- Part No: MN-06-310-HN-442
- Part No: 86-MV-5-12-511-M57
- Part No: MO-05-310-HN-442
- Part No: 4M31008A 4M31008A 4M31008A
- Part No: ME-07-511-HN-442
- Part No: Repair Kit For:KM-10-510-HNX-XXX
- Part No: KM-10-510-HN-442

- Part No: KN-05-510-HN-442 24VDC
- Part No: XV-080-125-210 - obsolete, replaced by - NYD-080-125-210
- Part No: NYD-080-125-210
- Part No: KN-05-520-HN-442
- Part No: 86-MV-3-18-311-M42
- Part No: KN-05-511-HN-442
- Part No: E-25-310
- Part No: E-28-310
- Part No: E-18-310
- Part No: E-18-310-Q
- Part No: E-18-510
- Part No: E-18-510-Q
- Part No: E-30-311-M12
- Part No: L-25-310
- Part No: L-25-311
- Part No: L-25-320
- Part No: L-25-320-Q
- Part No: L-25-511
- Part No: L-25-510
- Part No: MS-20-310-HN
- Part No: MS-20-310/n-HN
- Part No: 23-M-20-411
- Part No: 23-M-20-412
- Part No: 28-ST-02-01
- Part No: 28-ST-09-112
- Part No: 28-ST-09-127
- Part No: 28-ST-10-112
- Part No: 28-ST-10-127
- Part No: 28-ST-10-K3-112
- Part No: 28-ST-10-K3-127
- Part No: 28-ST-02-2-07
- Part No: 28-ST-02-2-05
- Part No: 23-SP-011-411
- Part No: 23-SP-011-422
- Part No: 23-SP-011-426

- Part No: 23-SP-012-431
- Part No: 23-SP-012-432
- Part No: 23-SP-011-1-711
- Part No: 23-SP-011-1-712
- Part No: 23-SP-011-1-722
- Part No: 23-SP-011-1-725
- Part No: 23-SP-011-1-727
- Part No: 23-SP-012-1-732
- Part No: 23-SP-011-5-O12
- Part No: 23-SP-012-5-O32
- Part No: 28-ST-04-112
- Part No: 28-ST-04-127
- Part No: 28-ST-06-112
- Part No: 28-ST-06-K3-112
- Part No: 28-ST-06-K3-127
- Part No: DC102
- Part No: VZ-25-310
- Part No: KND-05-530-HN-442
- Part No: M-07-310-HN-442
- Part No: SP011
- Part No: 23-M-09-17-442-T
- Part No: DC-1211-25B
- Part No: DC-1211-25N
- Part No: 86-MV-5-38-511-M42 (Alternative For AIRTAC-Ventil 4V310-10)
- Part No: ER-18-510
- Part No: MN-06-520-HN-457
- Part No: M-20-510-HN OEM
- Part No: 86-MV-5-38-511-M57
- Part No: MO-07-310-HN-727
- Part No: MN-06-530-HN
- Part No: EL-25-310
- Part No: P 18 522 obsolete, replaced by P-05-522
- Part No: P-05-522
- Part No: KM-10-510-HN
- Part No: 5250112