

# ENDURA SUPPLY

## Colvern Product List

- Part No: 4115320010 - not available, alternative - 4115302470
- Part No: 4001/22, 2KOK, 0019 discontinued
- Part No: 7319H CLR5001/ M40 5k?
- Part No: CP 10 / 006-2
- Part No: CP 16110 / M 50 - 5 Kohm (4115002470)
- Part No: LM10 3M29 5Kohm / 4114902470
- Part No: LM 10 / 3M29 - 5 Kohm +-20% Lin. (4114902470)
- Part No: 317-780
- Part No: CP.16/001/M165 not available/alternative CP16001/15S-5KOHM
- Part No: P/N: 4115002470 Type: CP 16110 / M 50 - 5 Kohm +-10% Lin ES 84
- Part No: LM 10/ 3M29 – 10K, ±20%
- Part No: LM 10 / 3M29 - 5 Kohm (4114902470)
- Part No: LM103M29001 KMAI 5 pcs
- Part No: 3104501222
- Part No: LM10/3M29 5K (4114902470)
- Part No: 3101106940
- Part No: CLR 4501/22 200R+-10% (45010022200RKAA)
- Part No: CP 16110
- Part No: CP 17/225 / 2584
- Part No: CLR 4001/11S 10K+-10% (4001011S010KKAA)
- Part No: CP 16110 / M 50 - 5 KOHM +-10% LIN ES 84
- Part No: 4115112470
- Part No: CP 17/225 / 2584 (4116020010)
- Part No: CLR4517/M25S 100R10%(4517M25S100RKAA)
- Part No: CP 16110 / M 50 - 5 Kohm (2-29 pieces)
- Part No: 4114902400 Type LM 10 / 3M29
- Part No: LM10/3M29 5KOM ES360 0809
- Part No: CP 17 / 556-9 / 4116212470
- Part No: 4115012401, type: CP 16001 / 9S
- Part No: 17/547/2699 4K 15M 9403. ES 133
- Part No: 1106/M50 500RK 9217
- Part No: CP 17 / 579-4 - 4K 15M

- Part No: 4K 15M
- Part No: 4001/11S
- Part No: CP16710/9S
- Part No: 4001 /M50 5K0K
- Part No: LM17/3M29
- Part No: P/N:4115112470: Type:LM24/3M29 - 5KOM
- Part No: 4115310010
- Part No: P/N:4115012450; Type: CP 16001 / 22 - 2 Kohm Lin. (350-825)
- Part No: LM10 5K (4114902470)
- Part No: LM 103M29005KMAA
- Part No: PD. 242
- Part No: P/N: 4115320010; Type:CP 17 / 542
- Part No: LM103M29001 KMAI 10 pcs
- Part No: CLR 4001/22 5K
- Part No: Art.Nr.8830 (4517/M25S 100 kOm) old P/N, Art.Nr.31045 (CLR 4517/M25S 100Kohm) new P/N
- Part No: Art.Nr.31045 (CLR 4517/M25S 100Kohm)
- Part No: CLR4001/M25
- Part No: 17 541 2684 obsolete,alternative CP 17 / 543, brand Ab Elektronik
- Part No: 17 515 2684, obsolete,alternative CP 17 / 543, brand Ab Elektronik
- Part No: CLR 4501/22 200R
- Part No: 20CPO11/6M20
- Part No: CP 16110/M50 5KOK 0827
- Part No: CLR 1232/268/250R
- Part No: CP17/583 (4116300010)
- Part No: LM10/3M29 5KOM ES360 9737
- Part No: 3104517210
- Part No: CLR4517/M25S
- Part No: CLR4517/M25S (6 pcs)
- Part No: CP 17 / 543 / 2584-3 4K15M 20%
- Part No: CP10/009-1
- Part No: 4517 / M25S 100RK 8830
- Part No: CLR 40109 / 115-135ohm
- Part No: 3104001160
- Part No: CP 17 / 543 / 2584-3 4K15M 20% ( 30 pcs )

- Part No: CP 17 /583 (4116300013)
- Part No: CP 10 / 006-2 to ES 128
- Part No: CP17/541/2684
- Part No: 4114902470 / LM 10/3M29 - 5 Kohm + -20% Lin
- Part No: CP16110/M50 5k0k 0825
- Part No: CP17/214/2646 4Kom
- Part No: CLR 7302/11
- Part No: LM10/3M29 1K
- Part No: CLR 1501/8S
- Part No: CP 17 / 543 / 2584-3 4K15M
- Part No: 4001/11S 10K
- Part No: LM21/3M29
- Part No: CP 16110 / M50 - 5 Kom
- Part No: LM10/3M29 – 5KoM – 0306
- Part No: 4517/M25S 100RK-8712
- Part No: CLR4517M25 10 O
- Part No: 4001/22 2K0K 0151 discontinued
- Part No: CP 17/225 4116020010
- Part No: 7037/15 10K
- Part No: 3001/ M50 10KK
- Part No: CLR4200
- Part No: CP17
- Part No: 4115012491 / CP16001 9S 10K
- Part No: 4114902490
- Part No: 17/531/2684 (77.01.203.488) - obsolete
- Part No: P/N: 4115002470, Type: CP 16110 / M 50
- Part No: DRGRS175
- Part No: CP 17 1 715-NS
- Part No: CP17/543 (CP 17 / 543) / 4115302470
- Part No: CP.16 /003/M165
- Part No: 5001/155 10KK 9438
- Part No: TPS - COLVERN CP17
- Part No: CP 16305 / M16S
- Part No: CP10/010-2 / 4116540010
- Part No: CP16100/M50

- Part No: 400I/M50
- Part No: LM10/3M29 5KOM (4114902470)
- Part No: LM10/3M29 5KOM 9950
- Part No: CLR5001-11S-250R/+/-10% A
- Part No: Code TP1 / CP17
- Part No: Nr. 4115302470 Type CP 17 /543
- Part No: CP 10 / 009-2 "D / 4116530010
- Part No: 4115302470 / CP 17 / 543 / 2584-3 4K15M 20%-90°ES10
- Part No: 400I/IIS
- Part No: CLR 4001/22 50KK
- Part No: CP17/575 6 KOM ES 234
- Part No: 2357/17 5K0J
- Part No: 2320/22 5K0J
- Part No: Ct.1319/M25S 5KOM 7949
- Part No: 1206/22/5K0K
- Part No: 9110.ES133 (4K15M)
- Part No: lm 10/3m29 5kom 9914
- Part No: 17/546/2699
- Part No: CP17-563 - 5K
- Part No: 4001/11S 5K0K
- Part No: 4114902400 / LM10 3M29 1Kohm
- Part No: CP-16001 / 22
- Part No: 1106/M50
- Part No: 4116510010
- Part No: CLR4001 Type 4001 11S 50KK