

# ENDURA SUPPLY

## AC Motoren Product List

- Part No: AC25M4200000
- Part No: ACM 180 L4 / HE
- Part No: AEF-024-204B
- Part No: AH31M4200004
- Part No: ATG TYPE: EDM-4-B3-7,5-132M-AZ0
- Part No: COVER FOR FBA 90S/4 D71 21 21 87
- Part No: DM-6-B5-0,55-80-A-Z0
- Part No: DREHSTROM-ASYNCHRON-MOTOR 1500U/MIN, B5, 0,37 KW
- Part No: DS-KZL-MOTOR 90W, 1500 U/MIN, B3
- Part No: EDM-2-B3-1,1-80-A-Z0
- Part No: EDM-4-B35-1,5-90L-A-ZO
- Part No: EDM-6-B5-0,75-90S-A-ZO
- Part No: FCA 132SA-6-S1-F-3KW ELECTRO MOTOR
- Part No: DM-4-B?-0,37-71-A-Z0
- Part No: FCA 71B-6
- Part No: FCA 90 L-4
- Part No: Type FCA 100 LA-6/HE (IE2AC10L6002)
- Part No: FCA-90L-6/HE
- Part No: FCA-90S-6/HE
- Part No: FCM 225 S - 4
- Part No: FCPA 90L-6 / 11012426
- Part No: FCPA 90L-6/HE
- Part No: FH280M-4
- Part No: FOM 160MA-4 - 11/13,2 KW.
- Part No: FOMP 160MB-4
- Part No: FY 80 A-4 NR 0080704A02
- Part No: IE1AC22M4000
- Part No: JM 225M-4/HE 1E2
- Part No: RAH-1738B1-C
- Part No: Type FCA 132 MC-4/HE(IP 55)
- Part No: TYPE:F CPA 100LB-4/HF NO:11071695
- Part No: FCA112M-2/HE

- Part No: FCPA71A-2
- Part No: FCA100L-2/HE
- Part No: FCM132M-4/HE
- Part No: FCA 90S-2
- Part No: EDM-2-B5-1,5-90S-A-ZO
- Part No: JM 112MC-4
- Part No: ACM 160 M4 / HE IE2
- Part No: ACA 160 M4 / HE IE2
- Part No: ACA 112 M4 / HE IE2
- Part No: FCA 90L 2/4 PC
- Part No: FY 71 A-4
- Part No: FCA 100 LC-4 / HE IE2
- Part No: FBA90S-4
- Part No: Klemmbrett fAr BaugrAAYe 200 + 225
- Part No: ACA 90L-4
- Part No: JM 112 M-4
- Part No: FCA 132 M4 / HE IE2
- Part No: FCMP 225M-4
- Part No: FY100LB-4
- Part No: FY100LA-4
- Part No: FA 112M-4
- Part No: FCA 112 M 4/HE
- Part No: FCMP 200 L 4/PHE
- Part No: FCA 100 LB-4/HE
- Part No: FCMP 225 M-4/HE
- Part No: FYP 100 LB-4
- Part No: FCA 112 M4 / HE IE2
- Part No: ACA132SA-2/HE
- Part No: LAfterflAgel fAr BaugrAAYe 200
- Part No: IE2AC16L6010
- Part No: IE2AC11MC207
- Part No: IE2AC13S4004
- Part No: FCPA 100LA-4
- Part No: RAL7030
- Part No: EDM-4-B35-0,75-80-A-Z0

- Part No: FHP280M-4
- Part No: FCPA 112M-6/HE
- Part No: FCPA 90LC-6/HE
- Part No: EDM-4-B35-3-100L-A-Z0
- Part No: FCM225 M4
- Part No: FCPA 100 LB-4/HE
- Part No: FBSP 71 B-4/HT
- Part No: IE2AC16MB202
- Part No: DM-8-B3-3-132M-A-Z1UL
- Part No: ECM 225S-4
- Part No: IE3AC22M4000
- Part No: MTR 5.5KW 3000RPM (OEM MX)
- Part No: ACM 250M-2/HE
- Part No: IE3AC18L4002, type ACM 180L4/PHE
- Part No: IE3AC25M6000, type ACM 250 M-6/PHE
- Part No: FBPA 100LA-4
- Part No: IE2AC13M4004, type IE2AC13M4004
- Part No: IE2AC10LA428, type ACA 100 LA-4/HE
- Part No: JM 200L-4/HE N 1309108285
- Part No: 11063520
- Part No: 11010612
- Part No: Type FCM 160 M-6/HE
- Part No: JM 90 LC-4
- Part No: 11071106
- Part No: 10123477 JM 112M-4/H
- Part No: PDM-4-B35-22-180L-G-Z1, 180L, 22 kW
- Part No: PDM-4-B5-3-100L-A-Z0
- Part No: PDM-4-B35-15-160L-G-Z1, FCA 100LB-4/HE
- Part No: IE2AC13MC400 , type FCA 132 MC-4/HE
- Part No: JM 90LC 2
- Part No: FCM 160L-4/HE
- Part No: PDM-2-B3-3-100L-A-Z1UL
- Part No: FCPA 132S-6/PHE
- Part No: IE3AC13S6004
- Part No: IE3AC10LA600

- Part No: IE2AC16L4024
- Part No: IE3AC13S4009
- Part No: 6020140
- Part No: COVER For ACA 132 M-4
- Part No: ACM 160 M-6/PHE
- Part No: Art.Nr.: 950050202000001
- Part No: FCPA 132 M-8
- Part No: 1304016759
- Part No: ACM 315 MA-4/PHE
- Part No: ACA132M-4/PHE
- Part No: ACA100LA-4/PHE
- Part No: FCA100LA-4
- Part No: FCY 132 M-4/HE (IE2GU13M4003)
- Part No: AC-225-00007 , P/N 8JL.013.0180
- Part No: FBPA 71B-4 REPLACED BY FCPA 71 B-4
- Part No: FCPA 71 B-4 (AC07B6200004)
- Part No: Type FCA 132 M-4/HE
- Part No: AC.LAœFTF.80
- Part No: Type ACM 355 MA-6
- Part No: Type FCA 80 B-4/HE
- Part No: Type FCA 90 L-2/HE
- Part No: FYC 132S-4/HE
- Part No: Type FCA 132 S-4/HE
- Part No: ACB5300B132N
- Part No: FCPA 100LA-6 09052268
- Part No: Type ACA 100 LA-6/PHE
- Part No: FCA 100 LB-4/PHE
- Part No: FCM 160 L 4/PHE
- Part No: FCM 180 L-4/PHE
- Part No: ACM 200 LA-6/PHE
- Part No: LAfterflAgel BG90
- Part No: FCPA132M-4/HE-IMB35-IE2-UL
- Part No: PDM-4-B3-22-180L-G-Z2
- Part No: DM-4-B14K-0,18-63-A-Z0
- Part No: FCA 100 LB 4/HE (IE2AC10LB408-P-V012960)

- Part No: FCM 160 M 4/HE (IE2AC16MB400)
- Part No: FCM 225 M 4/HE (IE2AC22M4001)
- Part No: PDM-2-B5-15-160M-G-Z2
- Part No: KL-42.CCA.000094
- Part No: FCA 90 S 4/PHE
- Part No: FCA71A-2
- Part No: ACM 280 S 2/HE
- Part No: AHR 315 S 4/PHE
- Part No: AHR315S-4
- Part No: 7020767
- Part No: F0M 180M-4
- Part No: FCM 180 M 4/PHE
- Part No: FCA 100 LB 4/HE (IE2AC10LB408-P-V021916)
- Part No: ACL 315 MA 4/PHE
- Part No: FCY 112 MC-4
- Part No: FCA 90S-4/PHE
- Part No: ACA 132S-4-IE2
- Part No: FCY 100 LB 4/HE
- Part No: ACA 132 M 4/HE
- Part No: JL3 90 L 4/PHE
- Part No: FCPA 100 LB 4/PHE
- Part No: FCA 90L-4
- Part No: IE3AC13MC204 (132 MC 2/PHE)
- Part No: TYPE JM 225M-4/HE
- Part No: FCPA 132MB-6/PBE
- Part No: IE3AC13M4024-P-V030728
- Part No: AC07A2100001-P-V031461 FCPA 71 A 2
- Part No: D-63110 FCBA 71A-2
- Part No: Type: FCPA 71A-2
- Part No: DM-8-B5-3-132M-A-Z1UL
- Part No: FCA 71B-2 6202ZZC3
- Part No: M 200 LB-6/HE IM B5/IM 3001
- Part No: Type FCM 200 LB-6/PHE
- Part No: Type FCM 200 LB-6/PHE (special execution 480V 60Hz)
- Part No: JM 90LC-27HE

- Part No: EDM-2-B14K-2,2-90L-A-Z0
- Part No: DM-4-B5-0,37-71-A-Z0
- Part No: FCA 132 M-4/HE
- Part No: FCA 132SA-6-S1-F-3KW
- Part No: FCA71B-6 /HE
- Part No: ACA 90 S
- Part No: FCPA 71B-4
- Part No: PDM-4-B35-11-160M-G-Z1 / FCMP 160MB-4
- Part No: JM 225M-4/HE 1E2 obsolete replaced by ACM 225 M-4
- Part No: ACM 250 M 4/PHE
- Part No: FCA112M-2/HE Pn(kW): 5.5, n (1/min): 2900
- Part No: FCPA71A-2 Pn(kW): 0.37, n (1/min): 2800
- Part No: FCA100L-2/HE Pn(kW): 3, n (1/min): 2900
- Part No: FCM132M-4/PHE
- Part No: FCM 200 L-4/HE
- Part No: FCA 90 L2/4
- Part No: Klemmbrett für Baugröße 200 + 225
- Part No: ACA 90L-4 - alternative EDM-4-B3-1,5-90L-A-Z0 (by ATG)
- Part No: FCA 132 M4 / HE
- Part No: FCMP 200L-4 replaced by FCA 112 M-4/HE
- Part No: FY100LB-4 replaced by FCMP 200 L-4/HE
- Part No: FY100LA-4 replaced by FCA 100 LB-4/HE
- Part No: FA 112M-4 replaced by FCMP 225 M-4/HE
- Part No: FCMP 225M-4 /PHE
- Part No: FYP 100 LB-4 not available, alternative - Atg - EDM-4-B5-3-100L-A-Z0
- Part No: ACA 132 SA-2/HE
- Part No: Lüfterflügel für Baugröße 200
- Part No: ACM 225 M-4
- Part No: Obsolete FCPA 100LA-4 Alternative RAL7030
- Part No: FCPA 100 LA-4/HE same as FCPA 100 LA 4/PHE
- Part No: FCA 90S-2/HE obsolete, replaced by Lüfterflügel BG90
- Part No: Type FCPA 100LB-4/ ? 09070506 replaced by EDM-4-B35-3-100L-A-Z0
- Part No: ACA 132 SB-2/HE
- Part No: ECM 225S-4 - alternative IE3AC22M4000
- Part No: FBPA 100LA-4 - alternative is IE2AC10LA428, type ACA 100 LA-4/HE

- Part No: JM 200L-4
- Part No: 11063520 - alternatives are types FCM 160 M-6/HE or FCM 160 M-6/PHE
- Part No: FCM 160 M 6 / PHE
- Part No: 10123477 Type: JM 112M-4/HE obsolete, replacement PDM-4-B3-4-112M-A-Z1UL (brand - ATG)
- Part No: PDM-4-B5-3-100L-A-Z0, Replacement for FCA 100LB-4 / HE
- Part No: Type: JM 90LC 2, obsolete, replacement PDM-2-B3-3-100L-A-Z1UL (brand ATG) (check type of construction)
- Part No: FCPA 100LA-6/PHE S/N: 1411304309 - not available, alternative -IE3AC13S6004
- Part No: FCPA 100LA-6/PHE SN: 1312142619 - not available, alternative - IE3AC10LA600
- Part No: FCM 160L-4/HE SN:1402176950 - not available, alternative - IE2AC16L4024
- Part No: FCPA 132S-6/PHE obsolete, replaced by IE3AC13S6004
- Part No: FCPA 100LA-6/PHE obsolete, replaced by IE3AC10LA600
- Part No: FCM 160L-4/HE obsolete, replaced by IE2AC16L4024
- Part No: FCPA 132S-6 /PHE
- Part No: FCM 160 L 4/HE / IE2AC16L4024
- Part No: FCA 132 S-4 / PHE B5 UL
- Part No: 06020140 obsolete, replacement ACM 160 M-6/PHE
- Part No: FRONT AND BACK COVER FOR TYPE:ACA 132 M-4 obsolete
- Part No: 1304016759 obsolete, alternative Siemens 1LE1023-1AA43-5AB4
- Part No: ACA 80 A-2/HE
- Part No: FCA100LA-4 / EDM-4-B5-2,2-100L-A-Z1
- Part No: FCY 132 M-4/HE
- Part No: AC.LÜFTF.80
- Part No: FCA 80 B-4 / PHE B5
- Part No: IE2AC13M4004
- Part No: TYPE FCPA 100LA-6 NO:09052268 replaced by Type ACA 100 LA-6/PHE
- Part No: ACA 112 M-6
- Part No: FCA 100 LB-4/ PHE
- Part No: FCM 160 L-4 / PHE UL
- Part No: JM 180 L-4 L-4 /PHE
- Part No: Lüfterflügel BG90
- Part No: PDM-4-B35-15-160L-G-Z1
- Part No: FCM 160 MB 4/HE (IE2AC16MB400) ALTERNATIVES : PDM-4-B5-11-160M-G-Z1 or EDM-4-B5-11-160M-G-Z1
- Part No: FCM 160 MB-2/PHE

- Part No: JM 90L-4/HE old code, new code FCA 90 L-4/HE
- Part No: GPW 235 SR 79
- Part No: FCA 71 A2
- Part No: FCPA 112 M
- Part No: AHR315S-4 obsolete/ replaced by AHR 315 S 4/PHE
- Part No: 07020767 obsolete, replaced by FCM 180 M 4/PHE
- Part No: F0M 180M-4 obsolete, replacement FCM 180 M 4/PHE
- Part No: FCA 112 M-4/PHE
- Part No: FCY 112 MC-4 not available, replacement FCA 112 M-4/PHE
- Part No: FCA 132 S 4 /PHE
- Part No: Type – JM 90L-4/HE REPLACED BY JL3 90 L 4/PHE
- Part No: FCPA 100LB-4, Nr:06104908 obsolete, replacement FCPA 100 LB 4/PHE
- Part No: FCPA 100 LB4 / PHE
- Part No: JM 225M-4 /HE
- Part No: P/N: AC07A2100001-P-V031461 Type: FCPA 71 A 2
- Part No: M 200 LB-6/HE IM B5/IM 3001 obsolete, replacement Type FCM 200 LB-6/PHE
- Part No: FOPA 100LA-4
- Part No: IE3AC11MC409 , type FCA 112 MC 4/PHE
- Part No: JM 160 L-4/PHE REPLACED BY ACM160L4/PHE
- Part No: ACM 160 L-4/PHE
- Part No: PCA 132S\*-4/HE
- Part No: FCA 90s
- Part No: AC-KB-BG200
- Part No: AC.KK-BG200A
- Part No: ABA100LA-4 obsolete, replacement ACA 100 LA 4/PHE
- Part No: FCA 100 LC-4 / HE
- Part No: FCA 100LB-8 ALTERNATIVE DM-8-B5-1,1-100L-A-Z0
- Part No: FCA 100 LB8 / IE1
- Part No: JM 200 LB-6/HE IM B5/IM 3001 obsolete, alternative FCM 200 LB-6/PHE
- Part No: FCA 71 B-2 / HE B5
- Part No: 3U-X-400-1 obsolete/replaced by 910013481 and 910013498
- Part No: 910013481
- Part No: 910013498
- Part No: FCA 112 M2 / PHE IE3
- Part No: FCM 160 MA 2 / HE IE2



- Part No: FYMP 180L-4/HE #1504AC07090169
- Part No: JM 112MC-4/HE alternative FCA 112 MC 4/PHE IE3
- Part No: 910013710 Type : FCPA 112 M2 / PHE IE3
- Part No: FCPA 112M-2/PHE
- Part No: FCA 112 MC 4 / PHE
- Part No: Bimetallschalter 3 x PTO
- Part No: Y2-180 2 4
- Part No: FCA 132MB-4/PHE
- Part No: FCA 100LA-2/PHE
- Part No: FCA 80B-4/PHE
- Part No: FCM 180 L-4 / PHE B5
- Part No: 3111582
- Part No: FCM 180 L-4 / PHE UL
- Part No: ACM 250M-4/PHE
- Part No: ACA 90 L-4/HE
- Part No: FCMP 160 L-4/HE
- Part No: 90S
- Part No: FCA 90-S6/HE
- Part No: FCA 90-S6/PHE
- Part No: FCPR160L-6/HE
- Part No: FCM225 M-4/PHE
- Part No: FCA132 M-4
- Part No: FCA100LA-4 / PDM-4-B5-2,2-100L-A-Z1
- Part No: Fan for FCA100LA-4 .
- Part No: PDM-4-B5-55-250M-G-Z2
- Part No: EDM-4-B5-11-160M-G-Z1 (same as FCM160M-4/HE)
- Part No: EDM-4-B5-45-225M-G-Z2 (same as FCM 225M-4/HE)
- Part No: FCA 132-4/HE
- Part No: PDM-6-B5-11-160L-G-Z1
- Part No: FCM280S-4/HE
- Part No: EDM-2-B5-3-90L-A-Z0UL
- Part No: acm 280 m-2 90 kW B5 version
- Part No: FCA 132 S-6/HE
- Part No: FCY 90L-4/HE -ALTERNATIVE EDM-4-B5-1,5-90L-A-Z1 (BRAND ATG)
- Part No: ACA 80 B 6

- Part No: FCA 100 L 2/PHE
- Part No: JM80B-4/HE
- Part No: Type: ACM 180L-4/HE obsolete,alternative PDM-4-B3-22-180L-G-Z2(brand ATG)
- Part No: B3 400/AWM 315 S-4/PHE ,alternative Type:PDM-4-B3-110-315S-G-Z2(brand ATG Motor)
- Part No: FCPA100LA-4/PHE-IMB35-IE3
- Part No: FCPA80B-4/PHE-IMB35-IE3
- Part No: FCMP 225 S-4/HE
- Part No: FCA 80B-2
- Part No: F0PA 90S-4
- Part No: JM 160MB
- Part No: FCA 100 LB-4/PHE, SN 18013111112
- Part No: FCPA 71 C-4 progressiv
- Part No: FCA 90 L-4/HE
- Part No: FCPA 71A-2
- Part No: FCPA 112 M-4 / PHE B35 400 / 690
- Part No: FCA100LA-6/HE - 1,5 kW
- Part No: FCA100LA-6/HE
- Part No: FCA 112 MC-4/HE progressiv
- Part No: FCPA 90 L-4 / PHE B35
- Part No: FCY 90L-6/HE
- Part No: Model: FBPA 80A-4
- Part No: IE3AC10LB422
- Part No: IE3AC16L4032
- Part No: IE3AC18L4028
- Part No: FCA 71A-4
- Part No: ACM 160 MB-2/PHE
- Part No: FBA 112M-4 obsolete,alternative type PDM-4-B5-4-112M-A-Z1,brand ATG
- Part No: JM 132M-4/HE
- Part No: FCA80A-4
- Part No: EDM-4-B35-2,2-100L-A-Z1
- Part No: FCMP 160 M 4 / PHE
- Part No: FCM 225 S-4 / PHE B35 UL
- Part No: FCMP 250 M-4/PHE
- Part No: FCPA 132 S-4/PHE
- Part No: FCMA 100LB-2/4

- Part No: FCA 132SB-2/PHE
- Part No: AC.LÜFTF2004
- Part No: ACA 80A-2/PHE, B3
- Part No: FCPA 100LA-4/PHE
- Part No: PDM-4-B5-2,2-100L-A-Z1
- Part No: FCA 71C-4
- Part No: FCA 132 S-2/PHE
- Part No: Cooling Fan for FCA 63B-2
- Part No: Lagerschild Drive End
- Part No: FCA 71C-2
- Part No: FCMP 160M-4/HE
- Part No: PDM-4-B3-15-160L-G-Z1
- Part No: FCA 63B-4
- Part No: ACM 315 LB-4/PHE
- Part No: ACA 112-M-4/PHE
- Part No: JM100LA-4
- Part No: ACM 180 L-6/PHE (IE3)
- Part No: ACM 200 LB-6/PHE (IE3)
- Part No: JM100LA-4/HE
- Part No: FCA90L-4 1.5kw version B3
- Part No: FCA90L-4 1.5kw version B5
- Part No: JM-132M-4/PHE / alternative FCA 132 M-4 / PHE B5 / UL
- Part No: ACA 112 MC-6 / PHE , 105737
- Part No: ACA 112M-6/PHE B5
- Part No: FCA 132 M-4 / PHE B5 / UL
- Part No: FCM 180 L-4/HE
- Part No: Type: JM1 160 L-6/HE
- Part No: ACM 225 5-4/HE
- Part No: FCPA 80 B4/PHE
- Part No: TYPE FCA 71A-4
- Part No: ACA 90 L-6/HE
- Part No: ACA 90 L- 6/PHE
- Part No: FCA 112 M-4 IE2
- Part No: ACM 160 L-4/HE
- Part No: AB-BK 14MF

- Part No: Type FCPA 112M - 6
- Part No: FEM180L-4/PH
- Part No: PCM 180L-4-HE
- Part No: FCE 80A-4
- Part No: ACA 100 LA-4 / PHE PTC
- Part No: FCPA 100LB-4
- Part No: FCA 112M-6/HE
- Part No: ACA 100 Lb-8
- Part No: FCPA 90S-2
- Part No: Oil Seal for FCM 180-4
- Part No: Wave Washer for FCM 180-4
- Part No: PDM-4-B3-55-250M-G-Z2
- Part No: FCA 100 La-4 / PHE B5
- Part No: FGSP-63B4
- Part No: 5KE184FC2001RZ
- Part No: P/N:101375; Type:FCM 160 M-4 / PHE B5
- Part No: FCPA 132 MA-6 / PHE B35
- Part No: ACA 132 S-4/HE, 715353-00165203
- Part No: Type: ACM 225 S-4/HE
- Part No: Type: ACM 160 MB-4/HE
- Part No: Type: ACM 180 M-4/HE
- Part No: P/N:106160; Type: FCA 71 B-2 B5
- Part No: FCPA 90 S 4 /PHE
- Part No: P/N:106156; Type:FCPA 100 LB-4 / PHE B35 - UL-PTC
- Part No: Type FCM 200 L 4 / HE
- Part No: AC.LÜFTF1004
- Part No: P/N:106168; Type:FCM 200-4 / HE B5
- Part No: P/N:102374; Type:FCM 200-4 / PHE B5
- Part No: FCA 100 LC-4 / PHE - B5 400 /690
- Part No: ACA 100 Lb-4 / PHE OEM
- Part No: FMY 280M-6/PHE S/N: 1606230448
- Part No: Type:FMY 280M/PHE S/N: 1606230448
- Part No: FCA 56 A-2
- Part No: FCMP 200L-4/PHE
- Part No: FCMP 160L-4/PHE

- Part No: IE3AC09L4000
- Part No: ACM200L-4/PHE
- Part No: Type:AOM 200L-4 05101039
- Part No: JM 225M-6 /PHE
- Part No: mot.3~Type MB-4 No.08076496
- Part No: FCPA 132M-4/PHE
- Part No: FCMP 200 L-4/HE
- Part No: FCA-112MC-6 / PHE B5
- Part No: FCPA 71 A-4
- Part No: Model AWM 315 S-4 / PHE
- Part No: FCM 255 M-4/PHE
- Part No: FCA 90 L-4/PHE
- Part No: FCPY 100 LA-4/HE
- Part No: FCPA 112 MC-4 /PHE
- Part No: JM 112M-4PHE
- Part No: FCM 132 MC-4 /PHE
- Part No: ACL 180 L-4
- Part No: JM 160L-4
- Part No: ACM 180 L-4 / PHE
- Part No: ACA 132 S8-2/PHE
- Part No: FCPA 80B-2 /PHE
- Part No: ACM 225 S-4/PHE
- Part No: ACM 200 LA-2/PHE
- Part No: ACM 250 M-2/PHE
- Part No: ACM 280S-2/PHE
- Part No: FCPA 90S-6/PHE
- Part No: FCA80 A-6
- Part No: FCPA 90L-4/HE
- Part No: FCA80 B-8
- Part No: Type FCA 90L-4 N°06102880
- Part No: 10090273
- Part No: JM 250M-4/HE
- Part No: FCM 160 L-4 / PHE B5
- Part No: AC16L4200030
- Part No: ACM 160 LC-4 / PHE

- Part No: FCMP 180 L-4/PHE
- Part No: FCMP 180M-4/PHE
- Part No: FCA 80 B-8 (IP55 S1)
- Part No: FCA 80 B-2 /PHE
- Part No: ACA 132 SB-2 /PHE
- Part No: FCA 112 MC-6 /PHE
- Part No: FCY 90S-4/PHE
- Part No: FCM 180 LC-4 /PHE
- Part No: Type:EMY 225 S-4/HF
- Part No: FCM 225 S-4 /PHE IM V1
- Part No: FCM 225 S-4 /PHE IM B35
- Part No: FCA 112M-4 /PHE
- Part No: FCM 160MB-8 /PHE
- Part No: FCA 90S-6 OEM
- Part No: B3/B14
- Part No: ACL 100 LB-4/HF
- Part No: le3ac08b4103
- Part No: FCPA 112M-4/HE
- Part No: FCPA 112M-4 /PHE 230/400 V - 50 Hz
- Part No: BG112
- Part No: FCPA132MD-6/HE
- Part No: ACM 315MA-4/HE
- Part No: front flange back cover for FCA-71B4
- Part No: front flange back cover for FCPA132MD-6/HE
- Part No: Front-Back Cover for ACM 315MA-4/HE
- Part No: propeller for FCA-71B4
- Part No: propeller for FCPA132MD-6/HE
- Part No: propeller for ACM 315MA-4/HE
- Part No: ACA 90 L 2 /PHE
- Part No: FCP 90S - 4
- Part No: TYPE FCPA 80A-4
- Part No: Blower wheel for FCM 160L-4/PHE
- Part No: ACM 280M-4/HE
- Part No: FCA 71 A4 / HE
- Part No: FCMP 280M-4/PHE

- Part No: 6306-C-2Z-C3
- Part No: FCM 160 MB-4 / PHE
- Part No: JM 250M-4
- Part No: ACA 112 MC 4
- Part No: JM 280 S 4
- Part No: ACM 180 M 4 / PHE
- Part No: FCA 71A-4/PHE
- Part No: ACY 132 SB 2/HE
- Part No: FCM132S-6 /PHE
- Part No: Motor connection box with terminal board for FBSP 71B-4
- Part No: JM 132SA-2/PHE
- Part No: ACA112M-4/PHE 4Kw
- Part No: Terminal box for FBSP 71 B4
- Part No: Terminal board for FBSP 71 B4
- Part No: FCA 132 MC-2 B5 / PHE
- Part No: FCA 90 S 2 /PHE
- Part No: ACA 160 MA-2 B5 / PHE
- Part No: ACA 132 MB 6/PHE (Design: IM B5)
- Part No: TYPE-FCA132SB-2/PHE
- Part No: P/N : 103973 , Type : FCA 132 M-4 / PHE B5 - PTC
- Part No: Type: FCA 132 M 4/PHE
- Part No: FCM 225 M-4 / PHE B5 PTC
- Part No: FCA 132 MC-2 B5 / PHE PTC
- Part No: ACM315LB-2 /PHE
- Part No: FCA132SB-2 /PHE
- Part No: FCA 160 MA-2 B5 / PHE PTC
- Part No: Y-225-4.6 250 4,6,8
- Part No: Fan cover 250
- Part No: ACM 225 M-6 / PHE
- Part No: FCPA 71 B-4 B34a / HE
- Part No: P/N: ART00857, Type: FCA 132 S-4 B5 /PHE
- Part No: FCM 16 L-4
- Part No: FCA 100 La-4 / PHE B5 PTC
- Part No: CD132M-4/7.5KW
- Part No: CD90L2-4/1.5KW

- Part No: CD160M-4/11.0KW
- Part No: CD100L2-4/3.0KW
- Part No: CD100L1-4/2.2KW
- Part No: FCM160 M-4 /PHE
- Part No: FCA 112 M-2 /PHE
- Part No: ART02123
- Part No: EDM-2-B5-0,37-71-A-Z0
- Part No: Mount for FCPA 90 L-4 / PHE B35
- Part No: ACA 80B-4/HE
- Part No: FCA 63C-4
- Part No: FCA 100 LA-4/PHE) 18110055991P
- Part No: GmbH FCMP 225 M-4/PHE)
- Part No: FCA 132 SA 2 / PHE
- Part No: ACA 63C-4
- Part No: IE 2AC90L4004 8019911
- Part No: FCPA 80 B4 /PHE SIL2
- Part No: FCPA 80 C 4 /PHE
- Part No: FCPA 80 C 2 /PHE
- Part No: FCY 132 SA 2 /HE
- Part No: FCA 100 LA-4 /PHE
- Part No: FCM 225 M-6/PHE SN 1604534034
- Part No: FCM 225 M-6 /PHE
- Part No: FCA 90 L 4/6 polig
- Part No: FCA 90 L 4/8 polig
- Part No: FCA 132 MC-2 /PHE
- Part No: FCM 180 L-4 /PHE
- Part No: FCPA 80 A2 B34a / PHE
- Part No: FCA 71A-6
- Part No: FCA 90 L-4 / PHE B5
- Part No: Typ ACA 132MA-4/HE
- Part No: FCPA 112 M-6/PHE
- Part No: AWM 355 MB-6 / PHE
- Part No: FCA 112-4 /PHE
- Part No: ACM 160 L2 / PHE
- Part No: FCA 80 C-4 / PHE B14a / ART02413



- Part No: ACA 100 LB-4
- Part No: FC132MB-4 B5
- Part No: FCPA132S-4/PHE
- Part No: FCPA 80 B-4 /PHE
- Part No: FCMP 225 M-6/PHE
- Part No: ACA 160 L-8 / PHE / B3 / IP 56
- Part No: FCA 112 M-4 / PHE B5 400/690
- Part No: FCA 80 B-4 B14a /PHE
- Part No: JM 71B-4 old code, new code FCA 71 B-4 / HE B5 UL
- Part No: FCPA 90S-6/HE
- Part No: MMP 80G4
- Part No: Repair kit for FCA 90 L-4/PHE
- Part No: Repair kit for FCPA 112M-4/PHE
- Part No: FCM 200 LB-2 / PHE B5
- Part No: Repair kit for FCM 200 LB-2/PHE
- Part No: Repair kit for FCM 225 S-4/PHE
- Part No: FCM 180 M-2 / PHE B5
- Part No: Repair kit for FCM 180 M-2/PHE
- Part No: FCA 71 B-4 / HE B5 UL
- Part No: FCA 132 MB 6/HE
- Part No: FCM 200 L4 / PHE B5
- Part No: FOPA 180 L-4 / PHE B35
- Part No: 8JL.306.10243
- Part No: FCA 63 A-2 / HE B5
- Part No: FCPA 100 Lb-4 / PHE B35 / PTC / ART02654
- Part No: FCA 90 S-4 / PHE B5
- Part No: FCPA 90 L-2 / PHE B35 PTC
- Part No: FCPA132M-4/HE
- Part No: FCA 80 B-2/PHE SN:18080039953P
- Part No: FCM 200L-4/HE
- Part No: Fan blade 180
- Part No: FCPA 132 M-4 / PHE - B35 - PTC
- Part No: FCA 100 LA 4/HE (IE2AC10L4000)
- Part No: Type FCM 160M-4/PHE
- Part No: FCA 80 A-2 / PHE B5 PTC

- Part No: FCPA 80 B-2 /PHE - B35
- Part No: FCA 90 S-4 / PHE B14a
- Part No: ACA 100 L-2 / PHE PTC
- Part No: Type ACA 160 MA-2 / PHE
- Part No: AWM 315 M 2 /SPE
- Part No: FCM 160 M-47PHE
- Part No: ACM 280 S-2 / PHE
- Part No: FCA 132 SA-2 / PHE B5
- Part No: ACM 315 M 2 / PHE
- Part No: ACA 90 L-2 / PHE PTC
- Part No: ACA 80 B-4 / PHE
- Part No: terminal box for FCM 180 L-4 / PHE UL
- Part No: clipboard for FCM 180 L-4 / PHE UL
- Part No: AWM 280 S-4/PHE
- Part No: ACA 80 B 2/PHE
- Part No: ACA 90 L 4/PHE
- Part No: FCA 132 M-4 9.0kW
- Part No: FCPA 112 M 4/PHE
- Part No: Typ: ACM 180 M 4 / PHE
- Part No: FCA 90 LC 2 / PHE progressive
- Part No: back cover for FCMP 200L-4
- Part No: fan for FCMP 200L-4
- Part No: fan cover for FCMP 200L-4
- Part No: ART03067 / FCPA 63 B-4 / HE B34 / PTC
- Part No: FCA 112 M-2
- Part No: FCA 112 MC-2 / PHE (S3)
- Part No: FCA 112 M-2 / PHE (S3)
- Part No: FCA 56 A-4
- Part No: ACA 132 SA 2 /PHE
- Part No: ACA 90 S 2 /PHE
- Part No: FCA 132 MC-4/PHE
- Part No: FCM 160 L-4 /PHE
- Part No: FCPA 100 Lb-4 / PHE B35
- Part No: ACM 250M-4 No. 04050660
- Part No: fan blade 250

- Part No: FCM 160 MA-2 B5 / PHE PTC
- Part No: FCPA 90S-HE
- Part No: AC.KK-BG250
- Part No: FCPA 90 S-2 /PHE
- Part No: FBPA 80A-4 No. 0807551 86
- Part No: FCPA 80A 4/HE
- Part No: FCA 90LC - 4
- Part No: FCA 112 M-2/PHE (SN 19050077220P)
- Part No: FCA 112M-4/HE SN: 1606549692
- Part No: ACM 280S - 4/HE
- Part No: FCA 80 B-6 /HE
- Part No: FBSP 71 B4
- Part No: FCA 112 M-2 B5 / PHE / 230-400V
- Part No: ACM 280 S 4/PHE
- Part No: FCA 160 -L 4/PHE
- Part No: ART03520 / FCPA 112 M-4 / PHE B35 / PTC
- Part No: JM 160MB-2/PHE
- Part No: FCA 71 B 2 /HE
- Part No: FCPA 100LB-4/PHE /SN: 2006200166
- Part No: E3AC08B4007-P old code, new code FCPA 80 B-4 /PHE
- Part No: FCPA 80B-6 old code, new code FCPA 80 B-6/HE
- Part No: FCPA 80 B-6/HE
- Part No: FCPA 132 SA-2/PHE
- Part No: FCPA 56 B-2/HE
- Part No: N1309031112
- Part No: AWM 315 MA 4/PHE
- Part No: AWM 355 LX 4/PHE
- Part No: FCM 200 L 4 / PHE
- Part No: FCA 71 B-4/HE
- Part No: FCA 132S-6/HE sn: 12061377
- Part No: filter for FCA 63B-2/SN: 1905044706
- Part No: FCMP 280S - 4/... SN: 1704688608
- Part No: FCA 71B-403
- Part No: FWMP 280 S 4 / PHE
- Part No: AWM 355 LB 4/PHE

- Part No: AWM 315 LA 4/PHE
- Part No: FCMP 160 MB-2/PHE
- Part No: FY-71 8-4
- Part No: FCA 71B-2
- Part No: YXJ6322E cUL IE3 0,25kW
- Part No: FCA 71B-2 (SN: 1803833897)
- Part No: ACM 160 L4 / HE / IE2
- Part No: FCA 132 MA-6 / PHE
- Part No: FCA 71 B 2 / IE2
- Part No: ACM 160 L4 / PHE / IE3
- Part No: FCPA 132 S8 / PHE
- Part No: FCA 132 S-6/PHE
- Part No: ACA 132 MB 6/PHE (Design: IM B3)
- Part No: FCPA 132 MC 4 / PHE ( IE3AC13MC465-P : V175046 )
- Part No: FCPA 132 MC 4 / PHE ( IE3AC13MC465-P : V175853 )
- Part No: FCA 71 B-6 /HE
- Part No: FCA 90 L-8 /HE
- Part No: FCPY 132S-4/PHE
- Part No: FCA 112 MC4 / PHE
- Part No: E253167
- Part No: terminal box for FCM 160L-4/PHE
- Part No: AC.KK-BG160A
- Part No: AC.KB-BG160
- Part No: ACA 132 M-4/PHE
- Part No: FCA 132M-4 / 10080701
- Part No: FCA 90L-2/HE
- Part No: step controller for FCA 100L-2/HE
- Part No: FCMP 225 M-6/PHE 1810935683
- Part No: FCA 90 L 2 / PHE
- Part No: FCMP 225M-4 /PHE , 1810935683
- Part No: FCA 90LC-4/HE
- Part No: FCA 71 C 4 / progressiv
- Part No: FCA 71 A 6 / HE
- Part No: terminal box for FCM 160 L-4 /PHE ZB450
- Part No: terminal box cover for FCM 160 L-4 /PHE ZB450

- Part No: 8JL.354.4029 / AC-KK-BG160
- Part No: Typ: FCPA 100 LB 4 / PHE
- Part No: FCA 100LA - 4, NO: 05072131
- Part No: impeller for FCA 100-4/PHE
- Part No: FCMP 225 S 4 / PHE
- Part No: FCMP 250 M-4/HE
- Part No: FCA 71 A 2/HE
- Part No: FCM 200 LD-4/PHE
- Part No: cooling fan assembly FOR FCM 200 LD-4/PHE
- Part No: FCA 63B-2 / 2008212436
- Part No: 1503356146/JM 100LB-8 / B5
- Part No: JM 100LB-8/1503356110 / B5
- Part No: FRPA 132 SA-2/HE
- Part No: IE3AC11M4056N-P-V184335
- Part No: IE3AC11M4015N
- Part No: IE3AC11M2003N-P-V184206
- Part No: IE3AC09L2053-P-V184216 2,2-2P-BG90-B3/B5/200-230/400/50-KL-KKR-Festl-IE3
- Part No: ACM 160L-2/HE
- Part No: FCA 71B-2 00450481
- Part No: TYPE: K-D346 No 93805
- Part No: Nr. IE3AC13M4030 Type FCPA 132 M 4 / PHE